



LITTLEFIELD HISTORIC PHOTO



Existing Entry Door to be Replaced

Existing Railing to be High-Perforance coated (PT-1)




Removing railing to be replaced with railing to match other existing railings




LITTLEFIELD














PAINT EXISTING PLASTER (PT-3)

HIGH PERFORMANCE COATED DECORATIVE STEEL PLATE & TRIM (PT-2)

STRUCTURAL STEEL MEMBER (PT-2)


HIGH PERFORMANCE COATED STEEL















nh 2ND FLOOR 16' - 0" - LAMINATED GLASS PANELS - W-FLANGE STRUCTURAL STEEL MEMBER - PLATE STEEL ABOVE