



2011 Chestnut




Damaged siding
Foundation not to code



Siding Pulling away > Structure
Rock loose



Vinyl Siding Not original




VINYL SOFFIT NOT original

Roof decking of garage



Not original



Garage addition - not inspected



Daylight through roof over garage

addition to house this area



termite, dry rot. inside bedroom




addition to house, not original



damaged siding - particle board




BACK of House - foundation has rotted
members, on porch deck concrete post base



Water damage in bedroom



tile floor popping due to foundation



original
cast iron
plumbing