



And
Unit B


1408
W. 9th





Unit B

1408
W. 9th



1408 W 9th



Existing West Side



Existing South Side



Existing East Side

Structure to be renovated and lifted in order for a new lower level addition to be created below the original structure.



Structure to be renovated and a new addition created



1408 W 9th

Existing Back North Side

1408 W 9th:
Renovated Bldg 2
Units: 201 and 202
Unit Types: E and F

Renovated existing
structure to be lifted

New addition constructed
below existing structure



Composition shingle roofing




Iron railing



Add stone accents

Renovate or replace existing
roof brackets and apply
painted finish

Renovate or replace
existing siding and
apply painted finish



New exterior windows and doors
to mimic the existing style

1408 W 9th Unit B



Existing North Side

Existing South Side



Existing East Side



Existing West Side






Structure to be demolished
and a new structure built

1408 W 9th Unit B:
Bldg 5
Units: 501, 502, 503, 504
Unit Types: B1

Painted reverse board
and batten siding




Painted roof brackets



Composition shingle roofing



Iron railing



Stone accents



Dark bronze metal exterior windows and doors