

the supervision of Paul C is not to be used for regu approval, permitting, or construction purposes.

ISSUED DATE PROJECT NUMBER

ASI-06

BASEMENT PL





FIRE DEPT. CONNECTION AT WALL

FIRE DEPT. CONNECTION FREE STANDING

X WALL TAG FOR NEW OR INFILL WALLS, RE: A5.0

EXISTING EXPOSED CONCRETE

NEW EXPOSED CONCRETE

NEW STRUCTURAL FLOOR

30 MINUTE FIRE PARTITION (IBC 708)


1 HOUR FIRE BARRIER (IBC 707)

1 HOUR FIRE PARTITION (IBC 708)

• • • • • • 30 MINUTE SMOKE PARTITION (IBC 708)

NEW TILE

ISSUED DATE /17 0 PROJECT NUMBER ASI-06



KESTORATION NOTES

DECAYED AND DAMAGED FLOOR FRAMING.

5. NEW FIRE SPRINKLER SYSTEM TO BE INSTALLED

REPLACEMENT OF HISTORIC CERAMIC FLOOR TILE.

10. PATCH, REPAIR, AND REFINISH WOOD TRIM.

9. DOOR HARDWARE TO BE REMOVED, CATALOGUED,

REPAIRED AND REPLACED IN SAME PLACE THROUGHOUT. IF HARDWARE CANNOT BE REPAIRED NEW HARDWARE TO BE

11. ALL WINDOWS ARE TO BE INSPECTED FOR WOOD ROT,

REPLACE ANY ROTTEN WOOD IN KIND. SEAL SHUT FROM EXTERIOR. INTERIOR FINISH TO MATCH ADJACENT WALLS. LEVEL 2 LEVER HANDLES TO BE REMOVED, ALL OTHER HARDWARE TO REMAIN. CAP ALL OPENINGS AT HEAD JAMBS WITH WOOD AND

2. NEW HVAC THROUGHOUT.

THROUGHOUT.

TO REMAIN IN PLACE.

FINISH TO MATCH.

FABRICATED TO MATCH EXISTING.

3. NEW PLUMBING THROUGHOUT.

THROUGHOUT. REFER TO FIRE PLAN.

. FOUNDATION TO BE REPAIRED THROUGHOUT. REPLACE ALL

4. GAS LINES AND SUPPLY TO BE INSPECTED AND REPLACED

6. EXISTING WOOD FLOORS TO REMAIN ARE TO BE SANDED AND RESEALED W/ DURABLE MATTE SEALER THROUGHOUT. RE:

7. EXISTING TILE FLOORS TO REMAIN ARE TO BE REGROUTED

INTERIOR STANDARDS PRESERVATION BRIEF 40 FOR REPAIR AND

8. REMNANTS OF OLD CALL SYSTEM THROUGHOUT THE HOUSE

AND REPAIRED AS REQUIRED. REFER TO SECRETARY OF THE

DRAWING LEGEND

EXISTING WALL TO REMAIN

NEW DOOR

EXISTING TILE

NEW CONSTRUCTION

EXISTING DOOR TO REMAIN (U.N.O)

AREA BELOW GRADE LEVEL

EXISTING WOOD FLOORING

SECOND FLO

RESTORATION NOTES DRAWING LEGEND 1. FOUNDATION TO BE REPAIRED THROUGHOUT. REPLACE ALL EXISTING WALL TO REMAIN FIRE DEPT. CONNECTION AT WALL EXISTING EXPOSED CONCRETE DECAYED AND DAMAGED FLOOR FRAMING. FIRE DEPT. CONNECTION FREE 2. NEW HVAC THROUGHOUT. 3. NEW PLUMBING THROUGHOUT. **NEW CONSTRUCTION** STANDING 4. GAS LINES AND SUPPLY TO BE INSPECTED AND REPLACED NEW EXPOSED CONCRETE THROUGHOUT. X WALL TAG FOR NEW OR INFILL WALLS, RE: A5.0 5. NEW FIRE SPRINKLER SYSTEM TO BE INSTALLED EXISTING DOOR TO REMAIN (U.N.O) THROUGHOUT. REFER TO FIRE PLAN. **NEW TILE** 6. EXISTING WOOD FLOORS TO REMAIN ARE TO BE SANDED AND RESEALED W/ DURABLE MATTE SEALER THROUGHOUT. RE: **NEW DOOR** 7. EXISTING TILE FLOORS TO REMAIN ARE TO BE REGROUTED NEW STRUCTURAL FLOOR AND REPAIRED AS REQUIRED. REFER TO SECRETARY OF THE AREA BELOW GRADE LEVEL INTERIOR STANDARDS PRESERVATION BRIEF 40 FOR REPAIR AND REPLACEMENT OF HISTORIC CERAMIC FLOOR TILE. • • • • • • 30 MINUTE SMOKE PARTITION (IBC 708) 8. REMNANTS OF OLD CALL SYSTEM THROUGHOUT THE HOUSE TO REMAIN IN PLACE. EXISTING WOOD FLOORING 9. DOOR HARDWARE TO BE REMOVED, CATALOGUED, 30 MINUTE FIRE PARTITION (IBC 708) REPAIRED AND REPLACED IN SAME PLACE THROUGHOUT. IF HARDWARE CANNOT BE REPAIRED NEW HARDWARE TO BE FABRICATED TO MATCH EXISTING. 1 HOUR FIRE BARRIER (IBC 707) **EXISTING TILE** 10. PATCH, REPAIR, AND REFINISH WOOD TRIM. 11. ALL WINDOWS ARE TO BE INSPECTED FOR WOOD ROT, 1 HOUR FIRE PARTITION (IBC 708) REPLACE ANY ROTTEN WOOD IN KIND. SEAL SHUT FROM EXTERIOR. INTERIOR FINISH TO MATCH ADJACENT WALLS. LEVEL 2 LEVER HANDLES TO BE REMOVED, ALL OTHER HARDWARE TO REMAIN. CAP ALL OPENINGS AT HEAD JAMBS WITH WOOD AND FINISH TO MATCH.

