City Of Austin Historic Landmark Commission Certificate of Appropriateness Review Committee 06.10.2019

NRD-2019-0033 3206 GLENVIEW AVENUE

Construct a second-story addition to a one-story contributing house





PHOTOS OF EXISTING STRUCTURES



FRONT OF RESIDENCE





REAR OF RESIDENCE



RIGHT SIDE OF RESIDENCE




SIDE OF GARAGE




FRONT OF GARAGE

3206 GLENVIEW AVE - COA REVIEW COMMITTEE 06.10.2019




EXISTING FLOOR PLAN


EXISTING RESIDENCE RENDERING



EXISTING RESIDENCE ISSUES/ CONCERNS

- 1. FOUNDATION IN POOR CONDITION
- 2. REAR ADDITION SHOWING EVIDENCE OF ACTIVE WOOD DESTROYING INSECTS
- 3. WATER LEAKS IN ROOF
- 4. WINDOWS IN POOR CONDITION WITH WATER INFILTRATION
- 5. ORGANIC GROWTH UNDER VANITY IN BATH 2
- 6. SUN ROOM FLOORING CONTAINS ASBESTOS
- 7. WOOD ROT






3206 GLENVIEW AVE - COA REVIEW COMMITTEE 06.10.2019


PROPOSED FLOOR PLAN

WORKSHOP



3206 GLENVIEW AVE - COA REVIEW COMMITTEE 06.10.2019

PROPOSED ELEVATIONS SUBMITTED FOR PERMIT



PROPOSED DESIGN FEATURES

BRICK FACADE ON ALL FOUR ELEVATIONS. EXISTING BRICK TO REMAIN AND NEW BRICK TO MATCH EXISTING BRICK SIZE AND COLOR






PROPOSED ELEVATIONS SUBMITTED FOR PERMIT






NORTH ELEVATION



PROPOSED DESIGN FEATURES

BRICK FACADE ON ALL FOUR ELEVATIONS ON FIRST LEVEL ONLY. EXISTING BRICK TO REMAIN, AND SECOND FLOOR TO BE BOARD AND BATTEN WITH A TRIM PIECE CLEARLY DELINEATING BETWEEN THE ORIGINAL AND THE NEW.



PROPOSED ELEVATIONS WITH DELINEATION

