

FIELD REPORT IMAGES

For existing conditions at 1410 and 1408 West 9th Street

Survey Date: Monday, June 17, 2019  
Time: 1:30pm - 3:45pm  
Location:  
Participants: Webber + Studio (Architect): Marek Hnizda (MH)  
JB Cumby Construction (Contractor): Robin Moore  
**BLACK** indicates action required.

- I. TOPICS:
- (1) Survey of Existing windows/doors/siding at 1410 West 9th Street
  - (2) Survey of Existing windows/doors/siding at 1408 West 9th Street

1220 Lavaca St.

AUSTIN, TX 78701



**Image of window condition 1410 West 9th Street (this page). Evidence of Rot, Termite damage, and physical damage present.**



Image of window condition 1410 West 9th Street (this page). Evidence of Rot, Termite damage, and physical damage present.





**Image of window condition 1410 West 9th Street (this page). Evidence of Rot, Termite damage, and physical damage present.**




**Image of window condition 1410 West 9th Street (this page). Evidence of Rot, Termite damage, and physical damage present.**





**Image of window condition 1410 West 9th Street (this page). Evidence of Rot, Termite damage, and physical damage present.**



**Image of window condition 1408 West 9th Street (this page). Evidence of Rot, Termite damage, and physical damage present.**





**Image of window condition 1408 West 9th Street (this page). Evidence of Rot, Termite damage, and physical damage present. Damage to existing windows due to plexiglass reinforcement and lack of weatherstripping causing further moisture damage at window frame.**





**Image of window condition 1408 West 9th Street (this page). Evidence of Rot, Termite damage, and physical damage present. Damage to existing windows due to plexiglass reinforcement and lack of weatherstripping causing further moisture damage at window frame.**



**Image of window condition 1408 West 9th Street (this page). Evidence of Rot, Termite damage, and physical damage present. Damage to existing windows due to plexiglass reinforcement and lack of weatherstripping causing further moisture damage at window frame.**





**Image of window and door condition 1408 West 9th Street (this page). Evidence of Rot, Termite damage, and physical damage present. Replacement windows without weatherstripping causing further moisture damage at window frame.**



**Image of window and siding condition 1408 West 9th Street (this page). Evidence of Rot, Termite damage, and physical damage present.**





**Image of window condition 1408 West 9th Street (this page). Evidence of Rot, Termite damage, and physical damage present. Damage to trim detailing. Repair/replacement in-kind proposed.**



**Image of exterior trim siding condition 1408 West 9th Street (this page). Evidence of Rot, Termite damage, and physical damage present. Damage to trim detailing. Repair/replacement in-kind proposed.**

End of Field Report.