

1911 Robbins Place conditions assessment photographs from Applicant



Street view



Entry arch



East elevation, low cracks



East elevation, high cracks





Crawlspace access



Sinking sill on south elevation



Open sill on west elevation



West elevation at front porch






Interior cracks



Interior cracks



Interior tile