

## **3003 E 18th Street Condition**

Roof deteriorated with water leaking through to the interior of the house

Rotted / carpenter ant damage to beams

Uneven floors inside of house due to damaged beams













