







base of column removed

wood siding replaced
with stucco

steel outrigger, supporting fascia





