



Existing chimney and proposed elevator shaft are not visible due to tree coverage



Existing chimney and proposed elevator shaft (outline) are partially visible due to tree coverage.

