

EXISTING CONDITIONS AND CONSTRAINTS





ALMOST THIRTY YEARS OF TREE GROWTH SINCE THE PLAY EQUIPMENT WAS INSTALLED



LOW BRANCHES LIMITING POSSIBLE LOCATION OF NEW PLAY EQUIPMENT



NO ACCESSIBLE PLAY OPTIONS AT EXISTING LOCATION. IF PEAGRAVEL WERE REPLACED WITH 12" DEEP SAFETY MULCH IT COULD CAUSE ROT AND MOISTURE DAMAGE AT THE BASE OF THE TREE TRUNKS



LOW BRANCHES THAT INTERACT WITH PLAY FEATURES CREATE SAFETY HAZARDS IN THE PLAY AREA



TYPE OF SWINGS ARE LIMITED BY TREE BRANCHES AND MEASURES OF CLEAR ZONES REQUIRED BY CONSUMER PRODUCT SAFETY COMMISSION


ALTERNATIVE PLAY OPPORTUNITIES UNDER THE LIVE OAK TREES








PRELIMINARY PLAYGROUND DESIGN



ONLINE SURVEY RESULTS





2-5 YEAR PLAY FEATURE




SWING & SPIN FEATURES

OPTION A







OPTION B







OPTION C







PROPOSED SITE AMENITIES & MATERIALS

SEATING AND PICNIC TABLES



LUEDER LIMESTONE BLOCK



MOVEABLE PICNIC TABLE

FENCE AND COLUMNS AT PARKING LOT



STONE COLUMNS




SPLIT RAIL FENCE


KIOSK AT ENTRY



KIOSK

NATURE PLAY & LOOSE PARTS PLAY (FORT BUILDING)







ALTERNATE, RUBBER SAFETY SURFACE

