




Adjust layout of irrigation system in the field around existing asphalt service road. Cut and patch road where pipes go under road. Layout heads where no water sprays onto the road. Half heads along edge of pavement to be 18" for edge of wires in PVC Sch 40 Sleeves. Any valves and/or valve boxes need to be a minimum of 6ft from edge of pavement.

Locate existing Golf Course irrigation system 4" main line for Point of Connection in this general area. Coordinate with Golf Course Superintendent.




Professional Project, Design and Construction

SRI and ASSOCIATES

Golf Courses, Commercial, & Residential
Water Management Design

STEIN BRONKHORST
TOLSON BRONKHORST
LOHMEYER BRONKHORST

3407 NORMAN BLVD
CROFTON, TEXAS 78014
(817) 300-0000 / FAX



BY			REVISION			DATE			NO.		

MUELLER SUBSTATION		
4307 Manor Road		
IRRIGATION PLAN		

L1.03		
SHEET		
- OF -		

GARCIA DESIGN INC.		
LANDSCAPE ARCHITECTURE		
PLANNING-URBAN DESIGN		
11500 Metric Blvd.		
Bldg. M-1, Suite 150		
AUSTIN, TEXAS 78758		
PHONE: (512) 892-0353 FAX: (512) 821-2085		
email - rgarcia@garciadesigninc.net		
http://www.garciadesigninc.net		

These documents are		
incomplete and may not be		
used for regulatory approval,		
permit, or construction.		
Roberto C. Garcia		
TX Landscape ACP, #1292		
Feb. 22, 1011		