


Comments		
Roadside Development	<div> <div></div> <div>Residential</div> <div></div> <div>Commercial</div> <div></div> </div>	
Accidents (attach summary if >5)		
Advisory Speeds (see attached ball bank form)	N/A	
Recommended Speed Zones	35 mph	
<div> <div> <div>Toward</div> <div>RM 620 (North Entrance)</div> </div> <div> <div></div> <div>Boulder Lane</div> </div> <div> <div>Roadway</div> <div>RM 620 (South Entrance)</div> <div>Toward</div> </div> </div>	<div> <div>RM 620</div> <div> <div>39.1</div> <div>55-60</div> <div>1,281</div> </div> </div> <div> <div>Cinnabar Trail</div> </div> <div> <div>Indigo Brush Dr</div> </div> <div> <div>Corbe Drive</div> </div> <div> <div>40</div> <div>60-65</div> <div>1,509</div> </div> <div> <div>Dona Villa Dr.</div> </div> <div> <div>RM 620</div> </div>	<div> <div>Barbrook Drive</div> </div> <div> <div>Aire Libre Drive</div> </div> <div> <div>Savannah Ridge Dr.</div> </div> <div> <div>46</div> <div>65-70</div> <div>3,035</div> </div>
Recommended Speed Zones	35 mph	
Advisory Speeds (see attached ball bank form)	N/A	
Accidents (attach summary if >5)		
Roadside Development	<div> <div></div> <div>Residential</div> <div></div> <div>Commercial</div> <div></div> </div>	
Comments		

XX
XX-XX
XX

85th Percentile Speed

Top Speed Measured

Number of Vehicles Checked



Mid Block Accident

Intersection Accident





Match Line

## SPEED ZONE MAP

Not to Scale


Speed Zone Investigation: Peter Marsh

## Existing




30 mph

## Proposed



35 mph




Comments										
Roadside Development	<div>Commercial</div> <div>Residential</div>									
Accidents (attach summary if >5)										
Advisory Speeds (see attached ball bank form)	N/A									
Recommended Speed Zones	35 mph									
<div> <div>Toward</div> <div>RM 620 (North Entrance)</div> </div> <div> <div>Boulder Lane</div> </div> <div> <div>Roadway</div> <div>RM 620 (South Entrance)</div> <div>Toward</div> </div>	RM 620	Foundation Road	<div>38.6</div> <div>55-60</div> <div>3,614</div>		Beckwood Drive	Crossland Drive	Crossland Drive	<div>34.7</div> <div>45-50</div> <div>2,989</div>	Chestnut Ridge Rd	Chestnut Ridge Rd
				Sweet Basil Drive	Appletree Lane	Appletree Lane		<div>32.7</div> <div>55-60</div> <div>2,801</div>	Ember Glen Drive	
Recommended Speed Zones	35 mph									
Advisory Speeds (see attached ball bank form)	N/A									
Accidents (attach summary if >5)	<div>①</div> <div>①</div> <div>①</div>									
Roadside Development	<div>Commercial</div> <div>Residential</div>									
Comments										

XX
XX-XX
XX

85th Percentile Speed

Top Speed Measured

Number of Vehicles Checked



Mid Block Accident

Intersection Accident



Match Line

## SPEED ZONE MAP

Not to Scale