


PROFESSIONAL STRUCIVIL ENGINEERS, INC. STRUCTURAL CIVIL ENVIRONMENTAL











PROFESSIONAL STRUCIVIL ENGINEERS, INC.





12710 RESEARCH BLVD., SUITE #390, AUSTIN, TEXAS 78759 FAX 512.258.8095 PSCE@PSCEINC.COM



June 23, 2014

Mr. Jim Bennett **Bennett Consulting** 11505 Ridge Drive Austin, Texas 78748

Reference: Residential Damage

> 3805 Red River Street Austin, Texas 78751


Dear Mr. Bennett:

Pursuant to your request, Professional StruCIVIL Engineers, Inc. (PSCE) performed visual reconnaissance of the damage to the residential structure located at 3805 Red River Street on May 16, 2014.

It is my opinion, based on our experience, that this foundation is not repairable and needs to be demolished. The structure is unsafe and unstable; a hazard to public safety. This letter needs to be read in conjunction with PSCE's previously prepared report, dated May 19, 2014, and with the memo prepared by Centex Foundation, dated June 19, 2014.

If you have any questions, please call my office at 512-238-6422.

Sincerely. PROFESSIONAL StruCIVIL ENGINEERS, INC.



Mirza Tahir Baig, P.E. Principal

5124784545

PAGE. 1/ 1

Print

https://us-mg204.mail.yahoo.com/neo/launch?-partner=sbc&.rand=0...

Subject: 3805 Red River

18.07.2014 07:39 PM

From: Dean Zubkoff (dean@welevelit.com)

To:

browning.k@sbcglobal.net;

Døte:

Tuesday, June 17, 2014 8:24 PM

Karen,

I inspected the house @ 3805 Red River today. It is my opinion that the slab foundation that has heaved in the center and dropped on the edges cannot be leveled due to a lack of structural integrity.

Since the slab cannot be leveled, the only fix would be to remove and replace it. There is no guarantee that a new slab foundation won't have the same issues as the existing one.

Dean Zubkoff

CenTex Foundation Repair

(512) 230-2310

dean@welevelit.com