HISTORIC LANDMARK COMMISSION JULY 24, 2017 DEMOLITION AND RELOCATION PERMITS HDP-2017-0320 1404 E. 2ND STREET

PROPOSAL

Demolish a ca. 1949 house.

ARCHITECTURE

One-story, rectangular-plan, front-gabled frame house with a front-gabled, partial-width independent porch offset to the right on the façade; single 6:6 fenestration.

RESEARCH

The house was built in 1949 by Juan Davila, who was a butcher. Juan and his wife, Concepcion, lived here until around 1955. The house was then purchased by Frank and Mary B. Moreno, who lived here until around 1975, although it appears that the house stayed in the family for longer than that – Robert Moreno, one of Frank and Mary Moreno's sons, was listed as the renter of the house in the 1981 directory.

STAFF COMMENTS


The house was not listed in the Comprehensive Cultural Resources Survey (1984). The Est Austin Historic Resources Survey (2016) shows that house as ca. 1951, with a recommendation that the house is not eligible for a local nor a National Register designation.


The house does not meet the criteria for landmark designation as set forth in City Code:

- a. **Architecture.** The house is a frame late 1940s bungaloid, a common style. The house has no architectural distinction within its architectural style.
- b. **Historical association**. There do not appear to be any significant historical associations.
- c. **Archaeology**. The house was not evaluated for its potential to yield significant data concerning the human history or prehistory of the region.
- d. **Community value**. The house does not possess a unique location, physical characteristic, or significant feature that contributes to the character, image, or cultural identity of the city, the neighborhood, or a particular demographic group.
- e. **Landscape feature**. The property is not a significant natural or designed landscape with artistic, aesthetic, cultural, or historical value to the city.

STAFF RECOMMENDATION

Encourage rehabilitation and adaptive re-use, then relocation over demolition, but release the permit upon completion of a City of Austin Documentation Package.





NOTIFICATIONS

CASE#: HDP-2017-0320 1404 E. 2ND STREET

This product is for informational purposes and may not have been prepared for or be suitable for legal, engineering, or surveying purposes. It does not represent an on-the-ground survey and represents only the approximate relative location of property boundaries.

1 " = 250 '

This product has been produced by CTM for the sole purpose of geographic reference. No warranty is made by the City of Austin regarding specific accuracy or completeness.



1404 E. 2nd Street ca. 1949



OCCUPANCY HISTORY 1404 E. 2nd Street

City Directory Research, Austin History Center By City Historic Preservation Office July, 2017

1992	John and Elizabeth A. Rodguizes,	renters
1002	John and Enzabeth A. Nouguizes,	ICHICIS

Employed by IBM

NOTE: The directory indicates that John and Elizabeth A. Rodguizes were new

residents at this address.

1985-86 Noemi T. Rodriguez, renter

No occupation listed

1981 Robert Moreno, renter

Retired

1977 Julia P. Moreno, renter

No occupation listed

1973 Mary B. Moreno, owner

Widow, Frank Moreno No occupation listed

1968 Mary B. Moreno, owner

Widow, Frank Moreno No occupation listed

1965	Mary B. Moreno, owner Widow, Frank Moreno No occupation listed
1961	Mary B. Moreno, owner Widow, Frank Moreno No occupation listed
1957	Frank and Mary Moreno, owners No occupation listed
1953	Juan and Concepcion Davila, renters Meat cutter NOTE: Frank and Mary Moreno are listed at 806 East Avenue; neither had an occupation shown.
1952	Juan and Concepcion Davila, owners Butcher, City Abattoir, 525 Pleasant Valley Road.
1949	The address is not listed in the directory. NOTE: Juan and Concepcion Davila are not listed in the directory.

BIOGRAPHICAL NOTES

Frank and Mary B. Moreno (ca. 1955 – ca. 1975)

Frank and Mary Moreno appear in the 1940 U.S. Census as the owners of the house at 806 East Avenue; that house was worth \$1,000. Frank Moreno was 58, had been born in Texas, and was a waiter in a restaurant. Mary Moreno was 51, had been born in Texas, and had no occupation listed. They had 3 children: Willie, 19, a waiter in a restaurant; Frances, 16, a "new worker"; and Rose, 12. All the children had been born in Texas. In addition, there was a grandson, Earl Moreno, 4, who had been born in Texas, and a step-daughter, Julia Penedo, 30, who had been born in Texas and was a saleslady in a ladies' ready-to-wear clothing store, and Julia's children, Anna, 9; Dora, 7; Jimmie, 5; Mary, 3; and Manuel, 2.

Frank Moreno died in 1960, while living at this address. He was born in 1880 in Texas, and was a waiter.

FRANK MORENO, SR.

Frank Moreno Sr., died at his home 1:01 East Second Wednesd day night.

Survivors are his widow, Mrs.
Mary Moreno; 5 daughters, Mrs.
Judy Pineda, Mrs. Lucille Herrera, Mrs. Ann Ledesma, and
Mrs. Francis Rincon all of Austin, and Mrs. Rose Tannlund of
California, Three sons, Frank
Moreno Jr., Robert Moreno and
Will Moreno all of Austin; a sister, Miss Lupe Moreno of San
Antonio, 48 grandchildren and 50
great grandchildren.

Funeral arrangements are pending with the Cook Funeral Home.

Obituary of Frank Moreno Austin <u>Statesman</u>, February 11, 1960

FRANK MORENO SR.

Requiem mass for Frank Moreno Sr. was held Friday at noon at Cristo Rey Church with Father Frank Briganto officiating. Burial was in Mt. Calvary Cemetery under the direction of the Cook-Chapel of Roses.

Palibearers were Willie Moreno Jr., Robert Moreno, Jimmie Pineda, Manuel Ledesma Jr., Ruby Moreno, Roland Moreno, Mario Rincon and Edward Moreno.

Notice of requiem mass for Frank Moreno Austin <u>Statesman</u>, February 12, 1960

John Bavilla 😘

1404 East 2nd Street

East 50'x138' of P

Frame residence.

42043 9-26-49

\$4000.00

Owner

5

E 50' XX38'4 P WATER SERV	ICE PERMIT	C Nº	23-A-7762			
Austin,		C IV.				
Received of JOHN V. D	AUICEA	Date /	1.24-10			
Address 1400 E 2	no	•				
Amount TWV ETVY	ANDA	Volive V	s 20 °:			
Plumber		Size of T	ap 3/4"			
Date of Connection 3-29-51 Size of Tap Made Size Service Made Size Main Tapped From Front Prop. Line to Curb Cock From Prop. Line to Curb Cock Location of Meter Type of Box Depth of Main in St. Depth of Service Line From Curb Cock to Tap on Main Checked by Engr. Dept. 5-1-51 NDEXED Water service permit to John	No. Fittings Curb Cock Elbow St. Elbow Bushing	Pipe Lead Comp Nipples Union Plug	Jud II C. D. D. Valves Job No. W. 323 & 02			
	, Texas	//11	(1051			
Received of owner Address 1404 E. 2nd.						
Amount		\$				
Builder or Owner John Davilla						
Lot W. 50'x138 ofP Block Subdivision Plat No. 23A						
Date of Connection 4/18/1951	9		6			
By City 34' E, of WLL	Price 8 .95		1.00 1.00			
By Plumber %						
Checked By Ramirez	a l		190111			
Size Main 6" Depth 4'	Size		5			
Main Assign. in alley 3' S. of N. PL Stub Depth Prop. Line 2'			R23 foreman			
Stub LocationFlop. Line 2	Fittings Pipe 6" Pipe Wyes Wyes 6" Reducers	Plugs Sand	R23 Forem			
Book No. B-885	Fittings Pipe 6" Pipe Pipe Wyes Bends 6	Sand Sand Gravel Remix Stoppe				
Paving CutNo.	10. F1	Sa Sa St	1 Othe			
		1111	1 1 1			

Sewer service permit referencing John (Juan) Davila as the owner of the house (1951)

26

Mrs. Mary Moreno 1404 East 2nd St. B.45' of W. 145' of 27

unplatted

Frame addition rear of residence

80198 6-15-61 100.00

P. Rincon

STORAGE

#147427 1-24-75 Mary B. Moreno Frm. Addn. to Res 375.00 192 Sq.Ft. Den

Building permit to Mary Moreno for a frame addition to the rear (1961) and for a frame addition (1975)