# HISTORIC LANDMARK COMMISSION NOVEMBER 27, 2017 DEMOLITION AND RELOCATION PERMITS HDP-2017-0683 3515 WEBBERVILLE ROAD

# PROPOSAL

Demolish a ca. 1929 frame building moved to the site in 1971.

## ARCHITECTURE

One-story L-plan wood-frame civic building clad in wood siding and capped by front- and side-gabled roofs. The building features a front-gabled enclosed entry porch, single-hung aluminum-sash windows, exposed rafter tails, and brackets in some gable ends.

## RESEARCH

The building was constructed at 3706 King Street ca. 1929 as rooming house or apartment complex. After World War II, the property was purchased by Post 8787 of the Veterans of Foreign Wars to serve as a gathering space and reception hall. The VFW sold the building to the Greater Union Missionary Baptist Church in July 1971 for \$60,000.

Greater Union Missionary Baptist was formed in 1970 and originally met at members' and pastors' homes, as well as the Salina Activity Center. The church moved the former VFW hall to a newly purchased 1-acre lot at 3515 Webberville Road. According to a 1990 church history by Reverend Dr. Rickey Williams, the new building contained a 150-seat auditorium, a hall, and a ladies' lounge. The building served as Greater Union's primary worship space from 1972 until 1976, when the congregation moved to a new building at 2939 Pecan Springs Road.

By 1980, the building had been purchased by the Unity Friendship Baptist Church, which worshiped there until 2016.

#### STAFF COMMENTS

3515 Webberville Rd. does not appear in any city surveys.

The structure does not appear to meet the criteria for designation as a historic landmark, as it does not retain its original location or use. Therefore, it does not meet the integrity requirements outlined in Section 25-2-352 of the Land Development Code.

# Designation Criteria—Historic Landmark


- 1) The building itself is over 50 years old, having been constructed ca. 1929. However, its period of significance as a religious building at its current address begins in 1971, which does not meet the 50-year threshold for age and significance.
- 2) The building does not retain integrity of location, setting, association, or feeling. It retains a moderate degree of integrity of design, craftsmanship, and materials.
- 3) Properties must meet two historic designation criteria for landmark designation (City of Austin Land Development Code (Section 25-2-352). The property does not appear to demonstrate significance according to any of the criteria.
  - a. **Architecture.** The building is built in a vernacular style. It does not appear to be architecturally significant.

- b. **Historical association**. At its current site, the building does not maintain its historic association with either the VFW or the original apartment residents.
- c. **Archaeology**. The property was not evaluated for its potential to yield significant data concerning the human history or prehistory of the region.
- d. **Community value**. The property does not appear to possess a unique location, physical characteristic, or significant feature that contributes to the character, image, or cultural identity of the community, Austin, or Texas as a whole. Its religious affiliation falls outside of the 50-year threshold for period of significance.
- e. Landscape feature. The property is not a significant natural or designed landscape with artistic, aesthetic, cultural, or historical value to the city.

## STAFF RECOMMENDATION

Encourage rehabilitation and adaptive re-use. If rehabilitation and adaptive re-use are not feasible, then encourage relocation over demolition and release the permit upon completion of a City of Austin Documentation Package consisting of photographs of all elevations, a dimensioned sketch plan, and a narrative history, for archiving at the Austin History Center.

## LOCATION MAP



# PROPERTY INFORMATION

Photos



Primary (west) façades and north elevation, looking south.



Primary façade of main entrance.



Primary façade of rear addition.


#### Occupancy History

City directory research, Austin History Center By Historic Preservation Office staff November 2017

1972	Greater	Union	Baptist	Church
------	---------	-------	---------	--------

- 1977 Greater Union Baptist Church
- 1985-86 Friendship Baptist Church Rev. Willie L. Bartee, pastor

#### Background Research



These newspaper clippings from 1929 (left) and ca. 1930s (right) show a building permit for 3706 King Street and advertisements for furnished rooms at the same address.

MERCHA	NDISE
57-BUILDI	NG MATERIALS
Street, to be of all main accepted unit For informat coll 477-9777.	<ul> <li>V.F.W. Building 3706 King moved and grounds cleared rials. Seated bids will be it 10:00 a.m. August 12, 1970 lon or appointment to inspect Mall bids to V.F.W. Post Mall bids to V.F.W. Post N. Austin, Texas 78751.</li> </ul>
ALL KINDS ond fixtures.	of used building materials Reasonable prices, 243-1100

Ad for auction of building at 3706 King St. Austin-American Statesman, August 1970.


Building Permits

South Union I	Bant Church	3515 Webberville Ro	d
OWNERPOUCH CHITCH I	Supt. ChurchDDRESS	JJIJ WEDDERVITTE KC	au
PLAT 263 LO	or 2	BLK	
SUBDIVISION Woma	ck Ad <sup>dn</sup> Sec 1		
OCCUPANCY Chur			
BLD PERMIT # 12363	1 <sub>DATE</sub> 6-22-71	OWNERS ESTIMATE \$30,000.00	
CONTRACTOR OWNER		NO. OF FIXTURES SEE pl	ans
WATER TAP REC # E60	5771 SEWER T.	<u>AP REC # 59764</u>	
One story w		g. to move on lot an	d
repair	3376 sq. f.t		
<b>D</b> :11: · · ·		1: ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( (	

Building permit to move commercial building at a cost of \$30,000, issued to Southern Union Baptist Church, 6-22-1971.

S≄gn OWNER	Southern	Union	Baptist	Chur <u>AD</u> D		515 Webber	ville Rd.
PLAT	263	LOT_	2				<u>3LK</u>
SUBDIV	ISION W	omack A	ddn Sec	1			
OCCUPA	NCY Sign-	Friend	ship Bap	ot ist	Church		
BLDG.	PERMIT #	200751	DA	TE	8/12/80	OWNERS ESTIMATE	\$150.00
CONTRA	CTOR Pe	psi Col	a			O. OF FIX	
WATER	TAP REC#			SEWER TAP REC#			

Sign permit for Friendship Baptist Church, issued to Southern Union Baptist Church, 8/12/1980.



1935 Sanborn map showing the building at 3706 King Street. It is not clear how the existing building aligns with the footprint shown.