



Current Traffic Issues

		AM Peak Hour ²		Peak our ¹		
Entering Vehicles						
Red River Street (just south of East César Chavez Street)	3,703	41%	283	41%	207	35%
Driskill Street (just west of I-35 Southbound Frontage Road)	1,010	11%	58	8%	37	6%
River Street (just west of I-35 Southbound Frontage Road)	2,239	25%	162	24%	222	37%
East Avenue (just south of River Street)	733	8%	60	9%	61	10%
Rainey Street (just south of River Street)	1,276	14%	124	18%	67	11%
Total Entering Vehicles	8,961		687		594	
Exiting Vehicles						
Red River Street (just south of East César Chávez Street)	3,535	37%	92	28%	359	43%
Driskill Street (just west of I-35 Southbound Frontage Road)	1,159	12%	19	6%	110	13%
River Street (just west of I-35 Southbound Frontage Road)	2,815	30%	123	37%	153	18%
East Avenue (just south of River Street)	646	7%	46	14%	51	6%
Rainey Street (just south of River Street)	1,369	14%	51	15%	160	19%
Total Exiting Vehicles	9,524		331		833	



	ghborho	od 1	[rip	Ge	nc
	gricorrio	00	ΥĽ	\mathbf{C}	
********					r
TABLE 10: E	STIMATED TRIP GENERATION FOR I	ENTIFIED REDEV	ELOPMENT S	ITES	
Development Name	Land Use	Daily Trips	AM Peak Hour Trips	PM Peak Hour Trips	
Homewood Suites	Hotel	858	56	63	
70 Rainey	Condo	704	53	63	
Waller Park Place	Condo, Hotel, Apartment & Office	5,641	575	587	
Hotel Rainey	Hotel	160	10	12	
48 East Avenue	Apartment & Retail	1,853	94	166	
Hotel Cambria	Hotel	858	56	63	
East Avenue Apartmen	ts: Apartment	1,052	81	98	
Villas on Town Lake	Condo, Hotel, Apartment & Office	5,641	575	587	
Sutton Company (Parking	Lot) Office & Retail	4,846	573	630	
MACC Master Plan	Parks and Recreation	N/A	26	95	
91 & 93 Red River Stre	et Condo	704	53	63	
World Class Capital (IH)	OP) Office & Retail	2,748	328	343	
54 East Avenue	Apartment & Retail	3,675	188	329	
76 East Avenue	Hotel	858	56	63	
74 & 78 Rainey Stree	t Office & Restaurant	1,851	96	204	
47, 49 & 51 East Aven	ae Apartment & Retail	3,675	188	329	
Fairmont Hotel (Red Riv	er) Hotel	6,005	390	441	
	TOTAL	41,129	3,398		





- Crippling a needed North/South alternative to Rainey St.
- Adding additional stress on a heavily trafficked Rainey St.
- Safety Concerns

