HISTORIC LANDMARK COMMISSION

APRIL 22, 2019

PERMIT IN NATIONAL REGISTER HISTORIC DISTRICT NRD-2019-0023

2105 NEWFIELD LANE OLD WEST AUSTIN HISTORIC DISTRICT

PROPOSAL

Demolish a ca. 1940 contributing house and replace with new construction.

ARCHITECTURE

The existing house is a one-story Minimal Traditional-style building clad in horizontal wood siding, with a cross-gabled composition shingle roof and gabled entryway. Its windows are 6:6 with wooden screens. It is set back approximately 25', in line with the other houses on the street. A contributing wood-frame accessory structure is located to the rear of the house.

PROJECT SPECIFICATIONS

The proposed primary building is two stories, with a standing-seam metal roof of varying heights and pitches. It is clad with horizontal fiber-cement siding at the first floor and vertical standing-seam metal at the second. It has fixed-pane windows of varying dimensions and irregular placement throughout, as well as a screened porch to the rear and stone fireplace at the south elevation. The building is set back 55' from the curb.

The proposed accessory structure is composed of garage space at the first floor and living space above. It has a gabled roof with two shed dormers at the north and south elevations and a spiral staircase leading to the second-floor entrance at the rear. It has horizontal siding and a standing-seam metal roof to match the main building. The accessory building is located in front of the house's primary elevation and set back 25' from the curb.

RESEARCH

The house at 2105 Newfield Lane was built around 1940 by real estate speculator Nat Franzetti. Its first owners were Lindsay B. and Carlotta Newsum. Lindsay Newsum worked as an engineer for the State Board of Insurance Commissioners, while Carlotta Newsum owned and operated Carlinda Antiques on Georgetown Road. By 1941, they had sold the property to J.D. and Gale Lemmon. Lemmon was in the Army, and sold the house shortly after purchase to Charles and Dorothy Kirstein, who owned the house less than two years. Kirstein, also a veteran, was trained as an expert furrier and worked at Snyder's department store for a number of years, along with his wife.

After the home's few initial owners, it was a rental property with relatively rapid occupant turnover. Many renters were affiliated with the University of Texas, either as students or staff members.

STANDARDS FOR REVIEW

The property does not appear to meet the standards for designation as a historic landmark according to the criteria specified in the City of Austin Land Development Code § 25-2-352.

- 1) The building is over 50 years old.
- 2) The building appears to retain integrity.

- 3) Properties must meet two historic designation criteria for landmark designation. The property does not appear to demonstrate significance according to any of the criteria.
 - a. Architecture. The building does not appear to be architecturally significant.
 - b. Historical association. While it was originally home to some unique Austin merchants, those occupants were short-term residents. There do not appear to be significant historical associations.
 - c. Archaeology. The property has not been evaluated for its potential to yield significant data concerning the human history or prehistory of the region.
 - d. Community value. The property does not appear to possess a unique location, physical characteristic, or significant feature that contributes to the character, image, or cultural identity of the community, city, or state.
 - e. Landscape feature. The property is not a significant natural or designed landscape with artistic, aesthetic, cultural, or historical value to the city.

The Secretary of the Interior's Standards for Rehabilitation are used to evaluate new construction projects in National Register historic districts. Applicable standards include:

- 9) New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.
 - The proposed new construction will require demolition of a contributing structure. It is differentiated from historic properties in the district by its modern cladding, fenestration, and two-story form. The proposed front-yard placement of the auxiliary garage structure and deep setback of the main house are not compatible with the lot placement of historic-age structures on the streetscape, nor are the proposed architectural features (metal siding, compound roof form, and irregular fenestration) compatible with the historic structures in the district.
- 10) New additions and adjacent or related new construction shall be undertaken in such a manner that if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.
 - If the proposed building were to be removed, the form and integrity of the historic district would be unimpaired; however, the proposed new construction requires removal of a contributing structure, thus impacting the overall integrity of the district.


COMMITTEE RECOMMENDATION

Consider retention and adaptive reuse of the existing house. For the proposed new construction, move the detached garage to the rear of the main house. Consider adding a porch to create a better transition between the two-story structure and the predominantly one-story streetscape.

STAFF RECOMMENDATION

Encourage rehabilitation and adaptive re-use of the existing building, including consideration of a demolition delay, as the building is contributing to the historic district. Encourage relocation over demolition. If the demolition permit is released, then staff recommends completion of a City of Austin Documentation Package, consisting of photographs of all elevations, a dimensioned sketch plan, and a narrative history, for archiving at the Austin History Center.

Staff supports all Committee recommendations for the new design and also recommends eliminating the metal siding from the new design, adding regular fenestration patterns and divided-light windows, and simplifying the roof form throughout to avoid visual competition with the smaller-scale Minimal Traditional buildings on the street.



Photos



Primary (west) façade of 2105 Newfield Lane.





Streetscape and adjacent structures, tree cover, and utility pole

Occupancy instens	Occu	pancy	History
-------------------	------	-------	---------

Completed by Historic Preservation Office staff April 2019

- 1939 Address not listed in directory
- 1941 Lindsay B. and Carlotta Newsum, owners
 Assistant engineer, State Board of Insurance Commissioners
 Proprietor, Carlinda Antiques, 5224 Georgetown Rd.
- 1944 J. D. and Gale Lemmon, owners U.S. Army
- 1947 Charles and Dorothy L. Kirstein, owners Furrier, Snyder's Smart Shop Saleswoman, Snyder's

Harry and Janice Dunlap, renters Office manager, KTBC

- 1949 Arthur W. and Jane Wilson, owners
 Department manager, Hutchins Brothers
- 1952 Shirley and Gertrude Gardner, renters Accountant

Mrs. Hildegaard S. Gardner, renter Assistant actuary, Western Reserve Life Insurance

- 1955 Edward S. and Hildegaard Gardner, renters Auditor Department head, Western Republic Life Insurance
- 1959 Edward S. and Hildegaard Gardner, renters
 Accountant
 Assistant actuary Western Republic & Plymouth Life Insurance, 702 Colorado
- 1962 Hillared Norman, renter Clerk
- 1965 Edward S. Gardner, renter student
- 1968 H.P. Ethleved and Anastasia Hammerloch, renters Animal tester approval

H.P. III and Emma Y. Ethleved, renters Animal tester

Gremillion T. Ethleved, renter Animal sampler Terry L. Weldon, renter Student

1973 Susan Martin, renter

Technologist, County Health Department

Note: The directory listing indicates that Susan Martin is a new resident.

1977 Randall A. Puckett, renter

Student

1981 John Dennison, renter

No occupation listed

Note: The directory listing indicates that John Dennison is a new resident.

1986 Grover S. Campbell, renter

Assistant professor, U of T

1992 Helen L. Lettunich, renter

Programs travel coordinator, U of T

Note: The directory listing indicates that Helen L. Lettunich is a new resident.

Background Research



Ad for early resident Charles Kirstein's services as a furrier. The Austin-American, 6-23-1946.

Na	t. Franzeti	: 1	2105 Newrie	ld La.
148	••	-	33	-
Enfield G				
Frame Res. & Box Carage				
18911 - 2-23-40				
		5		

Building permit issued to Nat Franzetti for frame residence and box garage, 2/23/1940.

	WATER SERVICE PERMITA	T Nº 17189 2c/48
1	Received of	Date .Feb. 26,1940
	Address 2105 Newfield Lane	
	Amount Two And 50/100	- \$ 2.50
. 1	Plumber Smoot	Size of Tap
Dec 7470"	Date of Connection 2 2 6 4 2 Size of Tap Made Size Service Made Size Main Tapped From Front Prop. Line to Curb Cock 2 7 From Prop. Line to Curb Cock 2 7 From Main in St. Depth of Main in St. Depth of Service Line From Curb Cock to Tap on Main Checked by Engr. Dept. 3-18-4016	Elbow St. Elbow Acturer Reducer Pipe Lead Comp. Nipples Union Plug The TIME Stop Stop Stop Told Valves

Water service permit issued to Nat Franzetti, 2/26/1940.

Connection Charge \$ 22 52 5	N 16588B
APPLICATED FOR SEWER CONNECTION.	
Austin, Texas, 2-23	19
To the Superintendent of Sewer and Public City of Austin, Texas	Improvements,
Sir:—	, <u>, , , , , , , , , , , , , , , , , , </u>
I hereby make application for sewer conn	ection and instructions
on premises owned by	itti
at 2105 Franchico	Lane Street
further described as lot, block	*
11113"	140
subdivision division division	, plat / 7 2,
which is to be used as a Reco	
In this place there are to be installed	fivturon
I agree to pay the City Sewer Departmen charge.	7
E DEE P Respectfully, 29 ha	unp
AT PI	ean pro-
Stub Out	
K- 5 40	Perment Pd
Connected	3-4-40
Size of Main 4 7 inches.	4-3-40
Size of Serviceinches.	Or
2 Feet Deep At Cuil	
	10 1013
Feet from Property Line	11 Jul 10 11
Feet from Curb Line	107 522
Inspected by Both Light	IT V
Connection made by Conding for	H-1381
Sever an Mant	Il lane
13146 lat location of Stu	A. L. H. B.
Source connection normit issued to Not Fr	nangotti 9/99/10/0