HISTORIC LANDMARK COMMISSION JUNE 24, 2019 PERMITS IN NATIONAL REGISTER HISTORIC DISTRICTS NRD-2019-0033 3206 GLENVIEW AVENUE OLD WEST AUSTIN NATIONAL REGISTER HISTORIC DISTRICT

PROPOSAL

Construct a second story atop a one-story house, replace all windows, and remove a rear addition.

ARCHITECTURE

L-plan house with cross-gabled roof, brick cladding, 8:8 wood-sash windows, and wood gableend cladding.

RESEARCH

Rankin and Elizabeth Gossett lived in the house between about 1947 and 1986. M. (Marion) Rankin Gossett was born in 1912. He grew up in Taylor, Texas, and moved to Austin in 1939. He worked as a salesman for Nelson Davis & Sons for at least 26 years, retiring by 1977. He died in 1989 in Austin.

Elizabeth Gossett was born in 1913. She worked as a secretary at UT, including for the Office of Naval Research in 1969. There, she was one of three Austin-area residents to receive commemorative medallions from the Apollo 8 crew, for their work administering NASA contracts for the voyage. Elizabeth Gossett died in 1984 in Austin.

PROJECT SPECIFICATIONS

The proposed project has four parts:

- 1) Construct a second story atop the existing house. The addition will be clad in boardand-batten siding and feature multi-lite casement windows, with a horizontal belt course dividing the first and second floors;
- 2) Replace all windows with multi-lite fixed, casement, and single-hung clad-wood windows to match existing lite patterns;
- 3) Replace the front door with a multi-lite door and add a shed-roofed awning; and
- 4) Remove a rear addition.

STANDARDS FOR REVIEW

The house is a contributing property in the Old West Austin Historic District. It does not appear to meet the standards for designation as a historic landmark.

Designation Criteria—Historic Landmark

- 1) The building is more than 50 years old, having been built ca. 1940.
- 2) The building appears to retain a high degree of integrity.
- 3) Properties must meet two historic designation criteria for landmark designation (City of Austin Land Development Code (Section 25-2-352). The property does not appear to meet the criteria.
 - *a.* **Architecture.** The building is an intact example of the Minimal Traditional style. It does not appear to be architecturally significant.

- *b.* **Historical association**. Rankin and Elizabeth Gossett lived in the house for about forty years. There do not appear to be significant historical associations.
- *c.* **Archaeology**. The property was not evaluated for its potential to yield significant data concerning the human history or prehistory of the region.
- *d.* **Community value**. The property does not appear to possess a unique location, physical characteristic, or significant feature that contributes to the character, image, or cultural identity of the community, Austin, or Texas as a whole.
- *e.* Landscape feature. The property is not a significant natural or designed landscape with artistic, aesthetic, cultural, or historical value to the city.

The Secretary of the Interior's Standards for Rehabilitation are used to evaluate projects in National Register historic districts. The following standards apply to the proposed project:

2) The historic character of a property will be retained and preserved. The removal of distinctive materials or alteration of features, spaces, and spatial relationships that characterize a property will be avoided.

The proposed project replaces historic-age windows and alters the massing and form of the building. It does not retain the historic character of the property.

- 5) Distinctive materials, features, finishes, and construction techniques or examples of craftsmanship that characterize a property will be preserved. The proposed project replaces historic-age windows.
- 6) Deteriorated historic features will be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature will match the old in design, color, texture, and, where possible, materials. Replacement of missing features will be substantiated by documentary and physical evidence.

The proposed project replaces historic-age windows with new windows with different operation type but retains the lite pattern. No evidence of deterioration has been presented.

9) New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work will be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportion, and massing to protect the integrity of the property and its environment.

The proposed addition will destroy the spatial relationships that characterize the existing one-story house. The new work will be differentiated from the old with a horizontal belt course and different cladding. However, it is not compatible with the historic size, scale, proportion, or massing of the historic building.

10) New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

The proposed project is not reversible. If the entire second story were removed, the original roof could be reconstructed. However, this is not a realistic scenario.

The proposed project does not meet the standards.

STAFF RECOMMENDATION

Release the permit upon completion of a City of Austin Documentation Package. The house does not meet the criteria for individual designation as a historic landmark.



This product has been produced by CTM for the sole purpose of geographic reference. No warranty is made by the City of Austin regarding specific accuracy or completeness.

PROPERTY INFORMATION

Photos



Primary (east) façade of 3206 Glenview Avenue.

Occupancy History

City directory research, Austin History Center By Historic Preservation Office staff May 2019

- 1941 Ted and Mary Jo Read, renters Secretary, Railroad Commission of Texas
- 1944 Ted and Mary J. Read, renters Reporter, *United Press*
- 1947 M. Rankin and Bettie B. Gossett, owners Salesman, Nelson Davis & Son
- 1949 M. Rankin and Elizabeth Gossett, owners Salesman, Nelson Davis & Son
- 1952 M. Rankin and Elizabeth Gossett, owners Salesman, Nelson Davis & Sons
- 1955 M. Rankin and Elizabeth Gossett, owners Salesman, Nelson Davis & Sons
- 1959 M. Rankin and Elizabeth Gossett, owners

Salesman, Nelson Davis & Son

- 1962 M. Rankin and Elizabeth Gossett, owners Salesman, Nelson Davis & Son (Rankin); administrative secretary, UT (Elizabeth)
- 1965 M. Rankin and Elizabeth Gossett, owners Salesman, Nelson Davis & Son (Rankin); office secretary administrator, UT (Elizabeth)
- 1968 Rankin and Elizabeth Gossett, owners Salesman, Nelson Davis & Sons
- 1973 Rankin and Elizabeth Gossett, owners Merchandiser, Nelson Davis & Son
- 1977 Rankin and Elizabeth Gossett, owners Retired
- 1981 Rankin and Elizabeth Gossett, owners No occupation listed
- 1986 Rankin and Elizabeth Gossett, owners No occupation listed
- 1992 Andrew Griffin, owner No occupation listed




"Apollo 8 medallions, The Austin Statesman, 8/13/1969.

Building Permits

3206 Glenview Ave. J. C. Smothers 2 4 Brykerwood B . brick veneer res. & frame gar. 299n - 1-2-40 5 #145783 10-16-74 Rankin Gossett Frm. Addn. to Res. Storage 112 Sq.Ft. 350.00

Building permit issued to J. C. Smothers for a brick veneer residence and wood-
frame garage, 1/2/1940. Below is a building permit issued to Rankin Gossett for a
112-square-foot wood-frame addition, 10/16/1974.



Water tap permit issued to J. C. Smothers, 1/3/1940.

1888 Nº 16447A APPLICA N FOR SEWER CONNECTION. 3. 19 40 Austin, Texas,__ To the Superintendent of Sewer and Public Improvements, City of Austin, Texas Sir:---÷... I hereby make application for sewer connection and instructions on premises owned by she Con Smothers at 3206 Glenview Street, further described as lot block outlof subdivision Bry Inwork B division plat which is to be used as a In this place there are to be installed ----fixtures. 3 I agree to pay the City Sewer Department the regular ordinance charge. Respectfully 3 DEE D Stub Out Connected 40 Size of Main inches. 40 Size of Service inches. Deep eet Feet from Property Line Feet from Curb Line Inspected by y and the second se -1 31 Connection made by 12820 C 20 JH O ۵

Sewer connection permit issued to J. C. Smothers, 1/3/1940.

OWNER Frank Gossett	ADDRESS 320	6 Gienriev torse and	
PLAT 75 LOT		BIK 2	
SUBDIVISION Brykerwoods	иDи		
OCCUPANCY Residence			
BLD PERMIT # 97117 DATE Sep	OWNERS t 11, 1965ESTIM		
CONTRACTOR Wilton Johns	on NO OI	FIXTURES 16,000.00	
WATER TAP REC #	SEWER TAP REC	#	
Remodel Interior of Frame Residence			
Duilding normit issued to Enorth	To a cost for an interi	an man a lal 0/14/1005	

Building permit issued to Frank Gossett for an interior remodel, 9/14/1965.