HISTORIC LANDMARK COMMISSION PERMITS IN NATIONAL REGISTER HISTORIC DISTRICTS SEPTEMBER 28, 2020 NRD-2020-0030 2525 HARTFORD RD.

OLD WEST AUSTIN NATIONAL REGISTER HISTORIC DISTRICT

PROPOSAL

Demolish a ca. 1950 house.

PROJECT SPECIFICATIONS

There are currently no plans for redevelopment.

RESEARCH

The house at 2525 Hartford Rd. was built in 1950 for George and Mary Williams. George Williams, an engineer, was killed in a car accident in 1958; Mary continued to live in the house until at least a year later, when she sold it to the Pfennig family. Robert W. Pfennig worked for the IRS; his wife, a nurses' aide, served at the Red Cross.

STAFF COMMENTS

The house is contributing to the Old West Austin National Register Historic District.


Designation Criteria—Historic Landmark

- 1) The building is more than 50 years old.
- 2) The building appears to retain high integrity.
- 3) Properties must meet two historic designation criteria for landmark designation (LDC §25-2-352). The property may demonstrate significance according to City Code:
 - a. Architecture. The building is constructed with Ranch-style influences.
 - b. Historical association. There do not appear to be significant historical associations.
 - c. *Archaeology*. The building was not evaluated for its potential to yield significant data concerning the human history or prehistory of the region.
 - d. *Community value*. The building does not possess a unique location, physical characteristic, or significant feature that contributes to the character, image, or cultural identity of the city, the neighborhood, or a demographic group.
 - e. *Landscape feature*. The property is not a significant natural or designed landscape with artistic, aesthetic, cultural, or historical value to the city.

STAFF RECOMMENDATION

Encourage rehabilitation and adaptive reuse, then relocation over demolition, but release the permit upon completion of a City of Austin Documentation Package.





NOTIFICATIONS

CASE#: GF 20-117987 LOCATION: 2525 HARTFORD RD

This product is for informational purposes and may not have been prepared for or be suitable for legal, engineering, or surveying purposes. It does not represent an on-the-ground survey and represents only the approximate relative location of property boundaries.

1"=333'

This product has been produced by CTM for the sole purpose of geographic reference. No warranty is made by the City of Austin regarding specific accuracy or completeness.



PROPERTY INFORMATION

Photos







Source: Realtor.com, 2020

Occupancy History

City Directory Research, 2020

Note: Due to facility closure, post-1959 research is unavailable.

1959 Mrs. Mary D. Williams, owner (wid. G. Davis)

1955 George D. and Mary Williams, owners

Consultant engineer

1952 George D. and Mary Williams, owners

Consultant engineer

Biographical Information

Road Crash Fatal for 2

The devastating collision of an automobile and milk truck east of the very seen. A pocket watch in Leconsulling engineers, George Davis (Dave) Williams, 55, of 252 vander's pocket was stopped at Hartford Road, and Carl Gustaf (Gus) Levander, 59, of 108 East 481 5:58.

Street.
Williams and Levander died in stantly in the collision which occurred at 5:58 p.m. Tuesday 6.3 miles cast of the city on the Bas trop Highway.

Funeral services for Levande are pending at Weed-Corley Fu-neral Home, Williams' body will lie in state at the funeral home until Thursday morning when it will be taken to Beaumont where Funeral services and burial will be held Thursday afternoon.

Levander's family asks that those wishing to do so may make contributons in his name to Hyde Park Christian Church. Williams family requests that friends who desire may make memorial contributions to their favorite char

Williams was driver of the east bound car, with Levander as a passenger, when it was in col lision with the truck driven by Alfred Winter, 52, of 1007 West Elizabeth. Winter was uninjured, according to Highway Patrolman Homer Smith.

The car was a twisted mass of wreckage, Patrolman Smith said. The impact knocked the front wheel from the truck, which then overturned.

An ambulance driver for Hyl tin-Manor Funeral Home, which sent two ambulances to the scene,

The force of the collision jammed the motor and firewall against the front seat of the car so tightly that wreckers had to be used to remove the bodies. One wreck-er was employed to anchor the car while another pulled the firewall (which separates the motor from the front seat) forward.

Levander was former city pub-lic works director, and when the late Walter Seaholm left as city manager in 1955 Levander re-signed to form a consulting firm with Seaholm.

After the death of Scaholm, Levander joined the engineering firm of Montgomery and Williams to form the firm of Montgomery,

Williams and Levander.
The firm, along with the Marvin
Turner Engineers, had just finished a long range water and sewer survey for the City of Austin, set ting up priority construction programs to meet needs of the city as it grows toward an anticipated population of 457,000 by 1980.

Levander began his engineering (See CRASH, Page 9)

(Continued From Page One)

work after graduation from Val. Street.

By degree in civil engineering, large and Windsor Road, Mrs. Illinois and sewer engineer in Lane and Windsor Road, Mrs. Illinois and sewer engineer in Lane and Windsor Road, Mrs. Illinois and sewer engineer in Lane and Windsor Road, Mrs. Illinois and sewer engineer in Lane and Windsor Road, Mrs. Illinois and sewer engineer in Joan Elizabeth Hodgkins, 28, of Lakeland, Fla., hefore joining the shoulder injury. She underwend gineer. He became director of treatment at Scion Hospital. gineer. He became director public works in Sept., 1919.

He belongs to several engineering and professional organizations.

Williams received his BS and MS degrees from Texas A&M Col-lege and came to Austin in 1938 as construction engineer with the Texas Highway Department, working under Julian Montgomery.

After Montgomery went into private business, he lured Williams away from the state job to be chief engineer in the construction of Bergstrom Air Force Base, and the men later became full partners in the firm of Montgo and Williams.

Levander's survivors include his widow; three sons, Dale H. Levander of Torrance, Calif., Ted Levander of Abuquerque,
N.M., and Richard Levander of
Waco; a daughter, Mrs. Mary
Rosado of New York City; and
two brothers, two sisters and
three grandchildren.

Williams is survived by his widow of Austin and one son, Lieutenant (ig) Dave H. Williams of New York City.

In a wreck inside the city at 41st and Duval Tuesday night, a motorcyclist, Norman Carroll Soward, 28, of 1311A Bracken-

ridge Apartments, sustained a fractured right foot and cuts and bruises about the body. His mo-torcycle was in collision with a pickup truck driven by Harold E. Lucksinger, 36, of 511 East 41st

The Austin Statesman: Oct 15, 1958



WHAT'S THAT?—Sending a blinker message from the Austin, Texas, and husband of Williams, son of Mr. and Mrs. George D. Williams of 2525 Hartford, Hartford Street Blinker message D. Williams of 2525 of 2000 Greenles Austin. Hartford Street. Blinker messages are a means of visual of 2000 Greenlee, Austin. communications by the Navy's warships at sea. Williams Refore entering the service in is one of 3,000 midshipmen cruising European waters in a January 1956, he graduated from training exercise.—(Navy Photo.) the University of Texas.

Dave Williams Is Advanced

ATLANTIC FLEET (FITTNG) Dave H. Williams was advanced to Navy lieutenant (junior grade) Dec. 1, while serving aboard the Atlantic Fleet surveying ship USS Maury.

He is the son of Mr. and Mrs.

The Austin Statesman: Jul 23, 1954 and Dec 19, 1957

R. W. Pfennig 'Civil Servant Of the Month'

September's "Civil Servant of the Month" award has gone to Robert W. Pfennig, Internal Revenue Service conference coordinator.

Selected by a citizens committee in observance of the Civil Service Act diamond anniversary. Plennig is a native of Travis County and a University of Texas graduate. He is technical advisor to District Director R. D. Phinney and an assistant technical coordinator for the Dallas Region of the Internal Revenue Service.

The award was presented by George Meriwether III, vice president of the Austin National Bank.

Plennig is a member of the State Society of Certified Public Accountants, the Austin Chapter, Certified Public Accountants and the National Association of Internal Revenue Employees.

The Austin Statesman: Sep 25, 1958

Mrs. Pfennig To Head Nurses' Aides

A new chairman of the nurses, High School and the other son is aldes program in the Travis Country a sophomore at the medical school in the Travis Country Chapter, American Red Cross, Mrs. Planning has been a Bad states there is a great need for the states the states there is a great need for the states the sta was announced Monday.

are the true example of Red Cross 20 hours classroom work; 20 hours "People helping People." They practical work on the hospital are close friends who not only share their Red Cross volunteer work together but other things as well. They are both members of St. Martins Lutheran Church and are Sunday School teachers there besides working in all the women's groups.

They each have two children and three grandchildren. Mrs. Pfennig and her husband reside at 2525 Hartford Rd. They have one son who is a Lutheran minister in Hondo, Texas, and a daughter who is a senior at the University of Texas majoring in sociology.

Mr. and Mrs. B. O. White, of 1706 West 31st, have two sons. One is in the physical education department at University Junior

Mrs. Plennig has been a Red was announced Monday.

Mrs. Robert W. Pfennig was appointed as nurses aides chairman to succeed Mrs. Joe Bland. New co - chairman, succeeding Mrs. H. M. Bettis, is Mrs. B. O. White has been a Nurses Aide since 1959. They both do their volunteer work at Bracken-ridge Hospital and have put in many faithful hours.

The training course for the Red Mrs. Plennig and Mrs. White Cross Nurses Aide is 40 hours:

states there is a great need for more Nurses Aides. Here in Austin, Red Cross Nurses Aide work at Brackenridge and Bergstrom Air Force Base Hospitals. An additional two hours Red Cross orientation is also a prerequisite in the training which will be held Tuesday, October 16th from 9:30 to 11:30 a.m. at the Red Cross Chapter House, 322 Jessie Street. Plans are also being made for a night orientation at a later date. Mrs. Pfennig asks that those interested in the nurses aide training course or those who would like to know more about the Nurses lide work, to call her at 3R 8-3908 or her co-chairman irs. White at GL 3-3725 or Red

Cross, GR 8-1601.

Red Cross volunteer nurses sides not only work in hospitals but in time of disaster are greatly needed to work in Red Cross disaster shelters. Both Mrs. Piennig and Mrs. White have had this experience here in Austin which included the big job of "Carla".

Your Red Cross is a working partner with United Fund.

The Austin Statesman: Oct 17, 1962

Permits

G. D. Williams

2525 Hartford Road

161

31

Pemberton Heights #10

Brick veneer residence and garage.

44962 6-15-50

\$17,000.00

H. T. Baker

Building permit, 6-15-50

OWNER R. W. Pfennig	ADDRESS 2525 Hartford Road			
PLAT 161 LOT	1 _{BLK} 31			
SUBDIVISION Pemberton Hts.				
OCCUPANCY Store Room				
BLD PERMIT #118254 DATE	OWNERS 7-29-70 ESTIMATE \$100.00			
CONTRACTOR OWNER NO. OF FIXTURES				
WATER TAP REC # Exist	SEWER TAP REC # Exist			
Frm acc bldg.				
70 sq. ft.	ding permit, 7-29-70			
	ADDRESS 2524 Hartford Rd.			
PLAT 161 LOT 1	BLK 31			
SUBDIVISION Pemberton Hts	•			
OCCUPANCY Den				
BLD PERMIT # 118834 DATE-8	OWNERS -70 ESTIMATE \$1,000.00			
CONTRACTOR OWNER	NO, OF FIXTURES			
WATER TAP REC # Exist	SEWER TAP REC #			

Remodel exist residence Remodel permit, 9-8-70

: B	TI bet 3/ WATER S	ERVICE PERMIT E	Nº 71209
	Received of Address 3525	Degreeig Pl.	Date 4/-54-71
	Amount & At		\$ 4000
120	Plumber		Size of Tap //4
RESIDENTIAL WATER	Date of Connection 5-25-72 Size of Tap Made 7 Size Service Made 7 Size Main Tapped 7 From Front Prop. Line to Curb Cock 7 From Prop. Line to Curb Cock 7 Location of Meter 6-26-8 Depth of Main in St. 3 Depth of Service Line 2 From Curb Cock to Tap on Main 3 Checked by Engr. Dept MM-1-1973 Water tap	No. Fittings 3 Pipe / 2 Pipe 2 Pipe 3 Pipe 4 Pipe	Service Clamp 24.7.7. Valve 14. Lock Lid Lock Lid Drain Tile Lid Stop & Drain Job Nor 24E 2.2.0. Poreman 1. Z. A.14.2. ELL