Item 14: Communication to Commissioner Hadden re Line Clearance

From: Vice, Jeffrey (Jeff)

Sent: Tuesday, September 08, 2020 4:00 PM

To: Hadden, Karen - BC <bc-Karen.Hadden@austintexas.gov>

Cc: 'Hopkins, Marty' <martyhopkins@eversheds-sutherland.com>; Hopkins, Marty - BC <BC-

Marty.Hopkins@austintexas.gov>; 'Karen Hadden' <karendhadden@gmail.com>

Subject: EUC Follow-up

Commissioner Hadden,

At the EUC's last meeting, during the Future Agenda Items discussion, you requested 1) some additional information/responses to questions re line clearance and herbicidal use; and 2) an update regarding electrification of the heavy-duty vehicles in the Austin Energy fleet (e.g., bucket trucks). Chair Hopkins and I reviewed the agenda for September, noting that it contained a briefing you had previously requested (from Office of Sustainability), as well as a long-delayed update on the SHINES project (requested by Commissioner Tuttle)...plus the 3rd Quarter Financial Report postponed from last meeting.

Recognizing that this month we wouldn't be able to take up your two concerns above, we wanted to 1) provide you with information that I hope will satisfy your request for additional information re line clearance...and 2) explain that we will schedule a fleet electrification update in the months to come (the last update was provided to EUC Nov 2019).

Please let me know if you have any questions or concerns.

Best, Jeff

Herbicide Use in Line Clearance Activities

- a) Treatment or removal of dead vines information is located on the Austin Energy Website Tree Pruning (https://austinenergy.com/ae/residential/residential-services/tree-pruning/tree-pruning/ FAQs section (https://austinenergy.com/ae/residential/residential-services/tree-pruning/faqs) regarding vines on utility poles (snap shot attached). In light of your concerns, we intend to change the verbiage from "treat" to "apply an EPA-approved herbicide to the base of the vine." To clarify, AE/AE's contractors will remove only vines from poles and not the remaining dead vines that may stretch out along a fence or into surrounding flora.
- b) You thought perhaps there was a prohibition of pesticide use at the City of Austin; we could not locate any such policy banning pesticide or herbicide use. Rather, the City maintains an Integrated Pest Management (IPM) plan (http://www.austintexas.gov/ipm) which is included in Austin Energy's forestry contract solicitations (language excerpt provided below).

NOTE:

The Contractor shall be responsible for all record keeping regarding pesticide application as required by the TDA Rules and Regulations and the City's Integrated Pest Management (IPM) plan. The Contractor shall abide by the City's IPM plan when using any general use chemicals, including fertilizer, herbicide or other chemicals, and shall obtain written approval from Austin Energy's Project Manager prior to any application. Application of chemicals shall be made only by individuals licensed by the TDA. If pesticide application is required and approved by Austin Energy, the Contractor shall maintain all Pesticide Application Records (the Records) as required by the terms of their License as outlined by the Laws and Regulations of the TDA. If Austin Energy requests the Records, the Contractor shall provide them within five calendar days. The Contractor shall maintain the Records for two years as required by the Laws and Regulations of the TDA.

The City of Austin's IPM plan website is at: http://www.austintexas.gov/ipm.

c) You had specific concerns re 1311 Alta Vista. For example, you asked about the notification process – please find a copy of the Vegetation Work Plan (VWP) below. You mentioned dead flowers at the site – please find below a short explanation of the treatment location and explanation of the physical presence of the site provided by Wright Tree Service. Wright Tree Service provided us with pictures of the site taken during a site visit we requested on Aug 10/the day of the EUC meeting, and I've included those below as well.



Distribution

V.W.P. ld: 2005-A79ZT-501			T-501	AUSTIN			Tickets 20 Wright	Wright Ticket Wright (Blank			
						\					
				Vegeta	tion	Wor	k Plan				
ne Austin ork is nec	Energy Util essary to e	ity Fores nsure sa	try Section is cu fe and reliable e	irrently prun electric serv	ing and ice to yo	Vor rem our area	oving vegetat a and is not at	on that is near to any additional e	he electric xpense to	facilities. This you.	
PATTERS	SON, ROB	ERT , ha	ve been notified	by a repres	entativ	e of Au	stin Energy of	the following wo	rk on my	property at	
dress 13	11 ALTA VI	STAAVE		Phone # 361-288-0133					No Work Required		
AUSTIN, 78704				Phone #					Limb by Limb		
ole # 236	406 to Pol	e # 2364	106							fusal	
			_		_					n Contact	
Dogs in	Yard	Locked	Gate Ca	II Ahead	∐N	fitigatio	nTrees	Shared Trees	St	ump Treatment	
Ribbon	2-7.9" dia	m: 0	8-12.9" diam	Exact Tree Size		.9" diar	n: 0 19	9 and greater" di	Action		
Number	1000			(in. DBH)	10000		REMOVE VII	NES	6,377		
1	Remove	R	Vines			Fast	FROM POLE AND SERVIC WIRES	Damous f	om around the pole		
ompleted,	nergy has d reviewed, may be re-	and new	an interim line pruning clearan	clearance S ices have b	Standar een est	d that was ablished	vill be in place d. At that time	until a tree regro , your trees will t	wth rate s be reviewe	tudy has been ed and additional	
Contra		Crew Type Crew F		oreman Start		Date	Comp D	ate Asses	Assess Date Work Or		
Vright Tre- ervice, In		HIC GCIPE		iow b	w 6-8-2		6-8-	20 05-06	05-06-2020 18814		
						193	1	AE Represe	entativ	9	
					Name				KYMBERLI HERRON		
Bob (Poster	in.	vertel	5/12	20	Ph	none#		51	2-696-1072	
1700	Co of C.	a Land Bar	01-	Date Sino	20	Ŀ.					

Subject: RE: 1311 Alta Vista


Treatment would have only been around the 2 poles. 1 pole along the side of the back yard and 1 pole along the alley. There are some dead vines along the fence by both poles. We wouldn't have sprayed the entire perimeter. Only at the poles where vines were cut.

Correct, there are some dead vines in the small hackberries. It appears customer raised canopy of these small trees and cut vines growing up the trunk of each small tree. The trees are alive; dead leaves are vines.

*** External email - Exercise caution ***

Here are some photos from 1311 Alta Vista. Vines cut on poles, but that's the only work that was done here by WTS.





It looks like customer or tenant did some recent pruning to some of the small trees in the back yard (not pruned by WTS). The ground is pretty bare here by the poles. I don't see any dead plants other than vines that were cut. Herbicide was likely applied to the cut vines, or else they would be most likely be growing back by now.



Some dead vines in small trees recently pruned by either customer or tenant?

Jeff Vice

Director, Local Government Issues Austin Energy, 721 Barton Springs Rd, Austin TX 78704 O: 512-322-6087 | C: 512-497-0966

<u>austinenergy.com</u> | twitter.com/austinenergy <u>linkedin.com/company/austin-energy</u>