

HOUSING DEVELOPMENT ASSISTANCE (RHDA/OHDA)

Application for Housing Development Financing

PLEASE NOTE: AHFC Reserves the right to fund projects at a lower amount than requested, and the right to deny applications that do not coincide with the <u>Austin Strategic Housing Blueprint</u> and policy direction from the Austin City Council.

Applicant Information

(If the developer involves multiple entities, is a partnership or joint venture, please provide the requisite information for each and identify the entity that will serve as the "lead" organization.)

Developer Name	Owner Name			
Guadalupe Neighborhood Development Corporation	iuadalupe Neighborhood Development Corporation			
Street Address				
813 E. 8th S	t, Austin TX 78702			
City	State Zip			
Austin	TX 78702			
Contact Name	Contact Telephone			
Mark C. Rogers	5124796275			
Contact Email				
Federal Tax ID Number	D-U-N-S Number (visit www.dnb.com for free DUNS#.)			
74-2247265	15287795			
The applicant/developer certifies that the data inc	cluded in this application and the exhibits attached			
hereto are true and correct. Unsigned/undated su	bmissions will not be considered.			
Legal Name of Developer/Entity	Title of Authorized Officer			
Guadalupe Neighborhood Development Corporation	Executive Director			
mal Oscar	1-1-			
Mal . Rocar Signature of Authorized Officer	1/31/2019			
Jighature of Authorized Officer	, Date			

INSTRUCTIONS: Applications will be reviewed on a quarterly basis. All applications submitted in the review period that achieve the minimum threshold score will be reviewed by an internal panel of NHCD staff. All awards will be made by the AHFC Board of Directors. To be considered for an award, please complete this application electronically, print, sign, and deliver to:

Department of Neighborhood
Housing and Community
1000 East 11th Street
Austin, Texas 78702
Attn: James May
Community Development Manager

City of Austin

JAN 3 1 2019

NHCD / AHFC

Project Summary F	orm				In Allera	
1) Project Na	me	2) Project Ty	pe 3) N	lew Construct	ion or Rehabilita	ation?
FJZ Street Pha		100% Afforda			onstruction	
4) Location Descri	ntion (Acresoe	side of street dist	ance from interes	etion) 5	Mobility Bond	Corridor
3104, 3105, 3108, 3					Airport Blv	
·					· · · · · · · · · · · · · · · · · · ·	
6) Census Tract	7) Council D) Elementary S		9) Affordability	
8.01	District	3	OAK SPRING	S EL	99 Years	
10) Type of Structur	re	11) Occu	pied?	12) Ho	w will funds be	used?
Single Family		No		С	onstruction Onl	У
	13\ %	ummary of Rent	al Unite by ME	I I ovol		
		One	Two	Three	Four (+)	
Income Level	Efficiency	Bedroom	Bedroom	Bedroom	Bedroom	Total
Less than 20% MFI						0
Less than 30% MFI				<u> </u>		0
Less than 40% MFI					 	0
Less than 50% MFI						0
Less than 60% MFI						0
Less than 80% MFI						0
Less than120% MFI						0
No Restrictions						0
Total Units	0	0	0	0	0	0
	14) Su	mmary of Units	for Sale at MF	l Level		
Income Level	Efficiency	One	Two	Three	Four (+)	Total
Less than 60% MFI			2	1		3
Less than 80% MFI			1	3	3	7
Less than 120% MFI				1		0
No Restrictions						0
Total Units	0	0	3	4	3	10
		15) Initiatives	and Priorities			
Initia	ative	# of U	nits	Initiative	# 0	of Units
Accessible Units for			Conf	inuum of Car	e Units	
Accessible Units for	Sensory Impair	ments 2				
Use the City of Aust	in GIS Map to	Answer the	questions bel	ow		
16) is the property wit	•		•		Yes	
17) Is the property with	thin 4/4 mile of	ia Ulah Casaw	T'4 C	42		
		• •	·	rop?	Yes	
18) Is the property with	thin 3/4 mile of	Transit Service	e? Yes]		
19) The property has	Healthy Food	Access?	Yes			
20) Estimated Source	es and Uses	of funds				
	Sources			<u>Us</u>	e <u>s</u>	
	Debt	1,150,000		Acquisition		0
Third Party		67,500		Off-Site		0
B (15)	Grant	10,000		Site Worl		0
Deferred Develop		143000		Sit Amenitie		0
614 a . 6 4	Other	0		Building Cost		30,200
City of A	เนรชก	1,235,200	l C	ontractor Fee		43,000
				Soft Cost		32,500
			7	Financing eveloper Fee		0
	Total \$	2.605.700	U	eveloper Fee: <i>Tota</i>)5 700

	Developm	nent Schedu	ıle	<u></u>	
				l Date	
Site Control			May-08	Jun-08	
Acquisition			Jan-09		
Zoning			Jun-08	Jun-08	
Environmental	Review		May-08		
Pre-Developn	nent		Dec-19	Jun-19	
Contract Execu	tion		Dec-19		
Closing of Othe	r Financing		Dec-19	Jun-19	
Development S	ervices Review		Dec-19		
Construction			Jun-19	Apr-20	
Site Preparation	n		Jun-19	Aug-19	
25% Complete			Jun-19		
50% Complete			Dec-19		
75% Complete			Feb-20	11 1	
100% Complete	2		Apr-20		
Marketing			Jan-19	Dec-19	
Pre-Listing					
Marketing Plan					
Wait List Proce	SS		Jan-19	Dec-19	
Disposition			Apr-20	Apr-20	
Lease Up					
Close Out			Apr-20	Apr-20	
Dec	-14 May-16	Sep-17	Feb-19	Jun-20	Oct-21
Site Control					
Acquisition					
Zoning					
Environmental Review					
Pre-Development					
Contract Execution				•	
Closing of Other Financing					
Development Services Review					
Construction			-		
Site Preparation					
25% Complete			•		
50% Complete				•	
75% Complete				•	
100% Complete				•	
Marketing					
Pre-Listing				_	
Marketing Plan					
Wait List Process					
Disposition					
Lease Up					
Close Out					
Close Out					-

	Development Budget					
	Total Decises 5- at	Requested AHFC Funds	Descriptio			
Pre-Development	Total Project Cost	Funds				
Appraisal	5,000		CAIDS on Brusse			
Environmental Review	3,000		GNDC or Buyer			
Engineering	15,000		CUDG			
Survey	8,000		GNDC			
Architectural	17,000		GNDC			
Subtotal Pre-Development Cost	\$45,000	\$0	GNDC			
Acquisition	\$43,000	30				
Site and/or Land						
Structures						
Other (specify)		T				
Subtotal Acquisition Cost	ėo	ćo				
Construction	\$0	\$0				
Infrastructure						
Intrastructure Site Work	10.000					
Demolition	10,000	0				
	0					
Concrete	220,000	220,000				
Masonry	0					
Rough Carpentry	290,000	225,000				
Finish Carpentry	70,000					
Waterproofing and Insulation	70,000					
Roofing and Sheet Metal	100,000	100,000				
Plumbing/Hot Water	130,000	0				
HVAC/Mechanical	160,000	160,000				
Electrical	85,000	30,000				
Doors/Windows/Glass	450,000	150,000				
Lath and Plaster/Drywall and Acoustical	80,000	80,000				
Tiel Work	160,000					
Soft and Hard Floor	100,200	35,200				
Paint/Decorating/Blinds/Shades	150,000	35,000				
Specialties/Special Equipment	30,000					
Cabinetry/Appliances	150,000	100,000				
Carpet	0					
Other (specify): Fencing	30,000					
Construction Contingency	243,000	100,000	Construction Contingency/Paid Dev			
Subtotal Construction Cost	\$2,528,200	\$1,235,200				
Soft & Carrying Costs						
Legal	0					
Audit/Accounting	0					
Title/Recording	20,000		GNDC			
Architectural (Inspections)	10,000		GNDC			
Construction Interest	2500		GNDC			
Construction Period Insurance	Ö					
Construction Period Taxes	0					
Relocation	0					
Marketing	0					
Davis-Bacon Monitoring	0					
Other (specify)						
Subtotal Soft & Carrying Costs	\$32,500	\$0				
	Ţ,- - -	φo				
	1					

Projected Affordability Data for Home Sales (OHDA)

	Unit Model 1	Unit Model 2	Unit Model 3	Unit Model 4	Unit Model 5	Unit Model 6	Unit Model 7
Number of Units	1	2	2	2	3	0	0
Number of Bedrooms	2	2	3	3	4	0	0
Square Footage	1086	1182	1379	1389	1550	0	0
Anticipated Sale Price	\$115,000	\$115,000	\$115,000	\$115,000	\$115,000	\$0	\$0
Borrower Contribution	\$145,570	\$145,570	\$145,470	\$145,570	\$145,470	\$0	\$0
Homebuyer Subsidy	\$0	\$0	\$0,	\$0	\$0	\$0	\$0
Total Principal Amount of Mortgage	\$115,000	\$115,000	\$115,000	\$115,000	\$260,570	\$0	\$0
Anticipated Interest Rate	5.00%	5.00%	5.00%	5.00%	5.00%	0.00%	0.00%
Monthly Principal Amount	\$485	\$485	\$485	\$485	\$485	\$0	\$0
Monthy Interest	\$140	\$140	\$140	\$140	\$140	\$0	\$0
Estimated Monthly Taxes	\$200	\$200	\$200	\$200	\$200	\$0.00	\$0.00
Estimated Monthly Insurance	\$85.00	\$85.00	\$85.00	\$85.00	\$85.00	\$0.00	\$0.00
TOTAL Estimated PITI	\$910	\$910	\$910	\$910	\$910	\$0	\$0

Project Name		
Project Type		
Council District	District 3	
Census Tract	8.01	
AHFC Funding Request Amount		
Estimated Total Project Cost		
High Opportunity		
High Displacement Risk		
High Frequency Transit	Yes	
Imagine Austin		
Mobility Bond Corridor	Airport Blvd	
SCORING ELEMENTS		Description
UNITS		
< 20% MFI	0	# of rental units at < 20% MFi
< 30% MFI	0	# of rental units at < 30% MFI
District Goal	0.00%	% of annual goal reached with units
High Opportunity	0.00%	% of annual goal reached with units
Displacement Risk	0.00%	% of annual goal reached with units
High Frequency Transit	0.00%	% of annual goal reached with units
Imagine Austin	0.00%	% of annual goal reached with units
Geographic Dispersion	0.00%	% of annual goal reached with units
Mobility Bond Corridor	0.00%	% of annual goal reached with units
SCORE	0	% of Goals * 20
< 40% MFI	0	# of rental units at < 40% MFI
< 50% MFI	0	# of rental units at < 50% MFI
District Goal	0.00%	% of annual goal reached with units
High Opportunity	0.00%	% of annual goal reached with units
Displacement Risk	0.00%	% of annual goal reached with units
High Frequency Transit	0.00%	% of annual goal reached with units
Imagine Austin	0.00%	% of annual goal reached with units
Geographic Dispersion	0.00%	% of annual goal reached with units
Mobility Bond Corridor	0.00%	% of annual goal reached with units
SCORE	0	% of Goals * 15
< 60% MFI	3	# of units for purchase at < 60% MFI
< 80% MFI	7	# of units for purchase at < 80% MFI
District Goal	1.59%	% of annual goal reached with units
High Opportunity	0.00%	% of annual goal reached with units
Displacement Risk	2.01%	% of annual goal reached with units
High Frequency Transit	7.60%	% of annual goal reached with units
Imagine Austin	7.60%	% of annual goal reached with units
Geographic Dispersion	0.00%	% of annual goal reached with units
Mobility Bond Corridor	9.08%	% of annual goal reached with units
SCORE	4	% of Goals * 15
Unit Score	4	MAXIMUM SCORE = 350
INITIATIVES AND PRIORITIES		
Continuum of Care	0	Total # of units provided up to 100 per year
Permanent Supportive Housing Score	0	(total CoC Units/100 + HF Units/50)*20
Access to Healthy Food	Yes	Within 1 Mile of Healthy Food (City GIS)
Permanent Supportive Housing Weighted Score	0	Mobility, Access to Jobs, Community Institutions, Social Cohesion
2 Bedroom Units	3	Total Affordable 2 Bedroom units
3 Bedroom Units	4	Total Affordable 3 Sedroom units
4 Bedroom Units	3	Total Affordable 4+ Bedroom units
Family Friendly Score	20	Multi-bedroom Unit/Total Units * 20
TEA Grade	64	Elementary School Rating from TEA
Family Friendly Weighted Score	6	Educational Attainment, Environment, Community Institutions, Social Cohesion, E
Accessible Units	4	mobility and sensory units
Non-PSH, Nan-Voucher Under 20% MFI	0	Total units under 20% MFI
Accessibility Score	8	Accessible Unit/Total Units * 20
Metro Access Service	Yes	Within 3/4 mile of fixed route transit
Accessibility Weighted Score	3	Housing Stability, Health, Mobility, Community Institutions
Initiatives and Priorities Score	36	MAXIMUM SCORE = 200
UNDERWRITING		
UNDERTRITING		
AHFC Leverage	47%	% of total project cost funded through AHFC request
	47%	% of total project cost funded through AHFC request 25 - (% leverage * 25)
AHFC Leverage		
AHFC Leverage Leverage Score AHFC Per Unit Subsidy Subsidy per unit score	13 \$123,520.00 10	25 - (% leverage * 25)
AHFC Leverage Leverage Score AHFC Per Unit Subsidy Subsidy per unit score AHFC Per Bedroom Subsidy	\$123,520.00 10 \$41,173.33	25 - (% leverage * 25) Amount of assistance per unit (\$200,000 - per unit subsidy)*25/\$200,000 Amount of assistance per bedroom
AHFC Leverage Leverage Score AHFC Per Unit Subsidy Subsidy per unit score AHFC Per Bedroom Subsidy Subsidy per Bedroom Score	13 \$123,520.00 10 \$41,173.33 20	25 - (% leverage ° 25) Amount of assistance per unit (\$200,000 - per unit subsidy) ° 25/\$200,000 Amount of assistance per bedroom (\$200,000 - per bedroom subsidy) ° 25/\$200,000
AHFC Leverage Leverage Score AHFC Per Unit Subsidy Subsidy per unit score AHFC Per Bedroom Subsidy Subsidy per Bedroom Score Debt Coverage Ratio (Year S)	\$123,520.00 10 \$41,173.33 20 #REF!	25 - (% leverage ° 25) Amount of assistance per unit (\$200,000 - per unit subsidy)*25/\$200,000 Amount of assistance per bedroom (\$200,000 - per bedroom subsidy)*25/\$200,000 Measured at the 5 Year mark
AHFC Leverage Leverage Score AHFC Per Unit Subsidy Subsidy per unit scose AHFC Per Bedroom Score Subsidy per Bedroom Score Debt Coverage Ratio (Year 5) Debt Coverage Ratio Score	13 \$123,520.00 10 \$41,173.33 20 #REF!	25 - (% leverage ° 25) Amount of assistance per unit (\$200,000 - per unit subsidy)*25/\$200,000 Amount of assistance per bedroom (\$200,000 - per bedroom subsidy)*25/\$200,000 Measured at the 5 Year mark Nilnimum = 1.0; Maximum = 1.5; 1.25 = best score
AHFC Leverage Leverage Score AHFC Per Unit Subsidy Subsidy per unit score AHFC Per Bedroom Subsidy Subsidy per Bedroom Score Debt Coverage Ratio (Year S)	\$123,520.00 10 \$41,173.33 20 #REF!	25 - (% leverage ° 25) Amount of assistance per unit (\$200,000 - per unit subsidy)*25/\$200,000 Amount of assistance per bedroom (\$200,000 - per bedroom subsidy)*25/\$200,000 Measured at the 5 Year mark
AHFC Leverage Leverage Score AHFC Per Unit Subsidy Subsidy per unit score AHFC Per Bedroom Subsidy Subsidy per Bedroom Score Debt Coverage Ratio (Year 5) Debt Coverage Ratio Score Underwriting Score APPLICANT	13 \$123,520.00 10 \$41,173.33 20 #REF!	25 - (% leverage ° 25) Amount of assistance per unit (\$200,000 - per unit subsidy)*25/\$200,000 Amount of assistance per bedroom (\$200,000 - per bedroom subsidy)*25/\$200,000 Measured at the 5 Year mark Nilnimum = 1.0; Maximum = 1.5; 1.25 = best score
AHFC Leverage Leverage Score AHFC Per Unit Subsidy Subsidy per unit scosidy AHFC Per Bedroom Score Subsidy per Bedroom Score Debt Coverage Ratio (Year 5) Debt Coverage Ratio Score Underwriting Score	13 \$123,520.00 10 \$41,173.33 20 #REF!	25 - (% leverage ° 25) Amount of assistance per unit (\$200,000 - per unit subsidy)*25/\$200,000 Amount of assistance per bedroom (\$200,000 - per bedroom subsidy)*25/\$200,000 Measured at the 5 Year mark Nilnimum = 1.0; Maximum = 1.5; 1.25 = best score
AHFC Leverage Leverage Score AHFC Per Unit Subsidy Subsidy per unit score AHFC Per Bedroom Subsidy Subsidy per Bedroom Score Debt Coverage Ratio (Year 5) Debt Coverage Ratio Score Underwriting Score APPLICANT	13 \$123,520.00 10 \$41,173.33 20 #REF! #REF!	25 - (% leverage * 25) Amount of assistance per unit (\$200,000 - per unit subsidy)*25/\$200,000 Amount of assistance per bedroom (\$200,000 - per bedroom subsidy)*25/\$200,000 Measured at the 5 Year mark Minimum = 1.0; Maximum = 1.5; 1.25 = best score MAXIMUM SCORE = 100
AHFC Leverage Leverage Score AHFC Per Unit Subsidy Subsidy per unit score AHFC Per Bedroom Subsidy Subsidy per Bedroom Score Debt Coverage Ratio (Year 5) Debt Coverage Ratio Score Underwriting Score APPLICANT FINAL QUANTITATIVE SCORE	13 \$123,520.00 10 \$41,173.33 20 #REF! #REF!	25 - (% leverage ° 25) Amount of assistance per unit (\$200,000 - per unit subsidy)*25/\$200,000 Amount of assistance per bedroom (\$200,000 - per bedroom subsidy)*25/\$200,000 Measured at the 5 Year mark Minimum = 1.0; Maximum = 1.5; 1.25 = best score MAXIMUM SCORE = 100
AHFC Leverage Leverage Score AHFC Per Unit Subsidy Subsidy per Unit Subsidy Subsidy per Bedroom Subsidy Subsidy per Bedroom Score Debt Coverage Ratio (Year 5) Debt Coverage Ratio Score Underwriting Score EAPPLICANT FINAL QUANTITATIVE SCORE Previous Developments	13 \$123,520.00 10 \$41,173.33 20 #REF! #REF!	25 - (% leverage ° 25) Amount of assistance per unit (\$200,000 - per unit subsidy)*25/\$200,000 Amount of assistance per bedroom (\$200,000 - per bedroom subsidy)*25/\$200,000 Measured at the 5 Year mark Minimum = 1.0; Maximum = 1.5; 1.25 = best score MAXIMUM SCORE = 100
AHFC Leverage Leverage Score AHFC Per Unit Subsidy Subsidy per unit scosidy Subsidy per Bedroom Score Debt Coverage Ratio (Year 5) Debt Coverage Ratio Score Underwriting Score APPLICANT FINAL QUANTITATIVE SCORE Previous Developments Compliance Score Proposal Supportive Services	13 \$123,520.00 10 \$41,173.33 20 #REF! #REF!	25 - (% leverage ° 25) Amount of assistance per unit (\$200,000 - per unit subsidy)*25/\$200,000 Amount of assistance per bedroom (\$200,000 - per bedroom subsidy)*25/\$200,000 Measured at the 5 Year mark Minimum = 1.0; Maximum = 1.5; 1.25 = best score MAXIMUM SCORE = 100
AHFC Leverage Leverage Score AHFC Per Unit Subsidy Subsidy per unit score AHFC Per Bedroom Subsidy Subsidy per Bedroom Score Debt Coverage Ratio (Year 5) Debt Coverage Ratio Score Underwriting Score EMPLICANT FINAL QUANTITATIVE SCORE Previous Developments Compliance Score Proposal Supportive Services Development Team	13 \$123,520.00 10 \$41,173.33 20 #REF! #REF!	25 - (% leverage ° 25) Amount of assistance per unit (\$200,000 - per unit subsidy)*25/\$200,000 Amount of assistance per bedroom (\$200,000 - per bedroom subsidy)*25/\$200,000 Measured at the 5 Year mark Minimum = 1.0; Maximum = 1.5; 1.25 = best score MAXIMUM SCORE = 100
AHFC Leverage Leverage Score AHFC Per Unit Subsidy Subsidy per unit scosidy Subsidy per Bedroom Score Debt Coverage Ratio (Year 5) Debt Coverage Ratio Score Underwriting Score APPLICANT FINAL QUANTITATIVE SCORE Previous Developments Compliance Score Proposal Supportive Services	13 \$123,520.00 10 \$41,173.33 20 #REF! #REF!	25 - (% leverage ° 25) Amount of assistance per unit (\$200,000 - per unit subsidy)*25/\$200,000 Amount of assistance per bedroom (\$200,000 - per bedroom subsidy)*25/\$200,000 Measured at the 5 Year mark Minimum = 1.0; Maximum = 1.5; 1.25 = best score MAXIMUM SCORE = 100

GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION BRIEF DESCRIPTION AND RELEVANT EXPERIENCE

Guadalupe Neighborhood Development Corporation ("GNDC") is a non-profit, community based organization created in 1981. The organization began as an initiative to revitalize the Guadalupe Neighborhood, which had been losing housing and residents since the early 1960's. After defeating the French Legation Park project in 1980, which would have displaced 20 households from the neighborhood, residents formed the Guadalupe Neighborhood Area Association (GNAA). In April 1981, GNAA produced the Guadalupe Community Development Program: Phase I Plan proposing use of Community Development Block Grant (CDBG) funds that had been set aside for the French Legation Park. Following City approval of the Phase I Plan and funding, the team purchased and renovated 10 housing units.

Mark Rogers began working as a Project Director for GNDC in 1994, and became Executive Director in 2001. Since its inception, GNDC has developed 64 single-family rental units, and enabled over 52 families to become home owners, many of which were supported with City funding. In August of 2008, GNDC completed its first affordable multi-family housing project, La Vista de Guadalupe, a twenty two unit project financed primarily thought Texas Department of Housing and Community Affairs, which awarded GNDC over three million dollars in tax credits, and the Austin Housing Finance Corporation (AHFC). In 2017, GNDC developed the Jeremiah Program Moody Campus in partnership with Jeremiah Program Austin, which offers 35 units of supportive and affordable housing to Jeremiah Program participants, as well as a 4-classroom pre-k school and daycare. This project was also supported by \$2 million in forgivable loans from the AHFC. GNDC is currently developing the 11-acre Guadalupe-Saldana Net-Zero Subdivision with a mix of multi-family, townhomes, duplex and single-family homes. At this time 59 units have been completed and, at final build-out, the innovative subdivision will provide 125 permanently affordable homes.

GNDC owns and manages all of its rental properties, and uses a Community Land Trust model to sell homes for homeownership, keeping them permanently affordable. GNDC is committed to respect the people it serves and is dedicated to improve the quality of life in the neighborhoods where it works. The organization has a long and successful history of working with the City of Austin to fund, develop, construct and manage its affordable housing for East Austin residents.

Certificate of Status, See Exhibit A

Developer Curriculum Vitae, See Exhibit B Attached:

- 1) CV of Mark C. Rogers, Executive Director
- 2) CV of Rachel Stone, Assistant Executive Director

Financial Capacity

GNDC has been developing affordable housing since the 1980s and has maintained a 30+ year relationship with the Austin Housing Finance Corporation throughout those projects. GNDC is well versed and experienced in multiple funding sources including, but not limited to, Low Income Housing Tax Credits, HUD's Neighborhood Stabilization Program, General Obligation Bonds, Community Development Block Grants, HOME funds as well as private Foundation support for its affordable housing developments. Some of GNDC's projects include a mix of AHFC funds with grant funding, such as the 35-unit Jeremiah Project, while others have CHDO, LIHTC, and other HUD funds layered into the project. GNDC has successfully developed 64 single-family rental units, 57 multifamily units, and over 52 homeownership units utilizing city, state, and foundation funding.

See Exhibit C

Attached:

- 1) IRS Tax Exemption Certification
- 2) Certified Audit for 2017
- 3) Board Resolution

Project Proposal

GNDC is requesting \$1,235,200 in AHFC funds to be applied as construction cost and associated soft cost assistance (\$130,000 per house) for 10 net-zero energy homes that will be sold in a Community Land Trust arrangement to income eligible homebuyers at the Guadalupe-Saldaña Net-Zero Subdivision.

GNDC has permit-ready building plans for 2-bedroom, 3-bedroom, and 4-bedroom homes, designed as net-zero energy capable. There are 12 vacant lots remaining along Father Joe Znotas Street in the subdivision. GNDC currently has over 80 applications from potential homebuyers with low-to-moderate incomes who would like to acquire the homes through a Community Land Trust sale. GNDC will serve households with 7 incomes at or below 80% and 3 households with incomes at or below 60% of the Austin-Round Rock – San Marcos Median Family Income (MFI). In its CLT program, GNDC gives the highest priority to its current GNDC renters; especially those whose income are nearest 80% of the Austin MFI. GNDC's 2nd highest priority is to serve residents and former residents of the neighborhoods surrounding the site, generally considered Central East Austin. GNDC aims to ensure that the mortgage payments (principal, interest, taxes and insurance) of the buyers is not more than 30% of their gross income.

The Guadalupe-Saldaña Net-Zero Subdivision (the Subdivision) is located near the intersections of Tillery Street, Goodwin Avenue, and Webberville Road in East Austin. This Subdivision is being developed with a 99-year affordability period, via a restrictive covenant running with the land, and GNDC is using a Community Land Trust for the home sales to qualified buyers while leasing the land via a long-term, 99-year ground lease. Currently GNDC has 16 CLT homes at the subdivision and 2 other CLT homes elsewhere in East Austin.

This project is unique because it is Austin's first subdivision using a community land trust, it is 100% affordable, and also is striving for the highest level of green and sustainable building. GNDC is proud to say that it developed the first Community Land Trust home in the State of Texas in 2012. Since that time, GNDC has developed 16 additional CLT homes and is now prepared to develop 24 more in phases over the next two to three years. GNDC is excited to develop additional Community Land Trust homes for sale at the Subdivision – GNDC's cornerstone Community Land Trust project.

The total project cost is \$2,605,700. GNDC is requesting \$1,235,200 in AHFC funds to be applied to construction and development soft costs for 8 homes. An additional 1,150,000 is being financed by a private lender; likely either Horizon Bank or Frost Bank. GNDC is providing \$77,500 toward project expenses. All funds are essentially committed except AHFC's. Horizon provided financing on Phase II and Frost is a frequent lender for GNDC.

Development Team

<u>List and Contact Info for Development Team</u>

1) Guadalupe Neighborhood Development Corporation, Developer

Mark C. Rogers 813 E. 8th St, Austin TX 78702 (512) 479-6275

2) hatch + ulland owen, Architects

Tom Hatch 1010 E.11th Street Austin, TX 78702 (512) 474-8548

3) Green Earth, Engineering

Tim Zhang 2500 W William Cannon Dr # 201, Austin, TX 78745 (512) 289-8086

Exhibit D:

Attached:

Curriculum Vitae for Development Team

Property Management Team

GNDC owns and manages affordable housing properties. Yolanda Alemán-Limón has overseen Property Management activities for 15 years, and is responsible for training and onboarding new Property Management staff, with the assistance of the Executive Director and Assistant Executive Director.

See Exhibit E:

Attached:

- 1) Resume of Yolanda Alemán-Limón
- 2) Compliance reports from NHCD indicating no open violations

6 of 238

Market Assessment

The Father Joe Znotas Street Phase IV project proposes to construct 10 new single-family homes for ownership through a community land trust. Three of the homes will be affordable to households with incomes at or below 60% and seven of the homes will be affordable to households with incomes at or below 80% of the Austin area median family income. All units are on Father Joe Znotas Street in the Govalle Neighborhood, 78702 zip code area of Austin.

The 78702 zip code area has been identified in a number of studies and reports, including the recently released <u>Uprooted</u>¹ report by the University of Texas Center for Sustainable Development and the Entrepreneurship and Community Development Clinic, as one of the most rapidly gentrifying areas in the United States. In 2016 the area had a population of approximately 23,000. Approximately 55% of the residents are renters, 15% higher than the state average. The median income between 2000 and 2016 rose nearly 100%. In 2010 approximately 55% of the population was Hispanic whereas by 2017 it had decreased by about 8% to about 47%. During those same 7 years the Black population had decreased from 17.4% to 13.2%.

A clear indication of the changing market is demonstrated by the fact that home and condo values nearly doubled between 2000 and 2018. The change in population is shown by the fact that the adjusted gross income increased from approximately \$23,500 in 2004 to \$38,500 just eight years later in 2012. Even so, in 2016, 23% of residents had income below the poverty level and 12% of residents had a household income below 50% of the poverty level.

The median sales price for a detached home was only about \$200,000 in 2000, and in 2016 it had risen to \$384,218 and the current median listing price for homes in 78702 is \$459,000 with a median price per square foot at \$383. The median house size is 1,244 square feet. The Tyndall, a condo development recently developed in 78702 just east of downtown Austin, has sales with costs per square foot between the high-\$400s and high \$700s which translates as condo units with 1,000 square feet selling for between about \$475,000 and \$790,000.

With current interest rates at about 4.5%, a \$375,000 mortgage would require a total monthly payment of about \$2,600. To be affordable, that would require a gross income of about \$105,000, which is over 150% of the MFI for a family of 2, 138% MFI for a family of 3, or 118% MFI for a family of 4 in Austin. There are predictions of tougher market for home buyers in 2019 with interest rates predicted to rise to between 5.55% and 5.8%.

Data from www.movoto.com/demographics/tx/78702/ shows the housing stock in the area displays a striking contrast in terms of age and style. Of the 10,254 housing units in the area, 3,403 were built between 2000 and 2016, during less than 20 years. There are only 2,724 homes from the preceding 40 years, those built between 1960 and 2000. At the other end of the age spectrum, 4,127 of the homes in 78702 were built prior to 1950 with 1,627 of those built before 1940.

¹ <u>Uprooted: Residential Displacement in Austin's Gentrifying Neighborhoods, and What Can Be Done About It,</u> available at https://sites.utexas.edu/gentrificationproject/

Current building trends are overwhelmingly aimed at apartment and condo development and single-family infill projects with two dwelling per lot.

Because GNDC gives priority to households with ties to the areas where it develops housing, it draws its home buyers and renters almost entirely households with ties to the East Austin community. GNDC currently has a waiting list for rental housing at over 700 households and a waiting list of interested buyers with over 80 households. Well over 90% of these prospective tenants and buyers have strong ties to East Austin. Remarkably, GNDC does virtually no marketing except and word of mouth has garnered applications from over 80 households interested in home ownership and over 700 desiring rental housing. Clearly there is a huge demand for affordable housing from households with low and moderate incomes coming from East Austin.

- ii. The majority of GNDC's buyers are likely to come from the 78702, 78721 and 78741 zip code areas. Because GNDC gives priority to those households from areas where displacement has occurred and where it continues to cost-burden long-time residents, the primary market/geographic area, based on neighborhood boundaries and zip code area is 78702, 78721 and 78741. These include the Central East Austin, East Cesar Chavez, Holly, Govalle, Rosewood, MLK, and Montopolis Neighborhoods.
- iii. GNDC began marketing its CLT Ownership program in 2014 after it found a mortgage lender for CLT homes. GNDC currently has 80 applicants hoping to purchase a home through its CLT program. There will be 7 homes for sale to households with incomes between 60% and 80% of the MFI and there are 25 buyers within that MFI range. The effective demand and capture rate therefore is 28%. There are 12 potential buyers with incomes between 50% and 60% of the MFI. The effective demand and capture rate therefore is 25%.
- iv. Analyze the Competition: There are virtually no other housing developments that are providing affordable single-family sales opportunities in the market area. The Austin Housing Finance Corporation produced 14 affordable ownership units between 2014 and 2018, but it appears their program has ceased. We are unable to identify any comparable units based on location, year of construction, target population, and property condition.
- **v. Absorption Period**. All 10 units will be pre-sold, meaning the sale will close within a week to a month after final completion..

Good Neighbor Policy - Father Joe Street Ownership Phase IV

GNDC has always included residents and property owners from the neighborhoods where it develops housing on its board of directors. Currently, Candace Fox, who serves on the Board of Directors, is also the Co-Chair of the Govalle Neighborhood. The Father Joe Street Phase IV Project is within the boundaries of the Govalle Neighborhood Association. Ms. Fox also serves as a representative on the Govalle Johnston Terrace Neighborhood Plan Contact Team. Additionally, Board of Directors Anna Maciel, lives within the Govalle Neighborhood.

GNDC has a Policy for Public Input which it adopted in 2002. In conformity with this policy, GNDC typically publicizes for a public meeting, via emails and flyers, to be held at an accessible public location, at which it presents new projects. The purpose of the meeting is to gather input regarding the location, design and program of the projects.

GNDC began designing the Guadalupe-Saldana Net-Zero Subdivision in 2007. On August 23, 2008 the project was presented at Santa Julia Church in the Govalle Neighborhood to neighborhood residents and property owners. The project was re-designed and was presented again in November 2008 and a survey seeking input was provided The survey results showed:

- -82% of the respondents liked or loved the project (only one person expressed dislike)
- -12% (2 people) wanted less affordable housing
- -12% (2 people) wanted more density than the down-zoning would allow
- -6% did not like the mix of ownership and rental
- -folks favored option A over the other two
- -the conceptual house designs were well received
- -favorite aspects of the project included the net zero energy goals and the focus on neighborhood resident retention
- -alterations to the project included safer parking, more ownership and community gardens
- -final feedback included suggestions to add density in some areas to better address affordable housing shortage

Subsequent Charettes and Input Meetings were held in May 2009 and April 2010. Construction began on the subdivision in 2011 with a number of neighborhood residents and leaders in attendance. Because this is the fourth phase of development along Father Joe Znotas Street, GNDC has had numerous opportunities to receive input and feedback from the neighborhood. The response has been overwhelmingly favorable. Currently, of the 16 home GNDC community land trust ownership units on Father Joe Znotas Street, all the owners come from East Austin and all but a few from the immediate Govalle Neighborhood.

Corporations Section P.O.Box 13697 Austin, Texas 78711-3697



Office of the Secretary of State

Certificate of Fact

The undersigned, as Secretary of State of Texas, does hereby certify that the document, Articles of Incorporation for GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION (file number 55666001), a Domestic Nonprofit Corporation, was filed in this office on April 06, 1981.

It is further certified that the entity status in Texas is in existence.

In testimony whereof, I have hereunto signed my name officially and caused to be impressed hereon the Seal of State at my office in Austin, Texas on January 22, 2019.



David Whitley Secretary of State

Dial: 7-1-1 for Relay Services Document: 862693910003

Phone: (512) 463-5555 Prepared by: SOS-WEB

Mark C. Rogers, Ph.D.

Mark@guadalupendc.org

Areas of expertise

Nonprofit residential development, affordable housing, green building, partnership development

Experience

Executive Director, Guadalupe Neighborhood Development Corporation

1994-Present

- Leads the growth of Guadalupe Neighborhood Development Corporation while focusing on its mission of
 preserving the residential character of, and prioritizing the households with ties to, the neighborhoods where it
 works.
- Oversees the operations and growth of the corporation while minimizing debt. 78% of GNDC's operating budget is generated by rental income.
- Oversees the development projects which include the 11-acre Guadalupe-Saldana Net-Zero Subdivision planned for 125 units of affordable, green housing, a growing portfolio of Community Land Trust homes, and the management of 105 rental units, and a variety of scattered site development initiatives.
- Coordinates partnerships and collaborations for various initiatives, including the Alley Flat Initiative with the
 University of Texas School of Architecture's Center for Sustainable Development and the Austin Community
 Design and Development Center and the Jeremiah Program Moody Campus with the Jeremiah Program Austin.
- Supervises development staff regarding grant and financing applications.
- Manages the design and programming of the development of new properties.
- Oversees compliance requirements to ensure the funding requirements for various projects.
- Manages the corporations and partnership assets and develops budgets for each.

Private Consultant 2004-Present

Works with several nonprofit and for-profit developers on a variety of projects including small subdivisions and infill rental and ownership projects.

PROJECTS LIST & COMPLETION DATE

- GNDC Exterior Rehab Project, 16 rental units, 1994
- Major Interior Rehab Project, 18 rental units, 1996
- Montopolis Good Neighbor Program, 6 lease-toown Rehabs, 1999
- Guadalupe Area Infill Project, 17 new homes, 2004
- Guadalupe HIP 2000, 9 rental units, new and rehab, 2003
- RHDA Rental Infill Project, 7 new rental units, 2007
- La Vista de Guadalupe, 22 LIHTC rental units, 2008
- SOL Rental Project, 8 rental units, Acquisition, 2009
- SOL Ownership Project, 6 Home ownership shared equity, 2010.
- 1313 Willow Community Land Trust home, 2012

- 807 Waller Community Land Trust home, 2014
- Guadalupe-Saldana Net-Zero, 125 units. Rental & ownership 2005-ongoing:
 - 4 Duplex Project. 8 new rental units, 2013
 - Rainey Street Relocation, 4 rehab homes, 2014
 - Jeremiah Program Moody Campus. 35 new multifamily rental units, 2017
 - Father Joe Znotas Street Phase II, 8 CLT ownership, 2018
 - Father Joe Znotas Street Phase III, 4 CLT ownership, 2018
 - RHDA Scattered Infill. 7 rental units. 2019

Rachel R. Stone

Rachel@guadalupendc.org

EMPLOYMENT EXPERIENCE:

Assistant Executive Director, GNDC, Austin TX, 2018-Present

- Development of Strategic Partnerships and Fundraising Relationships.
- Development of Affordable housing through completion of SMART Housing and Zoning Applications.
- Community outreach and engagement.

Program Development Manager, ICAST, Austin TX/Denver CO, 2015-Present

- Developed and managed financing, youth development and clean energy programs for a 501(c)3 national nonprofit dedicated to green rehab and preservation of multifamily affordable housing;
- Provide legal, technical assistance, research, and policy analysis on best practices for executing energy, affordable housing, workforce development, health, and financing programs;

Policy Coordinator, SPEER, Austin TX, 2014

- Coordinated and streamlined collaboration between Austin and other local Texas governments' energy efficiency initiatives through a City Energy Leadership Council.
- Drafted and edited model resolution, contract, application and provided technical assistance for cities and counties to use in the establishment of local Property-Assessed Clean Energy (PACE) programs.
- Researched and drafted extensive policy papers; organized and led webinars, workshops, and panels.

Clean Energy Attorney, Environment Texas, Austin TX, 2013–2014

- Led advocacy efforts expanding policies to promote solar power, wind power, and energy efficiency at the local and state level in Texas.
- Drafted and published research and policy fact sheets, developed media campaigns and coalitions, provided outreach and coordination of grassroots organizing.

Staff Attorney, U.S. Dept. Housing & Urban Development, Fort Worth TX, 2011-2013

- Provided research, counseling and written memoranda to resolve legal and regulatory questions regarding fair housing, community development grants, and government ethics.
- Assisted FEMA on disaster response, improved collaboration with outside agencies and government grantees, and proactively identified training and improvement needs within agency.

RELATED CLINICS & INTERNSHIPS:

Student Attorney, UT Community Development Clinic, Austin TX, 2010–2011

Law Clerk, Lower River Colorado Authority, Austin TX, 2010

Law Clerk, Texas Civil Rights Project, Austin TX, 2009

GIS Technician, City of Austin Watershed Protection, Austin TX, 2006–2007 Intern for the Mayor's Staff, City of New Haven City Hall, New Haven CT, 2005 Neighborhood Services Intern, Providence City Hall, Providence RI, 2004

COMMUNITY ENGAGEMENT:

Treasurer, Solar Austin Board of Directors, Austin TX, 2014-Present

Executive Committee Member, Austin Housing Coalition, Austin TX, 2017-Present

Vice President, Artstillery Board of Directors, Dallas TX, 2017-Present

Affordable Housing Group Chair, 2018 Bond Election Advisory Task Force, Austin TX, 2016-2018

LICENSURE & EDUCATION:

Texas State Bar Admission, 2011

J.D., The University of Texas School of Law, 2011 Austin TX

- Justice Center Award Recipient for Extraordinary Commitment to Public Service, 2011
- UT Center for Public Policy and Dispute Resolution Mediation Certification, 2010
- Related coursework: Administrative Law, Community Development Clinic, Regulation & Public Policy, Land Use Regulation, Property & Governance

B.A., **Brown University**, 2006 Providence RI

• Double Major: Urban Studies & Literary Arts

Internal Revenue Service District Director

FEB 9 1983

Date:

FEB 0 4 1000

CUADALUPE NEIGHBORBOOD DEVELOPMENT CORPORATION 1212 EAST 9TH STREET AUSTIN, TX 78702 Department of the Treasury

Employer Identification Number:

74-2247265
Accounting Period Ending:
OCTOBER 31
Foundation Status Classification:
170 (b) (1) (A) (vi) and 509 (a) (1)
Advance Ruling Period Ends:
OCTOBER 31, 1986
Person to Contact:
EO TECHNICAL ASSISTOR
Contact Telephone Number:
(214) 767-2728
EO:7215:WHJ

Dear Applicant:

Based on information supplied, and assuming your operations will be as stated in your application for recognition of exemption, we have determined you are exempt from Federal income tax under section 501(c)(3) of the Internal Revenue Code.

Because you are a newly created organization, we are not now making a final determination of your foundation status under section 509(a) of the Code. However, we have determined that you can reasonably be expected to be a publicly supported organization described in section 170(b) (1) (A) (vi) and 509(a) (1).

Accordingly, you will be treated as a publicly supported organization, and not as a private foundation, during an advance ruling period. This advance ruling period begins on the date of your inception and ends on the date shown above.

Within 90 days after the end of your advance ruling period, you must submit to us information needed to determine whether you have met the requirements of the applicable support test during the advance ruling period. If you establish that you have been a publicly supported organization, you will be classified as a section 509(a)(1) or 509(a)(2) organization as long as you continue to meet the requirements of the applicable support test. If you do not meet the public support requirements during the advance ruling period, you will be classified as a private foundation for future periods. Also, if you are classified as a private foundation, you will be treated as a private foundation from the date of your inception for purposes of sections 507(d) and 4940.

Grantors and donors may rely on the determination that you are not a private foundation until 90 days after the end of your advance ruling period. If you submit the required information within the 90 days, grantors and donors may continue to rely on the advance determination until the Service makes a final determination of your foundation status. However, if notice that you will no longer be treated as a organization is published in the Internal Revenue Bulletin, section 509(a)(1) grantors and donors may not rely on this determination after the date of such publication. Also, a grantor or donor may not rely on this determination if he or she was in part responsible for, or was aware of, the act or failure to act that status, or acquired knowledge that resulted in your loss of section 509(a) (1) the Internal Revenue Service had given notice that you would be removed from classification as a section 509(a)(1) organization.

If your sources of support, or your purposes, character, or method of operation change, please let us know so we can consider the effect of the change on your exempt status and foundation status. Also, you should inform us of all changes in your name or address.

Generally, you are not liable for social security (FICA) taxes unless you file a waiver of exemption certificate as provided in the Federal Insurance Contributions Act. If you have paid FICA taxes without filing the waiver, you should call us. You are not liable for the tax imposed under the Federal Unemployment Tax Act (FUTA).

Organizations that are not private foundations are not subject to the excise taxes under Chapter 42 of the Code. However, you are not automatically exempt from other Federal excise taxes. If you have any questions about excise, employment, or other Federal taxes, please let us know.

Donors may deduct contributions to you as provided in section 170 of the Code. Bequests, legacies, devises, transfers, or gifts to you or for your use are deductible for Federal estate and gift tax purposes if they meet the applicable provisions of sections 2055, 2106, and 2522 of the Code.

You are required to file Form 990, Return of Organization Exempt from Income Tax, only if your gross receipts each year are normally more than \$10,000.* If a return is required, it must be filed by the 15th day of the fifth month after the end of your annual accounting period. The law imposes a penalty of \$10 a day, up to a maximum of \$5,000, when a return is filed late, unless there is reasonable cause for the delay.

You are not required to file Federal income tax returns unless you are subject to the tax on unrelated business income under section 511 of the Code. If you are subject to this tax, you must file an income tax return on Form 990-T. In this letter, we are not determining whether any of your present or proposed activities are unrelated trade or business as defined in section 513 of the Code.

You need an employer identification number even if you have no employees. If an employer identification number was not entered on your application, a number will be assigned to you and you will be advised of it. Please use that number on all returns you file and in all correspondence with the Internal Revenue Service.

Because this letter could help resolve any questions about your exempt status and foundation status, you should keep it in your permanent records.

If you have any questions, please contact the person whose name and telephone number are shown in the heading of this letter.

IC: JANES W. PIPER

ESCLOSURE: 872-C

Sincerely yours,

R. C. Voskuil District Director

For tax years ending on and after December 31, 1982, organizations whose ross receipts are not normally more than \$25,000 are excused from filing Form 90. For guidance in determining if your gross receipts are "normally" not ore than the \$25,000 limit, see the instructions for the Form 990.

Exhibit C

Department of the Treasury Director, Exempt Organizations

Date:

MAY 24 2000

Guadalupe Neighborhood Development Corporation 1113 E 9th St. Austin, TX 78702 Internal Revenue Service P.O. Box 2508 Cincinnati, OH 45201

Employer Identification Number: 74-2247265

Document Locator Number: 310069476EO

Contact Person - ID Number: Mr. Evans - 31-02826

Contact Telephone Number: (877) 829-5500 Toll-Free

Our Letter Dated: October, 1986 Addendum Applies: No

Dear Sir or Madam:

We have received your correspondence dated February 23, 2000, which includes Form 8734.

Since your organization was issued its determination letter, the Internal Revenue Code has been revised and organizations exempt under 501(c)(3) are classified as either private foundations or public charities described in 509(a). Our records do not indicate that we have made this determination for your organization.

Your exempt status under section 501(a) of the Internal Revenue Code as an organization described in section 501(c)(3) is still in effect. Based on the information you submitted, we have determined that you are not a private foundation within the meaning of section 509(a) of the Code because you are an organization of the type described in sections 509(a)(1) and 170(b)(1)(A)(vi).

Grantors and contributors may rely on this determination unless the Internal Revenue Service publishes notice to the contrary. However, if you lose your section 509(a)(1) status, a grantor or contributor may not rely on this determination if he or she was in part responsible for, or was aware of, the act or failure to act, or the substantial or material change on the part of the organization that resulted in your loss of such status, or if he or she acquired knowledge that the Internal Revenue Service had given notice that you would no longer be classified as a section 509(a)(1) organization.

If we have indicated in the heading of this letter that an addendum applies, the addendum enclosed is an integral part of this letter.

Because this letter could help resolve any questions about your private foundation status, please keep it in your permanent records.

If you have any questions, please contact the person whose name and telephone number are shown above.

Sincerely yours,

Steven T. Miller
Steven T. Miller
Director, Exempt Organizations

Letter 1050 Modified (DO/CG)



Montemayor Britton Bender PC

CERTIFIED PUBLIC ACCOUNTANTS

GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION

CONSOLIDATED FINANCIAL STATEMENTS
AND
INDEPENDENT AUDITOR'S REPORT

31 DECEMBER 2017 AND 2016

Exhibit C 16 of 238



Montemayor Britton Bender PC

CERTIFIED PUBLIC ACCOUNTANTS

Board of Directors and Management Guadalupe Neighborhood Development Corporation

INDEPENDENT AUDITOR'S REPORT

We have audited the accompanying consolidated financial statements of Guadalupe Neighborhood Development Corporation (GNDC), a nonprofit organization, which comprise the consolidated statement of financial position as of 31 December 2017 and 2016, and the related consolidated statements of activities and cash flows for each year then ended, and the related notes to the consolidated financial statements.

Management's Responsibility for the Financial Statements

Management is responsible for the preparation and fair presentation of these consolidated financial statements in accordance with accounting principles generally accepted in the United States of America; this includes the design, implementation, and maintenance of internal control relevant to the preparation and fair presentation of consolidated financial statements that are free from material misstatement, whether due to fraud or error.

Auditor's Responsibility

Our responsibility is to express an opinion on these consolidated financial statements based on our audit. We conducted our audit in accordance with auditing standards generally accepted in the United States of America and the standards applicable to financial audits contained in *Government Auditing Standards*, issued by the Comptroller General of the United States. Those standards require that we plan and perform the audit to obtain reasonable assurance about whether the consolidated financial statements are free of material misstatement.

An audit involves performing procedures to obtain audit evidence about the amounts and disclosures in the consolidated financial statements. The procedures selected depend on the auditor's judgement, including the assessment of the risk of material misstatement of the consolidated financial statements, whether due to fraud or error. In making those risk assessments, the auditor considers internal control relevant to the entity's preparation and fair presentation of the consolidated financial statements in order to design audit procedures that are appropriate in the circumstances, but not for the purpose of expressing an opinion on the effectiveness of the entity's internal control. Accordingly, we express no such opinion. An audit also includes evaluating the appropriateness of accounting policies used and reasonableness of significant accounting estimates made by management, as well as evaluating the overall presentation of the consolidated financial statements.

2525 WALLINGWOOD DRIVE BUILDING 1, SUITE 200 AUSTIN, TEXAS 78746 PHONE: 512.442.0380 FAX: 512.442.0817 www.montemayor.team



We believe that the audit evidence we have obtained is sufficient and appropriate to provide a basis for our audit opinion.

Opinion

In our opinion, the consolidated financial statements referred to above present fairly, in all material respects, the financial position of GNDC as of 31 December 2017 and 2016, and changes in its net assets and its cash flows for the years then ended in accordance with accounting principles generally accepted in the United States of America.

Other Matters

Our audit was conducted for the purpose of forming an opinion on the consolidated financial statements taken as a whole. The accompanying schedule of expenditures of federal awards (page 24), as required by Title 2 U.S. Code of Federal Regulations (CFR) Part 200, Uniform Administrative Requirements, Cost Principles, and Audit Requirements for Federal Awards, is presented for additional analysis and is not a required part of the consolidated financial statements. The supplemental schedule of Community Land Trust sources and uses (page 27) is presented for additional analysis as required by Texas property tax code 11.1827, and is also not a required part of the consolidated financial statements. The supplemental financial statements of Guadalupe Jeremiah LP (pages 18-19) are presented for additional analysis, and are also not a required part of the consolidated financial statements. The schedule of expenditures of federal awards, the supplemental schedule of Community Land Trust sources and uses, and the supplemental financial statements of Guadalupe Jeremiah LP are the responsibility of management and were derived from and relate directly to the underlying accounting and other records used to prepare the consolidated financial statements. Such information has been subjected to the auditing procedures applied in the audit of the consolidated financials and certain additional procedures, including comparing and reconciling such information directly to the underlying accounting and other records used to prepare the consolidated financial statements or to the consolidated financial statements themselves, and other additional procedures in accordance with auditing standards generally accepted in the United States of America. In our opinion, the schedule of expenditures of federal awards, the supplemental schedule of Community Land Trust sources and uses, and the supplemental financial statements of Guadalupe Jeremiah LP are fairly stated in all material respects in relation to the consolidated financial statements taken as a whole.

Other Reporting Required by Government Auditing Standards

In accordance with Government Auditing Standards, we have also issued our report dated 15 May 2018, on our consideration of GNDC's internal control over financial reporting on our tests of its compliance with certain provisions of laws, regulations, contracts, and grant agreements and other matters. The purpose of that report is to describe the scope of our testing of internal control over financial reporting and compliance and the results of that testing, and not to provide an opinion on the internal control over financial reporting on compliance. That report is an integral part of an audit performed in accordance with Government Auditing Standards in considering GNDC's internal control over financial reporting and compliance.

15 May 2108 Austin, Texas Exhibit C

GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION

18 of 238

CONSOLIDATED STATEMENT OF FINANCIAL POSITION 31 DECEMBER 2017 AND 2016

	2017	2016
ASSETS	2017	<u>2016</u>
CURRENT ASSETS		
Cash	0/75 77/	#1 001 ac.i
Current portion of notes receivable	\$675,776	\$1,991,394
	5,100	5,100
Prepaid insurance and other	65,349	70,321
MONOURDENIT ACCEPTO	746,225	2,066,815
NONCURRENT ASSETS		
Fixed assets	10,036	0
Long-term portion of notes receivable	3,082,276	3,051,119
Long-term interest receivable	1,091,701	986,693
Construction in progress (including land of \$1,001,078)	3,482,651	9,532,201
Rental real estate	11,397,618	3,725,122
	\$19,810,507	\$19.361.950
LIABILITIES AND NET ASSE	TS	
CURRENT LIABILITIES		
Accounts payable	\$433,018	\$291,665
Accrued liabilities and deferred revenue	112,123	90,546
Retainage payable	144,173	598,884
Current portion of notes payable	77,033	34,226
	766,347	1,015,321
LONG-TERM LIABILITIES		
Minority interest liabilities	4,955,993	4,945,239
Long-term portion of notes payable	11,410,888	10,359,200
	17,133,228	16,319,760
NET ASSETS		
Unrestricted	2,595,426	2,916,790
Temporarily restricted	81,853	125,400
	2,677,279	3,042,190
	\$19,810,507	\$19,361,950

CONSOLIDATED STATEMENT OF ACTIVITIES

YEAR ENDED 31 DECEMBER 2017

REVENUE	Unrestricted	Temporarily Restricted	Total
Rent	6451 004	φA	0451.004
Foundation and corporate contributions	\$451,904	\$0	\$451,904
Interest	101,631	59,800	161,431
	105,008	0	105,008
Forgiveness of debt	10,368	0	10,368
Other	28,881	2,775	31,656
Net assets released from restriction	106,122	(106,122)	0
	803,914	(43,547)	760,367
EXPENSES			
Depreciation	355,523	0	355,523
Payroll	264,584	0	264,584
Loss on notes receivable	155,596	0	155,596
Repairs and maintenance	81,657	0	81,657
Insurance	69,522	0	69,522
Utilities	65,139	0	65,139
Professional services	29,296	0	29,296
Interest	25,037	0	25,037
Property taxes	19,671	0	19,671
Loss on disposal of houses	16,080	0	16,080
Other	43,173	<u>0</u>	43,173
	1,125,278	0	1,125,278
CHANGE IN NET ASSETS	(321,364)	(43,547)	(364,911)
BEGINNING NET ASSETS	2,916,790	125,400	3,042,190
ENDING NET ASSETS	\$2,595,426	\$81,853	\$2,677,279

GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION

CONSOLIDATED STATEMENT OF ACTIVITIES

YEAR ENDED 31 DECEMBER 2016

REVENUE	Unrestricted	Temporarily Restricted	Total
Rent	\$410.400	th O	M440 400
Foundation contributions	\$412,403	\$0	\$412,403
	21,932	113,000	134,932
Contributions including \$111,960 in contributed services Interest	119,460	0	119,460
120000	105,458	0	105,458
Forgiveness of debt	21,100	0	21,100
Other	30,784	0	30,784
Net assets released from restriction	3,000	(3,000)	0
	714,137	110,000	824,137
EXPENSES			
Payroll	229,002	0	229,002
Depreciation	174,622	0	174,622
Legal services	111,960	0	111,960
Repairs and maintenance	60,756	0	60,756
Insurance	49,491	0	49,491
Professional services	21,298	0	21,298
Utilities	21,071	0	21,071
Interest	20,590	0	20,590
Other	37,586	0	37,586
	726,376	0	726,376
CHANGE IN NET ASSETS	(12,239)	110,000	97,761
BEGINNING NET ASSETS	2,929,029	15,400	2,944,429
ENDING NET ASSETS	\$2,916,790	\$125,400	\$3,042,190

GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION 21 of 23

CONSOLIDATED STATEMENT OF CASH FLOWS YEARS ENDED 31 DECEMBER 2017 AND 2016

CASH FLOWS FROM OPERATING ACTIVITIES	2017	2016
Change in net assets	(\$364,911)	\$97,761
Depreciation	355,523	174,622
Amortization	7,297	7,297
Forgiveness of debt	(10,368)	(21,100)
Discount on note receivable	155,596	0
Loss on disposal of asset	16,080	0
Change in prepaid insurance and other	4,972	(52,524)
Change in interest receivable	(105,008)	(105,458)
Change in accrued liabilities and deferred revenue	21,577	5,663
Change in retainage payable	(454,711)	598,884
Change in accounts payable	141,353	291,665
	(232,600)	996,810
CASH FLOWS FROM INVESTING ACTIVITIES		
Notes receivable principal payments received	72,150	34,820
Notes receivable funded	(258,903)	0
Additions to construction in progress	(1,780,520)	(6,050,370)
Purchase of housing units and fixed assets	<u>0</u>	(292,554)
	(1,967,273)	(6,308,104)
CASH FLOWS FROM FINANCING ACTIVITIES		
Capital contribution to Guadalupe Jeremiah LP from limited partner	1,787	4,883,943
Distributions to Guadalupe Jeremiah LP limited partner	(215,098)	0
Principal payments on debt	(401,204)	(72,281)
Proceeds from debt	1,498,770	2,050,000
	884,255	6,861,662
NET CHANGE IN CASH	(1,315,618)	1,550,368
BEGINNING CASH	1,991,394	441,026
ENDING CASH	\$675,776	\$1,991,394
SUPPLEMENTARY INFORMATION: Cash paid for interest	<u>\$25,037</u>	\$20,590

NOTES TO CONSOLIDATED FINANCIAL STATEMENTS

NOTE 1: ORGANIZATION

Guadalupe Neighborhood Development Corporation (GNDC) is a Texas nonprofit corporation set up to provide affordable housing to families in the Austin area with very low to moderate incomes. In 2005, GNDC established a new entity and became the sole member of GNDC GP, LLC. In turn, GNDC GP, LLC became the general partner of Guadalupe-Saldana Affordable Homes, LP, Because GNDC has 100% of the voting interest in GNDC GP, LLC, and GNDC GP, LLC has a controlling financial interest in Guadalupe-Saldana Affordable Homes, LP (as general partner), the financial statements consolidate the financial statements of the 3 entities. Inter-company balances have been eliminated in the consolidation. GNDC GP, LLC's sole purpose is to serve as general partner of Guadalupe-Saldana Affordable Homes, LP. Guadalupe-Saldana Affordable Homes, LP owns land where GNDC will build approximately 125 homes. The accompanying consolidated financial statements report all of the activity of various funding sources which includes rental and interest income, grants, and contributions.

During 2007, GNDC established La Vista de Guadalupe, LLC (La Vista) with GNDC as the sole member. La Vista is serving as the 0.01% general partner in a low income housing development and GNDC is serving as the developer of the development. The financial statements of La Vista are not material and have not been consolidated. In addition, although GNDC (La Vista) serves as the general partner in the development, other partners, as stipulated in the partnership agreements, retain the controlling financial interest in the development.

In 2015, GNDC established GNDC Saldana GP, LLC (GNDC Saldana GP), with GNDC being the sole member. GNDC Saldana GP and the Jeremiah Program Austin, LLC subsequently formed a partnership, Guadalupe Jeremiah LP (Guadalupe Jeremiah), with GNDC Saldana GP as the general partner, and Jeremiah Program Austin, LLC as a limited partner. As GNDC, through GNDC Saldana GP, has a controlling financial interest in and is the primary beneficiary of Guadalupe Jeremiah, the financial statements of Guadalupe Jeremiah are consolidated with GNDC. Inter-company balances have been eliminated in the consolidation. In 2017, Guadalupe Jeremiah constructed a residential rental facility with 35 units for single parents pursuing education and career opportunities.

NOTE 2: SUMMARY OF SIGNIFICANT ACCOUNTING POLICIES

FINANCIAL STATEMENT PRESENTATION

GNDC is required to report information regarding its financial position and activities according to three classes of net assets: unrestricted net assets, temporarily restricted net assets, and permanently restricted net assets, as applicable.

BASIS OF ACCOUNTING

GNDC uses the accrual method of accounting which recognizes revenue when earned and expenses when incurred.

NOTES TO CONSOLIDATED FINANCIAL STATEMENTS

NOTE 2: SUMMARY OF SIGNIFICANT ACCOUNTING POLICIES

REVENUE

Unconditional grants and contributions received are recorded at fair value on the date of the award as unrestricted, temporarily restricted, or permanently restricted support depending on the existence and/or nature of any donor restrictions.

SUBSEQUENT EVENTS

Management of GNDC has evaluated subsequent events for disclosure through the date of the Independent Auditor's Report, the date the consolidated financial statements were available to be issued.

ESTIMATES

The preparation of consolidated financial statements in conformity with U.S. generally accepted accounting principles requires management to make estimates and assumptions that affect the reported amounts of assets and liabilities, disclosure of contingent assets and liabilities at the date of the financial statements, and the reported amounts of revenues and expenses during the reporting period. Actual results could differ from those estimates.

FUNCTIONAL EXPENSE ALLOCATION

The costs of providing various program, management and fundraising activities have been summarized on a functional basis. Accordingly, certain costs have been allocated among the functions benefitted.

FIXED ASSETS

Acquisitions of property and equipment valued at \$1,000 or more and a useful life greater than one year are capitalized at cost, or estimated fair market value on the date of donation, if donated. Repairs and maintenance costs are expensed as incurred. Depreciation is computed using the straight-line method based on the estimated useful life of the asset, which is 5 years for furniture and equipment and 25 years for building.

REAL ESTATE

Real estate consists of land, housing units and appliances. Real estate is capitalized at cost, which includes the cost of preacquisition, acquisition, development, and construction. Housing units leased and the appliances within are depreciated using the straight-line method based on an estimated useful life of 25 and 5 years, respectively. Housing units leased and held for sale are restricted for rental and sales to families with low incomes. Housing units held for sale were sold to families with low income during the year. Upon the sale of housing units, the difference between the cost and sale proceeds results in a net gain or loss.

GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION

NOTES TO CONSOLIDATED FINANCIAL STATEMENTS

SUMMARY OF SIGNIFICANT ACCOUNTING POLICIES NOTE 2:

RENTAL OPERATIONS

GNDC leases its real estate properties as single family residences under noncancellable operating leases. There were 58 available housing units for lease in 2017 and 2016. Generally, these leases have twelve month terms, automatically renewing on a month-tomonth basis thereafter

INCOME TAXES

In accordance with Section 501(c)(3) of the Internal Revenue Code, GNDC is exempt from federal income taxes. Consequently, no provision for Federal income taxes is included in the accompanying consolidated financial statements.

Guadalupe Saldana and Guadalupe Jeremiah have elected to be taxed as limited partnerships. Under such elections, federal taxable income or loss and tax credits are passed through to the individual partners. Texas state taxes are imposed at the entity level. Any federal taxes due by GNDC, as the general partner, or any state taxes due by the limited partnerships, are recognized in the financial statements when incurred, as tax expense and tax liability.

At 31 December 2017 and 2016, respectively, no interest, penalties, federal taxes, or state taxes have been or are required to be accrued. GNDC's policy is to record interest and penalties related to income taxes as interest and other expense and federal or state taxes as tax expense. GNDC, generally, is no longer subject to income tax examinations by federal authorities for years prior to 31 December 2015.

NOTE 3: CONTINGENCY

GNDC receives forgivable loans and cost reimbursement grants from the City of Austin to assist with implementation of its program. Should GNDC not comply with the terms of the loans and grants or should any costs be determined to be ineligible, GNDC will be responsible for reimbursing the grantor for these amounts. Management believes there will be no such disallowance.

As part of a development agreement, GNDC guaranteed to fund operating deficits, if any, of La Vista apartments up to \$85,000 via an unsecured loan to La Vista with interest at 8%. As of 31 December 2017 and 2016, no operating deficits have been incurred.

NOTE 4: COMMITMENTS

Under the terms of various agreements with funding agencies, GNDC is required to provide certain services including, but not limited to, using certain properties for low income housing and maintaining certain levels of insurance.

NOTES TO CONSOLIDATED FINANCIAL STATEMENTS

NOTE 5: RELATED PARTY TRANSACTIONS

As of 31 December 2017 and 2016, GNDC had interest receivable of \$1,091,701 and \$986,693, respectively, and notes receivable of \$2,820,626 and \$2,748,231, respectively, due from Guadalupe Family Community, L.P., an organization with common officers.

During the years ended 31 December 2017 and 2016, GNDC paid Saldana Homes, LLC, a related party, \$898,672 and \$87,304, respectively, to construct eight houses and for repairs to two houses. Saldana Homes, LLC invested \$63,000 in Guadalupe-Saldana to purchase land.

GNDC purchased a house from a board member for \$261,000 in 2015. As of 31 December 2017 and 2016, GNDC owed the board member \$253,100, which will be paid with a 0% interest 15 year note. Payments on the note were deferred for three years.

NOTE 6: RENTAL REAL ESTATE

GNDC:	2017	2016
58 housing units in 2017 and 2016 (with \$927,500 land)	\$5,275,028	\$5,282,377
Construction in progress	1,301,169	34,740
Closing costs	19,247	19,247
Land	409,147	409,147
Accumulated depreciation	(2,153,515)	(2,020,389)
	4,851,076	3,725,122
Guadalupe Jeremiah:		
17 housing units in service in 2017	6,749,012	0
Accumulated depreciation	(202,470)	<u>0</u>
	6,546,542	0
	\$11,397,618	\$3,725,122

NOTE 7: CONCENTRATIONS

92% and 93% of notes payable are due to one lender as of 31 December 2017 and 2016. See Note 13.

At 31 December 2016, GNDC had cash balances in excess of FDIC insurance amounted to \$1,430,300. GNDC has not experienced any losses due to this credit risk.

NOTES TO CONSOLIDATED FINANCIAL STATEMENTS

NOTE 8: FINANCING RECEIVABLE

GNDC has a financing receivable agreement with one borrower. The receivable is performing and current, and is fully collateralized by property. Thus, no allowance is needed.

NOTE 9: CONTRIBUTED SERVICES

During the year ended 31 December 2016, GNDC received \$111,960 in contributed legal services.

NOTE 10: FUNCTIONAL EXPENSES

	2017	2016
Program	\$848,172	\$644,812
Management	95,894	74,300
Fundraising	9,536	7,264
	953,602	726,376
Unallocated:		
Loss on note receivable	155,596	0
Loss on disposal of asset	16,080	0
	<u>\$1,125,278</u>	\$726,376

NOTE 11: CONSTRUCTION CONTRACT COMMITMENT AND SUBSEQUENT EVENTS

On 20 November 2017 GNDC entered into a contract with Saldana Homes, LLC to construct seven rental units. The total contract commitment is approximately \$1,243,000. Construction began subsequent to year-end.

On 2 February 2018 GNDC entered into a contract with Austin Habitat for Humanity to build four houses. The total commitment is \$300,000.

NOTE 12: NOTES RECEIVABLE

The notes are collateralized by real property as described in the note agreements. GNDC's access to the collateral is based on normal legal foreclosure processes. If the debtors fail to perform according to the terms of the agreements, and the collateral proves to be of no value, GNDC would incur a loss equal to the principal balance receivable.

GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION

NOTES TO CONSOLIDATED FINANCIAL STATEMENTS

NOTE 12: NOTES RECEIVABLE

	2017	2016
Note receivable from Guadalupe Family Community, L.P., collateralized by real estate, bearing an interest rate of 4%. See note 13 for the related note payable to the City of Austin in the same amount.	\$2,138,239	\$2,138,239
Note receivable from Guadalupe Family Community, L.P.,	+=,100,200	Ψ4,150,257
collateralized by real estate, note bears a 1.5% interest rate.	155,248	185,248
Note receivable from Guadalupe Family Community, L.P., collateralized by real estate, note bears a 0% interest rate.	78,399	77,457
Note receivable from Guadalupe Family Community, L.P.,		
collateralized by real estate, note bears a 0% interest rate.	102,365	0
Note receivable from Guadalupe Family Community, L.P., collateralized by real estate, note bears a 4.9% interest rate	350,000	350,000
Notes receivable agreements (4 in 2017 and 5 in 2016), collateralized by real estate, note bears a 0% interest, monthly payments are scheduled to begin in 2040. In the event of default, the receivable will begin to accrue interest at 10%.	139,100	176,150
Note receivable from one borrower, collateralized by real		
estate, note bears an interest rate of 0%.	124,025	129,125
	3,087,376	3,056,219
Less current portion of notes receivable	(5,100)	(5,100)
Long-term portion of notes receivable	\$3,082,276	\$3,051,119

During 2010, GNDC entered into six note receivable agreements as the result of the sale of six properties. The properties were sold by an independent party at appraised fair market value, but with the seller accepting amounts less than fair market value. The cash portion of the sales were financed by the purchasers with bank mortgages and down payment assistance from the City of Austin. The difference between the appraised value sales price and the cash required at purchase was secured by a third lien held by GNDC. The third lien note also provided GNDC with a share of equity based on the percentage value of its lien relative to the appraised value of the property. Based on current market value estimates, GNDC's interest in any appreciated value over the recorded value of the third lien notes is not considered significant at year-end. One property was sold during 2016, and GNDC received the portion of the third lien used to acquire the property, \$21,615, plus \$12,585 for its share of equity based on the appreciated value, calculated as the difference between the initial property value and the appraised value at resale. One property was sold during 2017, and GNDC received the portion of the third lien used to acquire the property, \$37,050, plus \$9,447 for its share of equity based on the appreciated value, calculated as the difference between the initial property value and the appraised value at resale.

NOTES TO CONSOLIDATED FINANCIAL STATEMENTS

NOTE 13: NOTES PAYABLE

The carrying value of assets pledged as collateral on loans is as follows:

	2017	2016
Construction in progress (including land of \$1,001,078)	\$3,477,345	\$3,477,345
Land	339,147	409,147
Rental real estate (with \$785,250 and \$807,750 in land in 2017 and 2016, respectively)	2,930,265	3,053,300
Note receivable (see Note 12)	2,138,339	2,138,239
	\$8,885,096	\$9,078,031
	2017	2016
Various notes payable to the City of Austin, collateralized by rental real estate, with interest at 6%. Repayment is waived as scheduled, provided GNDC maintains this property for low income families. Repayment waived for the year is disclosed in the statement of activities as forgiveness of debt. The note matures 27 February 2021.		\$25,000
Note payable to Austin Housing Finance, with a 0% interest, collateralized by real estate. The note will be forgiven as each of the housing units are sold. The remaining balance will be forgiven in its entirety if on 31 August 2110, GNDC is in compliance with all terms and conditions of the Loan Agreement.		1,396,154
Note payable to Mary Helen Lopez (a board member), at 0% interest, payable in monthly payments of \$1,450 starting June 2018 until June 2033, discounted to present value at a rate of 6%.		135,134
Note payable to Austin Housing Finance, collateralized by rental real estate. The note bears a 0% interest rate until maturity and the principal and interest shall be forgiven in its entirety if on 31 March 2112, GNDC is in compliance with all terms and conditions of the Loan Agreements.	h-I	600,000
Note payable to the Austin Housing Finance, collateralized by rental real estate, bearing interest at 0%, due in monthly installments through 1 April 2023.		22,750

NOTES TO CONSOLIDATED FINANCIAL STATEMENTS

NOTE 13: NOTES PAYABLE

	<u>2017</u>	<u>2016</u>
Notes payable to Austin Housing Finance, collateralized by rental real estate. The notes bear a 0% interest rate until maturity and the principal and interest shall be forgiven in its entirety if on 1 March 2107, GNDC is in compliance with all terms and conditions of the Loan Agreements.	102,354	102,354
Note payable to Austin Housing Finance, collateralized by rental real estate. The note bears a 0% interest rate until maturity and the principal and interest shall be forgiven in its entirety if on 23 April 2108, GNDC is in compliance with all terms and conditions of the Loan Agreement.	850,000	850,000
Note payable to Austin Housing Finance, collateralized by rental real estate. The note bears a 0% interest rate until maturity and the principal and interest shall be forgiven in its entirety on 11 November 2049 if GNDC is in compliance with all terms and conditions of the loan.	435,500	435,500
Note payable to Austin Housing Finance, collateralized by rental real estate. The note bears a 0% interest rate until maturity and the principal and interest shall be forgiven in its entirety on 1 February 2027. GNDC is in compliance with all terms and conditions for repayment.	395,000	395,000
Note payable to Austin Housing Finance, collateralized by GNDC's note receivable from Guadalupe Family Community, L.P. which in turn, is collateralized by the underlying rental real estate. The note bears a 0% interest rate until maturity and the principal and interest shall be forgiven in its entirety if on 1 September 2049, GNDC is in compliance with all terms and conditions of the Loan Agreement. See Note 12 for related note receivable.	2,138,239	2,138,239
Note payable to Austin Housing Finance, collateralized by rental real estate. The note bears a 0% interest rate until maturity and the principal and interest shall be forgiven in its entirety if on 31 January 2108, GNDC is in compliance with all terms and conditions of the Loan Agreement.	1,000,000	1,000,000
Note payable to Austin Housing Finance, collateralized by real estate. The note bears a 0% interest rate until maturity and the principal and interest shall be forgiven in its entirety if on 30 April 2049, GNDC is in compliance with all terms and conditions of the	22.416	and and
Loan Agreement.	60,000	60,000

GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION 30 of 238

NOTES TO CONSOLIDATED FINANCIAL STATEMENTS

NOTE 13: NOTES PAYABLE

	2017	2016
Note payable to Austin Housing Finance, collateralized by real estate. The note bears a 0% interest rate until maturity and the principal and interest shall be forgiven in its entirety if on 20 December 2108, GNDC is in compliance with all terms and conditions of the Loan Agreement.	555,000	555,000
Note payable to Wells Fargo, collateralized by real estate. The note bears a 5.65% interest rate, payable in monthly installments. The balance was paid in full in 2017.	0	273,248
Note payable to Wells Fargo, collateralized by real estate. The note bears a 4.5% interest rate, payable in monthly installments until 1 September 2016. The loan was extended to 31 December 2016.		
Notes payable to Texas Department of Housing and Community Affairs, at 0% interest, collateralized by real estate. \$162,000 is payable in monthly installments beginning 1 August 2014 until maturity 1 July 2044. \$161,000 is forgiven in annual increments of \$5,368, through maturity on 1 August 2043, provided GNDC is in compliance with all terms and conditions of the loan agreement.	283,082	62,886 292,161
Note payable to Austin Housing Finance, collateralized by real estate. The note bears a 0% interest rate until maturity and the principal and interest shall be forgiven in its entirety if on 31 December 2032, GNDC is in compliance with all terms and conditions of the Loan Agreement.	50,000	50,000
Note payable to Austin Housing Finance, collateralized by real estate. The note bears a 0% interest rate until maturity and the principal and interest shall be forgiven in its entirety if on 31 December 2114, GNDC is in compliance with all terms and conditions of the Loan Agreement.	2,000,000	2,000,000
Note payable to Frost, collateralized by real estate. The note bears a 4.75% interest rate, payable in monthly installments until 10 February 2027.	556,185	Ó
Note payable to Austin Housing Finance, uncollateralized. The note bears a 0% interest rate until maturity and the principal and interest shall be forgiven in its entirety if on 31 May 2021, GNDC is in compliance with all terms and conditions of the Loan		
Agreement.	893,868	<u>0</u>
	\$11,487,921	\$10,393,426

GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION

NOTES TO CONSOLIDATED FINANCIAL STATEMENTS

NOTE 13: **NOTES PAYABLE**

7. 15	4.4	
M/121	turities:	
TATA	unitios.	

2018	\$77,033
2019	82,400
2020	84,986
2020	87,699
2021	85,571
Thereafter	11,070,232
	\$11,487,921

GNDC has eight available loans totaling \$800,000, which bear interest at a rate of prime plus 0.25%, and are payable monthly until maturity 5 June 2018.

NOTE 14: MINORITY INTEREST LIABILITIES

	2017	2016
Saldana LLP interest in Guadalupe-Saldana Affordable	\$61,296	\$61,296
Jeremiah Program Austin, LLC interest in Guadalupe- Jeremiah LP	4,894,697	4,883,943
	\$4,955,993	\$4,945,239

NOTE 15: TEMPORARILY RESTRICTED NET ASSETS

	2017	2016
Feasibility study	\$40,678	\$100,000
Home ownership	15,400	15,400
Affordable housing	20,000	10,000
Other projects	<u>5,775</u>	<u>0</u>
	\$81,853	\$125,400

NOTE 16: FAIR VALUE DISCLOSURES

		Quoted Prices in Active Markets for Identical Assets	Significant Other Observable Inputs	Significant Unobservable Inputs
	Amount	(Level 1)	(Level 2)	(Level 3)
2017 discounted note receivable	\$102,365	N/A	\$102,365	N/A

Exhibit C

GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION

32 of 238

NOTES TO CONSOLIDATED FINANCIAL STATEMENTS

NOTE 16: FAIR VALUE DISCLOSURES

The discount on a long-term related party note receivable was valued by management based on market rates for similar organizations (see Note 12).

GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION 33 of 23

Exhibit C

SUPPLEMENTAL BALANCE SHEET

GUADALUPE JEREMIAH LP

31 DECEMBER 2017

ASSETS

CURRENT ASSETS

 Cash
 \$418,374

 Accounts receivable and other
 23,181

 441,555
 441,555

 RENTAL REAL ESTATE
 7,131,452

\$7,573,007

LIABILITIES AND PARTNERS' EQUITY

CURRENT LIABILITIES

Due to limited partner- Jeremiah Program Austin, LLC	\$267,720
Due to general partner- GNDC	100,000
Accrued liabilities	28,045
	395,765
PARTNERS' EQUITY	7,177,242
	\$7,573,007

GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION

SUPPLEMENTAL STATEMENT OF NET INCOME AND CHANGES IN PARTNERS' EQUITY

GUADALUPE JEREMIAH LP

YEAR ENDED 31 DECEMBER 2017

INCOME

Contributions and other	\$77,378
Rental income and other	28,097
	105,475
EXPENSES	
Depreciation	220,560
Utilities	33,830
Repairs and maintenance	29,403
Management fees	15,750
Insurance	14,024
Other	6,202
	319,769
NET INCOME/(LOSS)	(214,294)
BEGINNING PARTNERS' EQUITY, as previously reported	7,088,816
PRIOR PERIOD ADJUSTMENT-record partners' contributed capital	404,965
BEGINNING PARTNERS' EQUITY, restated	7,493,781
CAPITAL CONTRIBUTIONS- General partner- GNDC	111,066
CAPITAL CONTRIBUTIONS- Limited partner- Jeremiah Program Austin, LLC	1,787
CAPITAL DISTRIBUTIONS- Limited partner- Jeremiah Program Austin, LLC	(215,098)
ENDING PARTNERS' EQUITY	\$7,177,242



Montemayor Britton Bender PC

CERTIFIED PUBLIC ACCOUNTANTS

Board of Directors and Management Guadalupe Neighborhood Development Corporation

INDEPENDENT AUDITOR'S REPORT ON INTERNAL CONTROL OVER FINANCIAL REPORTING AND ON COMPLIANCE AND OTHER MATTERS BASED ON AN AUDIT OF FINANCIAL STATEMENTS PERFORMED IN ACCORDANCE WITH GOVERNMENT AUDITING STANDARDS

We have audited, in accordance with the auditing standards generally accepted in the United States of America and the standards applicable to financial audits contained in *Government Auditing Standards* issued by the Comptroller General of the United States, the consolidated financial statements of Guadalupe Neighborhood Development Corporation (GNDC) which comprise the consolidated statement of financial position as of 31 December 2017, and the related consolidated statements of activities and cash flows for the year then ended, and the related notes to the consolidated financial statements, and have issued our report thereon dated 15 May 2018.

Internal Control Over Financial Reporting

In planning and performing our audit of the consolidated financial statements, we considered GNDC's internal control over financial reporting (internal control) to determine the audit procedures that are appropriate in the circumstances for the purpose of expressing our opinion on the consolidated financial statements, but not for the purpose of expressing an opinion on the effectiveness of GNDC's internal control. Accordingly, we do not express an opinion of the effectiveness of GNDC's internal control.

A deficiency in internal control exists when the design or operation of a control does not allow management or employees, in the normal course of performing their assigned functions, to prevent, or detect and correct, misstatements on a timely basis. A material weakness is a deficiency, or combination of deficiencies, in internal control, such that there is a reasonable possibility that a material misstatement of the entity's financial statements will not be prevented, or detected and corrected on a timely basis. A significant deficiency is a deficiency, or a combination of deficiencies, in internal control that is less severe than a material weakness, yet important enough to merit attention by those charged with governance.



Our consideration of internal control was for the limited purpose described in the first paragraph of this section and was not designed to identify all deficiencies in internal control that might be material weaknesses or significant deficiencies. Given these limitations, during our audit we did not identify any deficiencies in internal control that we consider to be material weaknesses. However, material weaknesses may exist that have not been identified.

Compliance and Other Matters

As part of obtaining reasonable assurance about whether GNDC's consolidated financial statements are free from material misstatement, we performed tests of its compliance with certain provisions of laws, regulations, contracts, and grant agreements, noncompliance with which could have a direct and material effect on the determination of consolidated financial statement amounts. However, providing an opinion on compliance with those provisions was not an objective of our audit, and accordingly, we do not express such an opinion. The results of our tests disclosed no instances of noncompliance or other matters that are required to be reported under *Government Auditing Standards*.

Purpose of this Report

The purpose of this report is solely to describe the scope of our testing of internal control and compliance and the results of that testing, and not to provide an opinion on the effectiveness of the organization's internal control or on compliance. This report is an integral part of an audit performed in accordance with Government Auditing Standards in considering the organization's internal control and compliance. Accordingly, this communication is not suitable for any other purpose.

Montemaryn Britton Bender PC

15 May 2018 Austin, Texas



Montemayor Britton Bender PC

CERTIFIED PUBLIC ACCOUNTANTS

Board of Directors and Management Guadalupe Neighborhood Development Corporation

> INDEPENDENT AUDITOR'S REPORT ON COMPLIANCE FOR EACH MAJOR PROGRAM AND ON INTERNAL CONTROL OVER COMPLIANCE REQUIRED BY THE UNIFORM GUIDANCE

Report on Compliance for Each Major Federal Program

We have audited Guadalupe Neighborhood Development Corporation's (GNDC) compliance with the types of compliance requirements described in the *OMB Compliance Supplement* that could have a direct and material effect on each of GNDC's major federal programs for the year ended 31 December 2017. GNDC's major federal programs are identified in the summary of auditor's results section of the accompanying schedule of findings and questioned costs.

Management's Responsibility

Management is responsible for compliance with the requirements of federal statutes, regulations, and the terms and conditions applicable to its federal programs.

Auditor's Responsibility

Our responsibility is to express an opinion on compliance for each of GNDC's major federal programs based on our audit of the types of compliance requirements referred to above. We conducted our audit of compliance in accordance with auditing standards generally accepted in the United States of America; the standards applicable to financial audits contained in *Government Auditing Standards*, issued by the Comptroller General of the United States; and the audit requirements of Title 2 U.S. *Code of Federal Regulations* Part 200, *Uniform Administrative Requirements, Cost Principles, and Audit Requirements for Federal Awards* (Uniform Guidance). Those standards and Uniform Guidance require that we plan and perform the audit to obtain reasonable assurance about whether noncompliance with the types of compliance requirements referred to above that could have a direct and material effect on a major federal program occurred. An audit includes examining, on a test basis, evidence about GNDC's compliance with those requirements and performing such other procedures as we considered necessary in the circumstances.

We believe our audit provides a reasonable basis for our opinion on compliance for each major federal program. However, our audit does not provide a legal determination of GNDC's compliance.

2525 WALLINGWOOD DRIVE BUILDING 1, SUITE 200 AUSTIN, TEXAS 78746 PHONE: 512.442.0380 FAX: 512.442.0817 www.montemayor.team



Opinion on Each Major Federal Program

In our opinion, GNDC complied, in all material respects, with the types of compliance requirements referred to above that could have a direct and material effect on each of its major federal programs for the year ended 31 December 2017.

Report on Internal Control Over Compliance

Management of GNDC is responsible for establishing and maintaining effective internal control over compliance with the types of compliance requirements referred to above. In planning and performing our audit of compliance, we considered GNDC's internal control over compliance with the types of requirements that could have a direct and material effect on each major federal program to determine the auditing procedures that are appropriate in the circumstances for the purpose of expressing an opinion on compliance for each major federal program and to test and report on internal control over compliance in accordance with Uniform Guidance, but not for the purpose of expressing an opinion on the effectiveness of internal control over compliance. Accordingly, we do not express an opinion on the effectiveness of GNDC's internal control over compliance.

A deficiency in internal control over compliance exists when the design or operation of a control over compliance does not allow management or employees, in the normal course of performing their assigned functions, to prevent, or detect and correct, noncompliance with a type of compliance requirement of a federal program on a timely basis. A material weakness in internal control over compliance is a deficiency, or combination of deficiencies, in internal control over compliance, such that there is a reasonable possibility that material noncompliance with a type of compliance requirement of a federal program will not be prevented, or detected and corrected, on a timely basis. A significant deficiency in internal control over compliance is a deficiency, or a combination of deficiencies, in internal control over compliance with a type of compliance requirement of a federal program that is less severe than a material weakness in internal control over compliance, yet important enough to merit attention by those charged with governance.

Our consideration of the internal control over compliance was for the limited purpose described in the first paragraph of this section and was not designed to identify all deficiencies in internal control over compliance that might be material weaknesses or significant deficiencies. We did not identify any deficiencies in internal control over compliance that we consider to be material weaknesses. However, material weaknesses may exist that have not been identified.

The purpose of this report on internal control over compliance is solely to describe the scope of our testing of internal control over compliance and the results of the testing based on the requirements of Uniform Guidance. Accordingly, this report is not suitable for any other purpose.

Montemage Britton Bender PC

15 May 2018 Austin, Texas

GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION SCHEDULE OF EXPENDITURES OF FEDERAL AWARDS

YEAR ENDED 31 DECEMBER 2017

			Total	
			Expenses	
Loan	Balance at	beginning	of year	
	Original	Loan	Amount	
	Agency or	Pass-through	Number	
	Federal	CFDA	Number	
	Federal Grantor/	Pass-through Grantor/	Program Title	

U.S. Department of Housing & Urban Development:

HUD Section 8- Rental Assistance Passed Through the Austin Housing Finance Corporation:	14.195			N/A	\$110,907	\$110,907
Community Housing Development Organization	14.218		\$1,550,000 1,396,154	1,396,154		1,396,154
Home Investment Partnerships Program Home Investment Partnerships Program	14.239	GNDC 5-LaVista 2,138,239 GNDC 6 395,000	2,138,239	2,138,239		2,138,239
Home Investment Partnerships Program	14.239	728LN000202-A	100,000	25,000		25,000
Home Investment Partnerships Program	14.239	728EX000308	22,750	22,750		22,750
Home Investment Partnerships Program	14.239	SOL RENTAL	200,000	200,000		200,000
Home Investment Partnerships Program	14.239		946,610	0	893,868	893,868
				3,630,989		4,524,857
Passed Through Texas Department of Housing and Community Affairs Neighborhood Stabilization						
Program	14.239		323,000	293,850		293,850
			\$6,525,599	\$6,525,599 \$5,320,993	\$1,004,775 \$6,325,768	\$6,325,768

This schedule is prepared on the same basis of accounting as described in the notes to the financial statements on pages 7 through 16. See Note 13 for ending loan balances. GNDC did not elect to use the 10% de minimis indirect cost rate.

GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION

SCHEDULE OF FINDINGS AND QUESTIONED COSTS

FOR THE YEAR ENDED 31 DECEMBER 2017

I. SUMMARY OF AUDITOR'S RESULTS

A. FINANCIAL STATEMENTS

1. Type of auditor's report issued:

Unmodified

- 2. Internal control over financial reporting:
 - a. Material weakness (es) identified?

No

b. Significant deficiency(ies) identified that are not considered material weaknesses?

None noted

c. Noncompliance material to financial statements?

None

B. FEDERAL AWARDS

- 1. Internal controls over major programs:
 - a. Material weakness(es) identified?

No

b. Significant deficiency(s) identified that are not considered material weakness(es)?

None noted

2. Type of auditor's report issued on compliance with major programs:

Unmodified

3. Any audit findings disclosed that are required to be reported in accordance with 2 CFR Section 200.516(a)?

No

4. Major program: Home Investment Partnerships Program

CFDA #14.239

5. Dollar threshold used to distinguish between Type A and Type B programs:

\$750,000

6. Auditee qualified as a low-risk auditee?

Yes

II. FINANCIAL STATEMENT FINDINGS

- A. Current year none
- B. Prior year none

III. FEDERAL AWARD FINDINGS AND QUESTIONED COSTS

None noted.



Montemayor Britton Bender PC

CERTIFIED PUBLIC ACCOUNTANTS

Board of Directors and Management Guadalupe Neighborhood Development Corporation

INDEPENDENT AUDITOR'S REPORT ON COMPLIANCE WITH REQUIREMENTS OF THE TEXAS PROPERTY TAX CODE

We have audited the compliance of Guadalupe Neighborhood Development Corporation (GNDC) with types of compliance requirements described in Sections 11.182 and 11.1825 of the Texas Property Tax Code, Organizations Constructing or Rehabilitating Low-Income Housing: Property Not Previously Exempt, for the year ended 31 December 2017. Compliance with the requirements of the Texas Property Tax Code is the responsibility of GNDC's management. Our responsibility is to express an opinion on GNDC's compliance based on our audit.

We conducted our audit of compliance in accordance with auditing standards generally accepted in the United States of America. Those standards require that we plan and perform the audit to obtain reasonable assurance about whether noncompliance with the types of compliance requirements referred to above occurred. An audit includes examining, on a test basis, evidence about GNDC's compliance with those requirements and performing such other procedures as we considered necessary in the circumstances. We believe that our audit provides a reasonable basis for our opinion. Our audit does not provide a legal determination on GNDC's compliance with those requirements.

In our opinion, GNDC complied, in all material respects, with the requirements referred to above for the year ended 31 December 2017.

This report is intended for the information of the Board of Directors, management, others within the organization and state or federal agencies and is not intended to be and should not be used by anyone other than these specified parties.

. Britton Bender PC

15 May 2018 Austin, Texas

> 2525 WALLINGWOOD DRIVE BUILDING 1, SUITE 200 AUSTIN, TEXAS 78746 PHONE: 512.442.0380 FAX: 512.442.0817 www.montemayor.team

GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION 42 of 238

SUPPLEMENTAL SCHEDULE OF COMMUNITY LAND TRUST SOURCES AND USES YEAR ENDED 31 DECEMBER 2017

Sources of funds:

GNDC funds Father Joe Znotas Phase II	\$30,878
AHFC loan Father Joe Znotas Phase II	604,902
Horizon loans Father Joe Znotas Phase II (available to borrow)	533,026
1313 Willow mortgage principal	5,100
1313 Willow property tax & insurance escrow	2,940
1313 Willow maintenance escrow	1,440
1313 ground lease fee	300
807 Waller ground lease fee	300
3005 FJZontas ground lease fee	300
3001 FJZontas ground lease fee	300
3000 FJZontas ground lease fee	300
3004 FJZontas ground lease fee	300
	\$1,180,086
Uses of funds:	
Father Joe Znotas Phase II	\$1,168,806
1313 Willow principal reduction	5,100
GNDC ground lease income	1,800
1313 Willow property taxes	1,898
1313 Willow escrow refund	394
1313 Willow insurance	1,243
1313 Willow escrow deposit	560
1313 Willow maintenance escrow expense	285
	\$1,180,086
	V

RESOLUTION OF THE GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION TO SUBMIT AN APPLICATION TO THE AUSTIN HOUSING FINANCE CORPORATION FOR FUNDING

WHEREAS, the undersigned Officers of the Guadalupe Neighborhood Development Corporation (the "Corporation"), a Texas non-profit corporation, do hereby take the actions set forth below:

WHEREAS, the Corporation desires to undertake an affordable housing project in the Corporation's service area with up to 10 single-family units for home ownership for households with low to moderate incomes, and

WHEREAS, the Corporation already has financed design work and identified potential buyers for such a project, being a part of the Guadalupe-Saldana Net-Zero Subdivision, and called Father Joe Znotas Street Phase IV, but needs additional funding to complete construction of the project, therefore

BE IT RESOLVED THAT, for the purpose of securing construction related financing, at a meeting of the Board of Directors held on January 28, 2019, the Board of Directors hereby does authorize the Executive Director, on behalf of the Corporation, to submit an application to the Austin Housing Finance Corporation, in an amount not to exceed \$2,000,000.

THEREFORE, BE IT FURTHER RESOLVED, that the President, or Vice President, or Executive Director, and all other officers of the Corporation are hereby authorized and directed, to execute, attest, and deliver any and all applications, contracts, documents, certificates, instruments and writings necessary to secure said financing, and to take all other actions, as may be necessary or appropriate;

IN WITNESS WHEREOF, this Resolution is made this 28th day of January, 2019

MARQ

. President

Vice President

Secretary

, Treasurer

I, Jesse Hernandez, Secretary of the Guadalupe Neighborhood Development Corporation, do hereby certify the foregoing is a true and complete copy of the construction loan resolution of this organization as adopted by the Board of Directors on the 28th day of January, 2019.

Jesse Hernandez, Secretary

Exhibit D



GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION RESUME



GUADALUPE NEIGHBORHOOD DEVELOPMENT CORPORATION

The Guadalupe Neighborhood Development Corporation (GNDC) dedicates its resources to the development of high quality affordable housing for very low to moderate income persons. We work for the improvement, revitalization and preservation of the residential neighborhoods within our East Austin service area. GNDC is committed to respect the people it serves and is dedicated to improve the quality of life in the neighborhoods where it works. GNDC gives the highest priority to families with generational ties to the Guadalupe target neighborhoods.

BUILDINGS/PROPERTIES

For over 35 years, GNDC has been developing and managing high quality, affordable rental and ownership properties in East Austin. It currently owns and manages fifty-nine single-family properties, two multi-family family properties and operates six community land trust properties.

Under Construction, opening in 2017:

Jeremiah Program Moody Campus: 35 units of transition housing for single parent with preschool age children at 1200 Paul Teresa Saldana Street in the Guadalupe-Saldana Net-Zero Subdivision. In partnership with Jeremiah Program Austin, this development will provide highly affordable apartments, a fully licensed child development center and life-skills training and educational support in order to move families out of poverty two generations at a time.





GNDC COMMUNITY LAND TRUST:

GNDC built and sold the first Community land Trust home in Texas in 2012 and brought the first CLT mortgage to Texas in 2014. Currently GNDC operates 6 CLT properties and has 24 planned for 2017-18. AIA Austin 2014 Community Vision Award winner.





Home owner Mary Ybarra and family at 1313 Willow Street, the first community land trust home in Texas





In 2014, GNDC's CLT program enabled the Hernandez Family, Jesse, Becky and their three sons, to purchase 807 Waller Street, which had a market value of \$565,000, for \$85,000. This was the first community land trust home in Texas to be purchased with a private mortgage.






AISD teachers, Robert Aleman and Katie Heuer, with their daughter Evelyn on the porch their newly renovated CLT home that GNDC relocated from the Rainey Street National Register District in downtown Austin to the Guadalupe-Saldana Net-Zero Subdivision.

GUADALUPE-SALDANA NET-ZERO SUBDIVISION:

125 units of "super-green homes are planned. GNDC's subdivision merges sustainable design and supportive social services with affordable rental and homeownership homes. The Enterprise Green Community certified development is transforming a former "brownfield" into one of the "greenest" developments in Austin. The subdivision is made possible through the support from the Austin Housing Finance Corporation, Texas Department of Housing and Community Affairs, Austin Energy, the Austin Brownfield Revitalization Office, Enterprise Community Partners, Kresge Foundation, Cynthia and George Mitchell Foundation, Wells Fargo Bank, Bank of America, BBVA Compass and Shelter with Spirit. Envision Central Texas Community Stewardship Award: Innovation Winner 2011.









TOWNHOMES DESIGNED BY NELSEN PARTNERS FOR THE GUADALUPE-SALDANA NET-ZERO SUBDIVISION

LA VISTA DE GUADALUPE:





22 units of family housing opened in 2008. This Tax Credit development, prominently located on a hill overlooking downtown Austin, provides extremely affordable rents ranging from between \$330 per month for a one-bedroom unit to \$850 per month for a three-bedroom two-bath unit. One-bedroom market-rate units just one block away rent for over \$1,400 per month.

THE ALLEY FLAT INITIATIVE

GNDC began building secondary apartments—also called alley flats, granny flats and ADUs in 1999, even before Austin's land development code was changed to add this building type. In 2005 GNDC, the University of Texas Center for Sustainable Development, and the Austin Community Design and Development Center joined to form The Alley Flat Initiative. GNDC has developed nine alley homes and has four more planned in 2017. 2009 Envision Central Texas Community Stewardship Award Winner: Redevelopment.

Exhibit D 50 of 238



Rebecca Castillo and Daughter on the porch of the alley flat they rent from GNDC.





904-B Lydia Street is an alley flat designed and partially constructed by University of Texas architecture students. Margaret Renteria, grandmother of a tenant living in the main house, was the first tenant, making this a true Granny Flat.

HATCH + ULLAND OWEN ARCHITECTS

COMPANY HISTORY + EXECUTIVE SUMMARY






About Us - hatch + ulland owen architects (h+uo) is an Austin, Texas based architectural firm focused on creating visionary, sustainable and socially-responsible design. The firm was founded in 1978 by Tom Hatch, FAIA, with a commitment to help build strong, vibrant communities. It has evolved over several decades from its sole-proprietorship beginnings to its current partnership structure when, in 2006, Erik Ulland and Randall Owen joined him as partners. Our keen sense of community values has inspired a wide range of distinctive projects including, numerous multi-family communities for neighborhood non-profits, Foundation Communities, and market rate developers. Some noteworthy projects: 65 Whole Foods Markets across the country, including the original WFM Corporate Headquarters at 6th and Lamar; The Crossings (now Travaasa Experiential Resort and Spa); Threadgill's; Thundercloud Subs; Twin Oaks Library; Oak Point Park in Plano; McKinney Roughs Nature Park; a variety of Mueller Homes; numerous single-family residences; as well as farm worker housing in the valley and in the panhandle.



A dynamic design studio featuring a wealth of architectural expertise, h+uo prides itself on interpreting our clients' visions and delivering high quality, contextually responsive design in the Multi-family residential, Hospitality, Retail, Office, Community / Civic, Education, and Single-family residential markets. The culture of the firm, our reputation in Austin, throughout Texas and around the country, as well as the growing list of satisfied and repeat clients continues to thrive.





People Places - No matter what the project (whether park projects, public institutions, affordable housing or retail establishments), we believe that one of architecture's greatest contributions is to create places where people feel comfortable both alone and together, and where people can be enriched by interaction with each other. To that end, a common thread running through all of our work is the creation of "people places" that nurture the human spirit and respect the environment.



 Civic Involvement - Members of our firm currently serve or have in the past served on numerous boards and commissions, including the City of Austin Building and Standards Commission, Downtown Austin Alliance, Austin Energy Green Building Program, House the Homeless Task Force, and Meals on Wheels. Texas Low Income Housing Information Service, Housing Texas, Housing Works, Sharir Dance Company, Austin Woman's Club Advisory, and the Board of Planned Parenthood.



- Crossing Social and Economic Boundaries We believe that architecture and sound planning should be available to all people, so we have intentionally reached across social, cultural, and economic boundaries to seek out opportunities where our talents may be of use to all parts of our community. As part of that effort, as we have noted, we have completed numerous successful affordable housing projects in Austin and beyond, most notably M Station, one the few LEED Platinum certified affordable housing developments in the country, as well as many civic projects including libraries, schools, and parks.
- Our ongoing and past projects with the City of Austin have substantiated our commitment to civic responsibility. Further, we received a perfect score on the Consultant Performance Evaluation Form for a number of our recently completed projects.

COMPANY HISTORY + EXECUTIVE BACKGROUND (continued)



<u>Client Service</u> - Any architectural project involves a fine balance between the client's program, the opportunities and constraints of the site, available funding, building technologies, and greater societal interests. Achieving that balance and synthesizing the many interests is the essence of good client and environmental service. We pride ourselves on being good listeners and on being responsive and agile team players.



<u>Sustainable Design and Construction</u> – h+uo architects has long engaged in sustainable building, even before that practice became mainstream. It has always been part of the firm's philosophy that the act of building should be undertaken responsibly — both with respect to other humans and the natural environment. We bring to every project our commitment and expertise in sustainable design. We were the architects for Austin's first large scale, commercial "green" building (Whole Foods Market's previous store and headquarters at 6th and Lamar) and we have subsequently designed 64 other Whole Foods Markets and numerous other commercial green projects:



The new Foundation Communities' Michael and Susan Dell Foundation Learning Center at Lakeline Station was designed to meet the stringent criteria of The Living Building Challenge petal certification, which is a rating system that requires building to make positive contributions to the environment as opposed to minimizing the damage, per LEED. The Learning Center is the first non-industrial "net zero" commercial building in Austin, ultimately producing more energy than it consumes. It was the Austin Green Awards Project of the Year (2017).




Foundation Communities' M Station in East Austin, an affordable housing community and learning center achieved the highest scoring LEED Platinum rating in the country which was the first such accreditation for multifamily housing in the U.S. at that time. It also achieved Austin Energy 5 Star Certification, won the 2012 Austin Business Journal Social Impact Award, and won the 2012 Envision Central Texas Community Stewardship Award for New Development.



Foundation Communities' Homestead Oaks achieved Austin Energy Green Building 4-Star Rating in 2016. It is also seeking LEED Gold certification, currently pending.





- All of the buildings at LCRA's McKinney Roughs Environmental Learning Center, including an administrative building, a classroom building, a dining hall, and three dormitories.
- Morris Williams Golf Pro Shop and Cart Barn LEED Silver rated.
- American YouthWorks downtown facility as well as their LEED certified Green Collar Training Facility in southeast Austin.



We are firm believers in following an "integrated" design approach, where the various members of the design team and the client work parallel with each other in a coordinated fashion from the very beginning, rather than sequentially in an autonomous fashion.

RECENT RESIDENTIAL DESIGN PROJECTS

JEREMIAH PROGRAM

Austin, Texas Size: 49,865 SF

Budget: \$6 Million

Scope: Architectural / Engineer-

ing services.

Description: The Jeremiah Program Moody Campus includes 35 two-bedroom apartments, an on-site accredited five-classroom child development center for up to 60 children, two covered playground areas, empowerment and life skills classrooms, gathering spaces, and staff offices. The unique complex is a safe home for mothers and their children who have escaped abusive situations.





Client Reference:
Mark Rogers
Guadalupe Neighborhood
Develoment Corporation
813 E. 8th Street
Austin, Texas 78702

phone: 512.479.6275, ext. 3

Exhibit D 54 of 238

RECENT RESIDENTIAL DESIGN PROJECTS

LAKELINE STATION APART-MENTS & LEARNING CENTER

Austin, Texas

Size (Apartments): 122,824 SF Size (Learning Center): 6,874 SF

Budget: \$20 Million

Scope: Architectural / Engineering and Living Building Challenge.

Description: The Lakeline Station Learning Center is an activity and learning hub in the center of 128 affordable housing apartments. The Learning Center provides after school and summer education for children as well as exercise classes, tax preparation, and jobs training for adults.

This important project is at the top of its class in regards to sustainability. It was carefully designed to meet the rigorous green standards of the Living Building Challenge Petal Certification, a rating system which requires that a building be fully self-supporting for its energy production and contains no toxic materials. When complete the Lakeline Station Learning Center will be a beautiful, healthy, light-filled space for learning that will also grow its own food. It will be one of only a handful of Living Building Challenge Petal certified projects in the state of Texas.

Austin Green Building Project of the Year Award, 2017.

Client Reference: Walter Moreau Foundation Communities 3036 S. 1st Street, Ste. 200 Austin, TX 78704

phone: 512.447.2026









Exhibit D 55 of 238

RECENT RESIDENTIAL DESIGN PROJECTS

THE CHICON

Austin, Texas

Size: SE Bldg: 14,516 SF Size: SW Bldg: 16,311 SF

Budget: \$8 Million

Scope: Architectural / Engi-

neering services.

Description: A three-building multi-family, mixed-use development in East Austin aimed to preserve and support the history, legacy and culture of the Chestnut Neighborhood. The development offers residential units (both affordable and market rate condominiums) atop ground level retail, restaurant and office spaces.

The Chicon is currently under construction and on track to be complete Spring 2018.

Client Reference:
Sarah Andre
Chestnut Neighborhood
Revitalization Corporation
702 Rio Grande
Austin, TX 78701
phone: 512.689.3369







RECENT RESIDENTIAL DESIGN PROJECTS

NET ZERO HOMES

Austin, Texas

Size: 1,200 - 1,600 SF Homes

Budget: \$1 Million

Scope: Architectural / Engi-

neering services.

Description: The Guadalupe Neighborhood Development Corporation received funding to buy a sizable piece of land just off Tillery Street in East Austin. Their latest project on the land includes one and one, two, and three bedroom homes that are designed to be net zero in energy consumption. AHFH is building some of the homes along side of our designs built by Saldana Homes. The land is held in trust by GNDC and the homes are currently being sold at a very low point. Their property taxes reflect the low sales price. The new small very affordable subdivision is a jewel in East Austin.

Client Reference:
Mark Rogers
Guadalupe Neighborhood
Develoment Corporation
813 E. 8th Street
Austin, Texas 78702

phone: 512.479.6275, ext. 3







RECENT RESIDENTIAL DESIGN PROJECTS

CARDINAL POINT APART-MENTS & LEARNING CENTER

Austin, Texas

Size (Apartments): 117,168 SF Size (Learning Center): 5,200 SF

Budget: \$16 Million

Scope: Architectural / Engi-

neering.

Description: Multi-family community for Foundation Communities at Four Points in Northwest Austin. The affordable and environmentally friendly community includes a total of 5 three-story apartment buildings with a total of 120 units, a 2,300 SF leasing office, and a 5,200 SF learning center. Other amenities on site include a community playground, sport court, and covered bike shelter. A challenging 8.5 acre site required coordination with all consultants to incorporate Heritage trees, sufficient site drainage, a raingarden, and previously undiscovered caves. The project was completed with the Texas Department of Housing and Community Affairs (TDHCA) tax credit program. It began leasing units in early 2018.

Client Reference: Walter Moreau Foundation Communities 3036 S. 1st Street, Ste. 200 Austin, TX 78704

phone: 512.447.2026







RESUME: PROJECT PRINCIPAL

Thomas H. Hatch, FAIA

EDUCATION

Bachelor of Architecture (with Honors) Texas Tech University, 1969

REGISTRATION

Texas #5485 (1975)

EXPERIENCE

hatch + ulland owen architects (formerly Hatch Partnership) Austin, Texas (Jan. 1997 - Present)

Tom Hatch Architects

Austin, Texas (March 1978 - December 1996)

3-D International

Austin, Texas (1977 - 1978)

Independent Architects


Austin, Texas (1973 - 1977)

U.S. Coast Guard


Yorktown, Virginia, (1969 - 1971)



SAMPLE PROJECTS



A new affordable housing development for Foundation Communities with an onsite Learning Center. The Michael and Susan Dell Foundation Learning Center is pending Petal Certification for the Living Building Challenge.



A new affordable housing community for Foundation Communities with an onsite Learning Center. Like Lakeline Station, Cardinal Point is located in Northwest Austin where heretofore, there have been no affordable housing developments. Currently under construction.

Homestead Oaks • Austin, Texas

A Foundation Communities 140-unit affordable housing community with an onsite Learning Center. This is the first multi-family rental apartments in the City of Austin to pursue 134.16kW solar tied directly to residential units. THe apartments also feature 18 - 10,000 gallon rainwater collection cisterns used for irrigation. *Recipient of the Austin Energy Green Building Award Four-Star Rating*.



A 150-unit eco-friendly affordable housing development for Foundation Communities with an on-site learning center. M Station is the first LEED for Homes multi-family project in Austin and the first multi-family LEED for Homes Platinum community in Texas. *Recipient of the Austin Business Journal's Social Impact Award.*

Jeremiah Program Moody Campus • Austin, Texas

New 49,865 sf building that includes 35 two-bedroom apartments, an on-site accredited five-classroom child development center, two covered playground areas, empowerment and life skills classrooms, gathering spaces, and staff offices.

La Vista de Guadalupe • Austin, Texas

A 22-unit downtown affordable housing project for the Guadalupe Neighborhood serving our very low income working community.

Lyons Gardens • Austin, Texas

54-unit elder housing community of Family Eldercare in East Austin.

The Chicon • Austin, Texas

A three-building multi-family mixed-use development in East Austin under construction. It was commissioned by neighborhood members as a revitalization effort for the Chicon Street corridor, and will include affordable housing units, market-rate condominiums, and ground floor retail space.

Pease Mansion • Austin, Texas

Complete restoration of the Abner Cook Governor's Mansion in Pemberton Heights.

Various New and Rehabilited Homes • East Austin, Texas

Numerous new construction and revitalization of homes for AHFC and the Guadalupe Neighborhood Housing Corporation.







GreenEarth Engineering, Inc.

Consulting Structural Engineers Resume: **Tim (Zhigang) Zhang**

Title: Principal Engineer

Education: The University of Texas at Austin, MS, 1997, Civil Engineering

Qingdao Institute of Architecture & Engineering, BS, 1993, CE

Registration: Professional Engineer in the State of Texas, No. 88698

Professional US Green Building Council LEED Accredited Professional

Affiliation: City of Austin Green Building Program - Member

American Institute of Steel Construction - Member

Experience:

July 2004 to Present, Principal Engineer, GreenEarth Engineering. Inc.

Hill Ranch Apartments
 San Marcos, Texas
 96-unit apartments and Water Quality Ponds, site retaining walls.

 Seton Southwest Labor & Delivery Addition Austin, Texas
 9,000 SF, \$4.0 Million Two-story addition

Manchaca Fire Station #5
 Manchaca, Texas
 12,000 SF, \$1.8 Million Single-story fire station & office building

Esplanade Rehabilitation Hospital
 Corpus Christi, Texas
 30,000 SF, \$5.5 Million Single-story hospital – steel structure

Hays County RPTP Facility

— Office Building Addition

Hays County, Texas

15,000 SF, \$2.2 Million Single-story office building addition

 Refugio County Memorial Hospital – Physical Therapy & Wellness Center Addition
 Refugio, Texas
 Two single-story buildings with a combined gross area of 9,200 S.F.

Two single-story buildings with a combined gross area of 9,200 S.F. Completed

• Parsons House – 27,000 S.F. Assisted Living Community La Porte, Texas

Resume: Tim (Zhigang) Zhang

GreenEarth Engineering, Inc.

Consulting Structural Engineers

Single-story wood framing structure

- Meridell Achievement Center
 Single-story, 10,000 S.F. medical treatment center
- Seally Urgent Care Center Single-story, 8,000 S.F. Medical Office Building
- Buda Alzheimer's Home Two single-story, 8,500 S.F. Assisted Living Buildings
- Waterscape Villas Condo. Jonestown, Texas 6-story, 90-unit condominium, 75,000 S.F.
- Casa Trinidad, Lake Travis, Texas
 22,000 Square Feet single-family home
- Swanee 21 Apartments, Austin, Texas 3-story, 21 Unit apartment building
- Central United Methodist Church Childcare Center --- single-story, 23,000 square feet steel structure
- Lavaca Medical Center 10,000 S.F. steel structure
- Upland 2&3 Retail Center --- single story, 26,000 square steel structure
- Treaty Oak Bank 2-story, 10,000 S.F. steel office building
- Katherine Ann Porter School 32,000 S.F. school building expansion, renovation.
- Don Dario' Restaurant 5,000 S.F. restaurant with ICFS wall system.
- Potter Dental Clinic 4,500 S.F. wood framing dental clinic

Exhibit E 61 of 238

YOLANDA ALEMÁN-LIMÓN

EXPERIENCE: Property Manager

October 1, 2003 - Present

Guadalupe Neighborhood Development Corporation

- Receive all correspondence in person, telephone, mail, e-mail and fax
- Receive and record receipts for rental payments for 71 GNDC properties and La Vista de Guadalupe apartment complex
- Receive and receipt payments for 3 mortgage properties.
- Prepare and issue payments for all bills, including taxes, insurance premiums, maintenance and repair of properties, following the established procurement policies.
- Files kept in appropriate settings and locations to accommodate access by authorized Board, Staff, Auditors, Funding Providers, and Investors.
- Collect necessary income information from applicants and from new and existing tenants to determine eligibility for certification or re-certification in various programs.
- Oversee compliance with Federal, State and City guidelines and regulations in accordance to Low-Income Housing Tax Credit; HOME and RHDA programs.
- Prepare new and renewal leases.
- Manage move-out and move-in process.
- Prepare and deliver notices for late rent, late mortgage, lease violations and eviction.

Senior Patient Account Representative City of Austin, Health and Human Services

February 1993 - September, 2009

- Insured Billing and Collection of all first, second and third party billing.
- Verified insurance data from Medicaid Software for accuracy and completeness.
- Managed appeals for Medicaid, Medicare and HMO's in a timely manner
- Managed patient accounts to verify insurance or guarantor payer paid for services rendered.
- Contacted appropriate clinic sites by e-mail, fax or phone
- Managed itemized billing statements for Law Firms and other professional agencies.
- Collected and applied fees for the itemized statements.
- Directed 6 co-workers, served as Acting-Supervisor when needed.

Senior Administrative Clerk

October 1985 - February 1993

City of Austin, Woman and Children (WIC) Program

- Interviewed clients to ensure eligibility for State and City guidelines.
- Explained program to clients and issued WIC coupons.
- Translated for Spanish-speaking clients.
- Maintained and documented weekly inventory of coupons.
- Prepared reports for State and Federal agency departments.

EDUCATION: G.E.D Austin Community College, Austin, Texas

1985

SKILLS: Bilingual in Spanish, Proficient in Microsoft Word, bookkeeping, and accounting



Mark Rodgers
Executive Director
Guadalupe Neighborhood
Development Corporation
813 E. 8th Street
Austin, TX 78702

Re.:

2015 Rental Housing Development Assistance (RHDA) Monitoring

904-B Lydia, Austin, TX 78702

Dear Mr. Rodgers:

On June 27, 2016, Neighborhood Housing and Community Development (NHCD) conducted an on-site review of records for the above referenced location(s) and a physical inspection of selected units. The purpose of the monitoring was to ensure compliance with local and federal regulatory requirements set forth in your RHDA loan agreement with the Austin Housing Finance Corporation (AHFC).

I am pleased to inform you that Guadalupe Neighborhood Development Corporation has cleared all deficiencies and is now compliant with the terms of the loan agreement.

If you have any questions or need additional information, please contact me at 512-974-3110 or Susan.Kinel@austintexas.gov.

Regards,

Susan Kinel

Sr. Contract Compliance Specialist

Neighborhood Housing and Community Development

Attachment: Physical Inspection Report

XC: Yolanda Alemon-Limon, Property Manager, GNDC

Joseph A. Martinez, President, GNDC Board of Directors



Mark Rodgers
Executive Director
Guadalupe Neighborhood
Development Corporation
813 E. 8th Street
Austin, TX 78702

Re.:

2015 Rental Housing Development Assistance (RHDA) Monitoring 5908 Ventus, 5921 Ventus, 5916 Lux, 5929 Lux, 1129 A&B Altum

and 1133 A&B Altum

Dear Mr. Rodgers:

On June 27, 2016, Neighborhood Housing and Community Development (NHCD) conducted an on-site review of records for the above referenced location(s) and a physical inspection of selected units. The purpose of the monitoring was to ensure compliance with local and federal regulatory requirements set forth in your RHDA loan agreement with the Austin Housing Finance Corporation (AHFC).

I am pleased to inform you that Guadalupe Neighborhood Development Corporation has cleared all deficiencies and is now compliant with the terms of the loan agreement.

If you have any questions or need additional information, please contact me at 512-974-3110 or Susan.Kinel@austintexas.gov.

Regards,

Susan Kinel

Sr. Contract Compliance Specialist

Neighborhood Housing and Community Development

Attachment: Physical Inspection Report

XC: Yolanda Alemon-Limon, Property Manager, GNDC

Joseph A. Martinez, President, GNDC Board of Directors



Mark Rodgers
Executive Director
Guadalupe Neighborhood
Development Corporation
813 E. 8th Street
Austin, TX 78702

Re.:

2015 Rental Housing Development Assistance (RHDA) Monitoring

110 Chicon, Units A & B, Austin, TX 78702

Dear Mr. Rodgers:

On June 27, 2016, Neighborhood Housing and Community Development (NHCD) conducted an on-site review of records for the above referenced location(s) and a physical inspection of selected units. The purpose of the monitoring was to ensure compliance with local and federal regulatory requirements set forth in your RHDA loan agreement with the Austin Housing Finance Corporation (AHFC).

I am pleased to inform you that Guadalupe Neighborhood Development Corporation has cleared all deficiencies and is now compliant with the terms of the loan agreement.

If you have any questions or need additional information, please contact me at 512-974-3110 or Susan.Kinel@austintexas.gov.

Regards,

Susan Kinel

Sr. Contract Compliance Specialist

Neighborhood Housing and Community Development

Attachment: Physical Inspection Report

XC: Yolanda Alemon-Limon, Property Manager, GNDC

Joseph A. Martinez, President, GNDC Board of Directors



Mark Rodgers
Executive Director
Guadalupe Neighborhood
Development Corporation
813 E. 8th Street
Austin, TX 78702

Re.:

2015 Rental Housing Development Assistance (RHDA) Monitoring La Vista de Guadalupe Apts., 813 E. 8th Street, Austin, TX 78702

Dear Mr. Rodgers:

On June 27, 2016, Neighborhood Housing and Community Development (NHCD) conducted an on-site review of records for the above referenced location(s) and a physical inspection of selected units. The purpose of the monitoring was to ensure compliance with local and federal regulatory requirements set forth in your RHDA loan agreement with the Austin Housing Finance Corporation (AHFC).

I am pleased to inform you that Guadalupe Neighborhood Development Corporation has cleared all deficiencies and is now compliant with the terms of the loan agreement.

If you have any questions or need additional information, please contact me at 512-974-3110 or Susan.Kinel@austintexas.gov.

Regards,

Susan Kinel

Sr. Contract Compliance Specialist

Neighborhood Housing and Community Development

Attachment: Physical Inspection Report

XC: Yolanda Alemon-Limon, Property Manager, GNDC

Joseph A. Martinez, President, GNDC Board of Directors



Mark Rodgers
Executive Director
Guadalupe Neighborhood
Development Corporation
813 E. 8th Street
Austin, TX 78702

Re.:

2015 Rental Housing Development Assistance (RHDA) Monitoring

809-B San Marcos St., 907-B Spence St., 1009-B E. 10th St., 2320 Santa Rita St., 303 San Saba St., and 1002 Wheeless

Dear Mr. Rodgers:

On June 27, 2016, Neighborhood Housing and Community Development (NHCD) conducted an on-site review of records for the above referenced location(s) and a physical inspection of selected units. The purpose of the monitoring was to ensure compliance with local and federal regulatory requirements set forth in your RHDA loan agreement with the Austin Housing Finance Corporation (AHFC).

I am pleased to inform you that Guadalupe Neighborhood Development Corporation has cleared all deficiencies and is now compliant with the terms of the Ioan agreement.

If you have any questions or need additional information, please contact me at 512-974-3110 or Susan.Kinel@austintexas.gov.

Regards,

Susan Kinel

Sr. Contract Compliance Specialist

Neighborhood Housing and Community Development

Attachment: Physical Inspection Report

XC: Yolanda Alemon-Limon, Property Manager, GNDC

Joseph A. Martinez, President, GNDC Board of Directors

211 Inks Avenue- Monitoring Closed

Inbox

Jenny DeSilva <jennyd@shccnet.org>

Nov 27, 2018, 11:04 AM

to me

Good Morning Yolanda:

Let me apologize for this belated response to your June 7, 2018 email regarding the Developer Monitoring audit I performed on your two affordable units on Inks Avenue. I wanted you to have a formal notification that the monitoring, as a result of that compliance audit, was closed. Your response satisfied the required corrective actions detailed in the original summary letter issued on June 3, 2018.

I did want to alert you to a minor typo on the Form As completed for both units. On the blank for the maximum renewal income limit, you are to insert the figure that represents 120% of the median family income in effect at the time of the renewal. The correct figure should have been \$97,680. Your forms displayed \$97,700. This did not impact either households calculations, but I wanted to make sure you were aware so that you can update the forms. Here is a quick screenshot of how yours displayed.

Please give me a call if you have any questions. Thanks for your timely response.


Jenny DeSilva


Director Blueprint Housing Solutions A subsidiary of the Housing Authority of the City of Austin 1124 S. IH 35, Austin, Texas 78704

Office: (512) 767-7723 Fax: (512) 472-9905

Email: jennyd@blueprinthousing.org
Web: www.blueprinthousing.org

Maps of 3104, 3105, 3108, 3109, 3112, 3113, 3116, 3117, 3120, 3121 Father Jose Znotas Street, Austin, Texas 78702







High Frequency Bus Routes: 1/4-Mile Buffer

Bus Routes: 3/4-Mile Buffer



Exhibit F



-General Information-

Address: 3104 FATHER JOE ZNOTAS ST Tax ID: 0207140343 Appraisal District: Travis

-FEMA Floodplain-

Flood Zone: X Community Number: 480624 Panel Number: 48453C0465J Effective Date: 1/6/2016 100-Year Flood Elevation: N/A 500-Year Flood Elevation: N/A

-City of Austin Floodplain-

25-Year Flood Elevation: N/A 100-Year Flood Elevation: N/A



IF YOU ARE A NATURAL PERSON, NOTICE OF CONFIDENTIALITY RIGHTS: YOU MAY REMOVE OR STRIKE ANY OR ALL OF THE FOLLOWING INFORMATION FROM ANY INSTRUMENT THAT TRANSFERS AN INTEREST THE BEFORE ITIS FILEDFOR RECORD INSOCIAL SECURITY NUMBER OR YOUR DRIVER'S LICENSE NUMBER.

Warranty Deed with Vendor's Lien

Date:

January 3, 2009

Grantor:

Tillery, LLC

Grantor's Mailing Address:

Richmond, TX 12409

Grantee:

Guadalupe Neighborhood Development Corporation

Grantee's Mailing Address:

315 E Eighth Street Austin, TX 78702

Consideration:

A Promissory Note in the original principal sum of One Million and No/100 Dollars (\$1,000,000.00) payable to the order of Austin Housing Finance Corporation, a Texas public, non-profit corporation, which Promissory Note is secured by a Deed of Trust of even date to Margaret Shaw, Trustee.

The debt evidenced by this Note is in part payment of the purchase price of the Property. The debt is secured by deed of trust and by a vendor's lien on the Property, which is expressly retained. The lien created by the deed of trust and the vendor's lien is transferred to Lender by the deed. The deed does not waive the vendor's lien, and the two liens and the rights created by this deed of trust are cumulative. Lender may elect to foreclose under either of the liens without waiving the other or may foreclose under both.

Property (including any improvements):

A tract or parcel of land containing 3.998 acres, more or less, being out of and a part of Outlot No. 51, Division "A" of the Outlots of the Government Survey, adjoining the City of Austin, , Travis County, Texas, according to the map of the City of Austin on file in the General Land Office of the State of Texas, and being that same 4 acre tract conveyed to Tillery, LLC, by the deed recorded in Document No. 2007097412, of the Official Public Records of Travis County, Texas; the herein described 3.998-acre tract being more particularly described by metes and bounds on Exhibit "A" attached hereto and made a part hereof for all intents and purposes.

Reservations from Conveyance:

Nоле

Exceptions to Conveyance and Warranty:

Liens, if any, described as part of the Consideration and any other liens described in this deed as being either assumed or subject to which title is taken, validly existing easements, rightsof-way, and prescriptive rights, whether of record or not; all presently recorded and validly existing instruments, other than conveyances of the surface fee estate, that affect the Property; and taxes for the current year, which Grantee assumes and agrees to pay.

Grantor, for the Consideration and subject to the Reservations from Conveyance and the Exceptions to Conveyance and Warranty, grants, sells, and conveys to Grantee the Property, together with all and singular the rights and appurtenances thereto in any way belonging, to have and to hold it to Grantee and Grantee's heirs, successors, and assigns forever. Grantor binds Grantor and Grantor's heirs and successors to warrant and forever defend all and singular the Property to Grantee and Grantee's heirs, successors, and assigns against every person whomsoever lawfully claiming or to claim the same or any part thereof, except as to the Reservations from Conveyance and the Exceptions to Conveyance and Warranty.

Austin Housing Finance Corporation, a Texas public, non-profit corporation, ("Lender"), at Grantee's request, has paid in cash to Grantor that portion of the purchase price of the Property that is evidenced by the note. The first and superior vendor's lien against and superior title to the Property are retained for the benefit of Lender and are transferred to Lender without recourse against Grantor.


The vendor's lien against and superior title to the Property are retained until each note described is fully paid according to its terms, at which time this deed will become absolute.


When the context requires, singular nouns and pronouns include the plural.

Tillery, LLC

Kathleen Holler, Manager

STATE OF TEXAS)	•
COUNTY OF fif Bon ()	
This instrument was acknowledged before me	January <u>3/2)</u> , 2009 by Kathleen Holler,
Manager of Tillery, LLC, a Manager B.— li limited liability company.	mited liability company, on behalf of said
Note: Sente of Tongs Hy Commiscion Expires AUGUST 06, 2011	otary Public, State of Texas
Grantee's Address/Return to: 813 E Eighth St. Austin, 18702	





Founded by Congress, Republic of Texas, 1839 Planning and Development Review Department P.O. Box 1088, Austin, Texas 78767

December 2, 2013

Cassandra Ramirez Guadalupe Neighborhood Development Corporation 813 East 8th Street Austin, TX 78702

Dear Ms. Ramirez;

Please be advised that the properties locally known as 1126 Tillery Street and 3000-3128 Father Joe Znotas Street are currently zoned Family Residential – Neighborhood Plan (SF-3-NP). The properties are not a part of a Planned Unit Development and there do not appear to be any current Code violations.

The final plat of the preliminary plan C8-2009-01121A.SH was approved on January 7, 2009. A correction to the site plan was approved November 30, 2012. These approved plans reflect a development built to Single Family Residence Small Lot (SF-4A) site development standards, as per the City of Austin's Land Development Code Section 25-2-566 (Special Requirements for Affordable Housing in Certain Single Family Districts).

Provided that the construction is built in full compliance with the approved plans, relocated homes or homes built on-site would be in compliance with the requirements of zoning as specified in the City of Austin's Land Development Code.

If you need further assistance, please contact me at (512) 974-2330.

Sincerely

Robert Heil

Development Assistance Center

PHASE I ENVIRONMENTAL SITE ASSESSMENT

In Compliance with ASTM E 1527-05 and EPA's All Appropriate Inquiry Standards

1126 TILLERY STREET AUSTIN, TRAVIS COUNTY, TEXAS

Prepared for:

Jennifer J. Prenger Falvey Keenan Realtors

Prepared by:

Cuesta Resources, LLC 204 County Road 180 Leander, Texas 78641

> Project Nº 08-141 May 15, 2008

May 27, 2008

Jennifer J. Prenger, Realtor Falvey Keenan Realtors 11712 Barrington Way Austin, Texas 78759

SUBJECT: Phase I Environmental Site Assessment for 1126 Tillery Street Property

Dear Ms. Prenger:

Cuesta Resources, LLC (Cuesta) performed a Phase I Environmental Site Assessment (ESA) for the 1126 Tillery Street property, which is located on a residential street in east Austin.

Our services were performed for, and the reports can be relied on by Mr. and Mrs. Holler in accordance with the Terms and Conditions between the Hollers and Cuesta as established in Cuesta's Proposal. The attached report meets the minimum requirements of the American Society of Testing and Materials (ASTM) E 1527-05; Environmental Site Assessments: Phase I Environmental Site Assessment Process and 40 CFR Part 312; Standards and Practices for All Appropriate Inquiries.

The objective of our services was to identify and record any obvious existing or potential conditions that could cause potential environmental liability to, or restrict the use of, the subject property. We observed the standard of care generally exercised by the profession under similar circumstances and conditions to complete this Phase I ESA.

The report represents the condition of the property at the time the work was performed and may not represent the condition of the property at a later date.

This Phase I ESA did not include any inquiry with respect to asbestos, radon, methane, lead-based paint, lead in drinking water, formaldehyde, subsurface investigation activities, wetlands, regulatory compliance, air quality, mold, ecological resources, endangered species, cultural and historic resources, or other services, potential conditions, or features not specifically identified and discussed herein.

The discovery of any additional information concerning the environmental conditions at the Site should be reported to us for our review, so that we can reassess potential environmental issues and modify our recommendations, if necessary.

The information collected for this project is confidential and will not be released to anyone other

Phone: (512)431-5727 Fax: (512)528-0502 than to those shown on the distribution without your client's authorization. If you have any questions, please do not hesitate to contact us. We appreciate the opportunity to perform this service for you.

Very Truly Yours,

Will Boettner, P.G. Senior Scientist

Copies Submitted: 3

EXECUTIVE SUMMARY

Cuesta Resources, LLC performed a Phase I Environmental Site Assessment (ESA) using the guidance provided by the American Society for Testing and Materials (ASTM) 1527-05 Environmental Site Assessment, Phase I Environmental Site Assessment Process and 40 Code of Federal Regulations (CFR) Part 312; Standards and Practices for All Appropriate Inquiries. The objective of our services was to identify and record any obvious existing or potential conditions that could cause potential environmental liability to, or restrict the use of, the subject property. The approximate 4-acre tract of land is located at 1126 Tillery Street in Austin, Travis County, Texas, and is herein referenced as the 'Site'. The Site is located in a predominantly residential area. The scope of work performed, objectives, extent and limitations of the services are described in more detail in the text of the report.

In summary, our findings are:

Our review of the available historical information indicates the Site has changed very little from initial development about 1910. Historical aerial photographs of the site vicinity show the area was originally small farms and cultivated pastures until about 1970. The property contains one wood frame single family residence and an associated wood frame building used for storage of household items.

- Cuesta reviewed selected federal and state environmental regulatory lists. There is a nearby closed historical landfill site to the west that is recorded by the City of Austin and the City buffer for the old landfill site lies intrudes about 200 feet onto the property. The City of Austin landfill buffer is an estimated buffer that does not indicate the presence of waste materials but rather that the former landfill margins are not completely known and land owners should be aware of the possibility that the site may be influenced by the former landfill. It does not suggest that the former landfill presents an on-going environmental concern that would likely adversely impact the Site. The site soil conditions and historical aerial photography do not indicate that the closed landfill was on the 1126 Tillery property.
- No additional environmental concerns were identified during the site reconnaissance conducted on April 24 and 15, 2008.

Based on the results of this assessment, Cuesta has determined that one (1) "Recognized Environmental Condition", as defined by ASTM, was identified in connection with activities at or near the subject property. Additionally, other than the closed landfill site, the surrounding properties do not appear to pose a potential environmental concern to the Site. Cuesta recommends that two soil samples be collected to a depth of not less than 10 feet on the western boundary of the 1126 Tillery property to eliminate the possibility that the closed landfill site ever encroached upon the 1126 Tillery property.

1.0 INTRODUCTION AND SCOPE OF SERVICE

1.1 Purpose

The purpose of the Phase I ESA is to identify reasonably observable, on site and/or adjacent potential sources of contamination, which could adversely affect the environmental quality of the Site, and to ascertain the possibility of site contamination that may have resulted from historical use of the Site. This Phase I ESA was performed to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser on Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) liability: that is, the practices that constitute "appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice" as defined by the American Society for Testing and Materials (ASTM) Standard Practice for Environmental Site Assessments, E 1527-05.

The opinions included herein are based upon the information obtained during the study and our professional experience. In the event that other relevant information becomes available, we request the opportunity to review the information, and to modify our opinions, if warranted.

1.2 Detailed Scope of Services

This Phase I ESA was conducted to identify recognized environmental conditions on the Site and was performed in accordance with current ASTM standards and Cuesta's standard scope of services which are presented below:

- Perform a site visit (reconnaissance) to look for surficial indications of past and present activities involving hazardous substances and/or petroleum products. Will Boettner, P.G., a professional who is experienced in performing environmental assessments, performed the site reconnaissance on April 24 and 25, 2008;
- Conduct interviews with the current property owner(s) and/or "knowledgeable site
 personnel" in an attempt to determine current and/or historical onsite activities
 that may be relevant to the Site and/or adjoining properties;
- Review selected, available, historical information, including aerial photographs, Sanborn Fire Insurance Maps and topographic maps (where coverage is available) of the Site and surrounding properties in an attempt to determine on-site and off-site historical activities;
- Review selected, available, lists published by state and federal environmental regulatory agencies for records or comments pertaining to past or present environmental concerns at the Site and/or within the specified "search distances" from the Site. These search distances adhere to the standard distances proposed by

the ASTM;

- Perform a vehicular reconnaissance of selected areas in an attempt to verify the locations of listed facilities within search distances specified by ASTM and to assist in visually identifying nearby land use which may create the potential for an adverse, environmental impact on the Site; and
- Provide a written final report summarizing the Phase I ESA observations, interviews, file reviews, findings and conclusions.

1.3 Significant Assumptions

This Phase I ESA is intended to limit, but not eliminate, uncertainty regarding potential for recognized environmental conditions in connection with the Site with reasonable limits of time and cost. It is assumed that the user has provided Cuesta with any specialized knowledge or experience that is material to recognized environmental conditions in connection with the Site, including the reason why the property may have a significantly lower purchase price than comparable properties, if applicable (ASTM 1527-05 Section 6.5).

In general, groundwater flow direction has been inferred based on topography in the vicinity of the Site with the assumption that shallow groundwater flow will follow surface topography or other available water resources. No site-specific measurements of groundwater depth and flow direction have been performed.

Based on this interpretation, Cuesta has reviewed regulatory agency information for facilities that are located in a presumed up-gradient direction that, further based on proximity and knowledge of potential contaminant fate and transport, may present a potential impact to the Site.

Cuesta has reviewed historical aerial photographs in an attempt to determine the past use of the Site and adjoining properties. Although some uses can be determined, due to the quality and scale of the photographs, few on-site details are identifiable.

1.4 Limitations and Exceptions

Cuesta has endeavored to meet what it believes is the standard of care for the services performed and, in doing so, is obliged to advise the user of Phase I ESA limitations. Cuesta believes that providing information about limitations is essential to help the user identify and thereby manage risks. These risks can be mitigated, but not eliminated, through additional research. Cuesta will, upon request, advise the user of the additional research opportunities available and the associated costs.

This report is an instrument of service of Cuesta and includes limited research, a review of specified and reasonably ascertainable listings and a site reconnaissance to identify

"recognized environmental conditions" using the ASTM E 1527-05; Environmental Site Assessments: Phase I Environmental Site Assessment Process. "Recognized environmental conditions" are defined by the ASTM as "the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater or surface water of the property." The Phase I ESA was performed in accordance with generally accepted practices of the profession undertaken in similar studies at the same time and in the same geographical area. Cuesta has observed a standard of care generally exercised by the profession under similar circumstances and conditions.

The Phase I ESA did not include any inquiry with respect to asbestos, radon, methane, lead based paint, lead in drinking water, formaldehyde, endangered species, wetlands, subsurface investigation activities or other services or potential conditions or features not specifically identified and discussed herein.

This report represents Cuesta service to the addressee as of the report date. In that regard, the report constitutes Cuesta's final document, and the text of the report may not be altered in any manner after final issuance of the same. Opinions relative to environmental conditions given in this report are based upon information derived from the most recent site reconnaissance date and from other activities described herein. The addressee is herewith advised that the conditions observed by our firm are subject to change. Certain indicators of the presence of hazardous materials may have been latent or not present at the time of the most recent site reconnaissance and may have subsequently become observable. In a similar manner, the research effort conducted for a Phase I ESA is limited. Accordingly, it is possible that Cuesta's research, while fully appropriate for a Phase I ESA and in compliance with the scope of service, may not include other important information sources. Assuming such sources exist, their information could not have been considered in the formulation of our findings and conclusions.

This report is not a comprehensive site characterization or regulatory compliance audit and should not be construed as such. The opinions presented in this report are based upon findings derived from a site reconnaissance, a review of specified records and sources and comments made by interviewees. Specifically, Cuesta does not and cannot represent that the Site contains no hazardous or toxic materials, products, or other latent conditions beyond that observed by our company during the site assessment. Further, the services herein shall in no way be construed, designed or intended to be relied upon as legal interpretation or advice.

1.5 Special Terms and Conditions

In those instances where additional services or service enhancements are included in the report as requested or authorized by the user, those services are presented in the scope of work. There are no special terms and conditions.

1.6 User Reliance

The study and report have been prepared on behalf of and for the exclusive use of the addressee solely for its use and reliance in the environmental assessment of this Site. The addressee is the only party to which Cuesta has explained the risks involved and which has been involved in the shaping of the scope of services needed to satisfactorily manage those risks, if any, from the addressee's point of view. Accordingly, reliance on this report by any other party may involve assumptions whose extent and nature lead to a distorted meaning and impact of the findings and opinions related herein. Cuesta's findings and opinions related in this report may not be relied upon by any party except the addressee. With the consent of the addressee and Cuesta, we may be available to contract with other parties to develop findings and opinions that relate specifically to such other parties' unique risk management concerns related to the Site.

2.0 SITE DESCRIPTION

2.1 Locations and Legal Descriptions

The Site is an approximate 4-acre foot tract of land located in the City of Austin, in Travis County, Texas. The property consists of ~4-acres of grass covered former farm land that is currently not being used for any active agricultural activities. The Site is located west of the Tillery Street, a predominantly residential community of single family homes.

A Site Location Map, Site and Vicinity Map are provided at the end of this report.

2.2 Site and Vicinity General Characteristics

2.2.1 Topography

The Site is ranges in elevation from approximately 459 feet to 456 feet above mean sea level (MSL) based on the USGS 7.5 minute topographic map for the Austin East Quadrangle. Surface runoff travels to the east and southeast south from the topographically higher northwest corner.

2.2.2 Soil Conditions

Soils at the site are from the Bergstrom soils and Urban Land series and the Houston Black Clay Series as reported in the Web Soil Survey, published by the U.S. Department of Agriculture, Soil Conservation Service, 2008. These soils are characterized as being a

medium brown to dark brown silty sandy clay loam (Bergstrom and Urban) to a dark brown to black cobbly clay (Houston Black soils) that ranges in thickness from 0 to 13 inches and overlies a coarsely fractured indurated limestone bedrock. The Bergstrom soil is well drained, has moderate to slow permeability and rapid runoff. The Houston Black soils are less well drained, prone to shrink-swell behavior and low permeability.

A geotechnical study has not been conducted for the Site.

2.2.3 Geology

The Site is located on the Austin Group and Colorado River floodplain deposits. The Austin Group consists of Upper Cretaceous age marine limestone deposit characterized as a marly, fossiliferous formation subject to weathering and leaching. (Geologic Atlas of Texas, Austin Sheet, 2005, Bureau of Economic Geology).

2.2.4 Regional Groundwater Conditions

The Site is not located over a sole source aquifer according to the EPA Region VI, Sole Source Aquifer Office, Dallas, Texas found at http://www.epa.gov/earth1r6/6wq/swp/ssa/maps.htm. The depth to shallow ground water is dependent on several parameters such as seasonal water table conditions, elevation and site geology.

Based on surface elevations, shallow groundwater probably flows to the southeast towards the regional drainage channels that are present to the southeast and south. Although there are old cisterns and wells in the area, shallow ground water is not known to be used as a source of drinking water in the area.

2.2.5 Floodplain Information

The Site is not located in a flood hazard area according to the Revised City of Austin Floodplain maps for the area.

2.3 Current Use of the Property

The site is currently a single family home surrounded by a large (~4-acre) grassy pasture. There are two structures on the site, a single family stick built house and a small outbuilding/garage converted to storage of domestic furniture and toys. The home is currently occupied and adequately maintained. There were no hazardous substances stored inside of the residence or in the converted garage except for normal household cleaners, some limited quantities of paint and unused furniture.

2.4 Structures, Roads and Other Improvements

The Site is developed with a single family residence and a converted garage. An electric supply line crosses the property from north to south and has a power drop and meter to the residence and garage. The transformers on the poles are labeled as not containing PCB's and a call to Austin Energy did not reveal any evidence of PCB's in the transformers.

2.5 Current Uses of Adjoining Properties

Adjacent properties were visually examined from public access right-of-ways or from the legal boundaries of the Site. Visual assessment of adjacent property use, as well as the potential for environmental conditions was conducted during the site reconnaissance. Adjacent property and nearby descriptions are as follows:

- On the north side is a single family residence that also occupies a small parcel of former farmland;
- On the east is the route of Tillery Street, a tree-lined residential street with numerous single family residences;
- On the south is Ted's Tree Farm, a commercial nursery that includes landscaping materials and plants; and
- On the west if a vacant area that is extensively tree covered but that is owned by the Austin Community College system.

One former facility was identified by Cuesta or listed in the environmental database review on adjacent or nearby properties that indicated sources of potential environmental concern. The former landfill site referred to in the City of Austin closed landfill records as the Webberville-Govalle site is present to the northwest of the 1126 Tillery site. This abandoned and closed landfill has a buffer established by the City of Austin that extends approximately 200 feet onto the Tillery property. The buffer is only advisory and does not indicate the confirmed presence of landfill deposits. A review of the historical aerial photography did not reveal the presence of landfill activity on the Tillery property.

3.0 USER PROVIDED INFORMATION

3.1 Title Records

Cuesta was not provided with a Title Search Report and review of a title report was not included in the scope of this project.

3.2 Environmental Liens or Activity and Use Limitations

Activity and use limitations (AULs) are legal or physical restrictions or limitations on the use of, or access to, a property or facility to prevent exposure of hazardous substances or petroleum products. These restrictions may include institutional and engineering controls that may be recorded in a regulatory database or in the restrictions on the record of title.

According to the FirstSearch database report, the Site is not identified in the TCEQ's Brownfield database. According to the property owner, no environmental liens or restrictions have been placed on the property; however, Cuesta did not review title documents.

3.3 Specialized Knowledge

Further, if Cuesta or CLIENT have knowledge that the information being used from a prior Phase I ESA is not accurate or it is obvious that the information is not accurate, such information from a prior Phase I ESA may not be used. According to property owner, a prior Phase I ESA has not been conducted for the Site.

3.4 Commonly Known or Reasonably Ascertainable Information

Based on our interviews, CLIENT and/or property owner have no commonly known or reasonable ascertainable information about the parent property or Site that is material to determining recognized environmental conditions

3.5 Valuation Reduction for Environmental Issues

CLIENT and/or property owner indicated that the property value, purchase, or lease price has not been devalued, compared to comparable properties, as a result of environmental conditions at the Site, or surrounding properties.

3.6 Owner, Property Manager, and Occupant Information

The Site is currently owned and managed by the Hollers, and occupied by a renter/tenant. The current tenant is single family residential and no evidence of commercial or industrial activity was noted during the site visits.

3.7 Reason for Performing Phase I ESA

This Phase I ESA was requested by Client as part of their due diligence prior to the sale of the property.

4.0 RECORDS REVIEW

The purpose of the record review is to obtain and examine reasonably obtainable records to help identify recognized environmental conditions in connection with the Site. For this review, records were obtained from Banks Information Services, Inc. The approximate maximum search distance (MSD) radius, as recommended in the ASTM 1527-05 Section 8.2, for the site vicinity review is noted after each database listed below. The distance from the Site to the listed facility represents the approximate distances from the center of the

Site to the identified facility addresses and may not represent the actual distance from the boundary of the Site to the boundary of the listed facility. Regulatory data for listed facilities are provided in the appendices of this report.

4.1 Standard Environmental Record Sources

A summary of the federal and state databases searched is provided below.

- Federal NPL (MSD = 1.0 mile): The National Priorities List (NPL) was reviewed
 to identify facilities that the United States Environmental Protection Agency
 (EPA) considers to present the greatest risk to human health and the environment.
 No NPL, proposed NPL or delisted NPL facilities were identified within the
 search radius.
- Federal CERCLIS/NFRAP (MSD = 0.5 mile): The Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS) and the No Further Remedial Action Planned (NFRAP) databases are maintained by the EPA. CERCLIS contains facilities that are either proposed to be placed, or are currently on the NPL and facilities that are in the screening and assessment phase for possible inclusion on the NPL. NFRAP includes facilities where, following an initial investigation, no contamination was found, contamination was quickly removed, or the contamination does not require further NPL consideration as determined by the EPA. No CERCLIS/NFRAP sites were identified within the search radius.
- Federal RCRA COR (MSD = 1.0 mile): The EPA maintains a database of Resource Conservation and Recovery Act (RCRA) facilities that are undergoing "corrective action". A Corrective Action Order (COR) is issued when there has been a release of hazardous waste or constituents into the environment from a RCRA facility. No RCRA COR facilities were identified within the search radius.
- Federal RCRA-TSD (MSD = 0.5 mile): The EPA's RCRA program identifies and tracks hazardous waste from the point of generation to disposal. RCRA-TSD facilities treat, store, and/or dispose of (TSD) hazardous waste. No RCRA-TSD facilities were identified in the search radius.
- Federal RCRA GEN (MSD = 0.25 mile): This EPA database identifies RCRA facilities that are generators of hazardous waste. Inclusion on the RCRA GEN registry does not necessarily imply that an environmental release/problem exists at the facility. One RCRA Generator site was identified in the records search but is for the closed Austin Independent School District Deleon facility located about ¼ mile to the southeast. This site is not considered a threat to the Tillery property.
- Federal ERNS (MSD = 0.25 mile): The Emergency Response Notification

System (ERNS) is an EPA database used to collect information on reported releases of oil and hazardous substances. No ERNS facilities were identified within the search radius.

- State Site (MSD = 1.0 mile): The TCEQ maintains a database of facilities which may constitute an imminent and substantial endangerment to public health and safety or to the environment due to a release or threatened release of hazardous substances into the environment. No State Site facilities were identified within the search radius.
- State SWL (MSD = 0.5 mile): The TCEQ Municipal Solid Waste Division maintains a database of permitted Solid Waste Landfills (SWL), incinerators, or transfer stations. No SWL facilities were identified within the search radius.
- State LPST (MSD = 0.5 mile): The Texas Commission on Environmental Quality (TCEQ) Petroleum Storage Tank Division maintains a database of Leaking Petroleum Storage Tank (LPST) facilities. Nine LPST facilities were identified within the search radius. None of the identified LPST sites are close enough or up gradient to pose a risk to the Tillery site.
- State UST/AST (MSD = 0.25 mile): The TCEQ provides the Petroleum Storage Tank Database and the Aboveground Storage Tank Database for underground storage tank (UST) and aboveground storage tank (AST) facilities. One UST/AST facility was identified within the search radius but it is too far away and down gradient from the Tillery property and does not pose a threat to the site.
- BROWNFIELD (MSD = 0.50 mile): The TCEQ's Brownfield database includes all former industrial properties that lie dormant or underutilized due to liability associated with real or perceived contamination. Some sites are noted as having institutional and or engineering controls placed on them (also called activity and use limitations (AULs)). Also included in this database are the TCEQ's listing of all sites in the VCP (Voluntary Cleanup Program) and the IOP (Innocent Owner/Operator Program). Some VCP and IOP sites are noted as having institutional and or engineering controls placed on them. EPA's Brownfields Management System (BMS) is an analytical database designed to assist the EPA in collecting, tracking, and updating information, as well as reporting on the major activities and accomplishments of the various Brownfield grant programs.

In Texas, if a facility has institutional and or engineering controls in place, the TCEQ will include the facility in their Brownfield database. Because the Site and adjacent properties do not currently have institutional and or engineering controls in place, they are not listed in the TCEQ's Brownfield database. One Brownfield Voluntary Cleanup (VCP) site was identified and consists of a cleanup of a portion of the old Webberville-Govalle landfill site that was identified under the

City of Austin closed landfill survey.

- State OTHER (MSD = 0.25 mile): This Texas Industrial Hazardous Waste Notice of Registration database tracks industrial and hazardous waste generation and management activities in the state for industrial and hazardous waste transporters, receivers, generators, and one time shipments. One other facility was identified within the search radius but does not pose a threat to the Tillery property since it is the closed Deleon Austin ISD facility.
- Non-Geocoded Sites: The Banks Information Solutions, Inc. report identified eight non-geocoded sites but none of them pose a threat to the Tillery property.

4.2 Additional Environmental Record Sources

TCEQ Online Databases. Cuesta researched the LPST Database Query and Central Registry Query on the TCEQ website to ascertain records of underground storage tank installation and removal as well as and hazardous material spill incidents. According to the LPST Database Query and Central Registry Query, no records are available for the Site and no other adjoining properties were listed other than reported by the database search.

Capitol Area Council of Governments. Cuesta contacted the Capitol Area Council of Governments (CAPCOG) office to ascertain general environmental and developmental land use information regarding the Site and its immediately surrounding vicinity. CAPCOG maintains records of permitted and unpermitted landfills. CAPCOG provided Cuesta with ArcView file of the locations of permitted and unpermitted landfills in Travis County. According to their database, no landfills are located on the Site or in the site vicinity.

4.3 Physical Setting Sources

The Site is an approximate 4-acre tract of land located in the City of Austin in Travis County, Texas. The site consists of an undeveloped parcel of former farmland with scattered oaks and Pecans.

The Austin East, Texas, 7.5-minute topographic quadrangle map 1984 obtained from the Texas Natural Resource Information System (TNRIS) and printed at a scale of 1:24,000 by the United States Geologic Survey (USGS) was used to determine the physical setting of the Site. Review of the topographic may indicates that groundwater flow beneath the Site is likely to drain towards the southeast.

Other published information utilized in conducting this environmental assessment is listed in Section 10.0 References, of this report.

4.4 Historical Use Information of the Property

Standard historical sources (i.e. fire insurance maps, historical topographic maps, aerial photographs, etc.) are typically used to help determine historical site use. This section provides the "reasonably ascertainable" information obtained from our historical information search of the Site.

4.4.1 from First Development

Review of the historical sources indicates that the use of the Site has been identified back to the property's first developed use (including agricultural uses) or back to 1940. The Site has been developed since at least 1910. Records show no development of the Site prior to 1910. According to Mrs. Holler, the property owner, the Site is developed with a single family residence built in 1910. The property was used as a farm from about 1910 to about 1970. Review of the historical sources indicates that the use of the Site has been identified back to 1951as an agricultural field. Aerial photographs and other historical sources back to 1940 are not reasonably ascertainable and would not likely show a change of property use. It is our opinion that this data failure does not constitute a significant data gap or impact our ability to identify recognized environmental conditions at the Site.

4.4.2 City Directories

City directories are published for urban areas and provide listings of residents, businesses, and professional concerns. City directories were not available for the site vicinity because of its historically rural setting.

4.4.3 Sanborn Fire Insurance Maps

Sanborn Fire Insurance Maps are typically published for pre-1960 central business districts. In the late nineteenth century, the Sanborn Company began preparing maps for use by fire insurance companies. Sanborn Fire Insurance Maps are not available for this area because of its historically farming nature.

4.4.4 Historical Topographic Map Review

A historical topographic map depicting development of the Site and surrounding areas was reviewed and is summarized below.

Date	Map	Scale
1962	USGS Topographic Quadrangle Map of 'Austin East', Texas	Scale: 1: 24,000

No environmental concerns were identified from review of the historical topographic map.

4.4.5 Aerial Photograph Review .

Available aerial photographs depicting development of the Site and vicinity at periodic intervals were reviewed, and summarized below. The information obtained from the evaluation of the aerial photograph depends upon the scale and quality. Copies of the aerials are provided in the appendices.

	AERIAL PHOTOGRAPH SUMM	ARY
Date	Source of Aerial	Scale
1951	Agricultural Stabilization and Conservation Service	Scale: 1 inch = 500 feet

The Site and adjacent properties are open and agricultural fields with a few residential structures present. The current house is visible in the southeast corner of the property. There is no evidence of activities that would create lasting environmental limitations on the property. A drainage channel runs from the north to the south on the western edge of the property.

1964
1964

The Site and adjacent properties are very similar to the 1951 photo with the surrounding area still being used as agricultural or farming land with a few single family residences visible. On the northwest corner of the Tillery property, an extensive land disturbance is

Scale

AERIAL PHOTOGRAPH SUMMARY

Source of Aerial

visible on an adjoining property. This appears to be the former Webberville-Govalle

landfill described in the City of Austin survey of closed landfills report. The landfill appears to occupy the northern portion of its property and does not appear to be in contact with the Tillery property.

ar the rinery property.

Date

1970 | TXDOT | Scale: 1 inch = 500 feet

By 1970, the Webberville-Govalle landfill site to the north appears to be closed. The Site and adjacent properties are still farming and agricultural lands and there are an increasing number of residential sites visible. Trees along the fence lines are much larger and there does not appear to be any activity that could indicate environmental problems for the Tillery property.

1995 US Geological Survey Scale: 1 inch = 500 feet

The Site and adjacent properties are still open and undeveloped except for some additional single family residential construction. The site of the Webberville-Govalle landfill is overgrown with trees and obscuring vegetation. There do not appear to be activities either on the Tillery property or surrounding that would pose an environmental threat to the site.

2004 USDA Scale: 1 inch = 500 feet

The Site and adjacent properties are increasingly residential and built up. The Tillery property remains open and under pasture but the property to the direct south is now a tree nursery. The site of the former Webberville-Govalle landfill is extensively tree covered and overgrown.

No additional environmental concerns at the Site were identified from review of the aerial photographs. The past activities at the Webberville-Govalle landfill are the only apparent activities on the historical aerial photos that would pose a potential environmental threat to the Tillery property.

4.5 Historical Use Information of Adjoining Properties

The same standard historical sources used in the previous section (i.e. fire insurance maps, historical topographic maps, aerial photographs, etc.) were used to determine the property use of adjoining properties. Information obtained from the historical sources is summarized below.

HISTORICAL USE OF ADJOINING PROPERTIES			
Direction	First Developed	Description of Development and Use	
North	Pre-1951	Cropped field with fences and several residential and out buildings	
East	Pre-1951	Residential lots and structures	
South	Рге-1951	Farming and residential structures	
West	Pre-1970	Landfill and fences	

No additional environmental concerns beyond the Webberville-Govalle landfill on the adjoining property was identified from review of the historical sources.

5.0 SITE RECONNAISSANCE

5.1 Methodology and Limiting Conditions

The objective of the site reconnaissance is to obtain information indicating the likelihood of identifying ASTM recognized environmental conditions in connection with the Site to the extent not obstructed by bodies of water, adjacent buildings, or other obstacles.

The Site and adjoining properties were visually observed on April 24 and 25 by Will Boettner, P.G. The purpose of the reconnaissance was to note evidence of recognized environmental conditions. Additionally, reconnaissance of the adjoining properties was performed to identify land use and the associated potential for producing recognized environmental conditions.

Selected photographs taken during the site reconnaissance are provided in the appendices.

5.2 General Site Setting

The approximate 4-acre Site is located at 1126 Tillery Street in the City of Austin, Travis County, Texas. The Site is covered in tall grass and has a few pecan and oak trees. No evidence of hazardous materials or wastes was observed at the time of site reconnaissance.

• Topographic Observations: The Site appears to be relatively flat. The general direction of area runoff drainage appears to be to the southeast along with the slight topographic elevation change.

- Source of Drinking Water: Drinking water in the site vicinity is provided by the City of Austin.
- Sewage Disposal/Septic System: The property has City of Austin wastewater and sewage service.
- Hazardous Substances and Petroleum Products associated with Operations other than Storage Tanks: No evidence of hazardous substances or petroleum products was observed on the Site.
- Storage Tanks and Associated Equipment: No evidence of aboveground storage tanks (ASTs) was observed on the Site. No underground storage tanks (USTs) or evidence thereof, such as fill caps or pipes was observed on the Site.
- Odors: No odors suggesting a release or recognized environmental conditions were detected on the Site.
- Surficial Staining and Stressed Vegetation: No surficial staining or stressed vegetation was observed on the Site.
- **Drums and Other Containers:** No drums or other containers were observed on the Site.
- Polychlorinated Biphenyls (PCBs): No potentially-polychlorinated biphenyls (PCBs) containing equipment was observed on the Site.
- Heating and Cooling Systems: Heating, Ventilation and Air Conditioning (HVAC) systems were observed on the Site.
- Drains or Sumps: No drains or sumps were observed on the Site.
- Pits, Ponds or Lagoons: No pits, ponds or lagoons were observed on the Site.
- Solid Waste Disposal: No solid waste is disposed at the Site.
- Wastewater Discharges: No evidence of wastewater was observed on the Site.
- **Hydraulic Lifts:** No hydraulic lifts were observed on the Site.

5.3 Exterior Observations of Structures

The Site contains a one-story frame residence, a one story detached garage, landscaped areas and paved drive and parking. The exterior of the buildings consists of wood siding. The roof of the building consists of sheets of composite asphalt shingling.

5.4 Interior Observations of Structures

The structures on the property consist of a house and a detached garage. The interior of the building generally consists of drywall, plaster, tile (4-inch by 4-inch), linoleum tile floors (12-inch by 12-inch), sheet vinyl flooring and incandescent and fluorescent lighting. According to the property owner, the building has been renovated several times since original construction Cuesta did not observe insulated piping.

6.0 INTERVIEWS

6.1 Interview with Owner

Mrs. Holler was interviewed regarding the history of the Site. Her family has owned the property since about 1910 and they were not aware of an environmental concern on the property.

6.2 Interview with Site Manager

The Site or the parent property does not contain a facility with manager; therefore no interviews were conducted.

6.3 Interviews with Occupants

The current tenant was not available for interview purposes and was not contacted.

6.4 Interview with Local Government Officials

Cuesta contacted the TCEQ in Austin, Texas to ascertain general environmental and developmental land use information regarding the subject property and its immediately surrounding vicinity. The TCEQ maintains records of underground storage tank installation and removal as well as and hazardous material spill incidents. According to the TCEQ, no records are available for the Site.

Cuesta also contacted the Emergency Services Department in the City of Austin to ascertain general emergency, spills and disaster or accident history of the property. According to the Fire Marshal's office, no records are available for the Site.

6.5 Interview with Others

No other interviews were conducted for this report.

Local Electrical Utility Company. Cuesta contacted Austin Energy to determine if the pole-mounted transformers located in the utility easement contain polychlorinated biphenyls.

Local Fire Department. Cuesta contacted the Austin Fire Department to ascertain information regarding response calls made to the Site or site vicinity. The office stated that a written request for open records review must be submitted and the fee varies depending on any information. Since other information is available regarding the general land use and land development of the Site, Cuesta did not request a records search for the Site.

7.0 FINDINGS

In summary, our findings are:

Our review of the available historical information indicates the Site has changed very little from initial development about 1910. Historical aerial photographs of the site vicinity show the area was originally small farms and cultivated pastures until about 1970. The property contains one wood frame single family residence and an associated wood frame building used for storage of household items.

- Cuesta reviewed selected federal and state environmental regulatory lists. There is a nearby closed historical landfill site to the west that is recorded by the City of Austin and the City buffer for the old landfill site lies intrudes about 200 feet onto the property. The City of Austin landfill buffer is an estimated buffer that does not indicate the presence of waste materials but rather that the former landfill margins are not completely known and land owners should be aware of the possibility that the site may be influenced by the former landfill. It does not suggest that the former landfill presents an on-going environmental concern that would likely adversely impact the Site. The site soil conditions and historical aerial photography do not indicate that the closed landfill was on the 1126 Tillery property.
- No additional environmental concerns were identified during the site reconnaissance conducted on April 24 and 15, 2008.

Based on the results of this assessment, Cuesta has determined that one (1) "Recognized Environmental Condition", as defined by ASTM, was identified in connection with activities at or near the subject property. Additionally, other than the closed landfill site, the surrounding properties do not appear to pose a potential environmental concern to the Site. Cuesta recommends that two soil samples be collected to a depth of not less than 10 feet on the western boundary of the 1126 Tillery property to eliminate the possibility that the closed landfill site ever encroached upon the 1126 Tillery property.

Based on the results of this assessment, Cuesta has determined that no "Recognized Environmental Condition", as defined by ASTM, were identified in connection with activities on the 1126 Tillery property and the surrounding properties do not appear to pose a potential environmental concern to the Site.

The site of the former Webberville-Govalle landfill does represent the potential to affect the environmental character of the Tillery property if waste material had either been placed on the subject property or leachate had escaped the landfill site in the past. Based on the review of the aerial photos, there does not appear to be evidence that the landfill encroached onto the Tillery property. Limited soil sampling is recommended to confirm that the landfill site did not extend into the Tillery property. Cuesta reserves the right to alter our findings based on our review of any information received after the date of this report.

8.0 OPINION AND CONCLUSIONS

Cuesta has performed a Phase I Environmental Site Assessment in general conformance with the scope and limitations of ASTM E1527-05 of 1126 Tillery Street. This assessment has revealed no evidence of recognized environmental conditions in connection with the Site. The potential does exist that the former Webberville-Govalle landfill site may have contributed environmental impacts to the Tillery property and additional limited soil sampling should be conducted to rule out impacts from the landfill site.

9.0 DEVIATIONS

There were no significant deviations to the American Society for Testing and Materials (ASTM) 1527-05 Environmental Site Assessment, Phase I Environmental Site Assessment Process and 40 Code of Federal Regulations (CFR) Part 312; Standards and Practices for All Appropriate Inquiries.

10.0 SIGNATURES AND QUALIFICATIONS OF ENVIRONMENTAL PROFESSIONALS

I declare that, to the best of our knowledge, we meet the definition of Environmental Professional as defined in Section 312.10 of 40 CFR 312. I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. I have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Will Boettner, P.G.

APPENDIX A SITE PHOTOGRAPHS



Photo I View of front of residence at 1126 Tillery



Photo 2 View of converted garage structure at 1126 Tillery



Photo 3 View of interior of garage storage at 11 26 Tillery



Photo 4 View to east at adjacent property to 1126 Tillery



Photo 5 View to northwest along property line of 1126 Tillery showing heavy tree growth along channel of unnamed drainage



Photo 6 View from Tillery Street looking to the west and northwest at back of 1126 Tillery property

APPENDIX B

Historical Aerial Photographs

1126 Tillery Street Project Nº 08-141









1964 ASCS 1"=500"

















APPENDIX C

Records of Communication

RECORD OF COMMUNICATION

Project $N^{\underline{0}}$:

			_				
Site Name: 1126 Tillery			Loc	cation: Austin	ı, Texas		
Communications with: Mrs.	Holle	r	PHONE:				
Of:			Loc	ation: Austin	ı, Texas		
Communication Via:	X	Telephone		Letter	In Person		
Recorded By: Will Boettner			Of: Cuesta Resources				
At (Time):			On (Date): 4/24/2008				
Subject: Owner Interview							
Property been in family since Records exist for land back to No known environmental pro	1850	o's prior to he	r fami	ly purchase.	erty used for farming.		

APPENDIX D REGULATORY DOCUMENTATION

1126 Tillery Street Project Nº 08-141



Environmental FirstSearch™ Report

Target Property: Holler Property

1126 TILLERY

AUSTIN TX 78702

Job Number: ES35165

PREPARED FOR:

CUESTA RESOURCES, L.L.C.
204-A County Road 180
Austin, TX 78641
AAI

04-25-08



Tel: (512) 478-0059

Fax: (512) 478-1433

Environmental FirstSearch Search Summary Report

Target Site: 1126 TILLERY

AUSTIN TX 78702

FirstSearch Summary

Database	Sel	Updated	Radius	Site	1/8	1/4	1/2	1/2>	ZIP	TOTALS
NPL	Y	02-08-08	1.00	0	0	0	0	0	0	0
NPL Delisted	Y	02-08-08	0.50	0	0	0	0	-	0	0
CERCLIS	Y	02-08-08	0.50	0	0	0	0	-	0	0
NFRAP	Y	02-08-08	0.50	0	0	0	0	-	0	0
RCRA COR ACT	Y	04-01-08	1.00	0	0	0	0	0	0	0
RCRA TSD	Y	04-01-08	0.50	0	0	0	0	-	0	0
RCRA GEN	Y	04-01-08	0.25	0	0	1	-	-	0	1
Federal IC / EC	Y	02-08-08	0.50	0	0	0	0	-	0	0
ERNS	Y	12-31- 07	0.25	0	0	0	-	-	1	1
Tribal Lands	Y	12-01-05	1.00	0	0	0	0	0	0	0
State/Tribal Sites	Y	06-15-07	1.00	0	0	0	0	0	0	0
State Spills 90	Y	06-15-07	0.25	0	0	0	-	-	7	7
State/Tribal SWL	Y	06-15-07	0.50	0	0	0	0	-	1	1
State/Tribal LUST	Y	06-06-07	0.50	0	0	1	8	-	0	9
State/Tribal UST/AST	Y	06-06-07	0.25	0	0	1	-	-	0	1
State/Tribal EC	Y	06-06-07	0.50	0	0	0	0	-	0	0
State/Tribal IC	Y	06-07-07	0.25	0	0	0	-	-	0	0
State/Tribal VCP	Y	03/18/08	0.50	0	0	0	1	-	0	1
State/Tribal Brownfields		06-15-07	0.50	0	0	0	0	-	1	1
State Other	Y	06-15-07	0.25	0	0	1	-	-	0	1
- TOTALS -				0	0	4	9	0	10	23

Notice of Disclaimer

Due to the limitations, constraints, inaccuracies and incompleteness of government information and computer mapping data currently available to Banks Environmental Data, certain conventions have been utilized in preparing the locations of all federal, state and local agency sites residing in Banks Environmental Data's databases. All EPA NPL and state landfill sites are depicted by a rectangle approximating their location and size. The boundaries of the rectangles represent the eastern and western most longitudes; the northern and southern most latitudes. As such, the mapped areas may exceed the actual areas and do not represent the actual boundaries of these properties. All other sites are depicted by a point representing their approximate address location and make no attempt to represent the actual areas of the associated property. Actual boundaries and locations of individual properties can be found in the files residing at the agency responsible for such information.

Waiver of Liability


Although Banks Environmental Data uses its best efforts to research the actual location of each site, Banks Environmental Data does not and can not warrant the accuracy of these sites with regard to exact location and size. All authorized users of Banks Environmental Data services proceeding are signifying an understanding of Banks Environmental Data searching and mapping conventions, and agree to waive any and all liability claims associated with search and map results showing incomplete and or inaccurate site locations.



1 Mile Radius
ASTM Map: NPL, RCRACOR, STATE Sites



1126 TILLERY , AUSTIN TX 78702






.5 Mile Radius ASTM Map: CERCLIS, RCRATSD, LUST, SWL



1126 TILLERY , AUSTIN TX 78702




urce: 2005 U.S. Census TIGER Files		
Target Site (Latitude: 30,26864 Longitude: -97,70107)	0	-
identified Site, Multiple Sites, Receptor	83	elte.
IPL, DELNPL, Brownfield, Solid Waste Landfill (SWL), Hazardous Waste	188	
Triballand	881	
Kailroads		
lack Rings Represent 1/4 Mile Radius; Red Ring Represents 500 ft. Radius		



.25 Mile Radius ASTM Map: RCRAGEN, ERNS, UST



1126 TILLERY , **AUSTIN TX 78702**




urce: 2005 U.S. Census TIGER Files		
Target Site (Latitude: 30.26864 Longitude: -97.70107)	+	-
(dentified Site, Multiple Sites, Receptor	🔯	123
IPL, DELNPL, Brownfield, Solid Waste Landfill (SWL), Hazardous Was	te 🔯	
Triballand	1888	
Railroads	***	
Black Rings Represent 1/4 Mile Radius; Red Ring Represents 500 ft. Rai	dius	



.25 Mile Radius Non-ASTM Map: Other



1126 TILLERY , AUSTIN TX 78702






w e

Environmental FirstSearch

Topo : 1.00 Mile Radius Single Map



1126 TILLERY , AUSTIN TX 78702



φ Name: AUSTIN EAST Date Created: 1988— Date Revised: None-

3p Reference Code: 30097-C6-TF-024

miack Rings Represent 1/4 Mile Radii; Red Ring Represents 500 ft. Radius

Environmental FirstSearch Site Information Report

Request Date:

04-25-08

Requestor Name: Standard: Ashley Neve AAI Search Type: Job Number: COORD ES35165

Filtered Report

I HIGH

Target Site: 1126 TILLERY

AUSTIN TX 78702

Demographics

Sites:

23

Non-Geocoded: 10

10

Population:

NA

Radon: NA

Site Location

	Degrees (Decimal)	Degrees (Min/Sec)		<u>UTMs</u>	
Longitude:	-97.70107	-97:42:4	Easting:	624947.838	
Latitude:	30.26864	30:16:7	Northing:	3349086.339	
			Zone:	14	

Comment

Comment: TRAVIS COUNTY

Additional Requests/Services

Adjacent ZIP Codes: 1 Mile(s)				
ZIP Code	City Name	ST Dist/Dir Sel		
78721	AUSTIN	TX 0.27 NE Y		
78722	AUSTIN	TX 0.98 NW N		
78723	AUSTIN	TX 0.98 NW N		

Services:

	Requested?	Date
Sanborns	No	
Aerial Photographs	No	
Historical Topos	No	
City Directories	No	
Title Search/Env Liens	No	
Municipal Reports	No	
Online Topos	Yes	04-25-08

Environmental FirstSearch Selected Sites Summary Report

Target Property:

1126 TILLERY AUSTIN TX 78702

JOB: ES35165 TRAVIS COUNTY

TOTAL:

23

GEOCODED: 13

NON GEOCODED:

10

SELECTED:

23

Мар 🏗	DB Type	Site Name/ID/Status	Address	Dist/Dir	Page No.
	BROWNFIELD	GROVE LANDFILL/AUSTIN (NOW G20) G014/WITHDRAWAL	AUSTIN TX	NON GC	1
	ERNS	USAF 164588/FIXED FACILITY	FOUR SEASONS GARDEN SHOP AUSTIN TX	NON GC	2
1	LUST	FORMER AUSTIN ISD DE LEON CENTER 113293	1135 GUNTER AUSTIN TX 78701	0.23 SE	3
2	LUST	B and M TRANSMISSION 099911	1136 AIRPORT BLVD AUSTIN TX 78700	0.26 NE	6
3	LUST	DIAMOND SHAMROCK 84 115755	1140 AIRPORT BLVD AUSTIN TX 78702	0.28 NE	10
4	LUST	GOVALLE FOOD STORE 115047	1116 AIRPORT BLVD AUSTIN TX 78702	0,32 SE	14
5	LUST	MISSION PETROLEUM CARRIER 104573	1119 AIRPORT BLVD AUSTIN TX 78702	0,33 SE	17
7	LUST	EXXON 61683 093677	1149 1/2 AIRPORT BLVD AUSTIN TX 78762	0.38 NE	21
8	LUST	DOUBLE R I 112384	1149 AIRPORT BLVD AUSTIN TX 78702	0.39 NE	22
8	LUST	EXXON 61683 114391	1149 1/2 AIRPORT AUSTIN TX 78702	0.39 NE	26
9	LUST	JACK IN THE BOX 114839	1151 AIRPORT BLVD AUSTIN TX 78702	0.40 NE	32
1	OTHER	AUSTIN ISD IHW-72387/INACTIVE	1135 GUNTER ST AUSTIN TX 78702	0.23 SE	35
1	RCRAGN	AUSTIN ISD DELEON TXD981901655/VGN	1135 GUNTER AUSTIN TX 78702	0.23 SE	37
	SPILLS	GENERIC INCIDENT ZIP CODE 78702 72841/CLOSED	AUSTIN TX 78702	NON GC	38
	SPILLS	SBR PUMPING 8000/CLOSED	618 TILLERY ST AUSTIN TEXAS AUSTIN TX	NON GC	39
	SPILLS	SELLMAN PLUMBING AND SEPTIC TRANSF 45843/CLOSED	AUSTIN TX	NON GC	40
	SPILLS	SONIC DRIVE-IN 1379/CLOSED	AUSTIN TX	NON GC	41
	SPILLS	THOMAS C GREEN WATER 63245/CLOSED	AUSTIN TEXAS AUSTIN TX	NON GC	42
	SPILLS	ADVANCED MICRO DEVICES AMD LONE ST 82518/CLOSED	T AUSTIN TX	NON GC	43
	SPILLS	ALAMO CONCRETE PRODUCTS SOUTH PLA	и	NON GC	44
		62185/CLOSED	AUSTIN TX	11011 00	
	SWL	AUSTIN, CITY OF 42004	AUSTIN TX	NON GC	45

Environmental FirstSearch Selected Sites Summary Report

Target Property:

1126 TILLERY AUSTIN TX 78702

JOB: ES35165 TRAVIS COUNTY

TOTAL:

23

GEOCODED: 13

NON GEOCODED:

10

SELECTED:

23

Map ID	DB Type	Site Name/ID/Status	Address	Dist/Dir	Page No.
1	UST	AUSTIN ISD DELEON BUS TERMINAL 0048094	1135 GUNTER ST AUSTIN TX 78702	0.23 SE	46
6	VCP	AUSTIN COMMUNITY COLLEGE VCP-171/INVESTIGATION	3101 AND 3401 WEBBERVILLE R AUSTIN TX 78702	0.34 SW	49

Target Property:

1126 TILLERY

AUSTIN TX 78702

JOB: ES35165

TRAVIS COUNTY

BROWNFIELD

SEARCH ID: 23

DIST/DIR:

NON GC

MAP ID:

NAME: ADDRESS:

GROVE LANDFILL/AUSTIN (NOW G20)

A I ICPTUAL TOW

AUSTIN TX TRAVIS REV: ID1: ID2: 12/30/2006 G014

ID2: STATUS:

WITHDRAWAL

CONTACT:

PHONE:

BROWNFIELD PROGRAM SITE DETAILS

OTHER SITE IDENTIFIERS

TCEQ SWR NUMBER:

LPST NUMBER:

EPA TX ID/CERCLIS ID:

INSTITUTIONAL CONTROL:

STANDARD:

SITE INFORMATION

BF APP RECEIVED:

LEAD TYPE:

PROJECT MANAGER:

Owner Ellington

FACILITY TYPE:

Former Municipal Solid Waste Landfill

CONTAMINANT CATEGORIES:

MEDIA AFFECTED:

SIZE OF FACILITY:

acres

AGREEMENT DETAILS

CERT ISSUED DATE:

TYPE OF CERT:

TYPE OF REMEDY:

NOT REPORTED

BROWNFIELD APPLICANT INFORMATION

APPLICANT:

APP CONTACT:

APP TITLE:

APP ADDRESS:

APP ADDRESS2:

APP PHONE:

APP FAX:

APPLICANT ATTORNEY/CONSULTANT INFORMATION

ATTY/CONS COMPANY:

ATTY/CONS CONTACT:

ATTY/CONS TITLE:

ATTY/CONS ADDRESS:

APP ADDRESS2:

ATTY/CONS PHONE:

ATTY/CONS FAX:

Target Property:

1126 TILLERY

AUSTIN TX 78702

JOB: ES35165

TRAVIS COUNTY

E	ĸ	N	3

SEARCH ID:

DIST/DIR:

NON GC

MAP ID:

NAME:

CONTACT:

USAF

ADDRESS: FOUR SEASONS GARDEN SHOP

AUSTIN TX

TRAVIS

REV: ID1:

4/27/90 0: 164588

ID2: STATUS:

FIXED FACILITY

PHONE:

SPILL INFORMATION

DATE OF SPILL:

4/27/90

TIME OF SPILL:

1015

NO

PRODUCT RELEASED (1):

QUANTITY (1): UNITS (1):

PESTICIDES

UNK

PRODUCT RELEASED (2):

QUANTITY (2):

UNITS (2):

PRODUCT RELEASED (3):

QUANTITY (3): UNITS (3):

MEDIUM/MEDIA AFFECTED

AIR: LAND: NO YES GROUNDWATER: NO FIXED FACILITY: NO

WATER: NO WATERBODY AFFECTED BY RELEASE:

OTHER: NONE

CAUSE OF RELEASE

DUMPING: NATURAL PHENOMENON: OTHER CAUSE:

NO NO YES **EQUIPMENT FAILURE:** OPERATOR ERROR: TRANSP. ACCIDENT:

NO NO NO

DUN and BRADSTREET:

ACTIONS TAKEN:

UNKNOWN:

NO

CONTAINED ON-SITE-NO WATERWAYS AFFECTED.

RELEASE DETECTION: WATER FROM FIRE FIGHTING EFFORTS. FIRE IN WAREHOUSE

MISC. NOTES: **RUNOFF 3600-4000 GALL**

DISCHARGER INFORMATION

DISCHARGER ID: TYPE OF DISCHARGER: 164588

FEDERAL GOVERNMENT

NAME OF DISCHARGER: ADDRESS:

USAF

479-4100 AUSTIN TX

Selected Site Details Page - 2

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

LUST

SEARCH ID: 9

DIST/DIR:

0.23 SE

MAP ID:

1

NAME:

FORMER AUSTIN ISD DE LEON CENTER

ADDRESS: 1135 GUNTER

AUSTIN TX 78701

TRAVIS CONTACT: FRED FILLEY REV: D1: ID2:

02/27/07 113293 0048094

STATUS: PHONE:

512/414-2375

SITE INFORMATION

REPORTED:

ENTERED INTO SYSTEM:

SITE PRIORITY:

SITE STATUS:

PRP: PRP ADDRESS:

PRP CONTACT: PRP PHONE:

6/19/1998 6/26/1998

assessment incomplete, no apparent receptors impacted

Final concurrence issued, case close

AUSTIN ISD

1111 W 6TH ST BLDG C 230

AUSTIN TX 78703 FRED FILLEY 512/414-2375

LUST INFORMATION

TANK NUMBER:

STATUS: Removed From Ground

STATUS DATE: 06151998 INSTALL DATE: 01011960 REGISTERED DATE: 03281989 0010000 Gallons CAPACITY:

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL: CORROSION PROTECTION:

CORROSION PROT VARIANCE: STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE: PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE:

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE:

PIPE RLSE DETECTION METHODS: PIPE RLSE VARIANCE: SPILL/OVERFILL PREVENTION:

GASOLINE

No Variance

- None

- None

No Variance

Not Reported

- - - Inventory Control

No Variance - - - None No Variance

SPILL/OVERFILL VARIANCE: No Variance

Target Property:

1126 TILLERY **AUSTIN TX 78702**

JOB: ES35165 TRAVIS COUNTY

LUST

SEARCH ID: 9

DIST/DIR:

0.23 SE

MAP ID:

NAME:

FORMER AUSTIN ISD DE LEON CENTER

ADDRESS: 1135 GUNTER

AUSTIN TX 78701

TRAVIS CONTACT: FRED FILLEY

ID1: ID2: STATUS:

REV:

02/27/07 113293 0048094

512/414-2375

TANK NUMBER:

STATUS:

STATUS DATE: **INSTALL DATE:** REGISTERED DATE:

CAPACITY:

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL:

CORROSION PROTECTION:

CORROSION PROT VARIANCE: STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY: INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE: PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE:

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE:

PIPE RLSE DETECTION METHODS: PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE:

TANK NUMBER: STATUS:

STATUS DATE: 06151998 01011960 INSTALL DATE: REGISTERED DATE: 03281989 CAPACITY:

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL: CORROSION PROTECTION:

CORROSION PROT VARIANCE: STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE: STG 2 VAPOR RECOVERY EQUIP STATUS: PHONE:

06151998 01011960 03281989 0010000 Gallons

Removed From Ground

- None

No Variance Not Reported

- None No Variance

DIESEL

- - - Inventory Control

No Variance - - None No Variance

No Veriance

Removed From Ground

0004000 Gallons

- None No Variance Not Reported

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

LUUL	Ι	J	JS	1	
------	---	---	----	---	--

SEARCH ID: 9

DIST/DIR:

0.23 SE

MAP ID:

NAME:

FORMER AUSTIN ISD DE LEON CENTER

ADDRESS: 1135 GUNTER

AUSTIN TX 78701

TRAVIS

CONTACT: FRED FILLEY

REV: ID1:

02/27/07 113293

ID2: STATUS: 0048094

PHONE:

512/414-2375

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS and VALVES:

PIPE CORROSION PROTECTION:

- None

PIPE CORROSION PROT VARIANCE:

No Variance

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS:

TANK RLSE DETECTION VARIANCE:

PIPE RLSE DETECTION METHODS: PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE:

GASOLINE

- - - Inventory Control

No Variance - - - None

No Variance

No Variance

Target Property:

1126 TILLERY AUSTIN TX 78702 JOB: ES35165

TRAVIS COUNTY

LUST

SEARCH ID: 4

DIST/DIR:

0.26 NE

MAP ID:

2

NAME:

B and M TRANSMISSION ADDRESS: 1136 AIRPORT BLVD

AUSTIN TX 78700

TRAVIS

CONTACT: STEVE MCANGUS

REV: TD1:

02/27/07 099911

ID2: STATUS: PHONE:

0060445

512/328-9302

SITE INFORMATION

REPORTED:

ENTERED INTO SYSTEM:

SITE PRIORITY:

SITE STATUS: PRP:

PRP ADDRESS:

PRP CONTACT: PRP PHONE:

8/6/1991

gw impacted, no apparent threats or impacts to receptors

Final concurrence pending documentation of well plugging

MCANGUS INVESTMENTS

4501 PLACID PL **AUSTIN TX 78731** STEVE MCANGUS 512/328-9302

Removed From Ground

04291988

10091991

Steel

- None

No Variance

Not Reported

0003000 Gallons

LUST INFORMATION

TANK NUMBER:

STATUS:

STATUS DATE:

INSTALL DATE:

REGISTERED DATE: CAPACITY:

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL:

CORROSION PROTECTION:

CORROSION PROT VARIANCE:

STG 1 VAPOR RECOVERY EQUIP STATUS: STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME: INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE:

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS: PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE:

Steel

- None No Variance

GASOLINE

- - - None No Variance - - - None

No Variance

No Variance

Target Property:

1126 TILLERY **AUSTIN TX 78702** **JOB:** ES35165 TRAVIS COUNTY

	LUST					
SEARCH ID: 4	DIST/DIR:	0.26 NE	MAP ID:	2		
NAME: B and M TRANSMISSION		Th 17% 7.	00.000			
ADDRESS: 1136 AIRPORT BLVD		REV: ID1:	02/27/07 099911			
AUSTIN TX 78700			0060445			
TRAVIS		ID2: STATUS:	0000443			
CONTACT: STEVE MCANGUS		PHONE:	512/328-9302			
A RIVE NICE OF THE PARTY OF THE	3					
ANK NUMBER:	_					
TATUS:	Removed From Ground					
TATUS DATE:	04291988					
NSTALL DATE:	•					
REGISTERED DATE:	10091991					
CAPACITY:	0003000 Gallons					
EXT CONTAINMENT DESIGN:	•					
CONSTRUCTION MATERIAL:	Steel					
CORROSION PROTECTION:						
	- None					
CORROSION PROT VARIANCE:	No Variance					
STG 1 VAPOR RECOVERY EQUIP STATUS:	Not Reported					
STG 1 EQUIP INSTALL DATE:						
TTG 2 VAPOR RECOVERY EQUIP STATUS:						
TG 2 EQUIP INSTALL DATE:						
NOTE A LEG CORENA NA						
NSTALLER COMPANY:						
NSTALLER NAME:						
NSTALLER LICENSE NUMBER:						
TYPE OF PIPE:						
PIPE MATERIAL:	Steel					
PIPE DESIGN EXT CONTAINMENT:						
PIPE CONECTORS and VALVES:						
PIPE CORROSION PROTECTION:	~					
PIPE CORROSION PROT VARIANCE:	- None No Veriance					
	110 14111100					
SUBSTANCE STORED:	GASOLINE					
TANK RLSE DETECTION METHODS:	None					
TANK RLSE DETECTION VARIANCE:	No Variance					
PIPE RLSE DETECTION METHODS:	None					
PIPE RLSE VARIANCE:	No Variance					
SPILL/OVERFILL PREVENTION:						
SPILL/OVERFILL VARIANCE:	No Variance					
TANK NUMBER:	5					
STATUS:	Removed From Ground					
STATUS DATE:	07021991					
NSTALL DATE:						
REGISTERED DATE:	10091991					
CAPACITY:	0000500 Gallons					
XT CONTAINMENT DESIGN:	AND					
MI COMMUNICATI DESIGN:	-					
CONSTRUCTION MATERIAL:	Steel					
CORROSION PROTECTION:	-					
	- None					
CORROSION PROT VARIANCE:	No Variance					
STG 1 VAPOR RECOVERY EQUIP STATUS:	Not Reported					
STG 1 EQUIP INSTALL DATE:	-					
STG 2 VAPOR RECOVERY EQUIP STATUS:						
		- 0	Continued on next page -			

Target Property:

1126 TILLERY AUSTIN TX 78702

JOB: ES35165 TRAVIS COUNTY

-	AUSTIN 12		TRAVIS (
		LUST					
SEARCH ID:	4	DIST/DIR:	0.26 NE		MAP ID:	2	
ADDRESS: 1136 AUS TRA			REV: ID1: ID2: STATUS:	02/27/07 099911 0060445			
CONTACT: STE	VE MCANGUS		PHONE:	512/328-9	302		
TG 2 EQUIP INS	TALL DATE:						
INSTALLER CON INSTALLER NAM INSTALLER LIC	Œ:						
YPE OF PIPE:		O. 1					
PIPE MATERIAL PIPE DESIGN EX	: T CONTAINMENT:	Steel					
PIPE CONECTOR		• •					
PIPE CORROSIO	N PROTECTION:	- Mana					
PIPE CORROSIO	N PROT VARIANCE:	- None No Variance					
SUBSTANCE STO	ORED:	USED OIL					
ANK RLSE DET	ECTION METHODS:	None					
	ECTION VARIANCE:	No Variance					
'IPE RLSE DETE 'IPE RLSE VARI	CTION METHODS:	None No Variance					
	L PREVENTION:						
PILL/OVERFIL		No Variance					
•							
TANK NUMBER:		2					
STATUS:		Removed From Ground					
TATUS DATE:		04291988					
INSTALL DATE: REGISTERED DA	ATTE.	10091991					
CAPACITY:	ME:	0003000 Gallons					
EXT CONTAINM	ENT DESIGN:	-					
		-					
CONSTRUCTION		Steel					
CORROSION PRO	UTECTION:	- None					
CORROSION PRO	OT VARIANCE:	No Variance					
	COVERY EQUIP STATUS:	Not Reported					
STG 1 EQUIP INS							
STG 2 VAPOR RE STG 2 EOUIP INS	COVERY EQUIP STATUS:						
ord a regular me	TALL DATE:						
INSTALLER CON							
NSTALLER NAM							
NO LALLEK LİÇ	ENSE NUMBER:						
TYPE OF PIPE:							
PIPE MATERIAL		Steel					
	T CONTAINMENT:	-					
PIPE CONECTOR	S and VALVES: N PROTECTION:						
II E CORROSIO	TA A MOREOURN	- - None					
PIPE CORROSIO	N PROT VARIANCE:	No Variance					
		a					
SUBSTANCE STO	RED:	GASOLINE					

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165 TRAVIS COUNTY

		T TOO							
LUST									
SEARCH ID: 4	DIST/DIR:	0.26 NE	MAP ID: 2						
NAME: B and M TRANSMISSION		REV:	02/27/07						
DDRESS: 1136 AIRPORT BLVD		ID1:	099911						
AUSTIN TX 78700		ID2:	0060445						
TRAVIS		STATUS:							
CONTACT: STEVE MCANGUS		PHONE:	512/328-9302						
ANK RLSE DETECTION METHODS:	None								
ANK RISE DETECTION VARIANCE:	No Variance								
IPE RLSE DETECTION METHODS:	None								
IPE RLSE VARIANCE: PILL/OVERFILL PREVENTION:	No Variance								
PILL/OVERFILL VARIANCE:	No Variance								
ANK NUMBER:	1								
TATUS:	Removed From Ground								
TATUS DATE:	04291988								
NSTALL DATE:									
EGISTERED DATE:	10091991								
APACITY:	0003000 Gallons								
XT CONTAINMENT DESIGN:	•								
	-								
CONSTRUCTION MATERIAL:	Steel								
CORROSION PROTECTION:	-								
	- None								
CORROSION PROT VARIANCE:	No Variance								
TG 1 VAPOR RECOVERY EQUIP STATUS:	Not Reported								
TG 1 EQUIP INSTALL DATE:									
TG 2 VAPOR RECOVERY EQUIP STATUS:									
TG 2 EQUIP INSTALL DATE:									
NSTALLER COMPANY:									
NSTALLER NAME:									
NSTALLER LICENSE NUMBER:									
YPE OF PIPE:									
PIPE MATERIAL:	Steel								
PIPE DESIGN EXT CONTAINMENT:	-								
PIPE CONECTORS and VALVES:									
PIPE CORROSION PROTECTION:	- N								
PIPE CORROSION PROT VARIANCE:	- None No Variance								
HE CORROSION I ROT VARIANCE:	140 AURITRE								
UBSTANCE STORED:	GASOLINE								
TANK RUSE DETECTION METHODS:	None								
ANK RISE DETECTION VARIANCE:	No Variance								
IPE RLSE DETECTION METHODS:	None								
TPE RLSE VARIANCE:	No Variance								
PILL/OVERFILL PREVENTION:									
SPILL/OVERFILL VARIANCE:	No Variance								

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

LUST

SEARCH ID: 5

DIST/DIR:

0.28 NE

MAP ID:

3

NAME:

DIAMOND SHAMROCK 84 ADDRESS: 1140 AIRPORT BLVD

AUSTIN TX 78702

TRAVIS

CONTACT: C SHAY WIDEMAN

REV: ID1:

02/27/07 115755 0045188

ID2: STATUS: PHONE:

210/592-4663

SITE INFORMATION

REPORTED:

ENTERED INTO SYSTEM:

SITE PRIORITY:

SITE STATUS: PRP:

PRP ADDRESS:

PRP CONTACT: PRP PHONE:

6/11/2003

gw impacted, no apparent threats or impacts to receptors

monitoring

DIAMOND SHAMROCK REF and MKTG CO

PO BOX 696000

SAN ANTONIO TX 78269

LUST INFORMATION

TANK NUMBER:

STATUS:

STATUS DATE:

INSTALL DATE:

REGISTERED DATE: CAPACITY:

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL: CORROSION PROTECTION:

CORROSION PROT VARIANCE:

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE:

SUBSTANCE STORED: TANK RLSE DETECTION METHODS:

TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS:

Inventory Cntrl - - Tightness Testing PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION:

Container/Bucket/Sump SPILL/OVERFILL VARIANCE:

C SHAY WIDEMAN

210/592-4663

Removed From Ground

09262002 01011972 10081987 0006045 Gallons

Single Wall -

Steel

Cathodic Protection-Field Installed -

- Cathodic Protection

No Variance

Two-Point System or Coaxial System

Pressurizes

Fiberglass Reinforced Plastic (FRP)

Shear/Impact Valves (Under Despenser) - Steel Swing Joints (At Ends of Piping) -FRP Tank or Piping (Noncorrodible) - Ext Dielectric Coating/Laminate/Tape/Wrap

- Non Corrodible Material

No Variance

GASOLINE

SIR (Stat. Inventory Reonciliation) and Inventory Cntrl - - - Tightness Testing

Auto Leak Line Detector (3.0gph for pressure piping) - SIR (Stat. Inventory Reconciliation) and

No Variance

Auto Flow Restrictor Valve (AFRV) - Auto Delivery Shut Off Valve (ADSV) - Factory Built Spill

No Variance

Target Property:

1126 TILLERY

AUSTIN TX 78702

JOB: ES35165 TRAVIS COUNTY

LUST

SEARCH ID: 5

DIST/DIR:

0.28 NE

MAP ID:

3

NAME:

DIAMOND SHAMROCK 84 ADDRESS: 1140 AIRPORT BLVD

AUSTIN TX 78702

TRAVIS

CONTACT: C SHAY WIDEMAN

REV: ID1: ID2:

02/27/07 115755

0045188

STATUS: PHONE:

210/592-4663

TANK NUMBER:

STATUS:

STATUS DATE: INSTALL DATE: REGISTERED DATE:

CAPACITY:

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL:

CORROSION PROTECTION:

CORROSION PROT VARIANCE: **STG 1 VAPOR RECOVERY EQUIP STATUS:**

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EOUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS and VALVES:

PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE:

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE:

PIPE RLSE DETECTION METHODS:

Inventory Cutrl - - Tightness Testing

PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION:

Container/Bucket/Sump

SPILL/OVERFILL VARIANCE:

01011972 10081987

0004006 Gallons

09262002

Single Wall -

Steel

Cathodic Protection-Field Installed -

- Cathodic Protection

Removed From Ground

No Variance

Two-Point System or Coaxial System

Pressurizes

Fiberglass Reinforced Plastic (FRP)

Single Wall -

Shear/Impact Valves (Under Despenser) - Steel Swing Joints (At Ends of Piping) -

FRP Tank or Piping (Noncorrodible) - Ext Dielectric Coating/Laminate/Tape/Wrap

- Non Corrodible Material No Variance

SIR (Stat. Inventory Reonciliation) and Inventory Cntrl - - - Tightness Testing

No Variance

Auto Leak Line Detector (3.0gph for pressure piping) - SIR (Stat. Inventory Reconciliation) and

Auto Flow Restrictor Valve (AFRV) - Auto Delivery Shut Off Valve (ADSV) - Factory Built Spill

No Veriance

TANK NUMBER:

STATUS:

STATUS DATE: INSTALL DATE: REGISTERED DATE:

CAPACITY: EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL: CORROSION PROTECTION:

Removed From Ground

09262002 01011972 10081987 0004006 Gallons

Single Wall -

Steel

Cathodic Protection-Field Installed -

- Cathodic Protection

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

LUST

SEARCH ID: 5

DIST/DIR:

0.28 NE

MAP ID:

NAME: ADDRESS:

DIAMOND SHAMROCK 84 1140 AIRPORT BLVD

AUSTIN TX 78702

TRAVIS CONTACT: C SHAY WIDEMAN ID1: ID2:

REV:

02/27/07 115755 0045188

STATUS: PHONE:

210/592-4663

CORROSION PROT VARIANCE:

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

No Variance

Two-Point System or Coaxial System

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE:

SUBSTANCE STORED:

TANK RISE DETECTION METHODS: TANK RLSE DETECTION VARIANCE:

PIPE RLSE DETECTION METHODS:

Inventory Cntrl - - Tightness Testing

PIPE RLSE VARIANCE: SPILL/OVERFILL PREVENTION:

Container/Bucket/Sump

SPILL/OVERFILL VARIANCE:

Pressurizes

Fiberglass Reinforced Plastic (FRP)

Single Wall -

Shear/Impact Valves (Under Despenser) - Steel Swing Joints (At Ends of Piping) -FRP Tank or Piping (Noncorrodible) - Ext Dielectric Coating/Laminate/Tape/Wrap

- Non Corrodible Material

No Variance

GASOLINE

SIR (Stat. Inventory Reonciliation) and Inventory Cntrl - - - Tightness Testing

No Variance

Auto Leak Line Detector (3.0gph for pressure piping) - SIR (Stat. Inventory Reconciliation) and

No Variance

No Variance

Auto Flow Restrictor Valve (AFRV) - Auto Delivery Shut Off Valve (ADSV) - Factory Built Spill

TANK NUMBER:

STATUS:

STATUS DATE: INSTALL DATE:

REGISTERED DATE:

CAPACITY: EXT CONTAINMENT DESIGN: Removed From Ground

09262002 01011972 10081987

0009994 Gallons Single Wall -

CONSTRUCTION MATERIAL: CORROSION PROTECTION:

Cathodic Protection-Field Installed -

Two-Point System or Coaxial System

- Cathodic Protection No Variance

CORROSION PROT VARIANCE:

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL: PIPE DESIGN EXT CONTAINMENT: Pressurizes

Fiberglass Reinforced Plastic (FRP)

Single Wall -

Target Property:

1126 TILLERY AUSTIN TX 78702 JOB: ES35165
TRAVIS COUNTY

1	I	J	S	7	Γ

SEARCH ID: 5

DIST/DIR:

0.28 NE

MAP ID:

3

NAME:

DIAMOND SHAMROCK 84

ADDRESS: 1140 AIRPORT BLVD AUSTIN TX 78702

TRAVIS

CONTACT: C SHAY WIDEMAN

REV: ID1: 02/27/07 115755

ID2;

0045188

STATUS: PHONE:

210/592-4663

PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION:

Shear/Impact Valves (Under Despenser) - Steel Swing Joints (At Ends of Piping) - Ext Dielectric Coating/Laminate/Tape/Wrap - FRP Tank or Piping (Noncorrodible)

- Non Corrodible Material

No Variance

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE:

PIPE CORROSION PROT VARIANCE:

PIPE RLSE DETECTION METHODS:

Inventory Cntrl - - Tightness Testing

PIPE RLSE VARIANCE: SPILL/OVERFILL PREVENTION:

Container/Bucket/Summ

SPILL/OVERFILL VARIANCE:

GASOLINE

SIR (Stat. Inventory Reonciliation) and Inventory Cntrl - - - Tightness Testing

No Variance

Auto Leak Line Detector (3.0gph for pressure piping) - SIR (Stat. Inventory Reonciliation) and

No Variance

Auto Flow Restrictor Valve (AFRV) - Auto Delivery Shut Off Valve (ADSV) - Factory Built Spill

No Variance

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

T	т	т	C.	41	
L	J١	J	o	1	

SEARCH ID:

DIST/DIR:

0.32 SE

MAP ID:

4

NAME:

GOVALLE FOOD STORE ADDRESS: 1116 AIRPORT BLVD

AUSTIN TX 78702

TRAVIS

CONTACT: SULTANALIS MOMÍN

REV: ID1: ID2:

02/27/07 115047 0066096

STATUS:

PHONE:

512/926-4961

SITE INFORMATION

REPORTED:

ENTERED INTO SYSTEM:

SITE PRIORITY:

SITE STATUS:

PRP: PRP ADDRESS:

PRP CONTACT: PRP PHONE:

9/20/2000

gw impacted, no apparent threats or impacts to receptors

GOVALLE FOOD STORE **AUSTIN TX 78702**

512/926-4961

LUST INFORMATION

TANK NUMBER:

STATUS: STATUS DATE:

INSTALL DATE: REGISTERED DATE: CAPACITY:

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL: CORROSION PROTECTION:

CORROSION PROT VARIANCE: STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE: PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE:

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS:

PIPE RLSE VARIANCE: SPILL/OVERFILL PREVENTION:

SPILL/OVERFILL VARIANCE:

monitoring

1116 AIRPORT BLVD

SULTANALI S MOMIN

Removed From Ground

07242002 00000000 10261994 0010000 Gallons Single Wall -

Steel

No Variance

Not Reported

Suction Steel

No Variance

GASOLINE

No Variance

No Variance

No Variance

Target Property:

1126 TILLERY AUSTIN TX 78702 JOB: ES35165
TRAVIS COUNTY

512/926-4961

STATUS:

PHONE:

	L	UST			
SEARCH ID: 10	DIST/DIR:	0.32 SE		MAP ID:	4
NAME: GOVALLE FOOD STORE ADDRESS: 1116 AIRPORT BLVD AUSTIN TX 78702		REV: ID1: ID2:	02/27/07 115047 0066096		

TRAVIS
CONTACT: SULTANALI S MOMIN

NIZ NIIMBED.

TANK NUMBER: 2
STATUS: Removed From Ground
STATUS DATE: 07242002
INSTALL DATE: 00000000
REGISTERED DATE: 10261994
CAPACITY: 0006000 Gallons
EXT CONTAINMENT DESIGN: Single Wall -

CONSTRUCTION MATERIAL: Steel CORROSION PROTECTION:

CORROSION PROT VARIANCE:
STG 1 VAPOR RECOVERY EQUIP STATUS:
Not Reported
STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

 ${\bf STG~2~EQUIP~INSTALL~DATE:}$

INSTALLER COMPANY: INSTALLER NAME: INSTALLER LICENSE NUMBER:

TYPE OF PIPE: Suction
PIPE MATERIAL: Steel
PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS and VALVES: - PIPE CORROSION PROTECTION: -

PIPE CORROSION PROT VARIANCE: No Variance

SUBSTANCE STORED:
TANK RISE DETECTION METHODS:
TANK RISE DETECTION VARIANCE:
PIPE RISE DETECTION METHODS:
PIPE RISE VARIANCE:
No Variance
SPILL/OVERFILL PREVENTION:
SPILL/OVERFILL VARIANCE:
No Variance

TANK NUMBER: 3
STATUS: Removed From Ground
STATUS DATE: 07242002

| 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002 | 17242002

CONSTRUCTION MATERIAL: Steel CORROSION PROTECTION:

CORROSION PROT VARIANCE: No Variance STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

Target Property:

1126 TILLERY AUSTIN TX 78702

No Variance

JOB: ES35165

512/926-4961

TRAVIS COUNTY

PHONE:

LUST						
SEARCH	ID: 10	DIST/DIR:	0.32 SE	MAP ID:	4	
NAME: ADDRESS:	GOVALLE FOOD STORE 1116 AIRPORT BLVD AUSTIN TX 78702 TRAVIS		REV: ID1: ID2: STATUS:	02/27/07 115047 0066096		

STG 2 EQUIP INSTALL DATE:

CONTACT: SULTANALIS MOMIN

INSTALLER COMPANY: INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE: Suction
PIPE MATERIAL: Steel
PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION: -

PIPE CORROSION PROT VARIANCE:

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS:
TANK RLSE DETECTION VARIANCE:
PIPE RLSE DETECTION METHODS:
PIPE RLSE VARIANCE:
SPILL/OVERFILL PREVENTION:
SPILL/OVERFILL VARIANCE:
No Variance
No Variance

Target Property:

1126 TILLERY **AUSTIN TX 78702**

JOB: ES35165 TRAVIS COUNTY

LUST

SEARCH ID: 12 DIST/DIR:

0.33 SE

MAP ID:

5

NAME:

MISSION PETROLEUM CARRIER

ADDRESS: 1119 AIRPORT BLVD

AUSTIN TX 78721

TRAVIS

CONTACT: JOLENE FERGUSON

REV: ID1:

02/27/07 104573 0053881

ID2: STATUS:

PHONE:

281/836-1485

SITE INFORMATION

REPORTED:

ENTERED INTO SYSTEM:

SITE PRIORITY: SITE STATUS:

PRP: PRP ADDRESS:

PRP CONTACT: PRP PHONE:

9/10/1992 9/16/1992

gw impacted, no apparent threats or impacts to receptors

Final concurrence issued, case close TEXACO REFINING AND MARKETING 16800 GREENSPOINT PK STE 215 S

HOUSTON TX 77060 JOLENE FERGUSON

Removed From Ground

281/836-1485

12141992

01011978

05291990 0002000 Gallons

No Variance

Not Reported

LUST INFORMATION

TANK NUMBER:

STATUS: STATUS DATE:

INSTALL DATE: REGISTERED DATE: CAPACITY:

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL:

CORROSION PROTECTION:

Steel - None

CORROSION PROT VARIANCE: STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE: PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION:

- None No Variance

PIPE CORROSION PROT VARIANCE:

Empty

Steel

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS: PIPE RLSE VARIANCE:

No Variance - - - None No Variance

- - - None

SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE:

No Variance

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

L	UST	

SEARCH ID: 12

DIST/DIR:

0.33 SE

MAP ID:

5

NAME:

MISSION PETROLEUM CARRIER

ADDRESS: 1119 AIRPORT BLVD

AUSTIN TX 78721 TRAVIS

CONTACT: JOLENE FERGUSON

REV: ID1:

02/27/07 104573 0053881

STATUS:

PHONE:

281/836-1485

TANK NUMBER:

STATUS:

Removed From Ground

STATUS DATE: **INSTALL DATE:** REGISTERED DATE:

01011978 05291990

12141992

CAPACITY: EXT CONTAINMENT DESIGN: 0004000 Gallons

CONSTRUCTION MATERIAL: CORROSION PROTECTION:

Steel

CORROSION PROT VARIANCE: STG 1 VAPOR RECOVERY EQUIP STATUS:

- Nane No Veriance Not Reported

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME: INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL: PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION:

- None

Steel

PIPE CORROSION PROT VARIANCE:

No Variance

SUBSTANCE STORED: TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS:

- - - None No Variance - - - None No Variance

PIPE RLSE VARIANCE: SPILL/OVERFILL PREVENTION:

No Variance SPILL/OVERFILL VARIANCE:

TANK NUMBER:

STATUS:

STATUS DATE: **INSTALL DATE:** REGISTERED DATE: CAPACITY:

Removed From Ground 12141992

01011978 05291990 0003000 Gallons

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL: CORROSION PROTECTION:

Steel - None

No Variance

Not Reported

CORROSION PROT VARIANCE:

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

Target Property: 1126 TILLE AUSTIN TX		TRAVIS	JOB: ES35165 COUNTY	
	L	UST		
SEARCH ID: 12	DIST/DIR:	0.33 SE	MAP ID:	5
NAME: MISSION PETROLEUM CARRIER ADDRESS: 1119 AIRPORT BLVD AUSTIN TX 78721 TRAVIS CONTACT: JOLENE FERGUSON		REV: ID1: ID2: STATUS: PHONE:	02 <i>J</i> 27 <i>I</i> 07 104573 0053881 281/836-1485	
STG 2 EQUIP INSTALL DATE: INSTALLER COMPANY: INSTALLER NAME: INSTALLER LICENSE NUMBER: TYPE OF PIPE: PIPE MATERIAL: PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION: PIPE CORROSION PROT VARIANCE: SUBSTANCE STORED: TANK RLSE DETECTION METHODS: TANK RLSE DETECTION METHODS: PIPE RLSE DETECTION METHODS: PIPE RLSE DETECTION METHODS: PIPE RLSE VARIANCE:	Steel None No Variance Empty None No Variance None No Variance			
SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE: TANK NUMBER: STATUS:	No Variance 4 Removed From Ground			
STATUS DATE:	00000000			

INSTALL DATE: REGISTERED DATE:

05291990 0000550 Gallons CAPACITY: EXT CONTAINMENT DESIGN: Single Wall -

CONSTRUCTION MATERIAL: Steel CORROSION PROTECTION: - None

CORROSION PROT VARIANCE: No Variance STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported

STG 1 EQUIP INSTALL DATE: STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY: INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE: Gravity Steel PIPE MATERIAL: Single Wall -PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS and VALVES:

PIPE CORROSION PROTECTION:

- None No Variance PIPE CORROSION PROT VARIANCE:

SUBSTANCE STORED: **Empty**

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

LUST	•
------	---

SEARCH ID: 12 DIST/DIR:

0.33 SE

MAP ID:

5

NAME:

MISSION PETROLEUM CARRIER

ADDRESS: 1119 AIRPORT BLVD

AUSTIN TX 78721

TRAVIS

CONTACT: JOLENE FERGUSON

REV: ID1:

02/27/07 104573 0053881

ID2: STATUS:

PHONE:

281/836-1485

TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE:

PIPE RLSE DETECTION METHODS: PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE:

- - - None No Variance - - - None

No Variance

No Variance

Target Property:

1126 TILLERY AUSTIN TX 78702 JOB: ES35165

TRAVIS COUNTY

LUST

SEARCH ID: 8

DIST/DIR:

0.38 NE

MAP ID:

7

NAME:

EXXON 61683

ADDRESS: 1149 1/2 AIRPORT BLVD

AUSTIN TX 78762

TRAVIS

CONTACT: ERNIE VILLASENOR

REV: ID1: 02/27/07 093677 0026033

ID2: STATUS:

.

PHONE:

713/656-7701

SITE INFORMATION

REPORTED:

ENTERED INTO SYSTEM:

SITE PRIORITY:

SITE STATUS: PRP:

PRP ADDRESS:

PRP CONTACT:

9/8/1989

10/9/1989

gw impacted, no apparent threats or impacts to receptors

Final concurrence issued, case close

EXXON CO USA PO BOX 2180

HOUSTON TX 77252 ERNIE VILLASENOR

PRP PHONE: 713/656-7701

LUST INFORMATION

Target Property:

1126 TILLERY AUSTIN TX 78702 JOB: ES35165

TRAVIS COUNTY

LUST

SEARCH ID: 6

DIST/DIR:

0.39 NE

MAP ID:

8

NAME:

DOUBLE R I

ADDRESS: 1149 AIRPORT BLVD

AUSTIN TX 78702

TRAVIS
CONTACT: GUY OLIVER

TN TX 78702 7IS

ID2: STATUS: PHONE:

REV:

TD1:

112384 0019610

02/27/07

512/457-1977

SITE INFORMATION

REPORTED:

ENTERED INTO SYSTEM:

SITE PRIORITY:

SITE STATUS: PRP:

PRP ADDRESS:

PRP CONTACT: PRP PHONE:

6/11/1997 6/17/1997

gw impacted, no apparent threats or impacts to receptors

Final concurrence issued, case close STARTEX PETROLEUM INC

201 W STASSNEY LN AUSTIN TX 78745 GUY OLIVER 512/457-1977

LUST INFORMATION

TANK NUMBER: STATUS: STATUS DATE:

INSTALL DATE:
REGISTERED DATE:

CAPACITY: EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL: CORROSION PROTECTION: 01011981

No Variance

Exempt by TNRCC Rule

In Use

0012000 Gallons Single Wall -

Steel

CORROSION PROTECTION.

Cathodic Protection-Field Installed -

CORROSION PROT VARIANCE:

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

Pressurizes

Fiberglass Reinforced Plastic (FRP)

PIPE CONFECTORS and VALVES

PIPE CORROSION PROT VARIANCE:

PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION:

Single Wall Shear/Impact Valves (Under Despenser) - Steel Swing Joints (At Ends of Piping) Cathodic Protection-Field Installed - FRP Tank or Piping (Noncorrodible)

-No Variance

SUBSTANCE STORED:

GASOLINE
SIR (Stat. Inventory Reconciliation) and Inventory Cntrl - - -

TANK RLSE DETECTION METHODS:

TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS:

No Variano

Auto Leak Line Detector (3.0gph for pressure piping) - SIR (Stat. Inventory Reonciliation) and

Inventory Cntrl - -

PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION:

No Variance

Auto Flow Restrictor Valve (AFRV) - Factory Built Spill Container/Bucket/Sump - Tight - Fill

Fitting

SPILL/OVERFILL VARIANCE:

No Variance

Target Property:

1126 TILLERY **AUSTIN TX 78702**

JOB: ES35165 TRAVIS COUNTY

LUST						
SEARCH ID: 6	DIST/DIR:	0.39 NE	MAP ID:	8		
NAME: DOUBLE R 1 ADDRESS: 1149 AIRPORT BLVD		REV: ID1:	02/27/07 112384			
AUSTIN TX 78702 TRAVIS CONTACT: GUY OLIVER		ID2: STATUS: PHONE:	0019610 512/457-1977			

TANK NUMBER: STATUS:

In Use STATUS DATE: 01011981 **INSTALL DATE:** 05081986 REGISTERED DATE: 0012000 Gallons CAPACITY: Single Wall -EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL: Steel

CORROSION PROTECTION: Cathodic Protection-Field Installed -

CORROSION PROT VARIANCE: No Variance

STG 1 VAPOR RECOVERY EQUIP STATUS: **Exempt by TNRCC Rule**

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY: INSTALLER NAME: INSTALLER LICENSE NUMBER:

TYPE OF PIPE: Pressurizes

Fiberglass Reinforced Plastic (FRP) PIPE MATERIAL: PIPE DESIGN EXT CONTAINMENT: Single Wall -

Shear/Impact Valves (Under Despenser) - Steel Swing Joints (At Ends of Piping) -PIPE CONECTORS and VALVES: FRP Tank or Piping (Noncorrodible) - Cathodic Protection-Field Installed PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE: No Variance

SUBSTANCE STORED: SIR (Stat. Inventory Reconciliation) and Inventory Cntrl - - -TANK RLSE DETECTION METHODS:

TANK RLSE DETECTION VARIANCE: No Variance Auto Leak Line Detector (3.0gph for pressure piping) - SIR (Stat. Inventory Reonciliation) and PIPE RLSE DETECTION METHODS:

Inventory Cutrl - -PIPE RLSE VARIANCE:

Auto Flow Restrictor Valve (AFRV) - Factory Built Spill Container/Bucket/Sump - Tight - Fill SPILL/OVERFILL PREVENTION:

Fitting

SPILL/OVERFILL VARIANCE: No Variance

TANK NUMBER: In Use STATUS: STATUS DATE:

01011981 INSTALL DATE: 05081986 REGISTERED DATE: 0006000 Gallons CAPACITY: EXT CONTAINMENT DESIGN: Single Wall -

Steel CONSTRUCTION MATERIAL:

Cathodic Protection-Field Installed -CORROSION PROTECTION:

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

02/27/07

112384

0019610

512/457-1977

TRAVIS COUNTY

LUST

SEARCH ID:

DIST/DIR:

0.39 NE

REV:

TD1:

II12:

STATUS:

PHONE:

MAP ID:

8

NAME:

DOUBLE R 1

ADDRESS: 1149 AIRPORT BLVD **AUSTIN TX 78702**

TRAVIS

CONTACT: GUY OLIVER

CORROSION PROT VARIANCE:

No Variance Exempt by TNRCC Rule

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS: STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME: INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS and VALVES:

PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE:

SUBSTANCE STORED:

TANK RISE DETECTION METHODS:

TANK RLSE DETECTION VARIANCE:

PIPE RLSE DETECTION METHODS:

Inventory Cutrl - -

PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION:

Fitting

SPILL/OVERFILL VARIANCE:

Pressurizes

Fiberplass Reinforced Plastic (FRP)

Single Wall -

Shear/Impact Valves (Under Despenser) - Steel Swing Joints (At Ends of Piping) -Cathodic Protection-Field Installed - FRP Tank or Piping (Noncorrodible)

No Variance

DIESEL

SIR (Stat. Inventory Reonciliation) and Inventory Cntri - - -

No Variance

Auto Leak Line Detector (3.0gph for pressure piping) - SIR (Stat. Inventory Reconciliation) and

No Variance

Auto Flow Restrictor Valve (AFRV) - Factory Built Spill Container/Bucket/Sump - Tight - Fill

No Variance

TANK NUMBER:

STATUS:

In Use

STATUS DATE: INSTALL DATE:

REGISTERED DATE: CAPACITY:

01011981 05081986 0006000 Gallons Single Wall -EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL:

CORROSION PROTECTION:

Steel

No Variance

Exempt by TNRCC Rule

Cathodic Protection-Field Installed -

CORROSION PROT VARIANCE:

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT:

Pressurizes

Fiberglass Reinforced Plastic (FRP)

Single Wall -

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

SEARCH ID: 6

DIST/DIR:

0.39 NE

MAP ID:

8

NAME:

DOUBLE R 1

1149 AIRPORT BLVD ADDRESS:

AUSTIN TX 78702

TRAVIS CONTACT: GUY OLIVER REV: ID1:

02/27/07 112384 0019610

ID2: STATUS:

PHONE:

512/457-1977

PIPE CONECTORS and VALVES:

PIPE CORROSION PROTECTION:

Shear/Impact Valves (Under Despenser) - Steel Swing Joints (At Ends of Piping) -FRP Tank or Piping (Noncorrodible) - Cathodic Protection-Field Installed

PIPE CORROSION PROT VARIANCE:

SUBSTANCE STORED: TANK RLSE DETECTION METHODS:

TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS:

Inventory Cntrl - -

PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION:

GASOLINE

No Variance

SIR (Stat. Inventory Reconciliation) and Inventory Cntrl - - -

Auto Leak Line Detector (3.0gph for pressure piping) - SIR (Stat. Inventory Reconciliation) and

No Variance

Auto Flow Restrictor Valve (AFRV) - Factory Built Spill Container/Bucket/Sump - Tight - Fill

SPILL/OVERFILL VARIANCE:

No Variance

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

LUST

SEARCH ID: 7

DIST/DIR:

0.39 NE

MAP ID:

NAME:

EXXON 61683 ADDRESS: 1149 1/2 AIRPORT

AUSTIN TX 78762

TRAVIS CONTACT: HARRY JANKE

REV: ID1:

02/27/07 114391 0026033

TD2: STATUS: PHONE:

512/990-3236

SITE INFORMATION

REPORTED:

ENTERED INTO SYSTEM:

SITE PRIORITY:

SITE STATUS: PRP:

PRP ADDRESS:

PRP CONTACT: PRP PHONE:

1/13/1999

1/18/1999 gw impacted, no apparent threats or impacts to receptors

Final concurrence issued, case close **EXXON COMPANY USA**

2700 W PECAN ST STE 400 PFLUGERVILLE TX 78660

LUST INFORMATION

TANK NUMBER:

STATUS: STATUS DATE:

INSTALL DATE: REGISTERED DATE: CAPACITY:

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL: CORROSION PROTECTION:

Removed From Ground

HARRY JANKE 512/990-3236

09071989 01011965 05081986 0000550 Gallons

No Variance

Not Reported

Steel

- Cathodic Protection

CORROSION PROT VARIANCE: STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL: PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE:

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS: PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE:

Steel

- Cathodic Protection

No Variance

USED OIL - - - None

No Variance - - - None No Variance

No Variance

Target Property:

1126 TILLERY AUSTIN TX 78702

JOB: ES35165
TRAVIS COUNTY

AUSTIN T	X 78702	TRAVIS	COUNTY	
	L	UST		
SEARCH ID: 7	DIST/DIR:	0.39 NE	MAP ID:	8
NAME: EXXON 61683 ADDRESS: 1149 1/2 AIRPORT AUSTIN TX 78762 TRAVIS		REV: ID1: ID2: STATUS:	02/27/07 114391 0026033	
CONTACT: HARRY JANKE		PHONE:	512/990-3236	
TANK NUMBER:	3			
TATUS:	Removed From Ground			
TATUS DATE:	09071989			
NSTALL DATE:	01011965			
REGISTERED DATE:	05081986			
CAPACITY:	0006000 Gallons			
EXT CONTAINMENT DESIGN:	-			
CONSTRUCTION MATERIAL:	Steel			
CORROSION PROTECTION:	-			
	- Cathodic Protection			
CORROSION PROT VARIANCE:	No Variance			
TG 1 VAPOR RECOVERY EQUIP STATUS:	Not Reported			
TG 1 EQUIP INSTALL DATE:				
TTG 2 VAPOR RECOVERY EQUIP STATUS:				
TTG 2 EQUIP INSTALL DATE:				
NSTALLER COMPANY:				
NSTALLER NAME:				
NSTALLER LICENSE NUMBER:				
TYPE OF PIPE:	ma - d			
PIPE MATERIAL:	Steel			
PIPE DESIGN EXT CONTAINMENT:	-			
PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION:				
TIPE CORROSION PROTECTION:	- Cathodic Protection			
PIPE CORROSION PROT VARIANCE:	No Variance			
II E CORROGIONI ROI VINDENCE.	140 A Stiffried			
SUBSTANCE STORED:	GASOLINE			
TANK RLSE DETECTION METHODS:	None			
TANK RLSE DETECTION VARIANCE:	No Variance			
PIPE RLSE DETECTION METHODS:	None			
PIPE RLSE VARIANCE:	No Variance			
SPILL/OVERFILL PREVENTION:				
SPILL/OVERFILL VARIANCE:	No Variance			
TANK NUMBER:	2			
STATUS:	Removed From Ground			
STATUS DATE:	09071989			
INSTALL DATE:	01011965			
REGISTERED DATE:	05081986			
CAPACITY: EXT CONTAINMENT DESIGN:	0006000 Gallons			
ZAI COMMINIEMI DESIGN	-			
CONSTRUCTION MATERIAL:	Steel			
CORROSION PROTECTION:				
CORROSION PROT VARIANCE:	- Cathodic Protection			
CORRUDION I RUI TARIANCE:	- Cathodic Protection No Variance			
CORRUSION FROT VARIANCE: STG 1 VAPOR RECOVERY EQUIP STATUS:	No Variance			
	No Variance Not Reported			

Target Property:

1126 TILLERY

JOB: ES35165

N TX 78702	TRAVIS	COUNTY					
LUST							
DIST/DIR:	0.39 NE	MAP ID:	8				
	REV: ID1: ID2: STATUS: PHONE:	02/27/07 114391 0026033 512/990-3236					
Steel							
No Variance							
GASOLINE							
None							
No Variance							
None							
No Variance							
	Steel Cathodic Protection No Variance GASOLINE - None No Variance	LUST DIST/DIR: 0.39 NE REV: ID1: ID2: STATUS: PHONE: Steel	LUST DIST/DIR: 0.39 NE MAP ID: REV: 02/27/07 ID1: 114391 ID2: 0026033 STATUS: PHONE: 512/990-3236 Steel				

SPILL/OVERFILL PREVENTION: No Variance SPILL/OVERFILL VARIANCE:

TANK NUMBER: STATUS:

Removed From Ground 09071989 STATUS DATE: 01011965 INSTALL DATE: REGISTERED DATE: 05081986 0006000 Gallons CAPACITY: EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL: Steel

CORROSION PROTECTION: - Cathodic Protection

CORROSION PROT VARIANCE: No Variance STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY: **INSTALLER NAME:**

INSTALLER LICENSE NUMBER:

TYPE OF PIPE: PIPE MATERIAL: Steel PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION:

- Cathodic Protection

PIPE CORROSION PROT VARIANCE:

No Variance

SUBSTANCE STORED:

GASOLINE

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

- 3	1		G.	т
J	_	v	N)	Д

SEARCH ID: 7

DIST/DIR:

0.39 NE

MAP ID:

NAME:

EXXON 61683 ADDRESS: 1149 1/2 AIRPORT

AUSTIN TX 78762

TRAVIS

CONTACT: HARRY JANKE

REV: ID1: ID2:

02/27/07 114391 0026033

STATUS: PHONE:

512/990-3236

TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS:

PIPE RLSE VARIANCE: SPILL/OVERFILL PREVENTION:

SPILL/OVERFILL VARIANCE:

- - - None No Variance - - None

No Variance

No Variance

In Use

12011989

05081986

0012000 Gallons

Double Wall -

No Variance

Not Reported

TANK NUMBER:

STATUS:

STATUS DATE:

INSTALL DATE: REGISTERED DATE: CAPACITY:

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL:

CORROSION PROTECTION:

CORROSION PROT VARIANCE: STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME: INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS and VALVES: Joints (At Ends of Piping)

PIPE CORROSION PROTECTION:

Pressurizes

Fiberglass Reinforced Plastic (FRP) Double Wall -

FRP Tank or Piping (Noncorrodible) -

Fiberglass Reinforced Plastic (FRP)

Flexible Connectors (At Ends of Piping) - Shear/Impact Valves (Under Despenser) - Steel Swing

FRP Tank or Piping (Noncorrodible) - Coated Tank (Steel w/Ext Polyurethane Laminate)

No Variance

PIPE CORROSION PROT VARIANCE:

DIESEL

SUBSTANCE STORED: TANK RLSE DETECTION METHODS:

TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS:

PIPE RLSE VARIANCE: SPILL/OVERFILL PREVENTION:

Fitting

SPILL/OVERFILL VARIANCE:

Interstitial Monitoring within Secondary Wall/Jacket - - - Auto Tank Gauging and inv. contr

No Variance

Amnual Piping Tightness Test (.1 gph) - Auto Leak Line Detector (3.0gph for pressure piping) - -

Auto Flow Restrictor Valve (AFRV) - Factory Built Spill Container/Bucket/Sump - Tight - Fill

No Variance

TANK NUMBER: STATUS:

STATUS DATE:

INSTALL DATE: REGISTERED DATE: In Use

12011989 05081986

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

I	Ų	S	T

SEARCH ID: 7

DIST/DIR:

0.39 NE

MAP ID:

8

NAME:

EXXON 61683 ADDRESS: 1149 1/2 AIRPORT

AUSTIN TX 78762

TRAVIS **CONTACT: HARRY JANKE**

REV: ID1: TD2:

02/27/07 114391 0026033

STATUS: PHONE:

512/990-3236

CAPACTIY:

EXT CONTAINMENT DESIGN:

0012000 Gallons Double Wall -

No Veriance

Not Reported

CONSTRUCTION MATERIAL: CORROSION PROTECTION:

Fiberglass Reinforced Plastic (FRP) FRP Tank or Piping (Noncorrodible) -

CORROSION PROT VARIANCE:

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

Pressurizes

Double Wali -

Fiberglass Reinforced Plastic (FRP)

PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS and VALVES:

FRP Tank or Piping (Noncorrodible) -

Joints (At Ends of Piping)

PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE:

No Variance

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS:

TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS:

PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION:

SPILL/OVERFILL VARIANCE:

GASOLINE

Interstitial Monitoring within Secondary Wall/Jacket - - - Auto Tank Gauging and inv. contr

Flexible Connectors (At Ends of Piping) - Shear/Impact Valves (Under Despenser) - Steel Swing

Annual Piping Tightness Test (.1 gph) - Auto Leak Line Detector (3.0gph for pressure piping) - -Auto Flow Restrictor Valve (AFRV) - Factory Built Spill Container/Bucket/Sump - Tight - Fill

No Variance

TANK NUMBER:

STATUS:

STATUS DATE: INSTALL DATE:

REGISTERED DATE: CAPACITY: EXT CONTAINMENT DESIGN: In Use

12011989 05081986

No Variance

Not Reported

0012000 Gallons Double Wall -

CONSTRUCTION MATERIAL: CORROSION PROTECTION:

Fibergless Reinforced Plastic (FRP)

FRP Tank or Piping (Noncorrodible) - Coated Tank (Steel w/Ext Polyurethane Laminate)

CORROSION PROT VARIANCE:

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

1	Ľ	U	S	1	Γ

SEARCH ID: 7

DIST/DIR:

0.39 NE

MAP ID:

8

NAME:

EXXON 61683 ADDRESS: 1149 1/2 AIRPORT

AUSTIN TX 78762 TRAVIS

ID1: ID2: STATUS:

REV:

02/27/07 114391 0026033

CONTACT: HARRY JANKE

PHONE:

512/990-3236

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS and VALVES:

Joints (At Ends of Piping)

PIPE CORROSION PROTECTION:

Pressurizes

Fiberglass Reinforced Plastic (FRP)

FRP Tank or Piping (Noncorrodible) -

Double Wall -

Flexible Connectors (At Ends of Piping) - Shear/Impact Valves (Under Despenser) - Steel Swing

PIPE CORROSION PROT VARIANCE:

No Variance

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE:

PIPE RLSE DETECTION METHODS:

PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION:

SPILL/OVERFILL VARIANCE:

GASOLINE

Interstitial Monitoring within Secondary Wall/Jacket - - - Auto Tank Gauging and inv. contr

Amusal Piping Tightness Test (.1 gph) - Auto Leak Line Detector (3.0gph for pressure piping) - -

No Verience

Auto Flow Restrictor Valve (AFRV) - Factory Built Spill Container/Bucket/Sump - Tight - Fill

No Variance

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

-	100	

SEARCH ID:

DIST/DIR:

0.40 NE

MAP ID:

9

NAME:

JACK IN THE BOX ADDRESS: 1151 AIRPORT BLVD

AUSTIN TX 78721 CONTACT: PAUL DENEKA

TRAVIS

REV: **ID1:** TD2:

02/27/07 114839 0072937

STATUS: PHONE:

858/571-2689

SITE INFORMATION

REPORTED:

ENTERED INTO SYSTEM:

SITE PRIORITY: SITE STATUS:

PRP:

PRP ADDRESS:

PRP CONTACT: PRP PHONE:

11/12/1999

gw impact, public/domestic water supply well w/m 0.25mi

Final concurrence issued, case close

JACK IN THE BOX INC 9330 BALBOA AVE SAN DIEGO CA 92123 PAUL DENEKA

LUST INFORMATION

TANK NUMBER:

STATUS: STATUS DATE:

INSTALL DATE: REGISTERED DATE: CAPACITY:

EXT CONTAINMENT DESIGN:

Removed From Ground

01182000 08311987 02172000 0003000 Gallons Single Wall -

858/571-2689

CONSTRUCTION MATERIAL: CORROSION PROTECTION:

Steel - None

No Variance

Not Reported

CORROSION PROT VARIANCE: STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY: INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION:

- None

PIPE CORROSION PROT VARIANCE: No Variance

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS: PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE:

GASOLINE

Single Wall -

- - - None No Variance - - - None No Variance

No Variance

Target Property:

1126 TILLERY AUSTIN TX 78702 JOB: ES35165 TRAVIS COUNTY

	AUSTIN TX 7	8702	TRAVIS	COUNTY	
LUST					
SEARCH ID: 11		DIST/DIR:	0.40 NE	MAP ID:	9
NAME: JACK IN T ADDRESS: 1151 AIRI AUSTIN T TRAVIS CONTACT: PAUL DEI	PORT BLVD IX 78721		REV: ID1: ID2: STATUS: PHONE:	02/27/07 114839 0072937 858/571-2689	
			A HOILE.	030371 2007	
TANK NUMBER: STATUS: STATUS DATE: INSTALL DATE: REGISTERED DATE: CAPACITY: EXT CONTAINMENT!	0 0 0	emoved From Ground 1182000 8311987 2182000 003000 Gallons ingle Wall -			
CONSTRUCTION MAT	**	toel			
CORROSION PROT VA STG 1 VAPOR RECOV STG 1 EQUIP INSTALI STG 2 VAPOR RECOV STG 2 EQUIP INSTALI	ARIANCE: N ERY EQUIP STATUS: N L DATE: ERY EQUIP STATUS:	None to Variance tot Reported			
INSTALLER COMPAN INSTALLER NAME: INSTALLER LICENSE					
TYPE OF PIPE:					
PIPE MATERIAL:	_	iteel			
PIPE DESIGN EXT CO PIPE CONECTORS and PIPE CORROSION PR	I VALVES: • OTECTION: •	ingle Wall - -			
PIPE CORROSION PR		- None To Variance			
SUBSTANCE STORED TANK RLSE DETECT	ION METHODS:	GASOLINE None			
TANK RLSE DETECTION PIPE RLSE DETECTION OF THE PROPERTY OF TH		√o Variance None			
PIPE RLSE VARIANCI SPILL/OVERFILL PRI SPILL/OVERFILL VAI	EVENTION:	Vo Variance Vo Variance			
TANK NUMBER: STATUS:	=	Removed From Ground			
STATUS DATE: INSTALL DATE:)1182000)8311987			
REGISTERED DATE:	(2182000			
CAPACITY: EXT CONTAINMENT		003000 Gallons Single Wall -			
CONSTRUCTION MA	TERIAL:	ongie wan - - Steel			
CORROSION PROTEC		- - None			
CORROSION PROT V STG 1 VAPOR RECOV STG 1 EQUIP INSTAL	ARIANCE: 1 VERY EQUIP STATUS: 1	No Variance Not Reported			

Target Property:

1126 TILLERY AUSTIN TX 78702

- None

No Variance

JOB: ES35165

TRAVIS COUNTY

LUST					
SEARCH ID: 11	DIST/DIR:	0.40 NE	MAP ID:	9	
NAME: JACK IN THE BOX ADDRESS: 1151 AIRPORT BLVD		REV: ID1:	02/27/07 114839		
AUSTIN TX 78721 TRAVIS		ID2: STATUS:	0072937		
CONTACT: PAUL DENEKA		PHONE:	858/571-2689		

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY: INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS and VALVES:

PIPE CORROSION PROTECTION:

Steel

Single Wall-

PIPE CORROSION PROT VARIANCE:

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS:

TANK RLSE DETECTION VARIANCE:

PIPE RLSE DETECTION METHODS:

PIPE RLSE VARIANCE:

No Variance

No Variance

SPILL/OVERFILL PREVENTION:

SPILL/OVERFILL VARIANCE:

No Variance

Target Property:

1126 TILLERY AUSTIN TX 78702 JOB: ES35165

TRAVIS COUNTY

OTHER

SEARCH ID: 2

DIST/DIR:

0.23 SE

MAP ID:

NAME:

AUSTIN ISD ADDRESS: 1135 GUNTER ST

AUSTIN TX 78702

CONTACT: FRED FILLEY

TRAVIS

REV: mt: ID2:

04/04/2004 IHW-72387 TXD981901655

STATUS: PHONE:

INACTIVE 512-414-1700

FACILITY INFORMATION:

REGISTRATION NUMBER: INITIAL NOTIFICATION DATE:

LAST AMMENDMENT DATE: EPA ID:

TCEQ PERMIT:

SITE PRIMARY STD. IND. CODE:

GENERATOR OF WASTE: RECEIVERS OF WASTE:

TRANSPORTERS OF WASTE: TRANSFER FACILITY: MEXICAN FACILITY (Maquiladora):

TYPE OF GENERATOR:

INDUSTRIAL WASTE PERMIT NUMBER: MUNICIPAL WASTE PERMIT NUMBER: **MAILING ADDRESS:**

MAILING ADDRESS 2: MAILING ADDRESS 3:

MAILING COUNTRY:

LOCATION DESCRIPTION:

77387

19870501 20010727 TXD981901655

Not reported

99990 - Nonclassifiable - Nonclassifiable Establishments

Yes No No No

No

CESQG/Non-industrial and/or municipal Not reported

Not reported 1111 W 6th Ste C230

Austin TX 78703 -

USA 1135 Gunter St, Austin, TX

OWNER INFORMATION

COMPANY or INDIVIDUAL S NAME:

CONTACT: CONTACT PHONE:

OWNER MAILING ADDRESS: OWNER MAILING ADDRESS 2: OWNER P. O. BOX:

OWNER TELEPHONE: OWNER FAX: OWNER EMAIL: TYPE OF BUSINESS:

Austin ISD

Fred Filley 512-414-1700 1111 W 6th Ste C230

Austin TX 78703-Not reported 512-414-1700 Not reported Not reported Other/Misc

OPERATOR INFORMATION

COMPANY OF INDIVIDUAL S NAME:

OPERATOR MAILING ADDRESS: **OPERATOR MAILING ADDRESS 2: OPERATOR TELEPHONE:**

Austin ISD

1111 W 6th Ste C230 Austin TX 78703-512-414-1700

OPERATOR FAX: OPERATOR EMAIL:

TYPE OF BUSINESS:

Other/MiscOPERATOR TAX ID:

WASTE INFORMATION

TX WASTE CODE (8 character code):

TX WASTE CODE (6 digit code being phased out): 990001

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

OTHER

SEARCH ID: 2

DIST/DIR:

0.23 SE

MAP ID:

NAME:

AUSTIN ISD ADDRESS: 1135 GUNTER ST

AUSTIN TX 78702

TRAVIS

CONTACT: FRED FILLEY

REV: ID1: ID2:

IHW-72387 TXD981901655

STATUS: PHONE:

INACTIVE 512-414-1700

04/04/2004

WASTE CODE STATUS:

Inactive

WASTE DESCRIPTION FROM WASTE FORM:

GENERATOR S WASTE DESCRIPTION:

PRIMARY SOURCE:

TX WASTE CODE (8 character code):

TX WASTE CODE (6 digit code being phased out): 990002

WASTE CODE STATUS:

Inactive

WASTE DESCRIPTION FROM WASTE FORM:

GENERATOR S WASTE DESCRIPTION:

PRIMARY SOURCE:

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

R	CR	ΑŒ	Gì	V

SEARCH ID:

DIST/DIR:

0.23 SE

MAP ID:

NAME:

AUSTIN ISD DELEON

ADDRESS: 1135 GUNTER

AUSTIN TX 78702 TRAVIS

CONTACT: FD FILLEY

REV: **ID1:**

2/9/04 TXD981901655

ID2: STATUS:

VGN

PHONE:

5129267940

SITE INFORMATION

UNIVERSE TYPE:

CEG - CONDITIONALLY EXEMPT SMALL QUANTITY GENERATORS: GENERATES LESS THAN 100 KG/MONTH OF HAZARDOUS WASTE

SIC INFORMATION:

ENFORCEMENT INFORMATION:

AGENCY:

S-STATE

25-JUL-91

TYPE:

120 - WRITTEN INFORMAL

AGENCY: TYPE:

S-STATE 120 - WRITTEN INFORMAL

DATE:

25-JUL-91

VIOLATION INFORMATION:

VIOLATION NUMBER: DETERMINED:

CITATION: TYPE:

0001 25-JUL-91 335.9A2/3

RESPONSIBLE: **DETERMINED BY:** RESOLVED:

S-STATE S-STATE 23-AUG-91

SWR

VIOLATION NUMBER: DETERMINED: CITATION: TYPE:

0002 25-JUL-91 335.9A2/3 SWR

RESPONSIBLE: DETERMINED BY: RESOLVED:

S-STATE S-STATE 23-AUG-91

Target Property:

1126 TILLERY

AUSTIN TX 78702

JOB: ES35165

TRAVIS COUNTY

S	PII	LS

SEARCH ID: 17 DIST/DIR:

NON GC

REV:

ID1:

ID2:

STATUS:

PHONE:

MAP ID:

NAME:

CONTACT:

GENERIC INCIDENT ZIP CODE 78702

ADDRESS:

AUSTIN TX

TRAVIS

72841 RN104052303 CLOSED

4/14/2005

SPILL INFORMATION:

TYPE OF INCIDENT:

LEVEL OF IMPORTANCE/PRIORITY:

NOTIFICATION DATE: DATE OF INCIDENT/DISCHARGE:

STATUS DATE: TCEQ PROGRAM AREA:

POTENTIAL IMPACT: NUMBER OF REPORTS:

FREQUENCY OF OCCURRENCE:

NATURE OF INCIDENT: RECEIVING WATER BODY:

RECEIVING AIR SOURCE:

DISPUTED STATUS: DISPUTED STATUS DATE: **EMERGENCY RESPONSE**

3/6/2006 3/6/2006 3/28/2006 WASTE

PAST

MSWNONINDU

TRUCK

PUBLIC AUTO 03/17/2006

COMMENTS

ABSORBED LIQUID, REMOVED WASTE.

Target Property:

1126 TILLERY **AUSTIN TX 78702**

JOB: ES35165 TRAVIS COUNTY

SPILLS

SEARCH ID: 18 DIST/DIR:

NON GC

MAP ID:

NAME:

SBR PUMPING

ADDRESS:

CONTACT:

618 TILLERY ST AUSTIN TEXAS 78702

AUSTIN TX

TRAVIS

REV: ID1: TD2:

4/14/2005 8000

STATUS:

RN102881752 CLOSED

PHONE:

SPILL INFORMATION:

TYPE OF INCIDENT:

LEVEL OF IMPORTANCE/PRIORITY:

NOTIFICATION DATE:

DATE OF INCIDENT/DISCHARGE: STATUS DATE:

TCEQ PROGRAM AREA:

POTENTIAL IMPACT:

NUMBER OF REPORTS:

FREQUENCY OF OCCURRENCE: NATURE OF INCIDENT:

RECEIVING WATER BODY:

RECEIVING AIR SOURCE:

DISPUTED STATUS:

DISPUTED STATUS DATE:

COMPLAINT

9/16/2002

1/3/2003

WATER

ENVIRONMEN

CURRENT

ODOR

VACUUM TRUCK PUBLIC AUTO

COMMENTS

THIS INVESTIGATION WAS INITIATED FROM A TELEPHONE COMPLAINT ALLEGING A SBR VACUUM TRUCK WAS SPILLING SLUDGE OUT OF THE TRUCK ONTO THE GOLF COURSE NEAR THE HURST CREEK WASTEWATER TREATMENT PLANT (WWTP). TCEQ INVESTIGATOR KATHY ROECKER CONDUCTED A FILE REVIEW OF THE HURST CREEK WWTP (PERMIT NO. 12215-001) ON 09/30/2002 TO SEE IF THE PLANT WAS AUTHORIZED FOR LAND APPLICATION OF THEIR SLUDGE ON OR NEAR THE GOLF COURSE. THERE WAS NO PROVISION IN THAT PERMIT THAT WOULD ALLOW LAND APPLICATION OF SLUDGE FROM THE HURST CREEK WWTP ON OR NEAR THE GOLF COURSE. KATHY ROECKER MET WITH ANDY SULLIVAN TO CONDUCT A SITE INVESTIGATION AND RECORDS REVIEW ON 10/18/2002. KATHY ROECKER WAS UNABLE TO FIND A TRIP TICKET DATED 09/14/2002 SHOWING A SBR VACUUM TRUCK WAS AT THE HURST CREEK WWTP ON THAT DAY. SBR DOES HAVE AN AGREEMENT TO HAUL LEACHATE COLLECTED FROM A LOCAL LANDFILL AND IS AUTHORIZED TO DISPOSE OF THE LEACHATE AT THE HURST CREEK WWTP AS LONG AS THE LEACHATE DOES NOT ADVERSELY AFFECT THE PLANT. SEE ATTACHMENT A. NO EVIDENCE WAS FOUND TO SUBSTANTIATE THE COMPLAINANTS ALLEGATIONS. THE COMPLAINANT DID NOT PROVIDE AN ADDRESS AND WAS UNABLE TO BE REACHED BY TELEPHONE; THEREFORE, WAS NOT INFORMED OF THE RESULTS OF THIS INVESTIGATION.

Target Property:

1126 TILLERY **AUSTIN TX 78702**

JOB: ES35165 TRAVIS COUNTY

SPILLS

SEARCH ID:

DIST/DIR:

NON GC

MAP ID:

NAME: ADDRESS: SELLMAN PLUMBING AND SEPTIC TRANSFER STATION

REV: ID1:

4/14/2005 45843

AUSTIN TX

TRAVIS

ID2: STATUS: RN101668887 CLOSED

CONTACT:

PHONE:

SPILL INFORMATION:

TYPE OF INCIDENT:

COMPLAINT

LEVEL OF IMPORTANCE/PRIORITY:

NOTIFICATION DATE: DATE OF INCIDENT/DISCHARGE: 8/25/2004

STATUS DATE:

4/18/2005

TCEQ PROGRAM AREA:

WATER

POTENTIAL IMPACT:

HEALTH

NUMBER OF REPORTS:

FREQUENCY OF OCCURRENCE:

CURRENT

NATURE OF INCIDENT:

ODOR

RECEIVING WATER BODY:

RECEIVING AIR SOURCE:

SELLMAN PLUMBING AND SEPTIC

DISPUTED STATUS:

DISPUTED STATUS DATE:

04/18/2005

COMMENTS

INTRODUCTION THIS INVESTIGATION ORIGINATED FROM AN ANONYMOUS TELEPHONE COMPLAINT ALLEGING SELLMAN S PLUMBING AND SEPTIC OF EMPTYING LIQUID WASTE INTO HOLDING TANKS ON THEIR PROPERTY CREATING NUISANCE ODOR CONDITIONS. INVESTIGATION TCEQ INVESTIGATOR KATHY ROECKER ARRIVED AT SELLMAN S PLUMBING AND SEPTIC (TRANSPORTER REGISTRATION NO.: 21565) AT 10:35 AM ON SEPTEMBER 23, 2004. KATHY ROECKER MET WITH MR. CRAIG SELLMAN TO DISCUSS THE COMPLAINT. MR. SELLMAN IS A REGISTERED LIQUID WASTE HAULER AND ALSO MANUFACTURES CONCRETE SEPTIC TANKS AT THIS BUSINESS LOCATION. MANY CONCRETE TANKS WERE STORED ON SITE DURING THIS COMPLAINT INVESTIGATION; HOWEVER, NONE OF THE TANKS CONTAINED LIQUID WASTE OR APPEARED AT HAVE EVER CONTAINED LIQUID WASTE. NO NUISANCE ODORS WERE PRESENT THE DAY OF THE INVESTIGATION AND THE ALLEGATIONS OF LIQUID WASTE BEING STORED IN HOLDING TANKS COULD NOT BE SUBSTANTIATED. NO VIOLATIONS WERE NOTED DURING THIS THE COMPLAINANT WAS ANONYMOUS; THEREFORE, THE COMPLAINANT CONCLUSION COMPLAINT INVESTIGATION. WAS NOTIFIED AS TO THE RESULTS OF THE INVESTIGATION. NO FURTHER ACTION IS REQUIRED BY THE TCEQ AUSTIN REGION OFFICE FOR THIS COMPLAINT.

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

SPI	LLS
-----	-----

SEARCH ID: 20 DIST/DIR:

NON GC

MAP ID:

NAME: ADDRESS:

CONTACT:

SONIC DRIVE-IN

TRAVIS

AUSTIN TX

REV: ID1: TD2: STATUS:

1379 RN101510907 CLOSED

4/14/2005

PHONE:

SPILL INFORMATION:

TYPE OF INCIDENT:

LEVEL OF IMPORTANCE/PRIORITY: **NOTIFICATION DATE:** DATE OF INCIDENT/DISCHARGE:

STATUS DATE:

TCEO PROGRAM AREA: POTENTIAL IMPACT:

NUMBER OF REPORTS:

FREQUENCY OF OCCURRENCE: NATURE OF INCIDENT:

RECEIVING WATER BODY: RECEIVING AIR SOURCE: **DISPUTED STATUS: DISPUTED STATUS DATE:**

EMERGENCY RESPONSE

2/21/2002 2/21/2002 2/28/2002 WATER

ENVIRONMENT

CURRENT QUALITY

WILLIAMSON CREEK SONIC DRIVE-IN PUBLIC AUTO 01/01/1800

SPILL INFORMATION:

TYPE OF INCIDENT:

EMERGENCY RESPONSE

LEVEL OF IMPORTANCE/PRIORITY:

NOTIFICATION DATE: DATE OF INCIDENT/DISCHARGE: STATUS DATE: TCEQ PROGRAM AREA:

POTENTIAL IMPACT: NUMBER OF REPORTS:

FREQUENCY OF OCCURRENCE: NATURE OF INCIDENT:

RECEIVING WATER BODY: RECEIVING AIR SOURCE: **DISPUTED STATUS:** DISPUTED STATUS DATE:

2/21/2002 2/21/2002 2/28/2002 WATER

ENVIRONMENT

CURRENT QUALITY

WILLIAMSON CREEK SONIC DRIVE-IN PUBLIC AUTO

01/01/1800

COMMENTS

IT IS ALLEGED THAT SONIC DRIVE-IN WASHED ITS CAR PAD AND DRIVEWAY USING WATER AND A CLEANING AGENT. RUN OFF FROM THE WASH HAD ENTERED A STORM DRAIN THEN INTO A CREEK THAT FLOWS THROUGH AN APARTMENT COMPLEX.

COMMENTS

IT IS ALLEGED THAT SONIC DRIVE-IN WASHED ITS CAR PAD AND DRIVEWAY USING WATER AND A CLEANING AGENT. RUN OFF FROM THE WASH HAD ENTERED A STORM DRAIN THEN INTO A CREEK THAT FLOWS THROUGH AN APARTMENT COMPLEX.

Target Property:

1126 TILLERY AUSTIN TX 78702 JOB: ES35165

TRAVIS COUNTY

SPILLS

SEARCH ID: 21

DIST/DIR:

NON GC

MAP ID:

NAME:

CONTACT:

THOMAS C GREEN WATER

ADDRESS: AUSTIN TEXAS AUSTIN TX

TRAVIS

REV: ID1: ID2: STATUS:

63245 RN101608289 CLOSED

4/14/2005

PHONE:

SPILL INFORMATION:

TYPE OF INCIDENT:

LEVEL OF IMPORTANCE/PRIORITY: **NOTIFICATION DATE:**

DATE OF INCIDENT/DISCHARGE: STATUS DATE:

TCEQ PROGRAM AREA: POTENTIAL IMPACT: NUMBER OF REPORTS:

FREQUENCY OF OCCURRENCE: NATURE OF INCIDENT:

RECEIVING WATER BODY:

RECEIVING AIR SOURCE:

DISPUTED STATUS:

DISPUTED STATUS DATE:

EMERGENCY RESPONSE

8/13/2005 8/13/2005 9/19/2005

WATER

PAST OTHER

GREEN WATER TREATMENT PLANT

PUBLIC AUTO 08/27/2005

COMMENTS

PRIOR TO THE DISCOVERY THAT THE MATERIAL DISCHARGED TO THE SANITARY SEWER, SAMPLES WERE TAKEN, PH TAKEN, AND CITY OF AUSTIN WATERSHED PROTECTION CONDUCTED AN INVESTIGATION. PH AT OUTFALL WAS 8.5 AND DOWNSTREAM 50 FT 8.1 NORMAL CREEK PH IS 7.5 - 8. SAMPLES OF CREEK WERE TESTED FOR FLUORIDES. SAMPLES AT OUTFALL WERE 0.41 AND DOWNSTREAM 0.40. RAW WATER IS NORMALLY .2-.4.

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

SP	TT	T	O
O.	ш	JL	ωJ

SEARCH ID: 15

DIST/DIR:

NON GC

MAP ID:

NAME:

CONTACT:

ADVANCED MICRO DEVICES AMD LONE STAR SITE

REV:

4/14/2005

ADDRESS: **AUSTIN TX** ID1: ID2:

82518 RN105066112

TRAVIS

STATUS: PHONE:

CLOSED

SPILL INFORMATION:

TYPE OF INCIDENT:

EMERGENCY RESPONSE

LEVEL OF IMPORTANCE/PRIORITY: NOTIFICATION DATE:

10/10/2006 10/9/2006

DATE OF INCIDENT/DISCHARGE: STATUS DATE:

11/17/2006

TCEQ PROGRAM AREA:

WASTE

POTENTIAL IMPACT:

GENERAL

NUMBER OF REPORTS: FREQUENCY OF OCCURRENCE:

PAST

NATURE OF INCIDENT:

OTHER

RECEIVING WATER BODY:

BARTON CREEK

RECEIVING AIR SOURCE:

TRUCK

DISPUTED STATUS:

VERIFY

DISPUTED STATUS DATE:

10/11/2006

COMMENTS

SEE ABOVE FOR WORK COMPLETED BY EXCELL ENVIRONMENTAL.

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

SPI	П	LS
OLI		ديا

SEARCH ID:

DIST/DIR:

NON GC

MAP ID:

NAME: ADDRESS:

CONTACT:

ALAMO CONCRETE PRODUCTS SOUTH PLANT

TRAVIS

AUSTIN TX

REV: ID1: ID2: STATUS:

62185 RN100249549 CLOSED

4/14/2005

PHONE:

SPILL INFORMATION:

TYPE OF INCIDENT:

LEVEL OF IMPORTANCE/PRIORITY: NOTIFICATION DATE:

DATE OF INCIDENT/DISCHARGE: STATUS DATE:

TCEQ PROGRAM AREA: POTENTIAL IMPACT:

NUMBER OF REPORTS: FREQUENCY OF OCCURRENCE: NATURE OF INCIDENT:

RECEIVING WATER BODY: RECEIVING AIR SOURCE:

DISPUTED STATUS:

DISPUTED STATUS DATE:

EMERGENCY RESPONSE

8/1/2005 8/1/2005 11/15/2005 WASTE

ENVIRONMEN PAST

INDUSTRIAL

NORTH FLY ASH SILO

11/15/2005

COMMENTS

TANKER TRANSPORT COMPANY NOTIFIED THAT DRIVER SHOULD HAVE BEEN AWARE OF ACTIONS TO BE TAKEN IF SUCH AN EVENT OCCURED.

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

SEARCH ID:

DIST/DIR:

NON GC

MAP ID:

NAME:

CONTACT:

AUSTIN, CITY OF

ADDRESS:

TRAVIS

AUSTIN TX

ID2: STATUS:

REV:

ID1:

PHONE:

(512) 4720500

3/1/02

42004

SITE INFORMATION

TNRCC REGION:

TYPE OF LANDFILL:

RESOURCE RECOVERY/COMPOSTING FACILITY

FACILITY STATUS:

PROPOSED SITE (PERMIT HAS NOT BEEN ISSUED BEFORE FOR THIS SITE)

TYPE OF BUSINESS:

ESTIMATED CLOSE DATE:

ORIGINAL SIZE IN ACRES: TONS OF WASTE RECD PER DAY:

YDS OF WASTE RECD PER DAY: 0 POPULATION SERVED:

AREA SERVED:

PERMIT INFORMATION

PERMIT NUMBER:

42004

0

PERMIT STATUS:

APPLICATION WITHDRAWN

PERMIT APPLICANT NAME:

AUSTIN, CITY OF PO BOX 1088

APPLICANT ADDRESS:

AUSTIN TX 78767

APPLICANT PHONE:

(4720500) 4720500

OWNER INFORMATION

OWNER NAME:

AUSTIN, CITY OF

OWNER ADDRESS:

PO BOX 1088 **AUSTIN TX 78767**

Target Property:

1126 TILLERY AUSTIN TX 78702 JOB: ES35165

TRAVIS COUNTY

UST

SEARCH ID: 3

DIST/DIR:

0.23 SE

MAP ID:

1

NAME:

AUSTIN ISD DELEON BUS TERMINAL

ADDRESS: 1135 GUNTER ST

AUSTIN TX 78701

TRAVIS

CONTACT: DEL MARTINEZ

REV: ID1: 2/27/2007 0048094

ID2:

STATUS:

PHONE:

512-414-1718

FACILITY INFORMATION:

NUMBER OF USTS ON SITE:

NUMBER OF ASTS ON SITE: TNRCC FACILITY ID: TNRCC CUSTOMER ID: FACILITY TYPE: FACILITY MANAGER: 0003 0000

0048094 24616 Fleet Refuling Del Martinez 512-414-1718

OWNER INFORMATION

MANAGER PHONE:

TYPE:

COMPANY: ADDRESS: Local Government

AUSTIN ISD DELEON BUS TERMINAL

1111 W 6TH ST STE C230 AUSTIN TX 78703-5300

PO BOX:

CONTACT:
CONTACT PHONE:
AMENDMENTS:

KRIS HAFEZI 512-414-0240

Owner Contact Changed

UST INFORMATION (tank information)

TANK NUMBER:

2

STATUS: STATUS DATE: Removed From Ground

STATUS DATE: INSTALL DATE: REGISTERED DATE: CAPACITY: 06151998 01011960 03281989 0010000 Gallons

EXT CONTAINMENT DESIGN:

-

CONSTRUCTION MATERIAL: CORROSION PROTECTION:

- None

CORROSION PROT VARIANCE:

No Variance
US: Not Reported

STG 1 VAPOR RECOVERY EQUIP STATUS: STG 1 EQUIP INSTALL DATE:

SIG I EQUIT INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY: INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:
PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION:

-

- None

Target Property:

1126 TILLERY AUSTIN TX 78702 JOB: ES35165 TRAVIS COUNTY

AUSTIN TX	TRAVIS COUNTY			
SEARCH ID: 3	DIST/DIR:	0.23 SE	MAP ID:	1
NAME: AUSTIN ISD DELEON BUS TERMI ADDRESS: 1135 GUNTER ST AUSTIN TX 78701 TRAVIS	INAL	REV: ID1: ID2: STATUS:	2/27/2007 0048094	
CONTACT: DEL MARTINEZ		PHONE:	512-414-1718	
PIPE CORROSION PROT VARIANCE:	No Variance			
SUBSTANCE STORED: CANK RLSE DETECTION METHODS: FANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS: PIPE RLSE VARIANCE: SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE:	GASOLINE Inventory Control No Variance None No Variance No Variance			
TANK NUMBER: STATUS: STATUS DATE: NSTALL DATE: REGISTERED DATE: CAPACITY: EXT CONTAINMENT DESIGN:	1 Removed From Ground 06151998 01011960 03281989 0010000 Gallons			
CONSTRUCTION MATERIAL: CORROSION PROTECTION: CORROSION PROT VARIANCE: STG 1 VAPOR RECOVERY EQUIP STATUS: STG 1 EQUIP INSTALL DATE: STG 2 VAPOR RECOVERY EQUIP STATUS: STG 2 EQUIP INSTALL DATE:	- - None No Variance Not Reported			
INSTALLER COMPANY: INSTALLER NAME: INSTALLER LICENSE NUMBER:				
TYPE OF PIPE: PIPE MATERIAL: PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS and VALVES: PIPE CORROSION PROTECTION: PIPE CORROSION PROT VARIANCE:				
SUBSTANCE STORED: TANK RISE DETECTION METHODS: TANK RISE DETECTION VARIANCE: PIPE RISE DETECTION METHODS: PIPE RISE VARIANCE: SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE:	DIESEL Inventory Control No Variance None No Variance No Variance			
TANK NUMBER: STATUS: STATUS DATE: INSTALL DATE:	3 Removed From Ground 06151998 01011960			

Environmental FirstSearch Site Detail Report

Target Property:

1126 TILLERY

AUSTIN TX 78702

JOB: ES35165

TRAVIS COUNTY

UST

SEARCH ID: 3

DIST/DIR:

0.23 SE

MAP ID:

NAME:

AUSTIN ISD DELEON BUS TERMINAL

ADDRESS: 1135 GUNTER ST

AUSTIN TX 78701

TRAVIS

CONTACT: DEL MARTINEZ

REV: ID1: ID2:

STATUS: PHONE:

512-414-1718

2/27/2007

0048094

REGISTERED DATE:

03281989

- None

No Variance

Not Reported

CAPACITY:

0004000 Gallons

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL:

CORROSION PROTECTION:

CORROSION PROT VARIANCE:

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS and VALVES:

PIPE CORROSION PROTECTION:

- Nanc

PIPE CORROSION PROT VARIANCE:

No Variance

SUBSTANCE STORED:

TANK RISE DETECTION METHODS:

TANK RLSE DETECTION VARIANCE:

PIPE RLSE DETECTION METHODS:

PIPE RLSE VARIANCE:

No Variance - - - None No Variance

GASOLINE

- - - Inventory Control

SPILL/OVERFILL PREVENTION:

SPILL/OVERFILL VARIANCE:

No Variance

AST INFORMATION

Environmental FirstSearch Site Detail Report

Target Property:

1126 TILLERY **AUSTIN TX 78702** JOB: ES35165

TRAVIS COUNTY

VCP

SEARCH ID: 13

DIST/DIR:

0.34 SW

MAP ID:

6

NAME:

AUSTIN COMMUNITY COLLEGE ADDRESS: 3101 AND 3401 WEBBERVILLE ROAD

REV: ID1:

3/3/2008 VCP-1771

AUSTIN TX

ID2: STATUS: INVESTIGATION

TRAVIS

PHONE:

CONTACT:

VOLUNTARY CLEANUP PROGRAM SITE DETAILS

OTHER SITE IDENTIFIERS

PROGRAM COST ACCT NUMBER:

33971

TCEQ SWR NUMBER: LPST NUMBER:

EPA TX ID/CERCLIS ID:

EPA REGISTRATION NUMBER:

SITE INFORMATION

VCP APP RECEIVED:

12/20/2004

LEAD TYPE:

Owner

PROJECT MANAGER:

Settemeyer

FACILITY TYPE:

Landfill

CONTAMINANT CATEGORIES:

Methane

MEDIA AFFECTED:

SIZE OF FACILITY:

29acres

AGREEMENT DETAILS

AGREEMENT DATE:

1/28/2005

RULES - RISK REDUCTION OR PST:

RISK REDUCT 1, 2, 3, and PLAN A OR B:

CERT ISSUED DATE: TYPE OF CERT:

TYPE OF REMEDY:

VCP APPLICANT INFORMATION

APP COMPANY:

Austin Community College

APP CONTACT:

Becky Cole

APP TITLE:

Manager, EHS and Insurance

APP ADDRESS: APP ADDRESS2: 9101 Tuscany Way Austin, TX 78754

APP PHONE:

512-223-1015

APP FAX:

512-223-1035

APPLICANT ATTORNEY/CONSULTANT INFORMATION

ATTY/CONS COMPANY:

Geomatrix Consultants, Inc.

ATTY/CONS CONTACT:

Phil Bullock

ATTY/CONS TITLE: ATTY/CONS ADDRESS: Principal 5725 Highway 290 West, Suite 200-B

APP ADDRESS2:

Austin, TX 78735

ATTY/CONS PHONE:

512-494-0333

512-494-0334

Environmental FirstSearch Descriptions

NPL: EPA NATIONAL PRIORITY LIST - The National Priorities List is a list of the worst hazardous waste sites that have been identified by Superfund. Sites are only put on the list after they have been scored using the Hazard Ranking System (HRS), and have been subjected to public comment. Any site on the NPL is eligible for cleanup using Superfund Trust money.

A Superfund site is any land in the United States that has been contaminated by hazardous waste and identified by the Environmental Protection Agency (EPA) as a candidate for cleanup because it poses a risk to human health and/or the environment.

FINAL - Currently on the Final NPL

PROPOSED - Proposed for NPL

NPL DELISTED: *EPA* NATIONAL PRIORITY LIST Subset - Database of delisted NPL sites. The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

DELISTED - Deleted from the Final NPL

CERCLIS: EPA COMPREHENSIVE ENVIRONMENTAL RESPONSE COMPENSATION AND LIABILITY INFORMATION SYSTEM (CERCLIS)- CERCLIS is a database of potential and confirmed hazardous waste sites at which the EPA Superfund program has some involvement. It contains sites that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL.

PART OF NPL- Site is part of NPL site

DELETED - Deleted from the Final NPL

FINAL - Currently on the Final NPL

NOT PROPOSED - Not on the NPL

NOT VALID - Not Valid Site or Incident

PROPOSED - Proposed for NPL

REMOVED - Removed from Proposed NPL

SCAN PLAN - Pre-proposal Site

WITHDRAWN - Withdrawn

NFRAP: EPA COMPREHENSIVE ENVIRONMENTAL RESPONSE COMPENSATION AND LIABILITY INFORMATION SYSTEM ARCHIVED SITES - database of Archive designated CERCLA sites that, to the best of EPA's knowledge, assessment has been completed and has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

NFRAP - No Further Remedial Action Plan

- P Site is part of NPL site
- D Deleted from the Final NPL
- F Currently on the Final NPL
- N Not on the NPL
- O Not Valid Site or Incident
- P Proposed for NPL
- R Removed from Proposed NPL
- S Pre-proposal Site
- W Withdrawn

RCRA COR ACT: EPA RESOURCE CONSERVATION AND RECOVERY INFORMATION SYSTEM SITES - Database of hazardous waste information contained in the Resource Conservation and Recovery Act Information (RCRAInfo), a national program management and inventory system about hazardous waste handlers. In general, all generators, transporters, treaters, storers, and disposers of hazardous waste are required to provide information about their activities to state environmental agencies. These agencies, in turn pass on the information to regional and national EPA offices. This regulation is governed by the Resource Conservation and Recovery Act (RCRA), as amended by the Hazardous and Solid Waste Amendments of 1984.

RCRAInfo facilities that have reported violations and subject to corrective actions.

TREATMENT, STORAGE, and DISPOSAL FACILITIES. - Database of hazardous waste information contained in the Resource Conservation and Recovery Act Information (RCRAInfo), a national program management and inventory system about hazardous waste handlers. In general, all generators, transporters, treaters, storers, and disposers of hazardous waste are required to provide information about their activities to state environmental agencies. These agencies, in turn pass on the information to regional and national EPA offices. This regulation is governed by the Resource Conservation and Recovery Act (RCRA), as amended by the Hazardous and Solid Waste Amendments of 1984.

RCRA GEN: EPA RESOURCE CONSERVATION AND RECOVERY INFORMATION SYSTEM GENERATORS - Database of hazardous waste information contained in the Resource Conservation and Recovery Act Information (RCRAInfo), a national program management and inventory system about hazardous waste handlers. In general, all generators, transporters, treaters, storers, and disposers of hazardous waste are required to provide information about their activities to state environmental agencies. These agencies, in turn pass on the information to regional and national EPA offices. This regulation is governed by the Resource Conservation and Recovery Act (RCRA), as amended by the Hazardous and Solid Waste Amendments of 1984. Facilities that generate or transport hazardous waste or meet other RCRA requirements.

LGN - Large Quantity Generators

SGN - Small Quantity Generators

VGN - Conditionally Exempt Generator.

Facilities that treat, store, dispose, or incinerate hazardous waste.

Included are RAATS (RCRA Administrative Action Tracking System) and CMEL (Compliance Monitoring & Enforcement List) facilities.

Federal IC / EC: EPA BROWNFIELD MANAGEMENT SYSTEM (BMS) - database designed to assist EPA in collecting, tracking, and updating information, as well as reporting on the major activities and accomplishments of the various Brownfield grant Programs.

FEDERAL ENGINEERING AND INSTITUTIONAL CONTROLS- Superfund sites that have either an engineering or an institutional control. The data includes the control and the media contaminated.

ERNS: EPA/NRC EMERGENCY RESPONSE NOTIFICATION SYSTEM (ERNS) - Database of incidents reported to the National Response Center. These incidents include chemical spills, accidents involving chemicals (such as fires or explosions), oil spills, transportation accidents that involve oil or chemicals, releases of radioactive materials, sightings of oil sheens on bodies of water, terrorist incidents involving chemicals, incidents where illegally dumped chemicals have been found, and drills intended to prepare responders to handle these kinds of incidents. Data since January 2001 has been received from the National Response System database as the EPA no longer maintains this data.

Tribal Lands: DOI/BIA INDIAN LANDS OF THE UNITED STATES - Database of areas with boundaries established by treaty, statute, and (or) executive or court order, recognized by the Federal Government as territory in which American Indian tribes have primary governmental authority. The Indian Lands of the United States map layer shows areas of 640 acres or more, administered by the Bureau of Indian Affairs. Included are Federally-administered lands within a reservation which may or may not be considered part of the reservation.

State/Tribal Sites: TCEQ STATE SUPERFUND REGISTRY - TCEQ sites which may constitute an imminent and substantial endangerment to public health and safety or to the environment due to a release or threatened release of hazardous substances into the environment

State Spills 90: TCEQ Database of emergency response actions and spill releases dating from 2002 to present

State/Tribal SWL: TCEQ Listing of all permitted solid waste landfills, transfer stations, and incinerators

State/Tribal LUST: TCEQ Listing of all leaking underground petroleum storage tanks

State/Tribal UST/AST: TCEQ Listing of all underground petroleum storage tanks

State/Tribal EC: TCEQ See Institutional Controls database

State/Tribal IC: TCEQ Listing of sites in the Voluntary Cleanup Program (VCP) and the Innocent Owner/Operator Program (IOP) where Institutional or Engineering Controls heve been placed on them.

State/Tribal VCP: TCEQ Listing of all sites in the Voluntary Cleanup Program (VCP) and the Innocent Owner/Operator Program (IOP). Some VCP and IOP sites are noted as having institutional controls placed on them.

State/Tribal Brownfields: TCEQ/EPA Listing of all former industrial properties that lie dormant or underutilized due to liability associated with real or perceived contamination. Some sites are noted as having institutional controls placed on them.

Brownfields Management System (BMS) is an analytical database designed to assist EPA in collecting, tracking, and updating information, as well as reporting on the major activities and accomplishments of the various Brownfield grant Programs.

RADON: NTIS NATIONAL RADON DATABASE - EPA radon data from 1990-1991 national radon project collected for a variety of zip codes across the United States.

State Other: TCEQ Texas Industrial Hazardous Waste Notice of Registration (IHW NOR) data. The TCEQ enters all information submitted by industrial and hazardous waste transporters, receivers (including recyclers), generators and one time shipments into a database that tracks industrial and hazardous waste generation and management activities in the state of Texas. All facilities of these types receive a solid waste registration number.

Dry Cleaner Remediation Program (DCRP) - The Dry Cleaner Remediation Program (DCRP) was established by the Texas Legislature in 2003. It created the Dry Cleaning Facility Release Fund for state lead clean up of dry cleaner related contaminated sites. There are two listings from this program:

LIST#1 - A historic listing of any facility that registered with the DCRP indicating whether or not the facility has used Perchloroethylene (PERC) in the past.

LIST#2 - A Prioritization list of dry cleaner sites. Facilities on this list will be investigated in order to determine the existence and or extent of possible contamination. The DCRP administers the Dry Cleaning Facility Release Fund to assist with remediation of contamination caused by dry cleaning solvents.

Facilities which are not current on their DCRP payments get dropped from the program. Banks Information Solutions DOES NOT REMOVE these listings from our database so that we may present a more complete historical listing of facilities that may or may not have used PERC in the past.

State Other: US DOJ NATIONAL CLANDESTINE LABORATORY REGISTER - Database of addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the U.S. Department of Justice ("the Department"), and the Department has not verified the entry and does not guarantee its accuracy. All sites that are included in this data set will have an id that starts with NCLR.

Environmental FirstSearch Database Sources

NPL: EPA Environmental Protection Agency

Updated quarterly

NPL DELISTED: EPA Environmental Protection Agency

Updated quarterly

CERCLIS: EPA Environmental Protection Agency

Updated quarterly

NFRAP: EPA Environmental Protection Agency.

Updated quarterly

RCRA COR ACT: EPA Environmental Protection Agency.

Updated quarterly

RCRA TSD: EPA Environmental Protection Agency.

Updated quarterly

RCRA GEN: EPA Environmental Protection Agency.

Updated quarterly

Federal IC / EC: EPA Environmental Protection Agency

Updated quarterly

ERNS: EPA/NRC Environmental Protection Agency

Updated annually

Tribal Lands: DOI/BIA United States Department of the Interior

Updated annually

State/Tribal Sites: TCEQ The Texas Commission on Environmental Quality's Office of Permitting, Remediation and Registration, Remediation Division

Updated quarterly

State Spills 90: TCEQ The Texas Commission on Environmental Quality

Updated quarterly

State/Tribal SWL: TCEQ The Texas Commission on Environmental Quality's Office of Permitting, Remediation and Registration, Waste Permits Division, Municipal Solid Waste Permits Section

Updated annually

State/Tribal LUST: *TCEQ* The Texas Commission on Environmental Quality's Office of Permitting, Remediation and Registration, Waste Permits Division, Petroleum Storage Tank Program

Updated quarterly

State/Tribal UST/AST: TCEQ The Texas Commission on Environmental Quality's Office of Permitting, Remediation and Registration, Waste Permits Division, Petroleum Storage Tank Program

Updated quarterly

State/Tribal EC: TCEQ The Texas Commission on Environmental Quality

Updated quarterly

State/Tribal IC: TCEQ The Texas Commission on Environmental Quality

Updated quarterly

State/Tribal VCP: TCEQ The Texas Commission on Environmental Quality

Updated quarterly

State/Tribal Brownfields: TCEQ/EPA The Texas Commission on Environmental Quality

Updated quarterly

RADON: NTIS Environmental Protection Agency, National Technical Information Services

Updated periodically

State Other: TCEQ The Texas Commission on Environmental Quality's Office of Permitting, Remediation and Registration

Updated quarterly

State Other: US DOJ U.S. Department of Justice

Updated when available

Environmental FirstSearch Street Name Report for Streets within 1 Mile(s) of Target Property

Target Property:

1126 TILLERY AUSTIN TX 78702 JOB: ES35165 TRAVIS COUNTY


Street Name	Dist/Dir	Street Name	Dist/Dir
9th St EAST	0.77 SW	Harvard St	0.84 SW
Abbate Cir	0.45 NE	Harvey Ln	0.41 NW
Airport Blvd	0.27 NE	Harvey St	0.50 NW
lamo St	0.96 NW	Henninger St	0.14 SE
lexander Ave	0.65 NW	Hidalgo St	0.86 SW
If Ave	0.45 NE	Holmes Ct	0.65 NW
Ilen St	0.73 SW	Holton St	0.81 SW
Sedford St	0.33 NW	Jain Ln	0.77 SE
Bengston St	0.17 NE	Kay St	0.13 NE
lerger St	0.77 NE	Kirk Ave	0.31 SE
solm Rd	0.54 SE	Koerner Ln	0.97 SE
rass St	0.27 SW	Kuhlman Ave	0.51 SW
reedlove Ct	0.59 NE	Ledesma Rd	0.75 NE
Frookswood Ave	0.73 SE	Linden St	0.16 SW
Bryan St	0.85 SW	Loreto Dr	0.81 NE
Calle Limon	0.65 SE	Louis Ave	0.97 NE
	0.81 SW	Lovingood Dr	0.83 NW
Calles St	0.54 SW	Luna St	0.91 NE
Castro St			0.45 SW
Cedar Ave	0.84 NW	Lyons Rd	0.43 SW 0.98 SE
Cessal Ave	0.98 NE	Mahan Dr	
charles St	0.14 SE	Mansell Ave	0.60 SE 0.55 NE
Cherico St	0.23 SE	Map Cir	
hestnut Ave	0.85 NW	Map St	0.65 NE
chico St	0.96 NE	Maple Ave	0.93 NW
Chote Ave	0.60 SE	Mark St	0.69 NE
lifford Ave	0.66 NW	Marks Cir	0.60 SE
Coleto St	0.91 NW	Mason Ave	0.95 NE
Cometa St	0.97 NE	Maude St	0.54 SW
Commerce St	0.87 NE	Mc Kinley Ave	0.55 NW
Cornell St	0.97 SW	Mendoza Dr	0.85 NE
Coronado St	0.88 SW	Mercer Dr	0.60 NE
Courts Dr	0.48 NW	Milburn Ln	0.65 SE
Crest Ave	0.38 NW	Miriam Ave	0.88 NW
Custer Rd	0.70 SE	Morelos St	0.99 SW
Deloney St	0.82 NE	Munson St	0.33 NE
Denfield St	0.68 NE	N Pleasant Valley Rd	0.53 SW
Desirable Dr	0.97 SE	Neal St	0.26 SW
Dewey St	0.76 NE	New York Ave	0.94 NW
Diaz St	0.90 SW	New York Dr	0.77 NW
Oon Ann St	0.61 SE	Nickols Ave	0.98 NE
E 10th St	0.80 SW	Nile St	0.57 SW
11th St	0.83 SW	NORTH Pleasant Valle	0.53 SW
3 12th St	0.55 NW	Northwestern Ave	0.78 SW
E 13th St	0.61 NW	Nowotny Ln	0.69 SE
E 14th 1/2 St	0.70 NW	Oak Grove Ave	0.38 NW
E 14th St	0.66 NW	Oak Springs Dr	0.30 NW
E 16th St	0.77 NW	Pandora St	0.45 NW
E 17th St	0.81 NE	Pedernales St	0.80 SW

Environmental FirstSearch Street Name Report for Streets within 1 Mile(s) of Target Property

Target Property: 1126 TILLERY AUSTIN TX 78702

JOB: ES35165
TRAVIS COUNTY

Street Name	Dist/Dir	Street Name	Dist/Dir
E 18th 1/2 St	0.92 NW	Pennsylvania Ave	0.50 NE
E 18th St	0.87 NW	Peoples St	0.96 SW
E 5th St	0.99 SW	Perez St	0.86 NE
E 6th St	1.00 SW	Pershing Dr	1.00 NE
E 7th St	0.75 SW	Pickle Dr	0.14 SE
E 8th St	0.78 SW	Poquito St	0.96 SW
E 9th St	0.78 SW	Prado St	0.60 SW
E M Franklin Ave	0.71 NE	Prock Ln	0.55 NE
E Martin Luther King	0.98 NW	Prospect Ave	0.96 SW
EAST 10th St	0.80 SW	Rainbow Ridge Cir	0.98 NE
EAST 11th St	0.83 SW	Ramos St	0.55 SW
EAST 12th St	0.55 NW	Reyes St	0.81 NE
EAST 13th St	0.61 NW	Richardine Ave	0.90 SE
EAST 14th 1/2 St	0.70 NW	Ridge Dr	0.55 NE
EAST 14th St	0.66 NW	Ridgeway Dr	0.34 NW
EAST 16th St	0.77 NW	Rosewood Ave	0.34 NW
EAST 17th St	0.77 NW 0.81 NE	S L Davis Ave	
EAST 18th 1/2 St	0.92 NW	San Saba St	0.87 NW
EAST 18th St	0.92 NW 0.87 NW	Sanchez St	0.99 SW
EAST 5th St	0.87 N W 0.99 SW	Santa Anna St	0.72 NW
EAST 6th St	1.00 SW		0.88 NE
EAST 7th St		Sara Dr	0.62 NE
	0.75 SW	Saucedo St	0.67 SE
EAST 8th St	0.78 SW	Sellers St	0.56 SE
EAST 9th St	0.78 SW	Shady Ln	0.70 SE
EAST M Franklin Ave	0.71 NE	Singleton Ave	0.88 NW
EAST Martin Luther K	0.98 NW	Smith Dr	0.47 NE
Ebert Ave	0.84 SE	Sol Wilson Ave	0.48 NW
Estes Ave	0.96 SE	SOUTH L Davis Ave	0.87 NW
Euneva St	0.49 NW	Springdale Rd	0.39 SE
Fiesta St	0.27 SW	Spur St	0.71 NE
Francisco St	0.62 SW	Stokes Dr	0.33 SW
Garland Ave	0.91 NE	Stuart Cir	0.94 SE
Garwood St	0.66 SW	Swenson Ave	0.92 SW
Glen Oaks Ct	0.58 SW	Tanney St	0.70 NE
Glen Oaks Dr	0.51 SW	Thompson St	0.09 SW
Glen Rae St	0.46 SW	Tillery St	0.01 SE
Glissman Rd	0.70 SE	Ulit Ave	0.86 NW
Gonzales St	0.73 SW	Vermont Rd	0.88 SW
Goodwin Ave	0.07 NE	Walnut Ave	0.57 NW
Govalle Ave	0.19 SW	Walter St	0.66 SW
Graham St	0.62 NW	Wayneroy Dr	0.47 NE
Grant St	0.71 NE	Webberville Rd	0.32 NW
Greenwood Ave	0.54 NE	Wheat Ave	0.59 NW
Gullett St	0.70 SE	Wilcox Ave	0.74 SE
Gunter St	0.22 SE	Yale St	0.97 SW
Hamilton Ave	0.98 SW	Zaragosa St	0.59 SW
Hargrave St	0.57 NW		



Web Soil Survey 2.0 National Cooperative Soil Survey

Slide or Slip

Sinkhole

Sodic Spot

Stony Spot Spoll Area

\$\$\$ ø

Soll Map-Travis County, Texas (1126 Tillery Street)

MAP LEGEND

		■ Other	Special Line Features	رار Cully	Short Steep Slope	offe (i	Municipalities	Cities	Urban Areas	Water Features	Oceans	Streams and Canals	Transportation	אליים מיים מיים מיים מיים מיים מיים מיים	Interstate Highways	US Routes	State Highways	Local Roads	Other Roads	
Ares of Interest (AOI)	Area of interest (AOI)	Solls Soll Map Units		ఠ		Sorrow Pil	Clay Spot	♦ Closed Depression		Gravelly Spot	Dandfill (2)		小 Marsh	★ Mine or Quarry	Miscellaneous Water	Perennial Water	Rock Outcrop	+ Saline Spot	Sandy Spot	Severaly Erodad Spot	

MAP INFORMATION

Viewing scale and printing scale, however, may vary from the original. Please rely on the bar scale on each map sheet for proper Original soll survey map sheets were prepared at publication scale. map measurements.

Source of Map: Natural Resources Conservation Service Web Soil Survey URL: http://websoilsurvey.nrcs.usda.gov Coordinate System: UTM Zone 14N This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.


Soil Survey Area: Travis County, Texas Survey Area Data: Verslon 9, Jul 9, 2007

Date(s) aerial Images were photographed: 1/28/1995

imagery displayed on these maps. As a result, some minor shifting The orthophoto or other base map on which the soll lines were compiled and digitized probably differs from the background of map unit boundaries may be evident.

Map Unit Legend

Travis County, Texas (TX453)					
Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI		
Bh	Bergstrom soils and Urban land, 0 to 2 percent slopes	25.4	85.9%		
HsD	Houston Black soils and Urban land, 0 to 8 percent slopes	4.2	14.1%		
Totals for Area of Interest (A	OI)	29.5	100.0%		



Limited Phase II Environmental Site Assessment Targeted Brownfield Assessment Tillery Property (4-Acre Site) 1126 Tillery Street Austin, Travis County, Texas

ECOLOGY AND ENVIRONMENT, INC.

1412 Main Street, Suite 1500 Dallas, Texas 75202 August 14, 2009

Submitted to:

UNITED STATES ARMY CORPS OF ENGINEERS

Fort Worth District Fort Worth, Texas 76102



ecology and environment, inc.

International Specialists in the Environment

1412 Main St., Suite 1500 Dallas, Texas 75202 Tel: (214) 245-1000, Fax: (214) 245-1001

able of Contents

Sec	tion		Page
Exe	ecutive	e Summary	1
1	1-1		
Intr	oduct	ion	1-1
	1.1	Purpose	
	1.2	Scope of Services	
	1.3	Special Terms and Conditions	
2	2-1		
Bad	ckarou	und	2-1
	2.1	Site Description	
	2.2	Physical Setting of the Area	
	2.3	Geologic Setting	
	2.4	Site History and Land Use	
	2.5	Adjacent Property Land Use	
	2.6	Summary of Previous Assessment	
3	3-1		
Pha	ase II E	ESA Activities	3-1
	3.1	Supplemental Records Review	
	3.2	Conceptual Site Model and Sampling Plan	
	3.3	Work Plan Deviations	
	3.4	Environmental Data Search	
	3.5	Site Assessment Activities	
		3.5.1 Soil Investigation	
		3.5.2 Groundwater Investigation	
	3.6	Sampling and Chemical Analyses Methods	
		3.6.1 Soil Analyses	3-3
		3.6.2 Groundwater Analysis	3-3

Table of Contents (Cont.)

Sec	tion		Page
4	4-1		
Ana	alytical 4.1	Analytical Results 4.1.1 Soil Analytical Results 4.1.2 Groundwater Analytical Results 4.1.3 Investigation Derived Waste Analytical Results	4-1 4-2 4-2
5	5-1		
Dis	5.1 5.2 5.3 5.4	Recognized Environmental Conditions Affected Media Evaluation of Media Quality Conclusions	5-1 5-1 5-1
6	6-1		
Ref	erence	es	6-1
Α	A-1		
Soi	l Borin	ng Logs	A-1
В	B-1		
Ana	alytical	l Data Summaries	B-1
С	C-1		
Pho	otogra	phic Documentation	C-1

ist of Tables

Table		Page
4-1	Surface Soil Sample GPS Locations	4-4
4-2	Soil Analytical Results	4-5

ist of Figures

Figure		Page
2-1	Site Location Map	2-4
2-2	Site Vicinity Map	2-5
3-1	Soil Sample Location Map	3-4

ist of Abbreviations and Acronyms

ACM Asbestos Containing Material

msl above mean sea level

ASTM American Society for Testing and Materials

BGS Below Ground Surface

CERCLA Comprehensive Environmental Response, Compensation and Liability Act

COCs constituents of concern

COMB Combined

E & E Ecology and Environment, Inc.

EPA U.S. Environmental Protection Agency

ESA Environmental Site Assessment

GPS Global Positioning System

GW Groundwater

IDW Investigation-Derived Waste

ING Ingestion

LUST leaking underground storage tank

mg/kg milligrams per kilogram

PCL Protective Concentration Level

PID Photoionization Detector

QAPP Quality Assurance Project Plan

RCRA Resource Conservation and Recovery Act

REC Recognized Environmental Condition

SVOCs Semi-volatile Organic Compounds

SWMU Solid Waste Management Units

TBA Target Brownfield Assessment

TCEQ Texas Commission on Environmental Quality

List of Abbreviations and Acronyms (Cont.)

TOT Total

TRRP Texas Risk Reduction Program

TWDB Texas Water Development Board

USACE United States Army Corps of Engineers

USTs underground storage tanks

VOCs Volatile Organic Compounds

Executive Summary

Ecology and Environment, Inc., (E & E) was retained by the United States Army Corps of Engineers, Fort Worth District (USACE) to conduct a Limited Phase II Environmental Site Assessment (ESA) at the Tillery Property Targeted Brownfields Assessment (TBA) site, hereafter referred to as "The Tillery Site". The Tillery site is a 4 acre vacant property located at 1126 Tillery St, Austin, Travis County, Texas.

This Phase II ESA is being funded and provided on behalf of the City of Austin, Guadalupe-Saldona Affordable Homes, L P, and Guadalupe Neighborhood Development Corporation through the U.S. Environmental Protection Agency (EPA) Region 6 Targeted Brownfields Assessment program.

The Phase II ESA was prepared in accordance with Environmental Protection Agency (EPA) Requirements for Quality Assurance Project Plans (EPA QA/R-5, March 2001) and American Society of Testing and Material (ASTM) Standard Guide for Environmental Site Assessments: *Phase II Environmental Site Assessment Process* (Designation: E1903-97 (Reapproved 2002). The objective of the limited Phase II ESA was to evaluate the presence of buried construction debris and identify the presence of affected surface soils providing sufficient information to determine the presence and nature of any site contaminants. The Phase II was also intended to assist in making an informed decision about the property and where applicable, provide a level of knowledge necessary to satisfy the innocent purchaser defense under Comprehensive Environmental Response, Compensation and Liability Act (CERCLA).

During the March 26, 2009 investigation, eight soil samples were collected and analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), RCRA 8 metals, and pesticides. Analytical data results were compared to Texas Risk Reduction Program (TRRP) Tier 1 protective concentration levels (PCLs) for residential soils. The RCRA 8 metals were compared against the Texas-Specific Median Background and TRRP Tier I PCLs for GWSOIL_{ING} and TotSOIL_{Comb}. Lead and mercury were compared against Texas-Specific Median Background concentrations, Tier I and Tier II PCLs

Executive Summary

The Texas Commission on Environmental Quality (TCEQ) TRRP is the tiered process for determining human health and ecological protective concentration levels (PCLs) for constituents of concerns (COCs). TRRP Tier 1 ^{GW}SOIL_{ING} PCL for surface and subsurface soil is the soil-to-groundwater leaching of COCs for Class 1 and 2 groundwater. TRRP Tier 1 ^{Tot}SOIL_{Comb} PCL for residential soil is a risk based exposure (ingestion, dermal contact, inhalation of volatiles and particulates) pathway.

Calculated TRRP Tier 2 ^{GW}SOIL_{ING} PCL for Soil-to-Groundwater is a risk-based analysis to derive site-specific PCL for complete or reasonably anticipated completed exposure pathways. Tier 2 PCLS are determined utilizing site-specific exposure factors, as allowable and/or affected property parameters and Tier 1 default values.

Analytical results from soil samples collected at the site indicate that VOCs, SVOCs, and pesticides were below the respective Tier I PCLs. Analytical results for two RCRA 8 Metals (lead and mercury) were above their respective TRRP Tier I ^{GW}SOIL_{ING} PCL for Residential 0.5 acre Source Area and the Texas-Specific Soil Median Background concentration for metals. These two analytes were then compared to site-specific calculated Tier 2 values. Tier 2 calculations for lead and mercury determined both analytes were below their respective Tier 2 values.

Based on the soil sample analytical results, it can be determined that the soil media is not impacted by VOCs, SVOCs, pesticides and RCRA metals. RCRA metals with the exception of lead and mercury were below their respective Tier I PCLs. Additional evaluation of the tiered process, determined that lead and mercury were below their calculated Tier 2 values.

No groundwater samples were collected or analyzed during this site investigation. A groundwater monitoring well (MW-1) installed in February 2009 by another contractor was identified during the March 26, 2009 site investigation. Monitoring well MW-1 is located on the eastern side of the Tillery Site. A review of the analytical data from this existing groundwater monitoring well indicated that VOCs, SVOCs, pesticides and RCRA metals were below their respective Tier I GWSOIL_{ING} PCL values or detected below the sample quantitation limits.

1

Introduction

1.1 Purpose

The purpose of this limited Phase II ESA for the Tillery Site located in Austin, Travis County, Texas was to investigate the presence of construction debris in the subsurface soil, investigate the presence of constituents of concern (COCs) in the surface soils and groundwater. The Phase II ESA was designed to determine the absence/presence and nature of potential surface soil contamination at the site and where applicable, provide the level of knowledge necessary to satisfy the innocent purchaser defense under the Comprehensive Environmental Response Compensation and Liability Act (CERCLA).

1.2 Scope of Services

The scope of work for this assessment was conducted in accordance with the American Society of Testing and Materials (ASTM) Standard Guide for Environmental Site Assessments: *Phase II Environmental Site Assessment Process (Designation: E 1903-97(Reapproved 2002)).*

Specific tasks conducted as part of the site investigation included the following:

- Review of previous site data;
- Site investigation and sample collection;
- Laboratory data analyses; and
- Report preparation and findings.

1.3 Special Terms and Conditions

This phase II ESA does not address the presence of asbestos-containing materials (ACM) or lead based paint at the subject property. The findings and conclusions presented in this report apply only to the recognized environmental condition (REC) identified in previous site assessment reports (Section 6, References). The REC identified in previous reports includes waste piles and former unregistered landfill associated with the adjacent 7 acre property.

2

Background

2.1 Site Description

For the purposes of this investigation, the site consists of an approximate four acre area with the address of 1126 Tillery Street, hereafter referred to as "The Tillery Site", located in Austin, Texas. The geographic coordinates of the site are approximately N 30° 16' 07.1" and W 97° 42' 03.8". See Figure 2-1 for the Site Location map. An adjoining seven acre property is immediately adjacent to the northwest side of the four acre property and occupies the addresses of 2711 Goodwin Avenue and 3501 Webberville Road (Goodwin Property). Assessment activities associated with the seven acre property will be conducted under a separate site evaluation and investigation.

2.2 Physical Setting of the Area

The Tillery Site is located at 1126 Tillery Street, Austin, Travis County, Texas. The four acre property sits at an elevation of between approximately 450 feet to 470 feet above mean sea level (msl), approximately 1.5 miles northwest of downtown Austin. Austin is in a period of rapid growth. This is creating expansion of suburbs surrounding Austin. The City of Austin has a population of approximately 700,000 residents. The City of Austin is the county seat of Travis County. Travis County lies roughly on the boundary between the Blackland Praire and the Edwards Plateau. The average total annual precipitation in the region is 30-34 inches, with most of the precipitation occurring in April and May as thunderstorms. Temperatures range from an average low of 40°F in January to an average high of 96°F in July.

2.3 Geologic Setting

Travis County is divided by rolling hills to the west and flat gently easterly sloping sediments to the east. It is in the Colorado River Basin and bounded on the north by the Brazos River Basin. The Llano and Colorado Rivers converge approximately 50 miles to the northwest and Travis Lake is approximately 15 miles to the northwest of the City of Austin. Elevation ranges from less than 450 to more than 550 feet above mean sea level. Surface water from the site drains to-



ward Boggy Creek south of the site. Boggy Creek flows to the Colorado River approximately two and one-half miles east of the site.

Travis County lies on the eastern edge of the Edwards Plateau where the gently east dipping Lower Cretaceous Age sedimentary sequences of the Glen Rose Formation and Fredricksburg Group, Upper Cretaceous Austin Chalk, Navarro Group and Marlbrook Marl are truncated by the northeast-southwest trending Balcones Fault Zone. Additionally, the east side (east of Interstate-35) of the City of Austin lies on Quaternary Fluviatile terrace deposits commonly exposed at the surface.

2.4 Site History and Land Use

According to previous Phase I ESA and Phase II ESA reports conducted in 2007, 2008, and 2009 the Tillery Site is immediately adjacent to the Goodwin Site. The Tillery Property has been developed for residential and agricultural usage since as early as 1910. According to the Cuesta Phase I ESA the Tillery Site is a 4 acre grassy pasture with a single family resident. Previous site investiaiton reports conducted by Cuesta and URS identified one REC associated with the subject property. The REC identified in previous reports includes waste piles and former unregistered landfill associated with the Goodwin Site.

The Goodwin Site is a seven acre area that was formerly utilized as an unregistered landfill from the early 1950s until 1970 and referred to as the Webberville-Govalle landfill. The unregistered landfill was reportedly used for disposal of construction debris associated with the construction of nearby Interstate-35. The former unregistered landfill located on the adjacent 7-acre Goodwin Property is a concern for the adjacent subject 4-acre Tillery Property. On the surface, several piles of construction and household debris on the Goodwin Property may potentially pose a threat to human health and the environment.

A review of the Texas Commission on Environmental Quality (TCEQ) database and other accessible documentation did not identify any other use of the abovementioned properties.

2.5 Adjacent Property Land Use

The Tillery Site is located on Tillery Street which is south of Goodwin Avenue, east of Webberville Road, and north of Govalle Avenue. Adjacent property locations were taken from the Cuesta Phase I ESA report. See Figure 2-2 for the property location. Adjacent properties include the following:

North	Single family residence
South	Ted's Tree Farm Service
East	Tillery Street and numerous residential properties
West	The Goodwin (7 acre) Site




2.6 Summary of Previous Assessment


The following assessment documents were reviewed prior to conducting field activity associated with the subject property:

- URS Corporation. January 2009. Tillery Street Limited Site Investigation Austin, Texas Environmental Services Rotation List (2008-2010); Tillery Street Field Investigation Report
- Cuesta Resources, LLC. May 2008. Phase I Environmental Site Assessment at 1126 Tillery Street, Austin, Travis County, Texas
- Shaw Environmental, Inc. March 2008. Limited Phase II Environmental Site Assessment Brownfields, Investigation, Goodwin Property, Austin, TX.

The Cuesta Phase I ESA identified one REC during their assessment associated with trash and debris along the boundary of the 7 acre Goodwin property impacting the 4 acre Tillery property. According to the URS Field Investigation Report dated January 2009, the REC identified in the Cuesta Phase I ESA was evaluated by two trenches at a maximum depth of 10 feet or to native soils. Lead and selenium were detected above TCEQ Tier 1 Protective concentration levels. The URS report also confirmed the presence of construction debris on the margin of the Tillery Property and the adjoining Goodwin property.

An environmental regulatory database search was also conducted as part of the Cuesta Phase I ESA. Historical aerial photographs indicated the subject property has been used as an agricultural area until the 1970's. The database search did not identify registered Solid Waste Management Units (SWMU), EPA, underground storage tanks (UST) or Hazardous Waste Generator numbers associated with the subject property or sites within 0.25 mile radius of the subject property. The subject property is not listed or identified as a leaking underground storage tank (LUST) site.





3

Phase II ESA Activities

3.1 Supplemental Records Review

According to a Phase I Environmental Site Assessment (ESA) conducted in May, 2008 (Cuesta, 2008), the Tillery Property consists primarily of grassy pasture. The Tillery Property has been developed for residential and agricultural usage since as early as 1910, and according to the ESA conducted by Cuesta, one items of environmental concern was identified on the property that is associated with the former Goodwin Property unregistered landfill and de minimis conditions associated with agricultural usage.

3.2 Conceptual Site Model and Sampling Plan

The conceptual site model takes into consideration the potential distributions of contaminants with respect to the properties and fate and transport characteristics of the contaminant in a setting such as that being assessed. The Tillery Site assessment was designed to investigate the potential presence of soil contamination at the site. Site samples were collected from soil media only.

3.3 Work Plan Deviations

No deviations from the work plan occurred during the assessment. The work plan and sampling plan were presented by E & E in the Quality Assurance Project Plan (QAPP) dated March 2009.

3.4 Environmental Data Search

An Environmental Data Search was performed during the Phase I ESA complete by Cuesta Resources, LLC. The Cuesta Phase I ESA reported one potential recognized environmental condition originating from the adjacent seven acre property. A former unauthorized landfill was operated on the Goodwin Property and its boundary was determined to be undefined. No other recognized environmental conditions exist at the Goodwin Site.

Detailed findings from the Environmental Data Search can be found in the Phase I ESA document prepared by Cuesta Resources, LLC.



3.5 Site Assessment Activities

3.5.1 Soil Investigation

E & E conducted a site investigation on March 26, 2009, during this investigation two soil borings were advanced and eight surface soil samples were collected. The two soil borings were advanced on the subject property using a Geoprobe TM direct push machine. Placement of the soil borings were slightly adjusted due to the overgrowth of vegetation along the northwest portion of the property boundary. The soil borings were placed along the margin of the Goodwin Property and the Tillery Property to determine the presence of encroaching construction debris at depth on the four acre property, if any.

Soil borings were advanced to a depth of ten (10) feet below the ground surface (bgs). There were no visible indications of construction debris throughout the soil borings nor was there any indication of hydrocarbon vapor emitting from the soil boring as indicated by a photo-ionization detector (PID). No soil samples were collected from borehole SB-01 or SB-02. SB-01 was installed with in a ten foot radius of investigation Trench #1 conducted during the URS investigation.

Eight (8) surface soil samples were collected on the subject property using dedicated hand trowels. Each soil sample was immediately placed on ice for transport to Test America Laboratories in Arvada, Colorado.

Soil boring locations and surface soil sample locations were documented using a global positioning satellite (GPS) unit (See Table 4-1). Soil boring sample locations can be found on Figure 3-1. Boring logs are included in Appendix A.

3.5.2 Groundwater Investigation

Groundwater investigation was not a task of this Phase II ESA. E & E identified and documented the presence of a newly-installed groundwater monitoring well on the property during the March 26, 2009 site investigation. A review of the Texas Water Development Board (TWDB) Licensing and Regulations online date base documented that the monitoring well (MW-1) was installed on the Tillery Property on February 24, 2009 and is owned by Tillery LLC. No other information about the monitoring well was available from the database.

E & E received copy of the ground water analytical data associated with monitoring well MW-1. The groundwater sampling report documented that groundwater samples were collected from MW-1 and two other wells thought to exist on the 7 acre Goodwin Site. The groundwater samples were collected on February 25, 2009 and analyzed for VOCs, SVOCs, pesticides, and total metals. According to the analytical data, acetone was the only VOC detected above the SQL but below the MDL and is an estimated concentration. Acetone is a common laboratory contaminant therefore this estimated concentration cannot be considered a verifiable concentration. Barium and selenium were detected at concentrations that are

3. Phase II ESA Activities


above the sample detection limit. These concentrations are consistent with previously reported soil analytical data for the site.

3.6 Sampling and Chemical Analyses Methods 3.6.1 Soil Analyses

Surface soil samples collected during the March 26, 2009 investigation were screened for organic vapors using a PID. Surface soil samples were analyzed for volatile organic carbons (VOCs) by EPA method 8260B, semi-volatile organic carbons (SVOC) by EPA method 8270C, RCRA Metals by EPA method 6020 (Mercury by EPA method 7470/7471A) and Pesticides by EPA method 8081A. A summary of COCs for each soil sample can be found in Table 4-2.

3.6.2 Groundwater Analysis

No groundwater samples were analyzed during this investigation.



4

Analytical Results of Field Investigation

4.1 Analytical Results

The primary constituents of concern assessed as a part of the investigation include VOC, SVOC, RCRA 8 metals, and pesticides.

Analytical data for soil samples are summarized in Table 4-2. A copy of the analytical data package including the data validation memorandum is provided in Appendix B.

TRRP Tier 1 PCLs under a residential scenario with a 0.5 acre source area were used as assessment levels for contaminants found in soil. A Class 1 aquifer resource classification is assumed under these comparisons providing the most conservative assessment. With the exception of lead and mercury, RCRA 8 metals were compared against Tier I PCLs and the Texas-Site Specific Median Background Concentrations for soils. Lead and mercury were compared to Tier 1 PCLs, Tier II PCLs, and Texas-Site Specific Median Background Concentrations.

The TRRP is the tiered process for determining human health and ecological PCLs for COCs. TRRP Tier 1 ^{GW}SOIL_{ING} PCL for surface and subsurface soil is the soil-to-groundwater leaching of COCs for Class 1 and 2 groundwater. TRRP Tier 1 ^{Tot}SOIL_{Comb} PCL for residential soil is a risk based exposure (ingestion, dermal contact, inhalation of volatiles and particulates) pathway.

Calculated TRRP Tier 2 ^{GW}SOIL_{ING} PCL for Soil-to-Groundwater is a risk-based analysis to derive site-specific PCLs for complete or reasonably anticipated completed exposure pathways. Tier 2 PCLS are determined utilizing site-specific exposure factors, as allowable and/or affected property parameters and Tier 1 default values. Tier 2 calculations take into consideration depth to groundwater and soil pH to determine site-specific concentrations. The TRRP Tier 2 evaluation process was continued for COCs (lead and mercury) that did not meet the Tier 1 criteria.

4. Analytical Results of Field Investigation

4.1.1 Soil Analytical Results

Soil samples were collected from eight (8) surface sample locations (SS-01 – SS-08) from 0-6" bgs. All samples were analyzed for VOC, SVOC, RCRA 8 Metals and pesticides. Four (4) random samples were selected to evaluate the pH of the soil. Laboratory results indicated that all VOCs, SVOC, and pesticides were below TRRP Tier 1 $^{\rm GW}$ Soil $_{\rm Ing}$ PCLs for the contaminants of concerns. RCRA 8 metals with the exception of lead and mercury were below the respective TRRP Tier 1 $^{\rm GW}$ Soil $_{\rm Ing}$ values and their respective Texas Median Background Concentrations.

Volatile Organic Compounds

No volatile organic compounds contaminants were detected above the respective Tier 1 ^{GW}SOIL_{ING} PCL or Tier 1 ^{Tot}SOIL_{Comb} PCLs.

Semi-Volatile Organic Compounds

No semi-volatile organic compounds contaminants were detected above the respective Tier 1 ^{GW}SOIL_{ING} PCL or Tier 1 ^{Tot}SOIL_{Comb} PCLs.

RCRA Metals

RCRA 8 metals, with the exception of lead and mercury, compared against the Texas-Site Specific Median Background Concentrations and the TRRP Tier 1 $^{\rm GW}{\rm Soil}_{\rm Ing}$ PCLs were below their respective PCL values.

Lead and mercury were further evaluated using site-specific parameters and Tier 1 default values to determine Tier 2 $^{GW}SOIL_{ING}$ site-specific concentrations. A calculated Tier 2 value of 72.575 milligrams per kilogram (mg/kg) was determined for lead and a calculated Tier 2 value of 0.156 mg/kg was determined for mercury. Lead and mercury was shown to be below their repetitive Tier 2 values.

Pesticides

No pesticides were detected above the TRRP Tier 1 ^{GW}Soil_{Ing} PCLs or Tier 1 ^{Tot}SOIL_{Comb} PCLs for any soil samples.

4.1.2 Groundwater Analytical Results

No groundwater samples were collected during this limited site investigation.

A groundwater monitoring well (MW-1) installed in February 2009 by another contractor was identified during the March 26, 2009 site investigation. Monitoring well MW-1 is located on the eastern side of the Tillery Site. A review of the analytical data from this existing groundwater monitoring well indicated that VOCs, SVOCs, pesticides and RCRA metals were not detected above the sample quantitation limits



4. Analytical Results of Field Investigation

4.1.3 Investigation Derived Waste Analytical ResultsNo IDW was generated during this investigation. Soil cuttings were left on-site and returned to the original soil borings.

Table 4-1
Surface Soil Sample GPS Locations
Tillery Property - Targeted Brownfields
1126 Tillery Street, Austin, Travis County, Texas

Surface Sample Identification	Latitude (degrees)	Longitude (degrees)
SS-01	30.26891000	-97.70272000
SS-02	30.26918000	-97.70261000
SS-03	30.26894000	-97.70241000
SS-04	30.26866000	-97.70216000
SS-05	30.26894000	-97.70196000
SS-06	30.26858000	-97.70169000
SS-07	30.26881000	-97.70156000
SS-08	30.26864000	-97.70140000

Table 4-2ASoil Analytical Reults (TRRP Tier 1 Residential Soil)
Tillery Property Brownfield Assessment

				1						
Analyte										
Analyte		Sample ID:	SS-01	SS-02	SS-03	SS-04	SS-05	SS-06	SS-07	SS-08
		Date:	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09
1 1 1 2 TETD ACHI ODOETHANE	65.28		e Organic Compo			0.00056 U	0.00056.11	0.00056.11	0.00056.11	0.0005611
1,1,1,2-TETRACHLOROETHANE 1,1,1-TRICHLOROETHANE	52263	1.41 1.62	0.00056 U 0.00052 U	0.00056 U 0.00052 U	0.00056 U 0.00052 U	0.00056 U	0.00056 U 0.00052 U	0.00056 U 0.00052 U	0.00056 U 0.00052 U	0.00056 U 0.00052 U
1,1,2,2-TETRACHLOROETHANE	6.9	0.023	0.00052 U	0.00052 U 0.00061 U	0.00052 U 0.00061 U	0.00052 U 0.00061 U	0.00052 U 0.00061 U	0.00052 U	0.00052 U 0.00061 U	0.00052 U 0.00061 U
1,1,2-TRICHLOROETHANE	18.49	0.023	0.00081 U							
1,1-DICHLOROETHANE	4466	18.49	0.00088 U							
1.1-DICHLOROETHENE	2294	0.05	0.00021 U	0.00021 U	0.00021 U 0.00059 U	0.00021 U	0.00021 U	0.00021 U	0.00021 U	0.00021 U
1,1-DICHLOROPROPENE	36.18	0.03	0.00054 U	0.00054 U	0.00039 U 0.00054 U	0.00054 U	0.00054 U	0.00054 U	0.00054 U	0.00054 U
1,2,3-TRICHLOROBENZENE	193	26.28	0.00034 U							
1,2,3-TRICHLOROPROPANE	0.867	0.0022	0.00073 U							
1,2,4-TRICHLOROBENZENE	637	4.79	0.00081 U							
1,2,4-TRIMETHYLBENZENE	131	9.7	0.00073 U	0.00073 U	0.00073 U 0.00058 U	0.00073 U	0.00073 U	0.00073 U	0.00073 U	0.00073 U
1,2-DIBROMO-3-CHLOROPROPANE	0.153	0.0017	0.00058 U							
1,2-DIBROMOETHANE (ETHYLENE DIBROMIDE)	0.734	0.0002	0.00052 U	0.00052 U	0.00052 U	0.0005 U	0.00052 U	0.0005 U	0.0005 U	0.0005 U
1,2-DICHLOROBENZENE	719	17.88	0.00032 U							
1,2-DICHLOROETHANE	11.4	0.013	0.00043 U							
1,2-DICHLOROPROPANE	60.8	0.022	0.00055 U	0.0007 U	0.0007 U	0.0007 U				
1,3,5-TRIMETHYLBENZENE (MESITYLENE)	112	53.2	0.00057 U	0.00057 U	0.00055 U					
1,3-DICHLOROBENZENE	116	6.74	0.00037 U	0.00037 U	0.00037 U	0.00048 U	0.00037 U	0.00037 U	0.00037 U	0.00037 U
1,3-DICHLOROPROPANE	36	0.064	0.00051 U							
1,4-DICHLOROBENZENE	253	2.1	0.00031 U							
2,2-DICHLOROPROPANE	60.8	0.12	0.00044 U							
METHYL ETHYL KETONE (2-BUTANONE)	34376	29.28	0.0018 U							
2-CHLOROTOLUENE	1014	9.068	0.00051 U							
2-HEXANONE	107	3,87	0.0049 U							
4-CHLOROTOLUENE	4.8	37.8	0.00078 U	0.00078 U	0.00078 U	0.00078 U	0,00078 U	0.00078 U	0.00078 U	0.00078 U
METHYL ISOBUTYL KETONE (4-METHYL-2-PENT	5885	4.9	0.0044 U							
ACETONE	9849	42.7	0.0054 U							
BENZENE	65.7	0.0256	0.00047 U	0.00047 U	0.00047 U	0.00047 U	0,00047 U	0.00047 U	0.00047 U	0.00047 U
BROMOBENZENE	147	5,77	0.00049 U	0.00049 U	0.00049 U	0.00049 U	0,00049 U	0.00049 U	0.00049 U	0.00049 U
BROMOCHLOROMETHANE	621	3.039	0.0003 U	0,0003 U	0.0003 U					
BROMODICHLOROMETHANE	97.9	0.065	0.00022 U	0.00022 U	0.00022 U	0.00022 U	0,00022 U	0.00022 U	0.00022 U	0.00022 U
BROMOFORM	400	0.631	0.00022 U	0.00022 U	0.00022 U	0.00023 U	0.00022 U	0.00022 U	0.00022 U	0.00023 U
BROMOMETHANE	45.9	0.13	0.0005 U							
CARBON DISULFIDE	4647	13.58	0.00042 U							
CARBON TETRACHLORIDE	15.8	0.061	0.00063 U							
CHLOROBENZENE	522	1.092	0.00054 U							
CHLOROETHANE	26998	30.9	0.00089 U							
CHLOROFORM	15.57	1.019	0.00029 U							
CHLOROMETHANE	139	0.405	0.00077 U							
CIS-1,2-DICHLOROETHYLENE	767	0.248	0.00056 U							
CIS-1,3-DICHLOROPROPENE	7.58	0.00664	0.0013 U							
DIBROMOCHLOROMETHANE	72.29	0.0491	0.00057 U							
DIBROMOMETHANE	256	1.129	0.00084 U							
DICHLORODIFLUOROMETHANE	13475	239	0.00052 U							
ETHYLBENZENE	5340	7.63	0.00067 U							
HEXACHLOROBUTADIENE	19.6	3.289	0.00055 U							

Table 4-2A
Soil Analytical Reults (TRRP Tier 1 Residential Soil)
Tillery Property Brownfield Assessment

									SS-08
		000.00	00,-0,00	00,-0,00	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09
		le Organic Compo	unds SW8260B (mg/Kg)					
4343	347	0.00059 U	0.00059 U	0.00059 U	0.00059 U	0.00059 U	0.00059 U	0.00059 U	0.00059 U
804	0.621	0.00034 U	0.00034 U	0.00034 U	0.00034 U	0.00034 U	0.00034 U	0.00034 U	0.00034 U
392	0.013	0.00075 U	0.00075 U	0.00075 U	0.00075 U	0.00075 U	0.00075 U	0.00075 U	0.00075 U
8857	150.78	0.001 U	0.001 U	0.001 U	0.001 U	0.001 U	0.001 U	0.001 U	0.001 U
220	31.2	0.00063 U	0.00063 U	0.00063 U	0.00063 U	0.00063 U	0.00063 U	0.00063 U	0.00063 U
1896	121	0.00056 U	0.00056 U	0.00056 U	0.00056 U	0.00056 U	0.00056 U	0.00056 U	0.00056 U
2157	44	0.00058 U	0.00058 U	0.00058 U	0.00058 U	0.00058 U	0.00058 U	0.00058 U	0.00058 U
48153	70.7	0.00061 U	0.00061 U	0.00061 U	0.00061 U	0.00061 U	0.00061 U	0.00061 U	0.00061 U
3733	231	0.00049 U	0.00049 U	0.00049 U	0.00049 U	0.00049 U	0.00049 U	0.00049 U	0.00049 U
2083	84.8	0.00077 U	0.00077 U	0.00077 U	0.00077 U	0.00077 U	0.00077 U	0.00077 U	0.00077 U
6675	3.25	0.00063 U	0.00063 U	0.00063 U	0.00063 U	0.00063 U	0.00063 U	0.00063 U	0.00063 U
1937	99.97	0.0005 U	0.0005 U	0.0005 U	0.0005 U	0.0005 U	0.0005 U	0.0005 U	0.0005 U
103	0.0501	0.00059 U	0.00059 U	0.00059 U	0.00059 U	0.00059 U	0.00059 U	0.00059 U	0.00059 U
5934	8.21	0.00069 U	0.00069 U	0.00069 U	0.00069 U	0.00069 U	0.00069 U	0.00069 U	0.00069 U
589	0.49	0.00039 U	0.00039 U	0.00039 U	0.00039 U	0.00039 U	0.00039 U	0.00039 U	0.00039 U
36.18	0.0358	0.00067 U	0.00067 U	0.00067 U	0.00067 U	0.00067 U	0.00067 U	0.00067 U	0.00067 U
116.9	0.0336	0.00023 U	0.00023 U	0.00023 U	0.00023 U	0.00023 U	0.00023 U	0.00023 U	0.00023 U
15633	127	0.001 U	0.001 U	0.001 U	0.001 U	0.001 U	0.001 U	0.001 U	0.001 U
3.697	0.022	0.0013 U	0.0013 U	0.0013 U	0.0013 U	0.0013 U	0.0013 U	0.0013 U	0.0013 U
		Notes: U -	The material was an	alyzed for, but was r	not detected.	•	•	•	•
	804 392 8857 220 1896 2157 48153 3733 2083 6675 1937 103 5934 589 36.18 116.9 15633	4343 347 804 0.621 392 0.013 8857 150.78 220 31.2 1896 121 2157 44 48153 70.7 3733 231 2083 84.8 6675 3.25 1937 99.97 103 0.0501 5934 8.21 589 0.49 36.18 0.0358 116.9 0.0336 15633 127 3.697 0.022	Date: 03/26/09 Volatile Organic Comport	Date: 03/26/09 03/26/09 Volatile Organic Compounds SW8260B (4343 347 0.00059 U 0.00059 U 804 0.621 0.00034 U 0.00034 U 392 0.013 0.00075 U 0.00075 U 8857 150.78 0.001 U 0.001 U 220 31.2 0.00063 U 0.00063 U 1896 121 0.00056 U 0.00056 U 2157 44 0.00058 U 0.00061 U 0.00061 U 3733 231 0.00049 U 0.00049 U 0.00049 U 2083 84.8 0.00077 U 0.00077 U 0.00077 U 0.00077 U 6675 3.25 0.00063 U 0.00063 U 0.00059 U 0.00069 U	Date: 03/26/09 03/26/09 03/26/09 Volatile Organic Compounds SW8260B (mg/kg) 4343 347 0.00059 U 0.00059 U 0.00059 U 804 0.621 0.00034 U 0.00034 U 0.00034 U 0.00034 U 392 0.013 0.00075 U 0.00075 U 0.00075 U 0.00075 U 8857 150.78 0.001 U 0.001 U 0.001 U 0.001 U 220 31.2 0.00063 U 0.00063 U 0.00063 U 0.00065 U 1896 121 0.00056 U 0.00056 U 0.00056 U 0.00056 U 48153 70.7 0.00061 U 0.00061 U 0.00061 U 0.00061 U 3733 231 0.00049 U 0.00049 U 0.00049 U 0.00049 U 2083 84.8 0.00077 U 0.00077 U 0.00077 U 0.00077 U 0.00050 U 1937 99.97 0.00053 U 0.00053 U 0.00059 U 0.00059 U 103 0.0501 0.00059 U 0.00059 U 0.00059 U<	Date: 03/26/09 03/26/09 03/26/09 03/26/09 Volatile Organic Compounds SW8260B (mg/Kg) 4343 347 0.00059 U 0.00059 U 0.00059 U 0.00059 U 0.00059 U 0.00059 U 0.00034 U 0.00034 U 0.00034 U 0.00034 U 0.00034 U 0.00075 U 0.00063 U 0.00066 U 0.00066 U 0.00056 U 0.00058 U 0.00061 U	Date: 03/26/09 03/26/09 03/26/09 03/26/09 03/26/09 03/26/09 Volatile Organic Compounds \$W8260B (mg/Kg)	Date: 0.3/26/09 0.00059 0.00059 0.00059 0.00059 0.00059 0.00059 0.00059 0.00034 0.00034 0.00034 0.00034 0.00034 0.00034 0.00034 0.00034 0.00034 0.00034 0.00075 0.00075 0.00075 0.00075 0.00075 0.00075 0.00075 0.00075 0.00075 0.00056	Date: 03/26/09 000059 U 0.00059 U 0.00059 U 0.00059 U 0.00059 U 0.00034 U 0.00034 U 0.00034 U 0.00034 U 0.00034 U 0.00034 U 0.00075 U 0.00075 U 0.00075 U 0.00075 U 0.00063 U 0.00063 U 0.00063 U 0.00063 U 0.00056 U 0.00056 U 0.00056 U 0.00056 U 0.00056 U 0.00056 U 0.00058 U 0.00059 U 0.000

 $\label{eq:pcl} \text{PCL / }^{\text{Tot}} \text{SOIL}_{\text{Comb}}$ (March 2009 Tier I tables, 0.5 acre Source Area, Residential Use)

 ${\rm PCL}\:/\:^{\rm GW}{\rm SOIL_{lng}}$ (March 2009 Tier I tables, $\:$ 0.5 acre Source Area, Residential Use)

The associated numerical value is the sample quantitation or detection limit, which has been adjusted for sample weight/sample volume, extraction volume, percent solids, sample dilution or other analysis specific parameters.

J - The analyte was analyzed for, but the associated numerical value may not be consistent with the amount actually present in the environmental sample or may not be consistent with the sample detection or quantitation limit.
The value is an estimated quantity.

H - bias likely high

L- bias likely low

NA - Not Analyzed.

BOLD - Exceeds ^{GW}SOIL_{lng} for Residential Use BOLD - Exceeds ^{TOT}SOIL_{Comb} for Residential Use

Table 4-2BSoil Analytical Reults (TRRP Tier 1 Residential Soil)
Tillery Property Brownfield Assessment

Analyte		Samula ID.	SS-01	SS-02	SS-03	SS-04	SS-05	SS-06	SS-07	SS-08
•		Sample ID: Date:	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09
			emi-Volatile Organ				03/20/09	03/20/09	03/20/09	03/20/09
1,2,4-TRICHLOROBENZENE	637	4.79	0.028 U	0.028 U	0.028 U	0.028 U	0.028 U	0.028 U	0.028 U	0.028 U
1,2-DICHLOROBENZENE	719	17.8	0.028 U	0.028 U	0.028 U	0.028 U	0.028 U	0.028 U	0.028 U	0.028 U
1.2-DIPHENYLHYDRAZINE	5,637	0.032	0.022 U	0.022 U	0.022 U	0.022 U	0.022 U	0.022 U	0.022 U	0.022 U
1.3-DICHLOROBENZENE	116.9	6.74	0.012 U	0.012 U	0.022 U	0.012 U	0.012 U	0.012 U	0.012 U	0.022 U
1.4-DICHLOROBENZENE	253	2.1	0.012 U	0.012 U	0.012 U	0.012 U	0.012 U	0.012 U	0.012 U	0.012 U
2,4,5-TRICHLOROPHENOL	5069	33.8	0.014 U	0.014 U	0.014 U	0.01 U	0.01 U	0.01 U	0.014 U	0.014 U
2.4.6-TRICHLOROPHENOL	66.5	0.175	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U
2.4-DICHLOROPHENOL	196	0.35	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U
2.4-DIMETHYLPHENOL	1053	3.23	0.01 U	0.01 U	0.01 U	0.01 U	0.066 U	0.066 U	0.01 U	0.01 U
2.4-DINITROPHENOL	133	0.0936	0.33 U	0.33 U	0.000 U	0.33 U	0.33 U	0.33 U	0.33 U	0.33 U
2.4-DINITROTOLUENE	6.91	0.00532	0.066 U	0.33 U	0.066 U	0.066 U	0.066 U	0.066 U	0.066 U	0.33 U 0.066 U
2.6-DICHLOROPHENOL	65.5	0.00532	0.066 U	0.066 U 0.069 U	0.066 U	0.066 U 0.069 U	0.066 U 0.069 U	0.066 U	0.066 U 0.069 U	0.066 U
2.6-DINITROTOLUENE	6.91		0.069 U	0.069 U 0.028 U	0.069 U	0.069 U 0.028 U				0.069 U 0.028 U
2-CHLORONAPHTHALENE	5042	0.00481	0.028 U 0.01 U				0.028 U	0.028 U	0.028 U	
	384	669 1.63	0.01 U	0.01 U 0.021 U	0.01 U 0.021 U	0.01 U 0.021 U	0.01 U 0.021 U	0.01 U 0.021 U	0.01 U 0.021 U	0.01 U 0.021 U
2-CHLOROPHENOL 2-METHYLNAPHTHALENE										
	252	17 7.12	0.019 U	0.019 U	0.019 U	0.019 U	0.019 U	0.019 U	0.019 U	0.019 U
2-METHYLPHENOL	1529		0.013 U	0.013 U	0.013 U	0.013 U	0.013 U	0.013 U	0.013 U	0.013 U
2-NITROANILINE	14.1	0.0219	0.05 U	0.05 U	0.05 U	0.05 U	0.05 U	0.05 U	0.05 U	0.05 U
2-NITROPHENOL	114.2	0.134	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U
3,3'-DICHLOROBENZIDINE	10.4	0.062	0.09 U	0.09 U	0.09 U	0.09 U	0.09 U	0.09 U	0.09 U	0.09 U
3-METHYLPHENOL & 4-METHYLPHENOL	297*	0.63*	0.033 U	0.033 U	0.033 U	0.033 U	0.033 U	0.033 U	0.033 U	0.033 U
3-NITROANILINE	19.5	0.025	0.073 U	0.073 U	0.073 U	0.073 U	0.073 U	0.073 U	0.073 U	0.073 U
4,6-DINITRO-2-METHYLPHENOL	5.83	0.0046	0.33 U	0.33 U	0.33 U	0.33 U	0.33 U	0.33 U	0.33 U	0.33 U
4-BROMOPHENYL PHENYL ETHER	0.27	0.35	0.019 U	0.019 U	0.019 U	0.019 U	0.019 U	0.019 U	0.019 U	0.019 U
4-CHLORO-3-METHYLPHENOL	329	4.52	0.066 U	0.066 U	0.066 U	0.066 U	0.066 U	0.066 U	0.066 U	0.066 U
4-CHLOROANILINE	23.5	0.0208	0.082 U	0.082 U	0.082 U	0.082 U	0.082 U	0.082 U	0.082 U	0.082 U
4-CHLOROPHENYL PHENYL ETHER	0.163	0.032	0.021 U	0.021 U	0.021 U	0.021 U	0.021 U	0.021 U	0.021 U	0.021 U
4-NITROANILINE	218	0.108	0.072 U	0.072 U	0.072 U	0.072 U	0.072 U	0.072 U	0.072 U	0.072 U
4-NITROPHENOL	73	0.1	0.097 U	0.097 U	0.097 U	0.097 U	0.097 U	0.097 U	0.097 U	0.097 U
ACENAPHTHENE	2965	236	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U
ACENAPHTHYLENE	3781	408	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U
ANTHRACENE	17744	6889	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U
BENZIDINE	0.0154	0.000011	0.99 U	0.99 U	0.99 U	0.99 U	0.99 U	0.99 U	0.99 U	0.99 U
BENZO(A)ANTHRACENE	5.653	17.7	0.02 U	0.02 U	0.02 U	0.02 U	0.02 U	0.02 U	0.02 U	0.02 U
BENZO(A)PYRENE	0.564	7.64	0.02 U	0.081 J	0.02 U	0.02 U	0.02 U	0.02 U	0.02 U	0.02 U
BENZO(B)FLOURANTHENE	5.713	60.1	0.026 U	0.096 J	0.084 J	0.087 J	0.026 U	0.026 U	0.026 U	0.026 U
BENZO(GHI)PERYLENE	1780	46486	0.016 U	0.016 U	0.016 U	0.016 U	0.016 U	0.016 U	0.016 U	0.016 U
BENZO(K)FLUORANTHENE	57.23	615	0.04 U	0.04 U	0.04 U	0.04 U	0.04 U	0.04 U	0.04 U	0.04 U
BENZOIC ACID	687	189	0.33 U	0.33 U	0.33 U	0.33 U	0.33 U	0.33 U	0.33 U	0.33 U
BENZYL ALCOHOL	7050	29.29	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U
BIS(2-CHLOROETHOXY)METHANE	3.099	0.0117	0.023 U	0.023 U	0.023 U	0.023 U	0.023 U	0.023 U	0.023 U	0.023 U

Table 4-2BSoil Analytical Reults (TRRP Tier 1 Residential Soil)
Tillery Property Brownfield Assessment

Analyte										
Analyte		Sample ID:	SS-01	SS-02	SS-03	SS-04	SS-05	SS-06	SS-07	SS-08
		Date:	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09
			emi-Volatile Organ							
BIS(2-CHLOROETHYL) ETHER	2.17	0.0021	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U
BIS(2-CHLOROISOPROPYL) ETHER	50.6	0.19	0.023 U	0.023 U	0.023 U	0.023 U	0.023 U	0.023 U	0.023 U	0.023 U
BIS(2-ETHYLHEXYL) PHTHALATE	43.1	163	0.094 J	0.14 J	0.11 J	0.13 J	2.5	1.4	5.5	0.096 J
BUTYL BENZYL PHTHALATE	1608	264	0.043 U	0.043 U	0.043 U	0.043 U	0.043 U	0.043 U	0.043 U	0.043 U
CARBAZOLE	234	4.56	0.036 U	0.036 U	0.036 U	0.036 U	0.036 U	0.036 U	0.036 U	0.036 U
CHRYSENE	560	1545	0.027 U	0.027 U	0.027 U	0.027 U	0.027 U	0.027 U	0.027 U	0.027 U
DIBENZ(AH)ANTHRACENE	0.549	15.25	0.019 U	0.019 U	0.019 U	0.019 U	0.019 U	0.019 U	0.019 U	0.019 U
DIBENZOFURAN	266	33.37	0.02 U	0.02 U	0.02 U	0.02 U	0.02 U	0.02 U	0.02 U	0.02 U
DIETHYL PHTHALATE	2701	155.8	0.026 U	0.026 U	0.026 U	0.026 U	0.026 U	0.026 U	0.026 U	0.026 U
DIMETHYL PHTHALATE	1267	62.2	0.023 U	0.023 U	0.023 U	0.023 U	0.023 U	0.023 U	0.023 U	0.023 U
DI-N-BUTYL PHTHALATE	5115	3317	0.029 U	0.029 U	0.029 U	0.029 U	0.029 U	0.029 U	0.029 U	0.029 U
DI-N-OCTYL PHTHALATE	1285	1000000	0.014 U	0.014 U	0.014 U	0.014 U	0.014 U	0.014 U	0.014 U	0.014 U
FLUORANTHENE	2316	1917	0.036 U	0.036 U	0.036 U	0.036 U	0.036 U	0.036 U	0.036 U	0.036 U
FLUORENE	2262	298	0.018 U	0.018 U	0.018 U	0.018 U	0.018 U	0.018 U	0.018 U	0.018 U
HEXACHLOROBENZENE	1.07	1.129	0.029 U	0.029 U	0.029 U	0.029 U	0.029 U	0.029 U	0.029 U	0.029 U
HEXACHLOROBUTADIENE	19.6	3.289	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U	0.01 U
HEXACHLOROETHANE	66.56	1.83	0.021 U	0.021 U	0.021 U	0.021 U	0.021 U	0.021 U	0.021 U	0.021 U
INDENO(123-CD)PYRENE	5.72	173.37	0.022 U	0.032 J	0.022 U					
ISOPHORONE	2231	3.0014	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U
NAPHTHALENE	220.759	31.2	0.031 U	0.031 U	0.031 U	0.031 U	0.031 U	0.031 U	0.031 U	0.031 U
NITROBENZENE	65.67	0.351	0.022 U	0.022 U	0.022 U	0.022 U	0.022 U	0.022 U	0.022 U	0.022 U
N-NITROSODIMETHYLAMINE	0.074	0.000036	0.022 U	0.022 U	0.022 U	0.022 U	0.022 U	0.022 U	0.022 U	0.022 U
N-NITROSODI-N-PROPYLAMINE	0.399	0.00035	0.037 U	0.037 U	0.037 U	0.037 U	0.037 U	0.037 U	0.037 U	0.037 U
N-NITROSODIPHENYLAMINE	571	2.82	0.031 U	0.031 U	0.031 U	0.031 U	0.031 U	0.031 U	0.031 U	0.031 U
N-NITROSOPYROLIDINE	1.61	0.00084	0.021 U	0.021 U	0.021 U	0.021 U	0.021 U	0.021 U	0.021 U	0.021 U
PENTACHLOROPHENOL	2.41	0.0183	0.064 U	0.064 U	0.064 U	0.064 U	0.064 U	0.064 U	0.064 U	0.064 U
PHENANTHRENE	1705	415.7	0.33 U	0.33 U	0.33 U	0.33 U	0.33 U	0.33 U	0.33 U	0.33 U
PHENOL	2868	19.14	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U	0.017 U
PYRENE	1697	1116	0.018 U	0.018 U	0.018 U	0.018 U	0.018 U	0.018 U	0.018 U	0.018 U
				The material was a						

 $\mbox{PCL} \ / \ ^{Tot} \mbox{SOIL}_{Comb}$ (March 2009 Tier I tables, 0.5 acre Source Area, Residential Use)

 ${\rm PCL} \ / \ ^{\rm GW} {\rm SOIL_{lng}}$ (March 2009 Tier I tables, 0.5 acre Source Area, Residential Use)

U - The material was analyzed for, but was not detected.

J - The associated numerical value is the sample quantitation or detection limit, which has been adjusted for sample weight/sample volume, extraction volume, percent solids, sample dilution or other analysis specific parameters.

The analyte was analyzed for, but the associated numerical value may not be consistent with the amount actually present in the environmental sample or may not be consistent with the sample detection or quantitation limit.

The value is an estimated quantity.

- H bias likely high
- L- bias likely low
- NA Not Analyzed.
- BOLD Exceeds GW SOIL ing for Residential Use
- BOLD Exceeds TOT SOIL Comb for Residential Use
- *- PCL for 4-methylphenol, lower of the two

Table 4-2C Soil Analytical Results (TRRP Tier 1 & Tier 2 Residential Soil) Tillery Property Brownfield Assessment

Analyte				Sample ID:	SS-01	SS-02	SS-03	SS-04	SS-05	SS-06	SS-07	SS-08
				Date:	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09
						tal SW6020 (mg/	- 	ı	1		ı	1
ARSENIC	5.9	24.16		5.019	3.4	5.7	3	1.4	2.9	1.7	2.2	2.9
BARIUM	300	7962		443	59 J	81	36	31	34	46	41	61
CADMIUM	-	52.42		1.509	0.28	0.33	0.16	0.16	0.16	0.28	0.2	0.3
CHROMIUM	30	29744		2400	11	15	7.3	4.9	6.4	7.7	6.9	8.5
LEAD	15	500	72.575	3.028	16	24	11	8.4	8.1	18	11	14
SELENIUM	0.3	308		2.29	0.56	1	0.45	0.41	0.48	0.61	0.57	0.54
SILVER	-	95.72		0.478	0.055 J	0.064	0.035	0.029	0.033	0.052	0.037	0.048
	RCRA Metal SW7471 (mg/Kg)											
MERCURY	0.04	3.64	0.156	0.0078	0.015 J	0.021 J	0.012 J	0.0094 J	0.013 J	0.078	0.020 J	0.035
Texas-Specific Background Concentration PCL / Tot SOILComb (March 2009 Tier I tables, 0.5 acre Source Use) Tier 2 PCL / GW (0.5 acre Source Area, F	ce Area, I	ial Use)			H- L-	weight/sample volur The analyte was an environmental samp The value is an estir bias likely high bias likely low	nerical value is the me, extraction volur alyzed for, but the a ble or may not be co	sample quantitation or me, percent solids, sar	nple dilution or other a	has been adjusted for nalysis specific parame stent with the amount a tation limit.	eters.	
	MA - Not Analyzed. (March 2009 Tier I tables, 0.5 acre Source Area, Residential Use) BOLD - Exceeds Tier 1 GW SOILing for Residential Use											
(IVIATOTI 2009 TIEL I TABLES, U.	J acie S	ouice Area,	Nesiderillal U	100)								
						Exceeds Tier 1 TOTS Exceeds Tier 2 GWS						
								al Use pround Concentration				
					BOLD -	LACCOUS TEXAS-OPE	cinc wicdian backy	ground Concentration				


Table 4-2DSoil Analytical Reults (TRRP Tier 1 Residential Soil)
Tillery Property Brownfield Assessment

		1		1								
Amalista												
Analyte		Sample ID:	SS-01	SS-02	SS-03	SS-04	SS-05	SS-06	SS-07			
		Date:	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09	03/26/09			
	1	•	,	ides SW8081B	<u>, , , , , , , , , , , , , , , , , , , </u>		•	•	т			
4,4'-DDD	14.21	12.95	0.00055 U	0.00055 U	0.00055 U	0.00055 U	0.00055 U	0.00055 U	0.00055 U			
4,4'-DDE	10.17	11.77	0.00024 U	0.00060 J	0.00024 U	0.00024 U	0.00024 U	0.00024 U	0.00024 U			
4,4'-DDT	5.41	14.74	0.00059 U	0.00081 J	0.00059 U	0.00059 U	0.00059 U	0.00059 U	0.00059 U			
ALDRIN	0.05	0.102	0.00025 U	0.00025 U	0.00025 U	0.00025 U	0.00025 U	0.00025 U	0.00025 U			
alpha-BHC	0.255	0.0079	0.00021 U	0.00041 J	0.00021 U	0.00041 J	0.00021 U	0.00035 J	0.00021 U			
alpha-CHLORDANE	12.8	738	0.00032 U	0.00032 U	0.00032 U	0.00032 U	0.00032 U	0.00032 U	0.00032 U			
beta-BHC	0.9284	0.0289	0.00029 U	0.00029 U	0.00029 U	0.00029 U	0.00029 U	0.00029 U	0.00029 U			
delta-BHC	2.93	0.17	0.00040 U	0.00040 U	0.00040 U	0.00040 U	0.00040 U	0.00040 U	0.00040 U			
DIELDRIN	0.145	0.048	0.00021 U	0.00021 U	0.00021 U	0.00021 U	0.00021 U	0.00021 U	0.00021 U			
ENDOSULFAN I	60.95	30.81	0.00018 U	0.00018 U	0.00018 U	0.00018 U	0.00018 U	0.00018 U	0.00018 U			
ENDOSULFAN II	272	92.45	0.00029 U	0.00029 U	0.00029 U	0.00029 U	0.00029 U	0.00029 U	0.00029 U			
ENDOSULFAN SULFATE	384	4659	0.00028 U	0.00028 U	0.00028 U	0.00028 U	0.00028 U	0.00028 U	0.00028 U			
ENDRIN	8.84	0.75	0.00031 U	0.00031 U	0.00031 U	0.00031 U	0.00031 U	0.00031 U	0.00031 U			
ENDRIN ALDEHYDE	19.37	627	0.00017 U	0.00017 U	0.00017 U	0.00017 U	0.00017 U	0.00017 U	0.00017 U			
ENDRIN KETONE	18.77	50	0.00049 U	0.00049 U	0.00049 U	0.00049 U	0.00049 U	0.00049 U	0.00049 U			
gamma-BHC	1.105	0.0091	0.00046 U	0.00046 U	0.00046 U	0.00046 U	0.00046 U	0.00046 U	0.00046 U			
gamma-CHLORDANE	7.38	41	0.00027 U	0.00027 U	0.00027 U	0.00027 U	0.00027 U	0.00027 U	0.00027 U			
HEPTACHLOR	0.128	0.188	0.00021 U	0.00021 U	0.00021 U	0.00021 U	0.00021 U	0.00021 U	0.00021 U			
HEPTACHLOR EPOXIDE	0.239	0.058	0.00043 U	0.00043 U	0.00043 U	0.00043 U	0.00043 U	0.00043 U	0.00043 U			
METHOXYCHLOR	271	124	0.00045 U	0.00045 U	0.00045 U	0.00045 U	0.00045 U	0.00045 U	0.00045 U			
TOXAPHENE	1.24	11.5	0.016 U	0.016 U	0.016 U	0.016 U	0.016 U	0.016 U	0.016 U			
			Notes: U -		analyzed for, but wa							
							n or detection limit, whi sample dilution or othe					
PCL / Tot SOIL Comb				• .			•					
(March 2009 Tier I tables, 0.5 acre Source Area, Res	idential Use)		J.				al value may not be co e sample detection or		int actually present in			
,				The value is an es		20 consistent with th	o campio detection of	quantitation innit.				
			H - bias likely high									
PCL / GW SOIL Ing			L- bias likely low									
(March 2009 Tier I tables, 0.5 acre Source Ar	ea, Residentia	al Use)	NA - Not Analyzed.									
			BOLD -	Exceeds GWSOIL	ofor Residential Us	se						
				TOT								

BOLD - Exceeds TOT SOIL Comb for Residential Use

Tier 2 Soil to Groundwater PCL Equation

Analyte: Lead
Location: Tillery Property



^{GW}SOIL_{Ing} = Calculated Tier 2 Soil to Groundwater PCL.

^{GW}GW_{Ing} = Groundwater Ingestion Protective Concentration Level [mg/L]

LDF = Leachate Dilution Factor [unitless]
L₁ = Thickness of affected soil [cm]

L₂ = Depth from top of affected soil to gw [cm]

 ρ_b = Soil bulk denisity [g-soil/cm³-soil]

 θ_{as} = Volumetric air content of the vadose zone [cm³-air/cm³-soil] = θ_{t} - θ_{ws}

 θ_{ws} = Volumetric water content of the vadose zone (soil to groundwater) [cm³-water/cm³-soil]

K_d = Soil-Water Distribution Coefficient [unitless]


H' = Dimensionless Henry's Law Constant H' = H x 41.57 @ 20°C (cm³-H₂O/cm³-air)

K_{SW} = Soil-leachate partition factor for COC [mg/L-water/mg/kg-soil]

Variable		Value	Source
$^{GW}GW_{Ing}$	=	0.015	Tier 1 value for residential and commercial/industrial setting.
LDF	=	20	Tier 1 default for 0.5 acre source area.
L 1	=	0.50	Based on analytical result (0.5 feet).
L 2	=	10	Depth to shallowest groundwater table assumed to be approximately 10 feet bgl.
r b	=	1.67	Tier 1 default.
q as	=	0.21	Tier 1 default.
q ws	=	0.16	Tier 1 default.
K d	=	12	Figure 30 TAC 350.73(e)(1)(A) for clayey soil and pH \leq 5.
H'	=	0	Figure 30 TAC 350.73(e)
K SW	=	0.082673267	Calculated.

Tier 2 Soil to Groundwater PCL Equation

Analyte: Mercury
Location: Tillery Property



^{GW}SOIL_{Ing} = Calculated Tier 2 Soil to Groundwater PCL.

GWGW_{Inq} = Groundwater Ingestion Protective Concentration Level [mg/L]

LDF = Leachate Dilution Factor [unitless]
L₁ = Thickness of affected soil [cm]

L₂ = Depth from top of affected soil to gw [cm]

 ρ_b = Soil bulk denisity [g-soil/cm³-soil]

 θ_{as} = Volumetric air content of the vadose zone [cm³-air/cm³-soil] = θ_{t} - θ_{ws}

 θ_{ws} = Volumetric water content of the vadose zone (soil to groundwater) [cm³-water/cm³-soil]

K_d = Soil-Water Distribution Coefficient [unitless]

H' = Dimensionless Henry's Law Constant H' = H x 41.57 @ 20°C (cm³-H₂O/cm³-air)

K_{SW} = Soil-leachate partition factor for COC [mg/L-water/mg/kg-soil]

Variable		Value	Source
$^{\rm GW}{\rm GW}_{\rm Ing}$	=	0.002	Tier 1 value for residential and commercial/industrial setting.
LDF	=	20	Tier 1 default for 0.5 acre source area.
L_1	=	0.5	Based on analytical result (0.5 feet).
L ₂	=	10	Depth to shallowest groundwater table assumed to be approximately 10 feet bgl.
$ ho_{b}$	=	1.67	Tier 1 default.
θ_{as}	=	0.21	Tier 1 default.
$\theta_{\sf ws}$	=	0.16	Tier 1 default.
K_d	=	0.04	USEPA Supplemental Guidance for Developing Soil Screening Levels for Superfund Sites - Exhibit C-4 (pH of 4.9)
H'	=	0.474	Figure 30 TAC 350.73(e)
K_{SW}	=	5.117E+00	Calculated.

5

Discussion of Findings and Conclusions

The Phase II Environmental Assessment was conducted and documentation prepared in accordance with the ASTM 1903-97 (RE-approved 2002) guidance, regulatory requirements, and work plan documents prepared in association with the Tillery Property.

5.1 Recognized Environmental Conditions

The recognized environmental conditions assessed as part of this limited Phase II ESA include the potential contaminants associated with an adjacent unauthorized landfill. The assessment included the advancement of 2 borings, collection of 8 surface soil samples and field documentation of site conditions at the time of the investigation.

Soil analytical results determined that no soil concentration exceeded their respective protective concentrations levels. RCRA 8 Metals that exceeded TRRP Tier 1 PCLs and/or Texas-Site Specific Median Background Concentrations were further evaluated using TRRP Tier 2 site-specific calculated values.

No indications of organic vapors were detected by the PID in the surface soil borings or the surface samples and no hydrocarbon odors were noticed in any of the investigation borings or surface soil samples.

5.2 Affected Media

Based on the analytical soil sample results obtained from this limited Phase II ESA it can be stated the subsurface soil media is not impacted.

5.3 Evaluation of Media Quality

Data gathered during the assessment documents the presence of construction debris on the adjacent property.

No other media were investigated.



5. Discussions of Findings and Conclusions

5.4 Conclusions

Based on analytical results, it can be stated that the soil media is not impacted by VOCs, SVOCs, pesticides and RCRA metals. RCRA metals with the exception of lead and mercury were below their respective Tier I PCLs. Additional evaluation of the tiered process, determined that lead and mercury were below their calculated Tier 2 values.

6

References

- Bureau of Economic Geology. The University of Texas at Austin, Austin, Texas 78712. *Geologic Atlas of Texas, Austin Sheet.*
- ASTM E1903 97 (Reapproved 2002) Standard Guide for Environmental Site Assessments: Phase II Environmental Site Assessment Process.
- Texas Risk Reduction Program (TRRP), 2008, TRRP Tier 1 PCL Tables, Texas Commission on Environmental Quality, April 23, 2008.
- URS Corporation. January 2009. Tillery Street Limited Site Investigation Austin, Texas Environmental Services Rotation List (2008-2010); Tillery Street Field Investigation Report.
- Cuesta Resources, LLC. May 2008. *Phase I Environmental Site Assessment* at 1126 Tillery Street, Austin, Travis County, Texas
- Ecology and Environment Engineering, P.C. (E & E). *Quality Assurance Manual* (*QAM*), *Revision 5*, March 2004, Lancaster, New York.
- Ecology and Environment Engineering, P.C. (E & E). August 2000, *Quality Management Plan (QMP)*, Lancaster, New York.
- Shaw Environmental, Inc. March 2008. Limited Phase II Environmental Site Assessment Brownfields, Investigation, Goodwin Property, Austin, TX.



A Soil Boring Logs

DRILLING LOG OF WELL/BORING NO. SB-0	1	Page 1 of 1
Project/Location: Austin - Goodwin / 1126 Tillery Street Austin, Texas	Total Depth of Hole (feet BGS):	10
Boring Location: Southwest portion of property	Ground Elevation (feet above):	
	Inner Casing Elevation (TOC):	
Date Started/Finished: 3/26/09 - 3/26/09	Groundwater Depth (feet BGS):	
Drilling Contractor: Total Support Service	First Encountered:	_ Final: ▼
Drill Method: Geoprobe	Geologist:	

										COMMENTS
ELEVATION	DEPTH (feet)	WELL COMPLETI DIAGRAN			SOIL/ROCK DESCRIPTION	PID Readings (PPM)	RECOVERY (feet)	LEL (%)	Blow Counts	Reviewed By:
Ground Surface	Elevation				ground surface (gs)					
			\ \(\frac{1}{2} \)	0.5	Topsoil					
	4		1//	0.5	Silty Sand: fine to medium-grained,					
	1-				well sorted, subrounded grains, loose, slightly moist, dull brown to					
					dull orange.					
				2.0						
	2-				No Recovery					
	-									
	3-									
				4.0						
	4-				Clayey Sand: Fine to medium-grained, well sorted, subrounded grains, loose, slightly					
	1			9	subrounded grains, loose, slightly					
	5-				moist, light yellow orange to yellow orange					
	4				orango					
	6-									
				9						
	7-			1						
	4									
	8-									
]			•						
	9—			,						
	+			1						
	10			10.0						

PROJECT NAME: Austin - Goodwin WELL NO.: SB-01

DRILLING LOG OF WELL/BORING NO. SB-2	^{224 of 238} Page 1 of 1
Project/Location: Austin - Goodwin / 1126 Tillery Street Austin, Texas	Total Depth of Hole (feet BGS): 10
Boring Location: Northwest portion of property	Ground Elevation (feet above):
	Inner Casing Elevation (TOC):
Date Started/Finished: 2/26/09 - 3/26/09	Groundwater Depth (feet BGS):
Drilling Contractor: Total Support Service	First Encountered: ♀ Final: ▼
Drill Method: Geoprobe	Geologist:

ION feet)	WELL COMPLETION DIAGRAM	9010	SOIL/ROCK DESCRIPTION	SAMPLE INTERVAL	dings (PPM)	RECOVERY (feet)			COMMENTS Reviewed By:
ELEVATION DEPTH (feet)		GRAPHIC LOG		SAMPLE	PID Rea	RECOVE	LEL (%)	Blow Counts	
Ground Surface Elevation			ground surface (gs)						
1-			Silty Sand: with trace siliaceous gravel nodules, fine to medium-grained, well sorted, subrounded grains, loose, slightly moist, dull brown to dull orange.						
2— - 3—									
4— - 5—			Silty Sand: with trace siliaceous gravel nodules, fine to medium-grained, well sorted, subrounded grains, loose, slightly moist, dull brown to dull orange.						
6— - 7—									
8 9 10			8.0 Silty Sand: with trace siliaceous gravel nodules, fine to medium-grained, well sorted, subrounded grains, loose, slightly moist, dull brown to dull orange.						

PROJECT NAME: Austin - Goodwin WELL NO.: SB-2

B Analytical Data Summaries

Full data package (1528 pgs in electronic version)

DATA VALIDATION MEMORANDUM

DATE: April 24, 2009

TO: Patrick Johnson, Project Manager, E&E

FROM: Steven Elliott, Chemist/Data Validator, E&E Pensacola

SUBJ: Austin Goodwin Property Brownfield Assessment

Laboratory: TestAmerica, Arvada CO

Project	Lab Work Order
Goodwin Property - 002313.FW24	D9C270268

DELIVERABLES

The laboratory reports are complete, including raw sample and calibration data and supporting documentation, and sufficient to validate the reported data. Validation protocol followed is the US Army Corp of Engineers - EM 200-1-6, Chemical Quality Assurance for Hazardous Toxic and Radioactive Waste (HTRW), October 10, 1997, the US EPA document Methods for Chemical Analysis of Water and Wastes, EPA-600/4-79-020 and laboratory generated specific criteria where applicable.

SAMPLE INTEGRITY

Based on the information provided on the cooler receipt form, the samples arrived at the laboratory intact and properly preserved. Sample receipt temperatures were within the acceptance criteria of 4 ± 2 °C. Completed chain-of-custody (COC) documents are included in the laboratory report.

SAMPLE IDENTIFICATION

The field samples for this laboratory data packages and related laboratory identifications (IDs) are listed on the attached Table 1. Field duplicates for this project were not collected. Project-specific matrix spike/matrix spike duplicates (MS/MSD) were not designated in the field and extra volume was not noted on the COC. A summary of the analytical tests and the number of tests included in the laboratory work order are provided on Table 2. A summary of positive results for blanks samples and the associated qualified samples is provided on Table 3 and 3A. A summary of samples qualified due to surrogate recoveries outside QC limits is provided in Table 4. A summary of samples qualified due to MS/MSD recoveries outside QC limits is provided in Table 5. A summary of LCS recoveries outside QC limits is provided in Table 6. Reanalyzed samples are summarized in Table 7. All tables are attached to this memo.

Table 1 Sample Listing

Work Order	Matrix	Sample ID	Lab ID	Sample Date	Lab QC	MS/ MSD	ID Corrections
D9C270268	Soil	SS-01	D9C270268-001	3/26/2009	MS/MSD (8260, 6020)		None
D9C270268	Soil	SS-02	D9C270268-002	3/26/2009			None
D9C270268	Soil	SS-03	D9C270268-003	3/26/2009			None
D9C270268	Soil	SS-04	D9C270268-004	3/26/2009	MS/MSD (8081)		None
D9C270268	Soil	SS-05	D9C270268-005	3/26/2009			None
D9C270268	Soil	SS-06	D9C270268-006	3/26/2009			None
D9C270268	Soil	SS-07	D9C270268-007	3/26/2009			None
D9C270268	Soil	SS-08	D9C270268-008	3/26/2009			None

Table 2 Analyses

Lab Work Orders	Matrix	Test Method	Test Name	Number of Samples
D9C270268	Soil	SW6020A	Metals by ICP Method 6020A	8
D9C270268	Soil	SW7471A	Mercury by Method 7471A	8
D9C270268	Soil	SW8081	Pesticides by GC Method 8081	8
D9C270268	Soil	SW8260B	VOCs, by GCMS Method 8260B	8
D9C270268	Soil	SW8270C	Semivolatile Organics by Method 8270C	8
D9C270268	Soil	ASTM 2216-90	Percent Moisture	8
D9C270268	Soil	SW9045C	рН	4

HOLDING TIMES

All samples were analyzed within the project-specified holding time.

VOLATILE ANALYSES (8260B)

Blank Summary

Laboratory method blanks and field blanks were performed at the required frequency and no compounds were present above the Reporting Limit (RL) except for the following. Naphthalene and 1,2,3-trichlorobenzene were detected in the method blank associated with batch 9092060 at levels below the RL. Neither naphthalene nor 1,2,3-trichlorobenzene were detected in any of the associated samples and since the bias is high, no qualification was necessary. A summary

of positive results for blanks samples and the associated qualified samples is provided on Table 3 and 3A.

A trip blank was not included with this sample delivery.

Surrogates

The recoveries for surrogates; 1,2-Dichloroethane-d4, 4-Bromofluorobenzene, Dibromofluoromethane, and Toluene-d8 were within acceptable QC limits for all samples.

Matrix Spike/Matrix Spike Duplicates (MS/MSD)

The MS/MSD was performed at the required frequency on sample SS-01. MS/MSD samples were not indicated on the COC as project-specific QC. The percent recovery and relative percent difference (RPD) values were within laboratory QC limits.

Laboratory Control Sample (LCS)

The LCSs were analyzed at the required frequency and all recoveries were within QC limits.

Internal Standards

Internal standard responses were within retention time and area count limits except for

Calibration

The method calibration criteria for initial and continuing calibration were met for all samples.

SEMIVOLATILE ANALYSES (8270C)

Blank Summary

Laboratory method blanks and field blanks were performed at the required frequency and no compounds were present above the PQL except for the following. Bis (2-ethylhexyl) phthalate was detected in the method blank associated with batch 9089241. Bis (2-ethylhexyl) phthalate was detected in all associated samples. Bis (2-ethylhexyl) phthalate results have been qualified as not detected, U, in samples SS-01, SS-02, SS-03, SS-04, and SS-08. The concentration of bis (2-ethylhexyl) phthalate in samples SS-05, SS-06, and SS-07 had concentrations greater than 10x the concentration detected in the method blank so no qualification was necessary.

Surrogates

The recoveries for surrogates 2,4,6-tribromophenol, 2-fluorobiphenyl, 2-fluorophenol, nitrobenzene-d5, phenol-d5, and terphenyl-d14 were within acceptable QC limits with the exception of the dilution analysis of SS-07. All surrogates were reported not detected due to the sample dilution. The result for bis (2-ethylhexyl) phthalate in the diluted sample is the reported result and has been qualified as estimated, J, due to the low surrogate recoveries. A summary of samples qualified due to surrogate recoveries outside QC limits is provided in Table 4.

Matrix Spike/Matrix Spike Duplicates (MS/MSD)

The MS/MSD was performed at the required frequency by the laboratory but on samples not associated with this sample batch. An MS/MSD was not indicated on the COC as project-specific QC.

Laboratory Control Sample (LCS)

The LCSs were analyzed at the required frequency and all recoveries were within QC limits.

Internal Standards

Internal standard responses were within retention time and area count limits.

Calibration

The method calibration criteria for initial and continuing calibration were met for all samples.

Compound Identification and Quantitation

Sample SS-07 was analyzed at a dilution due to a high concentration of bis (2-ethylhexyl) phthalate. The diluted analysis result was within the calibration range of the instrument and should be the reported result. Reanalyzed samples are summarized in Table 7.

The peaks for benzo(b)fluoranthene and benzo(k)fluoranthene results for samples SS-02, SS-003, and SS-004 could not be resolved as part of the analysis. The two compounds are reported as benzo(b)fluoranthene while benzo(k)fluoranthene is reported as not detected. Therefore, the benzo(b)fluoranthene and benzo(k)fluoranthene results were qualified as estimated (J/UJ) with an indeterminate bias in the associated samples.

PESTICIDES (8081A)

Blank Summary

Laboratory method blanks and field blanks were performed at the required frequency. alpha-BHC was detected in the method blank at a level below the RL.. Associated samples have been U qualified if the concentration of the sample was < 5x the amount in the method blank for alpha-BHC.

Surrogates

The recoveries for surrogates decachlorobiphenyl (DCB) and Tetrachloro-m-xylene (TCMX) were within acceptable QC limits for all samples.

Matrix Spike/Matrix Spike Duplicates (MS/MSD)

The MS/MSD was performed at the required frequency on sample SS-04. An MS/MSD was not indicated on the COC as project-specific QC. The percent recovery and RPD values were within QC limits.

Laboratory Control Sample (LCS)

The LCSs were analyzed at the required frequency and all recoveries were within QC limits.

Calibration

The method calibration criteria for initial and continuing calibration were met for all samples with the exception of a continuing calibration verification (CCV) standard that had percent difference results outside of QC limits for methoxychlor. However, methoxychlor was not detected in any of the associated samples and since the bias is high, no qualification was necessary.

METALS (6020A/7471A)

Blank Summary

Laboratory method blanks and field blanks were analyzed at the required frequency and had no target analytes detected above the laboratory PQL.

Matrix Spike/Matrix Spike Duplicate (MS/MSD)

The MS/MSD was performed at the required frequency on sample SS-01 for 6020. A sample from another lot was used for 7471 MS/MSD analysis. An MS/MSD was not indicated on the COC as project-specific QC. The percent recovery and RPD values were within laboratory QC limits with one exception. The MS result for barium was outside QC limits. Barium has been qualified as estimated, J, in sample SS-01. A summary of samples qualified due to MS/MSD recoveries outside QC limits is provided in Table 5.

Laboratory Control Sample (LCS)

The LCSs were performed at the required frequency and all recoveries were within QC limits.

Serial Dilution

Serial dilutions were performed at the required frequency and the percent difference values were within QC limits.

Calibration

The method calibration criteria for initial calibration and continuing calibration criteria were met. Barium and cadmium were detected at levels less than 3x the RL for each compound in the interference check sample (ICS) A. The concentrations of the trace impurities in the solution are not believed to have an adverse affect on the quantitation of barium and cadmium in the samples analyzed.

FIELD DUPLICATE RESULTS

Field duplicates were not submitted with this sampling event.

Table 3 - List of Positive Results for Blank Samples

Method	Sample ID	Sample Type	Analyte	Result (mg/Kg)	Qual	MDL	PQL
SW8260	D9D0200000-060B	MBLK	Naphthalene	0.00080	None	0.00063	0.005
SW8260	D9D0200000-060B	MBLK	1,2,3-trichlorobenzene	0.00077	None	0.00075	0.005
SW8270	D9C3000000-241B	MBLK	Bis (2-ethylhexyl) phthalate	0.073	J	0.046	0.330
SW8081	D9C3100000-210B	MBLK	Alpha-BHC	0.00048	J	0.000021	0.0017

Table 3A - List of Samples Qualified for Method Blank Contamination

Method	Lab Blank	Analyte	Blank Result	Sample Result	PQL	Affected Samples	Sample Flag
SW8270	D9C3000000-241B	Bis (2-ethylhexyl) phthalate	0.073	0.094	0.330	SS-01,	U
SW8270	D9C3000000-241B	Bis (2-ethylhexyl) phthalate	0.073	0.140	0.330	SS-02	U
SW8270	D9C3000000-241B	Bis (2-ethylhexyl) phthalate	0.073	0.110	0.330	SS-03	U
SW8270	D9C3000000-241B	Bis (2-ethylhexyl) phthalate	0.073	0.130	0.330	SS-04	U
SW8270	D9C3000000-241B	Bis (2-ethylhexyl) phthalate	0.073	0.096	0.330	SS-08	U
SW8081	D9C3100000-210B	Alpha-BHC	0.00048	0.00041	0.0017	SS-02	U
SW8081	D9C3100000-210B	Alpha-BHC	0.00048	0.00041	0.0017	SS-04	U
SW8081	D9C3100000-210B	Alpha-BHC	0.00048	0.00035	0.0017	SS-06	U

Table 3B - List of Samples Qualified for Field Blank ContaminationNot applicable

Table 4 - List of Samples with Surrogates outside Control Limits

Method	Sample ID	Analyte	Surr. Rec.	Low Limit	High Limit	Dil Fac	Sample Qual.
SW8270	SS-07	Bis (2-ethylhexyl) phthalate	0.0%	35	125	4X	J Flag

Table 5 - List MS/MSD Recoveries and RPDs outside Control LimitsNone

Table 6 - List LCS Recoveries outside Control Limits None

Table 7 - Samples that were Reanalyzed

Method	Sample ID	Dil Fac	Reason
SW8270	SS-07	4X	Analyte concentration > cal range

Table 8 - Summary of Field Duplicate Results

Not Applicable

Note: Blank spaces indicate analytes was not analyzed or ND.

Key:

A = Analyte

NC = Not Calculated

ND = Not Detected

PQL = Practical Quantitation Limit

RPD = Relative Percent Difference

T = Tentatively Identified Compound



C Photographic Documentation

Photographic Log

#1 Observed construction debris

Date : Time 3/26/09 : 1230

Direction West

PhotographerDavid Aguinaga

#2 Observed construction debris

Date : Time 3/26/09 : 1231 **Direction**

West West

PhotographerDavid Aguinaga



Austin Tillery TBA 2313.FW24.01

Photographic Log

#3 Soil boring SB-02 Date : Time 3/26/09:1240 Direction North Photographer David Aguinaga #4 Soil boring SB-02 Date : Time 3/26/09:1241 Direction Down Photographer David Aguinaga

Austin Tillery TBA 2313.FW24.01

Photographic Log

#5

Looking Northwest from 4-acre property to 7-acre property

Date/Time 3/26/09 : 1232

DirectionNorthwest

PhotographerDavid Aguinaga


#6

Existing groundwater monitoring well

Date/Time 3/26/09 : 1150

DirectionNorth

PhotographerDavid Aguinaga



Austin Tillery TBA 2313.FW24.01