HISTORIC LANDMARK COMMISSION MAY 23, 2016 DEMOLITION AND RELOCATION PERMITS HDP-2016-0280 3213 STEVENSON AVENUE

PROPOSAL

Demolish a ca. 1950 house.

ARCHITECTURE

One-story, rectangular-plan, side-gabled, frame minimal traditional-style cottage with a recessed front entry; single and triple 6:6 fenestration.

RESEARCH


The house was built in 1950. The first owners and occupants were Harold and Eloise Anthony, who had previously lived in San Angelo and Dallas. Harold Anthony was an auditor for Sears, who had a department store at 9th Street and Congress Avenue. The Anthony's lived here until around 1955, when they moved to Beaumont and later to San Antonio for Harold's work as an auditor at Sears. The sales manager for J.R. Reed Music Company, W. Woody Parker, and his wife, Glory, owned and occupied the house in the late 1950s. The house as rented to an engineer, John H. Embry, and his wife, Cecelia, in the early 1960s, and from the mid-1960s onward, the house has been owned an occupied by Herbert and Mary T. Saegert. Herbert Saegert was an administrator at IBM.

STAFF COMMENTS

The house is not listed in any City survey.

STAFF RECOMMENDATION

Encourage rehabilitation and adaptive re-use, but release the permit upon completion of a City of Austin Documentation Package, consisting of photographs of all elevations, a dimensioned sketch plan, and a narrative history, for archiving at the Austin History Center. The house has neither the architectural nor the historical significance to warrant individual designation as a historic landmark.



3213 Stevenson Avenue ca. 1950



OCCUPANCY HISTORY 3213 Stevenson Avenue

From City Directories, Austin History Center Prepared by the City Historic Preservation Office April, 2016

1992	Herbert H. and Mary T. Saegert, owners Administrator, IBM
1985-85	Herbert H. and Mary T. Saegert, owners Administrator, IBM
1981	Herbert H. and Mary T. Saegert, owners Administrator, IBM
1977	Herbert H. and Mary T. Saegert, owners Administrator, IBM
1973	Herbert H. and Mary T. Saegert, owners Administrator, IBM
1968	Herbert H. and Mary T. Saegert, owners Administrator, IBM
1962	John H. and Cecelia Embry, renters

Engineer, Link, Chance, Vought (not listed in the alphabetical section of the
directory)

NOTE: Herbert H. and Mary T. Saegert are not listed in the directory.

1959	W. Woody and Glory G. Parker, owners
------	--------------------------------------

Sales manager, J.R. Reed Music Company, 805 Congress Avenue.

1955 Harold B. and Eloise Anthony, owners

Auditor, Sears & Roebuck, department store, 900-02 Congress Avenue.

1952 Harold B. and Eloise Anthony, owners

Auditor, Sears & Roebuck, department store, 900-02 Congress Avenue.

1949 The address is not listed in the directory.

NOTE: Harold B. and Eloise Anthony are not listed in the directory. They do appear in the 1950 city directory for Dallas, Texas; Harold B. Anthony was an auditor for Sears.

BIOGRAPHICAL NOTES

Harold B. and Eloise Anthony (ca. 1950 – ca. 1955)

Harold and M. Lois Anthony appear in the 1940 U.S. Census for San Angelo, Texas, where they owned their home. Harold Anthony was 37, had been born in Texas, and was a salesman for a retail grocery store. M. Lois Anthony was also 37, had been born in Texas, and was a saleswoman for a retail grocery store. They had no children listed with them. The 1930 U.S. Census shows Harold and Lois Anthony as the owners of a home in San Angelo. Harold Anthony is listed as a farmer.

Harold B. and Eloise Anthony are listed in the 1956 city director for Beaumont, Texas. He was an auditor for Sears. They were living in Sa n Antonio by 1959, when they appear in the city directory there. Harold B. Anthony was listed as a clerk at Sears.

C. T. Johnson

78 and 1/2 of 79

Tarrytown #4

Frame residence and carport attached.

45708 7-28-50

Owner

18thy 19		ERVICE PERMI'stin, Texas	T C	\mathbf{N}_{0}^{0} 6	990
Received of		- JOHNSO	•	Date 9	0-50
Address	32/3	STEUEN	50N	···	
Amount / M	NTY 7	- 110/125	<u> </u>	s-Z	000
-	PITTSFO		·	Size of Tap	111
Date of Connection Size of Tap Made Size Service Made Size Main Tapped From Front Prop. From Front Prop. Location of Meter Type of Box Depth of Main in Depth of Service From Curb Cock Checked by Engr	Line to Curb Cock Line to Curb Cock Line to Curb Cock Line to Tap on Main Dept. Dept. EXED 961	ings Size Size	Reducer Fipe JR 3/4" Coff Lead Comp.	Union Plug Plug Stop " LOO Box Loos W	Job No. Ld. S 23 - SO 2
OWNER H. H. S	aegert	ADDRESS	3213 Stev	renson Av	re
PLAT 164	LOT	78 and $\frac{1}{2}$ if	79	BLK	
SUBDIVISION Tar	rytown #4				
OCCUPANCY be	droom and bat	th			
" "4400			NERS	(000	20
BLD PERMIT #129	406 DATE	5-9-72 ES	STIMATE .	6,000.	,00
CONTRACTOR O	wner	NC	O OF FIXTU	RES se	veral
WATER TAP REC #	existing	SEWER TAP	REC #	existing	<u> </u>
Frm add	n to res. and	d remodel		<u>, , , , , , , , , , , , , , , , , , , </u>	
416 sq f	t		·		
Build	ling permit to Herb	ert Saegert for an add	dition (1972)		