HISTORIC LANDMARK COMMISSION AUGUST 22, 2016 DEMOLITION AND RELOCATION PERMITS HDP-2016-0513 1806 TREADWELL STREET

PROPOSAL

Demolish a ca. 1955 house.

ARCHITECTURE

One-story, rectangular-plan, flat-roofed brick-veneered house with multi-light, metal-framed casement windows.

RESEARCH

There is no building permit for this house, but utility permits indicate that noted local builder A.D. Stenger had a hand in the construction of this house. This is not the typical Stenger design, which was much more in keeping with the ideals of the mid-century Modern architectural movement, but there is no concrete evidence that Stenger did or did not design and build this house, since there is no building permit and no other record that indicates his level of involvement with the project.

The first owner of the house was Joseph J. Serafin, who is also noted on the utility records with Stenger. Serafin and his wife, Billie, came from Erie, Pennsylvania, where he worked as a clerk for General Electric. In Austin, he is listed as a supervisor for the City. The Serafins lived here until around 1957, and James S. and Bethel F. Henderson purchased the house. They owned it until the sale to the current owners. James S. Henderson was a salesman, then he and Bethel established the <u>Texas Textile Maintenance Reporter</u> (apparently from the house). Around 1980, after James' death, Bethel Henderson had Henderson & Henderson, a publishing firm.

STAFF COMMENTS

The house is not listed in any City survey to date.

STAFF RECOMMENDATION

Encourage rehabilitation and adaptive re-use, but release the permit upon completion of a City of Austin Documentation Package, consisting of photographs of all elevations, a dimensioned sketch plan, and a narrative history, for archiving at the Austin History Center. The house, even if not a Stenger design, represents some elements of mid-century Modern design, and is one of several mid-century Modern houses in this neighborhood, which is a little north and west of the heart of the neighborhood that Stenger designed (Airole Way and Arthur Street, off Rundell Place). However, it does not appear to meet the standards for individual designation as a historic landmark.



1806 Treadwell Street ca. 1955



OCCUPANCY HISTORY 1806 Treadwell Street

City Directory Research, Austin History Center By City Historic Preservation Office July, 2016

1992 Bethel F. Henderson, owner

Proprietor, Henderson & Henderson (no listing in the alphabetical section of the directory).

1985-86 Bethel F. Henderson, owner

Proprietor, Henderson & Henderson (no listing in the alphabetical section of the directory).

1981 Bethel F. Henderson, owner

Proprietor, Henderson & Henderson (no listing in the alphabetical section of the directory).

1977 Bethel F. Henderson, owner

Proprietor, Textile Maintenance Reporter (no listing in the alphabetical section of the directory).

1973 James S. and Bethel F. Henderson, owners

Proprietor, Henderson & Henderson (no listing in the alphabetical section of the directory).

1968 James S. and Bethel F. Henderson, owners Proprietors, Texas Textile Maintenance Reporter (no listing in the alphabetical section of the directory). 1965 James S. and Bethel F. Henderson, owners Proprietors, Texas Textile Maintenance Reporter (no listing in the alphabetical section of the directory). 1962 James S. and Bethel F. Henderson, owners Proprietors, Texas Textile Maintenance Reporter (no listing in the alphabetical section of the directory). 1959 James S. and Bethel F. Henderson, owners Proprietors, Texas Textile Maintenance Reporter (no listing in the alphabetical section of the directory). 1958 James S. and Bethel F. Henderson, owners Salesman 1957 Joseph J. and Billie F. Serafin, owners Supervisor, City of Austin NOTE: James S. and Bethel F. Henderson are not listed in the directory. 1955 Billie Serafin, owner Business machine operator, Department of State NOTE: Joseph J. Serafin is not listed in the directory. 1954 Albert R. and Marcella Reed, owners Field auditor, State Education Agency

NOTE: Neither Joseph J. nor Billie Serafin are listed in the directory. They do appear in the 1954 city directory for Erie, Pennsylvania, where Joseph Serafin was a clerk at General Electric.

NOTE: The house was built in 1955, and replaced an older house on the site.

BIOGRAPHICAL NOTES:

James S. and Bethel Henderson (ca. 1956 -)

According to his 1975 death certificate. James Shelby Henderson was living in this house at the time of his death. He was born in 1883 in Illinois and was a sales executive for the Butler Manufacturing Company.

The 1940 U.S. Census shows James S. Henderson as the owner of a house in Kansas City, He was 56, had been born in Illinois, and was a sales manager for Butler Manufacturing Company. His wife's name was Lillian, 51, who had been born in Missouri and had no occupation listed. Lillian had a daughter, Lora G. Henderson, 30, who had been born in Missouri and had no occupation listed.

The 1930 U.S. Census shows James S. and Lillian B. Henderson as the renters of a house in Kansas City, Missouri, where James S. Henderson was a salesman. Lillian B. Henderson had no occupation listed. Her daughter, Lora, when by the last name of Montgomery, and had no occupation listed.

HENDERSON, James S., 92, 1806 Treadwell, died Tuesday. Services 10 a.m. Friday at Wilke-Clay Funeral Home. Survivors: wife, Bethel Fox Henderson of Austin: daughter, Helen Thomas of Boulder, Colo.; stepdaughter, Laura Montgomery of Los Angeles, Calif.; sons, James -Russell Henderson *Portland, Ore., Lloyd Henderson of Overland Park. Kan.; sisters, Jo Hall *Pueblo, Colo., Sallie Martz of 🕏 Sarasota, Fla., Ruth Bellman Tof El Monte, Calif.; eight grandchildren; *great-gra**nd**children; a n d *several nephews and nieces.

> Obituary of James S. Henderson Austin American-Statesman, March 6, 1975

Receipt	t No. 2370 /	Seogle 7			n	N935	223 A
	Must -		Au	stin, Texa	6-2	7	19=35
To t	he Superintendent of	Sanitary Sewe r D i	vision, Cit	y of Austir	, Texas.		
Sir:— I hereby make application for sewer connection and instructions on premises owned by							
further	described as Lot	112	Block	C OI	itlot	Divisio	Street,
subdiv	isia Lun	IPR	Place	, which is			
In this I agree	place there are to be it to pay the City of Au	nstalled fixtur stin, the regular ord	es. linance ch	Plumbing Parge.	ermit No.	1182	4-a
Depth	at Prop. Line 2		3 2 A	ctfully.	4 ×		
Stub-C Connec	12- = /	1/1	-t		Shin	The same	·
Date	6- 295	ition)			2	,	
Ву	Viller	call				1	1 12
NOTE:	Connection Instruction	m & See	iec	ct a	بلاي	29	Dey
Ma	(in 22,50	37719	i Gu	((2)	L > 1	A	3969
	. 2	o Suit	~ CW	166 01	-//		
Sew	er connection appl	cation by A.D. S	tenger ar	nd J.J. Se	rafin for	this hous	se (1955)
}	WA	TER SERVIC	E PERM	ЛIT	F	No '	29 5 5
(C)		Austin, Tex	cas	,	5 <u></u>		2000
Re	ceived of A.D.	STENGER.				Date	ソーノブ
Ad	dress 1806	TREADWEL	LS	<u> </u>	; { 		
Ar		a & Nat 10				_	
	mount LLENGT	117	<u> </u>		,	\$.	20
Pl		HER THE			Si	ze of Tap	3/4
— Σε	umber 5 F L AA	LER THES. 24-55			Si	ze of Tap	3/4
Da _ Siz	umber B. F. LAA	Lied Theo. 24-55 tale in place			Si	ze of Tap	3/4
Da Siz Siz	ate of Connection ze of Tap Made ze Service Made ze Main Tapped	Les Rés. 24-55 tapi in place	Size		Si	ze of Tap	3/4
Da Siz Siz Siz Fr	ate of Connection & ze of Tap Made ze Service Made ze Main Tapped com Front Prop. Line to	Like Place. 24-55 tale in filose Curb Cock	Size		Si	ze of Tap	3/4/
De Siz Siz Fr	ate of Connection	Curb Cock	Size		Si	ze of Tap	3/4/200-25:5:
Da Siz Siz Fr Fr	ate of Connection. 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Curb Cock	Size			ze of Tap	3/4 -202-828
Da Siz Siz Siz From From Lo	ate of Connection ze of Tap Made ze Service Made ze Main Tapped com Front Prop. Line to com Prop. Line to continuous Meter ze General form ze Main Tapped	Lafe in file we Curb Cock Curb Cock	Size Cock		mp	-	Wo. No. 333-50 2- 100 20 No.
Da Siz Siz Siz Fr Fr	ate of Connection. 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Les These Late in file we Curb Cock	Size Cock		mp	-	talves ob No. A. J. J. J. S. J. S.
Da Siz Siz Siz From From Local Ty De De	ate of Connection ze of Tap Made ze Service Made ze Main Tapped com Front Prop. Line to com Prop. Line to continuous Meter zepth-of Main in St	Les Place. 2 & - 5 5 tale in filose Curb Cock. Curb Cock.	Fittings Size Curb Cock Elbow	St. Elbow. Bushing Reducer.	Comp.		Lid. Valves Job No. Act. 3, 3, 3, - 5, - 5, - 5, - 5, - 5, - 5,
Da Siz Siz Siz From From Lo	ate of Connection	Les The Cock Curb Cock Curb Cock	tings Size Curb CockElbow		mp	-	Lid Walves Valves Job No. 4. 3. 3. 3 5. 2 7. 5. 5. 7.

August 4, 2016

To: Steve Sadowsky, Historic Preservation Officer, City of Austin

From: Liza Shapiro and John Allison, Homeowners 1806 Treadwell St.

Re: Application for Demolition permit 2016-083505 PR. (1806 Treadwell St.)

Dear Mr. Sadowsky:

Below is information pertinent to the demolition application for 1806 Treadwell St, specifically, to the issue that has been raised that AD Stenger might have designed it. Thank you for taking it into consideration.

1806 Treadwell St. does not have the signature look of a Stenger house (no stone, no fireplace, no exposed beams, etc). Below we provide some additional background information pointing to the *unlikelihood* that AD Stenger was the architect for 1806 Treadwell St.

Below are two classified ads from 1955-1956 (Austin American Statesman) that prominently displayed Stenger's name as architect, plus a newspaper article discussing two architectural awards he received, one in March 1957 and one in May 1957.

Around that same time, in April 1957, a classified ad for 1806 Treadwell appeared (see below), with no mention of Stenger. Stenger thus was clearly a well known, award winning architect one month before, as well as one month after, the ad appeared for 1806 Treadwell. Since his name is not advertised in association with 1806 Treadwell, it appears unlikely that Stenger designed it, or at at least unlikely that the house was representative of Stenger's iconic architectural style. We hope this information is useful in clarifying the historical issues surrounding our house. Thank you.

Attached are the classified ads and the 1957 article (larger versions are attached as separate pdfs).

Austin Amer Statesman Aug 21, 1955

2000 Dexter - lists Stenger as architect

We Know You Will Be Pleased

With one of our fine, well-planned, quality constructed homes. See this choice home today in South Lund Park.

- Dining room.
 klichen, utilities
- Double garage, brick walk, paved driveway
- 100x176 ft. lot, large private patio
- Large oak trees, 2% it, diameter, creek rear of lot
- 3 bedrooms, den, 80% Mexican living room brick construction Real fireplace, abundance of glass
 - Electric kitchen,
 Sions York year
 around air conditioning
 Walls and ceilings
 heavily insulated
 - Wood paneling throughout house

Architect-Builder-

Developer Phone 8-8921

Build

in

South

Lund

Park





in Ridgewood Village

A. D. STENGER 2000 Dexter Open. House

Austin Amer statesman

Jan 8, 1956

1112 Bluebonnet - lists Stenger as architect

SOUTH LUND PARK 3 BEDROOMS—DEN 214 BATHS \$28,500.

Large oak trees, 212 feet diameter. Privacy — creek in rear, Lot 100x175 feet.
All electric kitchen. Large fireplace,
Masonry construction. 1112 Bluebonnet
Lane. A. D. Stinger, architect and builder. GR 8-8921. May 1957—note this article is dated one month after the ad (Aprill 1957) for our house. The article also mentions that in March of 1957 (one month before the ad for our house) he won the Austin Home Builder's Assn award for home of the month (in Ridgewood Village). So Stenger was a well known, award winning architect one month before, as well as one month after, the ad appeared for 1806 Treadwell. Since his name is not advertised in association with 1806 Treadwell, it appears unlikely that he designed it



Ad for 1806 Treadwell, from Austin American Statesman April 7, 1957- No mention of Stenger

OPEN HOUSE

SUNDAY

2-6 P.M.

1806 TREADWELL (South Lund Park)

Go by Sunday and look at this very attractive, all brick. 3 bedroom. 2 bath home on paved street. Has many attractive features. F.H.A. loan of \$12,000 which can be assumed. Payments \$20 per month includes everything. See it today or call GR 2-1149.

Welch & Co.

300