HISTORIC LANDMARK COMMISSION NOVEMBER 21, 2016 DEMOLITION AND RELOCATION PERMITS HDP-2016-0822 3513 E. CESAR CHAVEZ STREET

PROPOSAL

Demolish a ca. 1946 house.

ARCHITECTURE

One-story, Tudor Revival-styled multi-gabled stuccoed frame house with a new standingseam metal roof, a round-arched vestibule, and single and paired 1:1 fenestration.

RESEARCH

Documentary evidence seems to suggest a 1946 construction date for this house, but staff believes that the house is likely earlier, as it reflects the Tudor Revival design more popular before World War II than afterwards. The first known owners and occupants were James Lauren Johnston and his wife, Paula, who lived here for many years. James Lauren Johnston went into the flooring business, and had his office and woodworks in (possibly) a separate building on this property. His father had also been in the wood flooring business, and James Lauren Johnston's first listings in the city directories for this business show his father, Leroy L. Johnston, as a partner in the business. James Lauren Johnston passed away in 1972; his widow, Paula, continued to live here through the 1990s.

STAFF COMMENTS


The house is beyond the bounds of any City survey to date.

STAFF RECOMMENDATION

Postpone to December 19, 2016 to fully evaluate alternatives to demolition of the house, which is an excellent example of Tudor Revival style, and appears to be in very good condition, with a brand new standing-seam metal roof. If the Commission does not vote to postpone, then staff must recommend release of the permit upon completion of a City of Austin Documentation Package, consisting of photographs of all elevations, a dimensioned sketch plan, and a narrative history, for archiving at the Austin History Center. In an area of the city with very few historic-age houses of this caliber, it seems much more important to reconsider demolition in favor of rehabilitation and adaptive re-use. The other building on the site, a stuccoed former house with very few windows, does not have any historical or architectural significance, and staff recommends release of that permit.

LOCATION MAP

1"=173'




This product has been produced by CTM for the sole purpose of geographic reference. No warranty is made by the City of Austin regarding specific accuracy or completeness.

3513 E. Cesar Chavez Street ca. 1946



This house is vacant – it actually faces Red Bluff Drive, but mail found on the ground at the site indicates its address is 3513 E. Cesar Chavez Street.



D.50 - 4



Stuccoed building (former house) to the west of the house – with a residential-style carport bearing the house number of 3513. There are only two un-stuccoed windows on this building.





East side of the stuccoed former house to the west of the house.

OCCUPANCY HISTORY 3513 E. Cesar Chavez Street

City Directory Research, Austin History Center By City Historic Preservation Office November, 2016

1992	Paula C. Johnston, owner Retired
1985-86	Paula C. Johnston, owner Retired
1981	Paula C. Johnston, owner No occupation listed
1977	Paula C. Johnston, owner Widow, J. Lauren Johnston No occupation listed
1973	Paula C. Johnston, owner Widow, J. Lauren Johnston No occupation listed
1968	J. Lauren and Paula C. Johnston, owners Proprietors, Johnston Wood Floor Company (at the house)
1965	James L. and Paula C. Johnston, owners Proprietors, Johnston Wood Floor Company, finishing contractors (at the house)

1961	James L. and Paula Johnston, owners Proprietors, Johnston Wood Floor Company, finishing contractors (at the house)
1957	James L. and Paula Johnston, owners Proprietor (with Leroy L. Johnston), Johnston Wood Floor Company (at the house. NOTE: Leroy L. (and Ella L.) Johnston lived at 3421 E. 1 st Street.
1953	James L. and Paula C. Johnston, owners Proprietor (with Leroy L. Johnston), Johnston Wood Floor Company (at the house)
1952	James L. and Paula Johnston, owners Proprietor (with Leroy L. Johnston), Johnston Wood Floor Company (at the house).
1949	The address is not listed in the directory. NOTE: James L. and Paula C. Johnston are not listed in the directory.

BIOGRAPHICAL NOTES:

James Lauren and Paula C. Johnston (ca. 1946 -)

The 1940 U.S. Census shows James L. Johnston as the 22-year old son of L.R. and Ella L. Johnston who rented their house at 1903 Canterbury Street in Austin. James L. Johnston was born in Kansas and was a helper in a floor contracting business. His father, L.L. Johnston, 48, had been born in Arkansas, and was a floor contractor. His mother, Ella Johnston, 48, had been born in Kansas, and had no occupation listed. The family had lived in San Antonio in 1935.

The 1930 U.S. Census shows Lauren Johnston as the 12-year old son of Leroy R. and Lois Johnston of San Antonio. Leroy Johnston was a floor contractor. Lauren was their only child.

J. LAUREN JOHNSTON J. Lauren Johnston; 53, of 3515 East First Street, died on Wednesday in Minden, La., from injuries sustained in an automobile accident.

He had been a resident of Austin for 35 years and for the past 25 years had been owner and general manager of Johnston Wood Floor Company. Lauren was a member of Central Assembly of God Church, Carpenters Local No. 1266, and was a widely-known sportsman. member a Of Austin Bass Club and Capitol Bass Club. 1.1.1.1.1.1

For 20 years he had been Chief Aviation Ordinance Officer of the U. S. Naval Reserve. He was a Veteran of World War II.

Survivors include his widow, Mrs. Paula Cranford Johnston of Austin; a daughter, Mrs. Kenneth (Paula Maureen) Keller of San Antonio; a granddaughter, Kimberly Kathleen Keller of San Antonio; his parent, Mr and Mrs. Lee Roy Johnston of Austin.

The body will lie in state at Wilke - Clay Funeral Home beginning Thursday evening; services are scheduled tentatively for Saturday, 2 p.m., at Wilke Clay Funeral Home.

> Obituary of James Lauren Johnston Austin <u>American</u>, March 23, 1972

D.50 - 9

WATE	R SERVICE P	ERMIT		N	? 20	150	2
· · · · · · · · · · · · · · · · · · ·	Austin, Texas			· • • •	? 20	· · · ·	ŝ
Received of Hiram	Moody	~ ~ ~			Date 9-	9-43	
Received of Hiram 3513 5771 2000	East Tst Stree	E- CES	AR Cha	VEZ S	51.		
Amount Tow a	nd 50/100	Ţ.	· · · · · · · · · · · · · · · · · · ·			\$2.50	
Plumber Self		5. ⁻	····/	Sin	of Ten	5/8	•
Date of Connection						-	1
Size of Tap Made			S TP	The -			ľ
Size Service Made	The	18前位于		DIN			1
Size Main Tapped	24	0	246			1	ţ.
From Front Prop. Line to	Currh Cook 2'	山派	1			3	
From Dring Ling to	Cumb Goals 4 -	LALAS JUSES		29	1. 24	C11 3	
Location of Meter	AB	A B		12.	5.3	2 3	
Type of Box	oltin	Ser /	N So S	No No	- Sur	<u> 11</u>	
Depth of Main in St	- 2'	b C	E u lo lo	ples	50, 0	N. ves.	2
Depth of Service Line	2' =	Elb Cur	St. Bus	L N Lea	La E	Lid	
From Curb Cock to Tap on	Main 15'1'	E No	1 3:		11		ľ
Checked by Engr. Dept.Z.	nB.7. 10-6-43	No					
TRUCTO							
From 2, Frop. Line to Location of Meter Type of Box Depth of Main in St Depth of Service Line From Curb Cock to Tap on Checked by Engr. Dept.Z. INDEXED	ter service permi SANITARY SEWER S			(1943)	No. 2136	2	
	SANITARY SEWER S Austin,	SERVICE PE Texas	RMIT		No. 2136		
Received ofI.LJohns	SANITARY SEWER S Austin,	GERVICE PE Texas	RMIT	Dat	No. 2136		
Received of <u>I.L. Johns</u> Address <u>3513 E. 1st.</u>	SANITARY SEWER S Austin,	SERVICE PE Texas	RMIT	Dat	No. 2136 te <u>10/1/</u>	1946	
Received of <u>I.L. Johns</u> Address <u>3513 E. 1st.</u> Amount	SANITARY SEWER S Austin,	ERVICE PE Texas	RMIT	Dat	No. 2136 te <u>10/1/</u> \$	1946	
Received of <u>I.L. Johns</u> Address <u>3513 E. 1st.</u> Amount <u>J.L. J</u>	SANITARY SEWER S Austin, on ohnson	SERVICE PE Texas	RMIT	Dat	No. 2136 te <u>10/1/</u> \$	1946	
Received of <u>I.L. Johns</u> Address <u>3513 E. 1st.</u> Amount Builder or Owner <u>J.L. J</u> Lot <u>75'x200'</u> Bloc	SANITARY SEWER S Austin, on ohnson	SERVICE PE Texas	RMIT	Dat	No. 2136 te <u>10/1/</u> \$	1946	
Received of <u>I.L. Johns</u> Address <u>3513 E. 1st</u> Amount Builder or Owner <u>J.L. J</u> Lot <u>75'x200'</u> Bloc res.	SANITARY SEWER S Austin, on ohnson kSui	SERVICE PE Texas	RMIT	Dat	No. 2136 te <u>10/1/</u> \$	1946	
Received of <u>I.L. Johns</u> Address <u>3513 E. 1st.</u> Amount <u>J.L. J</u> Builder or Owner <u>J.L. J</u> Lot <u>75'x200'</u> Bloc res. Date of Connection <u>4/25/</u>	SANITARY SEWER S Austin, on ohnson kSui	SERVICE PE Texas	RMIT	Dat	No. 2136 te <u>10/1/</u> \$	1946	
Received of <u>I.L. Johns</u> Address <u>3513 E. 1st.</u> Amount <u>J.L. J</u> Builder or Owner <u>J.L. J</u> Lot <u>75'x200'</u> Bloc res. Date of Connection <u>4/25/</u> By City <u>93' W of MH in 1</u>	SANITARY SEWER S Austin, on ohnson kSui	SERVICE PE Texas	RMIT	Dat	No. 2136 te <u>10/1/</u> \$	1946	
Received of <u>I.L. Johnse</u> Address <u>3513 E. 1st.</u> Amount Builder or Owner <u>J.L. J.</u> Lot <u>75'x200'</u> Bloc <u>res.</u> Date of Connection <u>4/25/</u> By City <u>93' W of MH in 1</u> By Plumber	SANITARY SEWER S Austin, on ohnson kSui	SERVICE PE Texas	RMIT	Dat	No. 2136 te <u>10/1/</u> \$	1946	
Received of <u>I.L. Johns</u> Address <u>3513 E. 1st.</u> Amount <u>J.L. J</u> Builder or Owner <u>J.L. J</u> Lot <u>75'x200'</u> Bloc res. Date of Connection <u>4/25/</u> By City <u>93' W of MH in 1</u> By Plumber <u>Checked By Kirby</u>	SANITARY SEWER S Austin, on ohnson k 1947 st	SERVICE PE Texas	RMIT	Dat	No. 2136 te <u>10/1/</u> \$	1946 00. 264 00. 1 00. 1 00. 00 07 07 07 00 07	
Received of <u>I.L. Johns</u> Address <u>3513 E. 1st.</u> Amount <u>J.L. J</u> Builder or Owner <u>J.L. J</u> Lot <u>75'x200'</u> Bloc res. Date of Connection <u>4/25/</u> By City <u>93' W of MH in 1</u> By Plumber <u>Checked By Kirby</u>	SANITARY SEWER S Austin, on ohnson k 1947 st	ervice pe Texas	RMIT	Dat	No. 2136 te <u>10/1/</u> \$	1946 00. 264 00. 1 00. 1 00. 00 07 07 07 00 07	
Received of <u>I.L. Johns</u> Address <u>3513 E. 1st.</u> Amount <u>J.L. J</u> Builder or Owner <u>J.L. J</u> Lot <u>75'x200'</u> Bloc <u>res.</u> Date of Connection <u>4/25/</u> By City <u>93' W of MH in 1</u> By Plumber <u></u> Checked By <u>Kirby</u> Size Main <u>6"</u> <u>D</u> Main Assign. <u>in E. 1st.</u>	SANITARY SEWER S Austin, on ohnson k 1947 st epth	ervice pe Texas	RMIT	Dat	No. 2136 te <u>10/1/</u> _\$ Plat N	1946 00. 264 00. 1 00. 1 00. 00 07 07 07 00 07	
Received of <u>I.L. Johns</u> Address <u>3513 E. lst.</u> Amount <u>J.L. J</u> Builder or Owner <u>J.L. J</u> Lot <u>75'x200'</u> Bloc <u>res.</u> Date of Connection <u>4/25/</u> By City <u>93' W of MH in 1</u> By Plumber <u></u> Checked By <u>Kirby</u> Size Main <u>6''</u> D Main Assign. <u>in E. lst.</u> Stub Depth <u></u> P	SANITARY SEWER S Austin, on ohnson k 0.L. 16 st epth con	ervice pe Texas	Plumb E.H. Dea	Dat	No. 2136 te <u>10/1/</u> _\$ Plat N	1946 00. 264 00. 1 00. 1 00. 00 07 07 07 00 07	7 02
Received of <u>I.L. Johns</u> Address <u>3513 E. lst.</u> Amount <u>J.L. J</u> Builder or Owner <u>J.L. J</u> Lot <u>75'x200'</u> Bloc <u>res.</u> Date of Connection <u>4/25/</u> By City <u>93' W of MH in 1</u> By Plumber <u></u> Checked By <u>Kirby</u> Size Main <u>6"</u> D Main Assign. <u>in E. lst.</u> Stub Depth <u>P</u>	SANITARY SEWER S Austin, on ohnson k 0.L. 16 st epth con	SERVICE PE Texas	Plumb E.H. Dea	Dat	No. 2136 te <u>10/1/</u> _\$ Plat N	r tap saddle .20 0 truck @.40 40 57 1 hr. @1.00 1.00 95	7 07
Received of <u>I.L. Johns</u> Address <u>3513 E. lst.</u> Amount <u>J.L. J</u> Builder or Owner <u>J.L. J</u> Lot <u>75'x200'</u> Bloc <u>res.</u> Date of Connection <u>4/25/</u> By City <u>93' W of MH in 1</u> By Plumber <u></u> Checked By <u>Kirby</u> Size Main <u>6''</u> D Main Assign. <u>in E. lst.</u> Stub Depth <u></u> P	SANITARY SEWER S Austin, on ohnson k 0.L. 16 _Sub 1947 st epth6' rop. Line3'	ervice pe Texas	Plumb E.H. Dea	Dat	No. 2136 te <u>10/1/</u> \$	tap saddle .20 0 tck (3.40 40 7 hr. (31.00 1.00 79	7 07

Sewer service permit to J.L. Johnston for this address (1946)