

Project Name: Mary Street Local Historic District

Case Number: C14H-2018-0015 Update #: 0 Case Manager: Steve Sadowsky

Team:

Date Filed: January 31, 2018 Date Dist: February 01, 2018

## Comments Due Date: February 21, 2018

Discipline	Name

NPZ Historic Review NPZ Legal Department Review NPZ Mapping Review NPZ Comprehensive Planning Review

Notice Zoning

Steve Sadowsky Cathy Curtis – email Mapping Review Kathleen Fox

Andrew Rivera - email



Report run on:

1/31/18

TO:

 FROM: SITE PLAN REVIEW DIVISION

 TYPE/SUBTYPE:
 Historical/

 PROJECT:
 Mary Street Local Historic District

 LOCATION:
 502 E MARY ST

 CASE MANAGER:
 Steve Sadowsky

 FILED FOR UPDATE:
 TENTATIVE PC DATE:

 TENTATIVE CC DATE:
 LANDUSE::

CASE # C14H-2018-0015

PHONE 512-974-6454 COMMENT DUE DATE REPORT DATE:

	AREA:	ACRES (SQ FT)	LOTS:	
	EXISTING ZOI	NING: 999 - SEE CON	/MENTS	•
	EXISTING USI	E:		
	TRACT:	ACRES/SQFT	PROPOSED ZONING	PROPOSED USE
			See Comments	
	WATERSHED:	Blunn Creek, ,		
	COUNTY:	TRAVIS	'n	
	JURISDICTIO	N Full-Purpose		Urban Watersheds
	GRIDS:		WATER:	
	GRIDS:		ELECTRIC:	
	GRIDS:		SEWERAGE:	
•	GRIDS:			
	PROPERTY D	ESCRIPTION:		
	PLAT: 0302	020419		
	DEED REFER	ENCE:		
	VOL./PAG	E /		

LEGAL DESCRIPTION:

LOT 19 \*LESS W 10.7SQ FT TRI BLK 9 BLUE BONNET HILLS RELATED CASES (if any):

CONTACTS:

50027 Distribution Memorandum



# Applicant

917-328-3357

James Bilodeau

502 E MARY STREET AUSTIN TX 78704

Mary Street Local Historic District Nomination

Reviewed for completiness 1/29/2018.

MARY STREET LOCAL HISTORIC DISTRICT NOMINATION FORM

1. NAME OF DISTRICT

Mary Street Local Historic District

2. GEOGRAPHIC DESCRIPTION

> The district boundaries follow the length of E. Mary St. between Newning Avenue and East Side Drive. The district includes homes on the north and south side of the 500 block of E. Mary Street. The district is bordered by Stacy Park on the west.


**PROPERTIES WITHIN THE DISTRICT** 3.

> There are 19 properties within the district; 17 structures (89%) are contributing to the historic character of the district and 2 properties (11%) are not contributing. Structures inventoried include principal structures and outbuildings of substantial scale that serve as a residence. In order to be considered contributing, structures must date to the district's period of significance (1929-1939) and maintain integrity (see Section 7). The two structures that are not contributing were still constructed in the period of significance. They have just had modifications that would prevent them from being contributing. The combined legal acreage of properties in the district is 2.848 acres.

4. PRINCIPAL ARCHITECTURAL STYLES AND PERIODS OF CONSTRUCTION

Representing more than 50 percent of the properties in the Mary Street Historic District, the Craftsman style is the most prevalent architectural style. Tudor revivals represent 26% of the homes in the district and minimal traditional, 11%. Colonial Revival and Neoclassical represent 5% each. The contributing Craftsman style homes were constructed throughout the period of significance for the district (1929-1939. The contributing Minimal Traditional style homes were constructed in 1935 and 1939. The Tudor revival style homes in the district were constructed between 1930 and 1936. The Colonial Revival home the Neoclassical home were both built in 1931.

Coren Bentrem Deputy Historic Presemention Office




## ARCHITECTURAL STYLES OF CONTRIBUTING STRUCTURES IN THE DISTRICT



**506 East Mary Street** is a good example of the **Craftsman** style in the Mary Street Historic District. This single-family, rectangular plan dwelling was constructed in 1931. The structure has clapboard siding and rests on a masonry pier and beam foundation. The windows are double hung and feature wooden screens. The glazed front door also has a screen door. The roof is a front-facing jerkinhead gable featuring an extended cornice, exposed rafters, and brackets. The partial-width front porch features a smaller jerkinhead gable and mimics the detailing of the larger gable. The porch is supported by square posts and features wood railings and banisters.

**512 East Mary Street** is a good example of the **Minimal Traditional** style. Constructed in 1935, this two-story, massed plan house is clad in stucco and has a hipped roof with gable. The low-pitched roof has composition shingles. Consistent with the simplicity of design common to Minimal Traditional style homes, the house has little architectural detailing. The windows are double hung wood. A partial width porch features an inset and metal porch railings.





502 East Mary Street is a good example of the **Tudor Revival** style. The house was constructed in 1930 and features the original wooden "teardrop" siding. The roof is comprised of composition shingles with steeply pitched front gables typical of the Tudor style. The larger gable features a decorative arched attic vent. The entryway is also arched, and features wood inlays typical of the Tudor Revival style.

5. PERIOD(S) OF SIGNIFICANCE

The period of significance for the Mary Street Historic District is 1929 to 1939. Mary Street was platted in 1928 as part the Blue Bonnet Hills Subdivision and the first home in the district was constructed in the following year (see Section 9). The final year of the period of significance is 1939, 78 years prior to the date of this application (2017). No homes within the district were constructed outside of the period of significance.

### 6. ARCHITECTURAL COMPOSITION OF THE DISTRICT

CONTRIBUTING SINGLE-FAMILY RESIDENTIAL BUILDINGS

A. STORIES

Four of the buildings in the district have two stories, two of which are not contributing. The remaining two have additions that do not detract from the character of the houses, allowing for contributing status. All of the remainder of the houses in the district are single story. All of the single-story structures are contributing.

B. MATERIALS

WALLS

Almost 85 percent of contributing buildings in the district are clad in wood. One building is clad in asbestos siding, another in vinyl and another in stucco.

### ROOF

Most homes in the district (85 percent) have composition shingle roofs. The remaining 15 percent are metal.

### WINDOWS

Over 89 percent of windows in the district are wooden double-hung units. Other window materials include vinyl and aluminum.

C. ROOF TYPES

The most prevalent roof type in the district is side-gabled (40 percent), followed by frontgabled (25 percent). Other roof types include cross-gabled, hipped, and flat.

D. ADDITIONS

Additions to contributing structures allow the buildings to retain integrity and are therefore commonly found at the rear of the house and executed with compatible materials and scale. 500 Mary St. provides an example of an addition that is compatible with the existing character.

E. PORCHES

Front porches are a significant architectural feature of houses in the district. Porches are present on the vast majority of contributing structures in the district; over 80 percent have a full or partial width front porch.

F. CHIMNEYS

Only 1 contributing building in the district has a chimney which is constructed from stone.

G. GARAGE APARTMENTS

There are no contributing structures in the district that are garage apartments.

H. WALLS/FENCES/LANDSCAPE FEATURES


Many of the district's lots are shaded by dense mature tree cover. Oak wilt killed many of the live oaks on the south side of the district. The neighborhood was able to spare the live oaks on the north side of the street by "trenching" to prevent spread of the disease through tree root systems. As a result, many large "heritage" oaks can be found along the north side of the district. The lot at 500 E. Mary St (at the intersection with Newning Ave.) is known for having some of the largest live oaks in the Travis Heights neighborhood.

The designed landscape elements within the district are varied and eclectic. Generous yards, commonly twenty feet deep, are as often heavily covered with dense groundcover, plantings, fences and stone-lined gardens as they are open grass lawns with a few shade trees. Because there are no sidewalks in the district, many yards have walkways of various types from the street to the front door or porch. These walkways are generally separate from driveways, which often lead to the side or rear of the buildings. On some lots, fences and short retaining walls line the edge of the street. Additionally, a lack of sidewalks promotes dense plantings along the street curb, which often spill over into the street.

### 7. ASSESSMENT OF INTEGRITY

The evaluation of architectural integrity and the determination of which buildings are contributing and non-contributing to the historic district was made by architectural historians meeting the Secretary of the Interior's Professional Qualifications for an Architectural Historian, as described in Code of Federal Regulations Title 36, Chapter I, Part 61.

For the Mary Street Historic District, individual structures were evaluated to determine whether each building has retained sufficient historic integrity of those features necessary to convey its significance. The National Park Service has identified seven aspects of integrity: location, design, setting, materials, workmanship, feeling, and association. Structures that have lost integrity were determined to be noncontributing to the district. Only two houses that date to the period of significance were determined to lack sufficient integrity to contribute to the historic character of the district, primarily due to large additions. The nature of these additions and other modifications resulted in the loss of integrity of design, materials, and/or workmanship. These types of modifications include incompatible, large-scale additions and replacement or removal of character-defining features. Modifications were considered in sum for each property; replacement of doors or windows alone did not necessarily result in a determination of loss of integrity. Porch enclosures also did not always necessarily result in a determination of loss of integrity; some buildings retain the ability to convey their historic appearance with enclosed partial width porches.



Section of E. Mary Street shown on 1962 Sanborn map

Regarding the district as a whole, the Mary Street Historic District retains a remarkable degree of integrity. The spatial organization of the district has remained relatively unchanged over time. Although early maps showed a portion of E. Mary Street west of Newning Street, this section was never opened and was in-filled with lots sometime after 1962. In 1932, the residents of Lockhart Drive petitioned the City Council to open the street from Brackenridge Street to Newning Avenue, which required the purchase of one lot; the remaining land between the lot and Brackenridge Street was donated by the owner.<sup>1</sup> Mary Street was not paved when it was first established and was still not paved in 1940.

based on an analysis of historic aerial photography. Although the street has since been

improved, they have not been widened and sidewalks have not been added.

Eight-nine percent of homes in the district have retained their integrity and are contributing structures. The district appears much as it did during the period of significance. There has been no new construction in the district since the period of significance.

## 8. BUILDING LOCATIONS AND LANDSCAPE FEATURES

Buildings are generally oriented towards the street and are set back from the lot line by around twenty feet. In a typical small lot, a driveway will extend from the street past the side of the house to the rear of the lot where there might be a back yard, a garage or other outbuildings. Most of the driveways are single-car width. A majority of the homes have have detached garages. Historically, the majority of homes had garages as well. Other outbuilding types include detached sheds and studios. See Section 6.A.viii for further discussion of landscape features.

## 9. HISTORIC CONTEXT OF THE DISTRICT

### SOUTH AUSTIN CONTEXT

Mary Street is part of the Blue Bonnet Hills Addition which is located in south-central Austin, approximately one mile south of the Colorado River and one block north of Live Oak Street. As of 1927, one year before Blue Bonnet Hills was platted, Live Oak Street was the southern boundary of the city limits. The Colorado River served as the southern boundary of the 1839 plat of Austin; the city limits were not extended south of the river until 1891. In 1852, James G. Swisher granted Travis County right of way through his farm for a road connecting Austin to San Antonio that would later become South Congress Avenue. Development was limited, however, by the lack of a reliable crossing over the Colorado River. After the collapse of several wooden bridges, an iron bridge was constructed in 1883, financed by a toll.<sup>2</sup> The City of Austin and Travis County purchased the bridge and opened it to the public free of charge in 1886.<sup>3</sup> At the time the free bridge was opened, two residential areas had been platted south of the river in

<sup>1</sup> Austin City Council Meeting Minutes, April 14,1932

<sup>2</sup> Early Austin Bridge," The Texas Public Employee, January 1969.

<sup>3</sup> Ibid

anticipation of the desirability of the area for development.

In 1876, James Swisher's son, John Milton Swisher, subdivided 180 acres of the family farm into lots along both sides of South Congress Avenue. Fairview Park, established by Charles Newning and his partners William Stacy and George Warner, was platted in 1886, north and east of the Swisher Addition. Newning established a line of horse-drawn omnibuses that carried southsiders across the bridge; the fare was exclusive of the bridge toll, which he subsidized.<sup>4</sup> Although Fairview Park enjoyed some early success, including the construction of several large homes for prominent Austin businessmen, growth in the district was limited by two factors: the small market for large homes and lots as well as wealthy Austinites' disinclination to live south of the river, separated from the employment and political center of town.

The late 1920s and early 1930s were an important period in the development of south Austin. The effects of the Great Depression were countered somewhat by New Deal programs, which worked to pave streets and build bridges and parks.<sup>5</sup> Although citizens had been petitioning the City to pave South Congress since at least 1916, the 90-foot wide paving to Riverside was finally completed in 1931.<sup>6</sup> In 1928, the Dallas engineering firm Koch and Fowler developed the first comprehensive planning document for the city of Austin, which recommended that all of the land along Blunn Creek between the river and East Live Oak Street become parkland. Much of the land that comprises today's Blunn Creek greenbelt was initially platted as part of residential subdivisions. In 1929 the City purchased almost all of the land that would comprise Big and Little Stacy Parks and the greenbelt from individual property owners as well as the developers of the Travis Heights subdivision.

<sup>4</sup> Austin Weekly Statesman, Vol. 18, No. 27, Ed. 1, Thursday, May 23, 1889

<sup>5</sup> Elizabeth " Travis County," Handbook of Texas, http://www.tshaonline.org/handbook/online/articles/hct08.

<sup>6</sup> Austin City Council Meeting Minutes, March 7, 1929; Austin Daily Statesman, January 5, 1916, as transcribed in the 1916 Austin File Chronological, Austin History Center.

By 1931, 600 lots had been sold in Travis Heights, with 171 homes built.<sup>7</sup> By 1937, over 300 homes had been built, and developer Harwood Stacy described the year as the neighborhood's best to date.<sup>8</sup> Meanwhile, in Fairview Park, sales had slowed since the initial opening, and parts of the neighborhood were subdivided to create smaller lots. Woodlawn and Norwood Heights were subdivided from Fairview Park in 1926 and 1930, respectively. Blue Bonnet Hills was platted in 1928, and the small Roy C. Archer subdivision was platted in 1935. Although early development in Fairview Park and Travis Heights was characterized by grand Victorian homes on large lots, more modest homes dominated development in the late 1920s and later. Within the earliest platted subdivisions, bungalows slowly in-filled previously undeveloped lots, creating an eclectic mix of styles and periods of construction. Travis Heights area subdivisions platted in the 1920s and later reflected more rapid and uniform development in terms of style and scale. Blue Bonnet Hills was over 60 percent built out by 1935, with an overwhelming majority of the homes constructed in that period executed in the Craftsman and Tudor Revival styles. The demographics of residents also shifted; in contrast to the wealthy first residents of Fairview Park, Blue Bonnet Hills was a working-class neighborhood comprised of a mix of owners and renters.

A flood in June 1935 caused significant damage to South Austin, including South Congress Avenue. The city entered into an agreement to with the State Highway Department to finance flood repairs to the avenue, and destroyed buildings were also rebuilt. The Statesman noted in 1936 that the businesses that were destroyed "have been replaced by bigger, more attractive structures."<sup>9</sup> South Congress Avenue continued to develop as a commercial corridor, including

several roadside motels. The Austin Motel was established in 1938 and the San Jose Motel was built a year later. According to a 1939 issue of the South Austin Advocate reflecting on the history of South Austin, in 1909 "South Congress was a muddy lane with three grocery stores and one market"; by 1939 there were 13 groceries and markets and many other types of business.<sup>10</sup> In 1941, the South Lamar bridge was constructed, providing an alternative to the Congress Avenue bridge. Development in South Austin still paled in comparison to the growth of the city north of the river. In 1950, the population south of the river was only 15,000, compared to a population of 132,000 for the city as a whole.<sup>11</sup> The first high school in South Austin, Travis High School, was constructed in 1953, and in 1956 Oltorf Street was extended to connect Lamar Boulevard and the new Interregional Highway (I-35).

#### BLUE BONNET HILLS

Historical development patterns in the Blue Bonnet Hills District were traced based on an analysis of Travis County Central Appraisal District year-built data; Austin City Directory records from 1927, 1929, 1930-31, 1932-33, and 1935; and Sanborn maps from 1922, 1935 and 1962. The "Paul H. Pfeifer Subdivision" was platted in March 1928, comprised of 33 lots along Leland Street and Terrace Drive, east of Brackenridge Street. One month later, the subdivision was expanded under the name "Blue Bonnet Hills Addition," which extended the boundaries to the north and east.

The Blue Bonnet Hills Addition had nine blocks with between five and 23 lots in each block. Blocks Six through Eight were platted on the east side of East Side Drive; these 22 lots becamepart of the Blunn Creek Greenbelt rather than ever being developed as residential property. Only one existing structure is depicted on the 1928 plat map—a relatively large one-story dwelling on Terrace Drive that has since been demolished. Also of note, the portion of Annie Street west of Newning was labeled Turner Avenue on the Blue Bonnet Hills plat map; by the time the first residences were constructed there (1930), the street was known as Annie, a continuation of the street that extended west of S. Congress Avenue. Leland Street was also historically labeled on maps as Sandow Avenue, although this street name did not appear in city directories.

The first homes in the Addition were constructed the same year the subdivision was platted (1928), on Lockhart Drive and Terrace Drive. The oldest homes in the district are likely 511 Lockhart Drive, 514 Lockhart Drive, and 503 Terrace Drive. Four more homes were constructed

<sup>7 &</sup>quot;Stacy Firm Has Fostered Many Additions," Austin Statesman, August 12, 1931.

 <sup>8 &</sup>quot;Travis Heights Develops Rapidly," clipping in Austin File Collection S6300: Subdivisions—Travis Heights, Austin History Center.
 9 Madison, "Our Little Town."


<sup>10</sup> South Austin Advocate, Centennial Edition, #21, Vol. 3, April 28, 1939.

<sup>11</sup> Mike Cox, "South Austin Comes of Age," Austin-American Statesman, 1976, clipping in Austin File Collection S6290: Subdivisions—South Austin, Austin History Center.

in 1929, followed by a surge of building activity in the early 1930s. It should be noted that because a single city directory was published for the years 1930-1931 and 1932-1933, addresses first appearing in these editions were conservatively assumed to have been constructed in the second year of the publishing dates. Based on data from Sanborn maps and city directories, it is estimated that 74 homes, or approximately 63 percent of the district, had been constructed by 1935 (65 of those remain today). At this time, within seven years of its platting, development was spread relatively uniformly throughout the district, with East Side Drive and Leland Street having the most vacant lots. An additional 22 homes were constructed between 1936-1939, after which development began to taper off; seven homes were constructed in the 1940s and six were constructed in the 1950s. According to Sanborn maps, only five vacant lots remained within the district in 1962. The uptick in new home construction in the district beginning in 2006 illustrates the recently renewed interest in the larger Travis Heights/ Fairview Park community as an attractive, close-in neighborhood. This area is so desirable that buyers are willing to purchase developed lots and demolish existing structures to make way for larger modern residences.

#### MARY STREET

Over 50 percent of the homes in the Mary Street district constructed between 1929 and 1939 were Craftsman style and over 25% are Tudor Revival. The district also has representation of Colonial Revival, Neoclassical and Minimal Traditional that was built during this period as well.



## HOMES CONSTRUCTED IN MARY STREET HISTORIC DISTRICT BY YEAR, 1929-1939

Mary Street was settled as a working class neighborhood with many former veterans of World War I. Multiple residents were employed by the Steck Company, a printing and office supply company located on 9<sup>th</sup> and Lavaca St. Elgin O Burrer, the initial resident of 512 E. Mary St. was a barber at the Driskill Barber Shop from 1932 to at least 1949. He then became proprietor of the Commodore Perry Hotel Barber Shop at 800 Brazos St. Other residents were mechanics, retail sales clerks, plumbers, electricians, carpenters, beauticians and stenographers.

Many were also employed in federal and state government. Edward Sponberg of 500 E. Mary St. was a postal worker. Leslie Sedwick who resided at 502 E. Mary St. from 1930 to at least 1966 was a firefighter. William M. Ferguson, the initial resident of 508 E. Mary St. was an IRS Auditor from 1932

to 1958.

Many of the initial residents of Mary St. lived there for extended periods of time. Edward and Hattie Sponberg who moved into 500 E. Mary St. in 1929, lived there until at least 1980. Lois Huber lived at 516 E. Mary St. from 1930 until 1986.

#### SIGNIFICANT EVENTS REFLECTED IN THE DISTRICT

Mary Street and the surrounding Travis Heights neighborhood reflect several important development trends that shaped the growth of the City of Austin and also follow nationwide trends. In 1928, the Dallas engineering firm Koch and Fowler developed the first comprehensive planning document for the city of Austin. Recommendations made in the plan reflected several nationwide trends, including the City Beautiful Movement.

The rapid growth of American cities following the Civil War was largely unplanned, and caused concern among architects. As director of the 1893 World's Columbian Exhibition, architect Daniel Burnham helped to spread a growing nationwide interest in urban planning that would continue to develop over the next several decades as the City Beautiful Movement. This concept promoted beautification through order and harmony in architecture and urban design, including incorporation of parks and green spaces. The execution of some of these trends in Texas was several years behind the east coast (as is also observed in the spread of architectural styles), but is nonetheless part of the legacy of the movement.

The 1928 plan mapped existing as well as proposed parkland, and recommended that all of the land bordering the north side of the Colorado River within the city limits be future park space. In South Austin, the area between South 1st Street and Lamar Boulevard; the area that today is occupied by Edgecliff Terrace; and all of the land along Blunn Creek between the river and Live Oak Street was proposed for parkways. The City took action to purchase the required land almost immediately. The 1927 Austin city directory reported eight parks; by 1931 the number had increased to 12, encompassing 375 acres.

The strip of parkland directly abutting the Mary Street District is known as the Blunn Creek Greenbelt and links Big Stacy Park on the south to Little Stacy Park to the north. Part of the land that comprises the greenbelt was initially platted as part of the Blue Bonnet Hills subdivision in 1928. In the spring of the following year, the City purchased almost all of the land that would comprise these two parks and the greenbelt between. In April of 1929, all of the lots platted east of East Side Drive within Blue Bonnet Hills were sold to the City. Seventeen lots in Blocks Seven and Eight were sold by T.H. Lockhart and his wife Sadie, while the five lots in Block Six were sold by Albert and Beatrice Moore. To complete the contiguous parkway, the Stacy Realty Company, the developers of the Travis Heights subdivision, sold additional land to the City in the following months. Minutes from a 1934 City Council meeting noted the receipt of a letter of thanks from Mrs. Frances H. Stacy for the naming of Stacy Park after her deceased husband, William H. Stacy.

#### DEVELOPER PAUL PFEIFER

Mary Street was platted as part of the Blue Bonnet Hills Addition by Paul Herbert Pfeifer (1894-1989), a real estate and insurance agent. He is listed in the 1924 Austin city directory as a salesman at Carl Wendlandt & Sons, a real estate firm. In 1927 he was listed as being employed as an agent at Hal Hailey Company; by 1929 he had hung out his own shingle as Pfeifer & Baggett Real Estate, Loans, and Insurance with an office on Lavaca Street. In the 1930-1931 city directory, the company is listed as Paul H. Pfeifer Company Real Estate, Loans, and Insurance with an office on Colorado Street.

Pfeifer was recorded in the 1930 Census as residing with his wife Mildred Giles Pfeifer in a home they owned at 4209 Avenue G in Hyde Park. Pfeifer married Mildred Giles in 1927. She was born in Manor, Texas, and the 1924 city directory indicates that she worked as a teacher while living with her parents on W. 23rd Street. Her father served as president of Capital City Farm Loan Association. In the 1930 Census, Pfeifer reported that his father was born in Germany and his mother was born in Sweden. By the time of the 1940 Census, the Pfeifers had two sons and were living at 911 W. 5th Street. Pfeifer was listed as the owner of the dwelling,

with five other households listed as renters at the address. The 1940 Census record indicates that

Pfeifer had a 6th grade education; his wife was listed as having completed four years of college. By 1947, the Pfeifers had moved to 4413 Avenue G in Hyde Park. Pfeifer continued to work in real estate and died in Austin in 1989 at age 94.

#### **RESIDENTS OF THE DISTRICT**

An analysis of early residents of the district utilizing Austin city directories and the 1940 Census suggests that Mary Street was part of a working-class neighborhood comprised of a mix of primarily owners and some renters.

#### NEIGHBORING SUBDIVISIONS

When Mary Street was established as part of the Blue Bonnet Hills subdivision in 1928, most of the immediately surrounding land had been already been platted. To the west were Fairview Park (1886) and Newning and Warner's Subdivision (1894); to the south were Pleasant View (1915) and the Swisher Addition (1876); to the east was Travis Heights (1913). To the north was the Roy C. Archer subdivision, platted in 1935. This small, 15-lot development was subdivided out of Fairview Park and was the only neighboring subdivision to post-date the first development in Blue Bonnet Hills. Although the other adjacent subdivisions had been platted decades before Blue Bonnet Hills, these subdivisions were not yet built out in 1928 and continued to be developed contemporaneously with Blue Bonnet Hills. In terms of architectural character, the style, scale, and age of the housing stock on Mary Street and Blue Bonnet Hills in general is very similar to that of neighboring subdivisions, including Travis Heights. Like Blue Bonnet Hills, homes in the adjacent subdivisions are primarily one-story, modest-scale homes in the Craftsman, Tudor Revival, and Minimal Traditional styles.

#### SIGNIFICANT BUILDINGS IN THE DISTRICT

There are no homes or buildings in the district that have been landmarked individually.

### 10. ARCHITECTURE AND BUILDERS


No architects or builders have been identified for contributing buildings within the Mary Street Historic District. The neighborhood likely includes a mix of custom homes designed by architects and vernacular homes inspired by model house designs and published pattern books, constructed by local contractors.

NOMINATION PREPARED BY


James Bilodeau 502 E. Mary St. Austin, TX 78704 917-328-3357

NEIGHBORHOOD REPRESENTATIVE


James Bilodeau 502 E. Mary St. Austin, TX 78704 917-328-3357



11








1962 Sanborn






- + = Contributing property
- Signed in support

Contributing TCAD Property	389	283348 LOT 1 BLK 5 BLUE BONNET HILLS	283388 LOT 19 *LESS W 10.7SO FT TRI BLK 9 BI UF BONNET HILLS	283349 LOT 3 BLK 5 BLUE BONNET HILLS	283387 LOT 18 BLK 9 BLUE BONNET HILLS	283350 LOT 5 BLK 5 BLUE BONNET HILLS	283386 LOT 17 BLK 9 BLUE BONNET HILLS	283351 LOT 7 BLK 5 BLUE BONNET HILLS	283385 LOT 14 BLK 9 BLUE BONNET HILLS	283352 LOT 9 BLK 5 BLUE BONNET HILLS	283384 LOT 15 BLK 9 BLUE BONNET HILLS	283353 LOT 11 BLK 5 BLUE BONNET HILLS	283383 LOT 16 BLK 9 BLUE BONNET HILLS	283354 LOT 13 BLK 5 BLUE BONNET HILLS	283382 LOT 13 BLK 9 BLUE BONNET HILLS	283355 LOT 15 BLK 5 BLUE BONNET HILLS	283381 LOT 12 BLK 9 BLUE BONNET HILLS	283356 LOT 17 BLK 5 BLUE BONNET HILLS	283380 LOT 11 BLK 9 BLUE BONNET HILLS
Contributir to J HD	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	٥N	Yes	Q						
Owner Support	Yes	ş	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	(	Yes	Yes	1	۱	Yes	ı	Yes	ſ
TCAD Owner Name	PARKINSON TONY & MARYANNE	WILLIAMS ROBERT T & MARIE	BILODEAU JAMES	CALVERT WILLIAM HAMILTON	TONGATE JOHN T	BORAH MATTHEW	REGIMBEAU PASCAL G & SYBIL R	JONES DAVID F & CYNTHIA L WILL	BARKER NORMAN R JR ET AL	KREPS KAREN R	LANIER TROY & MIRIAM MURTUZA	HUBELE LAUREN & JOACHIM	OTTO GRETCHEN ALYNNE &	GIBSON JENNIFER M & JOSEPH M HEBERT	CURTIS MICHAEL D	TEXADA EVELYN	LAMBERT ELIZABETH GS TRUST	DOWNER MICHAEL WAYNE	LAMBERT ELIZABETH ANN
ion Style	Colonial Revival	Craftsman	Revival - Tudor	Neoclassical	Revival - Tudor	Minimal Traditional	Craftsman	Craftsman	Revival - Tudor	Craftsman	Revival - Tudor	Craftsman	Minimal Traditional	Craftsman	Craftsman	Revival - Tudor	Craftsman	Craftsman	Craftsman
Construction Year	1931	1931	1930	1931	1930	1939	1931	1931	1933	1929	1936	1933	1935	1939	1935	1933	1933	1929	1931
Address	500 E Mary St	501 E Mary St	502 E Mary St	503 E Mary St	504 E Mary St	505 E Mary St	506 E Mary St	507 E Mary St	508 E Mary St	509 E Mary St	510 E Mary St	511 E Mary St	512 E Mary St	513 E Mary St	514 E Mary St	515 E Mary St	516 E Mary St	517 E Mary St	518 E Mary St

- = No kispinsh



.

# **Table of Contents**

Purpose and Goals	.1
Design Review Process	
Design Standards	
A. Overview	
B. Contributing Properties: Repair and Rehabilitation	
C. Contributing Properties: Additions	
D. Contributing Properties and New Construction: Site Features1	
E. New Construction	

.

. .

.

· · ·

.

. <u>.</u> .

.

.

# **Purpose and Goals**

Design standards help preserve and protect the character-defining features of historic areas. These design standards provide guidance for the repair, rehabilitation, preservation, and restoration of contributing buildings within the Mary Street Historic District; and will guide new construction to be compatible with the district's architectural character.

The goals of the design standards are to:

- Protect the eclectic and vibrant character of Mary Street by identifying and preserving the historic elements that contribute to these qualities while encouraging residents to invest in livable adaptations to their homes;
- Preserve the architectural heritage of the district through retention and preservation of historic buildings and landscape features;
- Prevent demolition of contributing buildings and discourage demolition of buildings easily restored to contributing status;
- Support preservation of historic buildings by providing guidance in building maintenance and repair;
- Ensure that alterations to contributing buildings are compatible with the character of the building and the district;
- Support sustainable design by providing guidance to improve energy efficiency and building performance; and
- Ensure that ground-up new construction will be compatible with the historic character of the district.

This document is a tool for property owners and architects who are planning projects covered by the standards, as well as for the Historic Landmark Commission as it evaluates each project.

.

.

# **Design Review Process**

## A. Certificate of Appropriateness

## PURPOSE

The Certificate of Appropriateness (COA) review process ensures that proposed projects and new construction within the district comply with these design standards. A COA must be granted before a building permit will be issued by the City, and may be required for work even if a building permit is not necessary.

Property owners are *not* required to make changes to their properties or restore buildings to their historic appearance. The design review process applies only when a property owner initiates a construction project that requires a COA.

### WHEN A COA IS REQUIRED

A COA is required for ground-up new construction of a new primary building and the following changes to contributing properties if the proposed changes are visible from the street (disregarding vegetation, fences, or other barriers), unless exempted below:

- 1. Exterior alterations to existing buildings, including but not limited to the construction of additions; the replacement of windows, doors, or roofing materials that do not qualify as ordinary repair and maintenance; or the relocation of windows or doors;
- 2. Demolition or relocation of an existing building;
- 3. New construction;
- 4. Major foundation or structural work that does not qualify as ordinary repair and maintenance; and
- 5. Modifications to outside areas requiring a City permit, including but not limited to the construction of a deck, pool, or other outbuilding.

# A COA is not required for:

- 1. Interior work that does not affect the exterior of the building;
- 2. Routine maintenance projects, provided that work does not affect the historic character of the building, including but not limited to painting and repairs to masonry or the foundation;
- 3. Work not visible from the street (disregarding vegetation, fences, or other barriers); and
- 4. Projects on non-contributing buildings.

# COAPROCESS

Submit a Certificate of Appropriateness application to the City Historic Preservation Office. Property owners should contact City staff in the early planning stages of a project for assistance in interpreting these standards, developing solutions to any issues, and understanding the review process. Staff can also provide on-site consultations and other technical assistance.

The Historic Preservation Officer may administratively grant COAs for the following projects:

- Accurate restoration or reconstruction of a documented missing historic architectural element of the structure or site;
- Changes that do not affect the appearance of the building from the principal street frontage, including but not limited to:
  - o Demolition of garages, sheds, carports, or other outbuildings;
  - o Construction of a ground-floor, one-story addition or outbuilding;
  - o Two-story additions to the rear of two-story houses; or
  - o A pool, deck, fence, back porch enclosure, or other minor feature.

The Historic Landmark Commission will review all other COA applications.

The Historic Preservation Office or Historic Landmark Commission shall grant the COA if the application conforms to these design standards. The Commission also has the authority to grant exemptions to the standards if it determines that the proposed project will maintain the character-defining features of the property and/or district.

If the Historic Landmark Commission denies the COA, the applicant may revise and resubmit the application. The applicant also may appeal the denial to the appropriate land use commission and the City Council per City Code.

### APPLICANT RESPONSIBILITIES

The responsibility for demonstrating that the proposed project meets these design standards lies with the applicant. The applicant shall submit sufficient photographs and/or physical documentation to demonstrate that the proposed project meets these standards or otherwise maintains the character-defining features of the property and/or district.

## **B.** Penalties for Violations

Any person or corporation who violates provisions of these design standards is subject to the same criminal misdemeanor and/or civil penalties that apply to any other violation of the City Code.

### C. Periodic Review

These standards are not intended to be static, but subject to periodic review, revision, and amendment. The process for revising or amending the design standards shall follow the process set forth for neighborhood plans, as described in the Land Development Code:

The directar shall conduct a general review of a neighborhood plan not earlier than five years after the adoption of the plan and may recommend amendments of a plan to the Planning Commission and council. The director shall include neighborhood stakeholder input in the review pracess.

# **Design Standards**

## A. Overview

## WHEN TO USE THE DESIGN STANDARDS

All work requiring a Certificate of Appropriateness (COA) shall follow these design standards (see p. 2 for a list). Non-contributing properties are encouraged to consider the design standards as advisory guidelines for compatible alterations and additions.

### SECRETARY'S STANDARDS FOR REHABILITATION

The Secretary of the Interior's Standards for Rehabilitation are national preservation standards that guide alterations, additions, and repair and replacement of deteriorated features. See the table on p. 5 for a general interpretation of each standard. The Secretary of the Interior also has Standards for Preservation, Restoration, and Reconstruction, which may be appropriate in some cases.

The rest of this document interprets the Secretary's Standards for Rehabilitation specifically for use in the Mary Street Historic District. If a proposed project or project component is not addressed by the design standards, the Secretary's Standards shall guide the project evaluation and COA decision.

### **ACCESSIBILITY**

When increasing accessibility, design ramps, lifts, and entrances to avoid damage, removal, or obscuring historic fabric to the greatest extent possible. Contributing buildings may qualify for variances from the Texas Accessibility Standards.

### ENERGY EFFICIENCY

Construction of any new buildings or alterations of existing buildings shall be done in such a way as to meet or exceed the intent and requirements of current energy codes as required by the City, except in cases where compliance would adversely impact the historic character of the property or district.

The City of Austin recognizes that protection of cultural heritage contributes to sustainable communities and preserves embodied energy used in a building's construction. Compliance with energy or building codes may never be used as a reason to remove historic features or demolish a contributing building.

### Definitions

CHARACTER-DEFINING FEATURES: Visual aspects and physical features that characterize a building's appearance.

CONTRIBUTING PROPERTIES: Buildings, structures, or sites that are at least 50 years old, were built during the district's period of significance, and retain a high degree of integrity.

IN-KIND REPLACEMENT: Replacing a current element (whether a single material or a whole feature) with a new element that has the same profile, dimension, and texture as the material of the current or historic element; color may also be important to match. A new material may or may not be the same material as the current or historic material. In-kind materials are not appropriate if they damage historic materials.

INTEGRITY: A property's ability to convey its historic significance. Seven aspects are used to evaluate integrity: location, design, setting, materials, workmanship, feeling, and association.

NON-CONTRIBUTING PROPERTIES: Buildings, structures, or sites that are fewer than 50 years old, were not built during the district's period of significance, and do not retain integrity.

PERIOD OF SIGNIFICANCE: Span of time in which a property or district attained significance, usually when a substantial amount of construction took place.


Secretary's Standards for Rehabilitation	General Meaning
<ol> <li>A property will be used as it was historically or be given a new use that requires minimal change to its distinctive materials, features, spaces, and spatial relationships.</li> </ol>	If a new use is necessary, prioritize a use that will allow preservation of a property's character-defining features.
2. The historic character of a property will be retained and preserved. The removal of distinctive materials or alteration of features, spaces, and spatial relationships that characterize a property will be avoided.	Do not remove or change character- defining features such as building scale, massing, materials, and how parts of a property relate to each other.
3. Each property will be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as adding conjectural features or elements from other historic properties, will not be undertaken.	Avoid false historicism with alterations and additions.
4. Changes to a property that have acquired historic significance in their own right will be retained and preserved.	Preserve historic-age elements if they are compatible with the historic building, even if they are not original to the property.
5. Distinctive materials, features, finishes, and construction techniques or examples of craftsmanship that characterize a property will be preserved.	Preserve character-defining architectural elements, materials, and finishes.
6. Deteriorated historic features will be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature will match the old in design, color, texture, and, where possible, materials. Replacement of missing features will be substantiated by documentary and physical evidence.	Repair first. Do not replace or alter historic- age elements unless they are deteriorated beyond repair, and then replace them in- kind to the greatest extent possible. Avoid conjecture when replacing a missing element.
7. Chemical or physical treatments, if appropriate, will be undertaken using the gentlest means possible. Treatments that cause damage to historic materials will not be used.	Don't treat a building with materials and techniques that may damage historic materials.
8. Archeological resources will be protected and preserved in place. If such resources must be disturbed, mitigation measures will be undertaken.	If site or foundation work is occurring, be mindful of archeological resources that may be present.
9. New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work will be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportion, and massing to protect the integrity of the property and its environment.	Ensure that alterations and additions do not damage or destroy character-defining features. Design new construction so that it is compatible with but differentiated from the historic-age property.
10.New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.	Design new construction to minimally impact historic fabric. If possible, additions should be able to be reversed without major damage to the historic building.

## B. Contributing Properties: Repair and Rehabilitation

- 1. FAÇADE
  - a. Do not change the character, appearance, configuration, or materials of the primary façade, except to restore a building to its original appearance.
  - b. Do not add conjectural architectural features to the primary façade.
  - c. If original elements of the primary façade are missing *and* if sufficient documentation exists to ensure accuracy, those elements may be restored to their historic appearance.
  - d. Minimize changes to historic-age secondary elevations of the building that are visible from the principal street frontage.
- 2. EXTERIOR WALL MATERIALS
  - a. Repair damaged exterior wall materials, details, and ornamentation to the greatest extent possible, using treatments that do not damage historic materials. Replace only materials and wall sections that are deteriorated beyond repair, and prioritize in-kind replacement if possible.
  - b. Fiber cement siding and other board siding that matches wood siding in profile, dimension, and texture may be used as in-kind replacement for wood siding that has deteriorated beyond repair, if the replacement material does not damage historic siding.
  - c. Do not apply aluminum or vinyl siding as a replacement for or over historic siding. These siding types can cause irreparable damage to underlying materials and structural members.
  - d. Do not paint masonry that has not already been painted. Moisture may become trapped between the paint and masonry, causing deterioration of the underlying materials and structural members.
- 3. PORCHES
  - a. Retain the rails, posts, and brackets of an original front porch. If replacement is necessary, use in-kind materials. Wood porch floors may be replaced by a concrete slab on grade if the height, dimensions, and other character-defining features of the porch are unchanged.
  - b. Do not enclose a front porch with any material other than screening. If a front porch is screened, install the screens in a way that is reversible, does not damage any historic fabric, and is compatible with the historic design.




Damaged exterior wall materials can be repaired or replaced in-kind, as in the fascia board to the left.



Deteriarated waod porch elements can be repaired in place with epoxy consolidants and fillers.

- c. Do not add conjectural elements to the porch that were not historically present.
- d. If original elements of the porch are missing *and* if sufficient documentation exists to ensure accuracy, those elements may be restored to their historic appearance.
- 4. ROOFS
  - a. Retain the shape and slope of the original roof as seen from the street, including original dormers.
  - b. Maintain and repair original decorative roof elements such as exposed rafter ends, bargeboards, and cornices. Do not add decorative roof elements that were not historically present.
  - c. Maintain and repair existing roof materials whenever possible. Replace damaged roofing materials in-kind (preferred) or with a compatible substitute material that gives a similar appearance to the existing or historic roof. Metal roofs are allowed under these design standards but should not be considered as the first choice for replacement.
- 5. WINDOWS AND SCREENS
  - a. Do not enlarge, move, or enclose original window openings.
  - b. Maintain and repair original wood-sash windows. Wood-sash windows will last for many decades, whereas new windows have a shorter lifespan and typically must be replaced entirely, as opposed to repairing or replacing components as needed.
  - c. Use interior or exterior storm windows and window inserts to provide increased energy efficiency and soundproofing without damaging historic windows. Install exterior storm windows in a way that does not damage historic fabric. Solar screens may also be used.
  - d. If the original windows no longer exist and if no documentation can be found that shows the original windows, non-original windows may be replaced with windows that are appropriate in style, configuration, dimensions, and materials to the style of the building. If documentation showing the original windows can be found the appearance of any replacement windows from the public right-of-way must closely resemble the original in size, configuration, profile, and finish. Vinyl windows are not appropriate replacement windows.



Asphalt shingles are an incompatible replacement substitute for the original Spanish clay tiles.



Da nat replace historic windows with new windows that do not convey the same appearance.

- e. When replacing divided-lite windows, use windows with true divided lites or dimensional muntins placed on the outside of the glass, along with spacers on the inside of the glass that are an appropriate color, material, and thickness, so that the window appears to have true divided lites when viewed from all angles.
- 6. DOORS
  - a. Do not enlarge, move, or enclose original door openings.
  - b. Retain original doors, door surrounds, sidelights, and transoms, unless deteriorated beyond repair.
  - c. If a replacement door is necessary, replace in-kind or select a new style of door that is appropriate for the building age and style. Steel and hollow-wood doors are not appropriate for main entries.
  - d. If a replacement door surround, sidelight, or transom is necessary, replace it in-kind.
- 7. CHIMNEYS
  - a. Retain original chimneys.
- . C. Contributing Properties: Additions

Additions can be designed sensitively so that they do not visually overpower the existing building or compromise its historic character, but even well-designed additions can have a large impact. When possible, adapt the interior of existing buildings to meet needs, or consider a lower-impact alternative such as a basement conversion or dormers, which can create usable space with minimal visual impact.

- 1. LOCATION
  - a. Retain all character-defining features on historic-age exterior façades that are visible from the principal street frontage.
  - b. Retain as much historic-age building fabric as possible by limiting the wall area where the addition connects to the existing building. Large additions may be constructed as separate buildings that connect to the existing building with a linking hallway or breezeway.
  - c. Whenever possible, locate additions behind the existing building and design them to be neither taller nor wider than the existing building.
  - d. Set additions back from the front façade at least 15 feet or one-third the depth of the building, whichever is greater.
  - e. On buildings with a side-gabled, hipped, or pyramidal roof form, set back second-story additions behind the ridgeline of the original roof, in addition to the setback requirement in (e).
  - f. Locate dormers on a side or rear elevation.
- 2. HEIGHT
  - a. Do not exceed the height of the tallest contributing building on a similarly sized lot on the block.
- 3. DESIGN AND STYLE
  - a. Design additions to be inconspicuous and subordinate to the historic building.
  - b. Design additions so that the existing building's overall shape appears relatively unaltered from the principal street frontage.
  - c. Design additions to complement the scale, massing, materials, and fenestration patterns of the

original historic building. Design window-to-wall area ratios, floor-to-floor heights, window patterns, and bay divisions to be similar to the existing building.


- d. Differentiate the design of the addition so as not to be replicative or give a false sense of history. Additions do not need to mimic the architectural style of the original historic building, but they should be compatible in scale, design, and materials.
- e. If constructing dormers, match them to existing dormers in design and scale, or match the dormers on similar buildings in the district.



This compatible side addition (ta the left) is set back from the front of the original house.



This incompatible side addition is flush with the front of the original house.




This compotible rear addition is subordinate to the original house.



This incompatible rear addition dominates the original house.






The contemporary two-story addition behind this house is compatible because it is located in the reor of the property and is subordinate in scale to the original house.

- 4. EXTERIOR WALLS
  - a. Use exterior wall materials that complement the existing building, as well as the collective character of the district.
  - b. Differentiate an addition from the existing building by means of a hyphen or joint using a different material, varying trim boards, slightly varying dimension of materials, varying orientation of materials, or other means.
- 5. PORCHES
  - a. Do not add a front porch to a building that did not have a front porch historically.
- 6, ROOFS
  - a. Use a simple roof style and slope that complements the roof of the existing building.
  - b. Use materials that match or are compatible with the roof materials on the existing building.
- 7. WINDOWS AND SCREENS
  - a. Use windows that complement the fenestration pattern, size, configuration, profile, and finish of windows on the existing building.
  - b. Do not use false muntins attached to or inserted between the glass in windows.
- 8. DOORS
  - a. Use doors that are compatible with those on the existing building in terms of materials and lite configurations.
- 9. CHIMNEYS
  - a. Design chimneys to match existing chimneys in design, materials, and scale. If the existing building does not have a chimney, match chimneys on similar buildings in the district.
- D. Contributing Properties and New Construction: Site Features
  - 1. TOPOGRAPHY
    - a. Maintain and repair the grade of the site as much as possible to preserve the historic grade. Do not otherwise alter the current grade of the site except to restore it back to its historic state. The current grade of the site shall not be artificially raised to gain additional building height.
    - b. If a change in grading is necessary to improve drainage, minimize the impact to the site and any historic landscape features.
  - 2. DRIVEWAYS 📐
    - a. Configure driveways in a way that maintains the district's historic streetscape pattern.
  - 3. MECHANICAL EQUIPMENT
    - a. Locate new mechanical or energy conservation equipment so that it does not obscure the view of the primary building from the principal street frontage.
    - b. When mechanical equipment must be attached to an exterior wall of a contributing building, minimize damage to the historic wall material. For masonry walls, anchor attachments into the mortar rather than the masonry unit.

- c. Design roof systems to be on the same plane and scale as the roof, and choose panels in a color compatible with surrounding roof materials. For contributing properties, design photovoltaic and solar thermal installations to avoid or minimize damage to historic-age architectural features and materials.
- d. Locate photovoltaic, solar thermal, wind power systems, and satellite dishes on ancillary buildings or new additions to contributing properties to the maximum extent feasible. Locate solar panels on the rear of the roof whenever possible so that they are not visible from the street.
- e. For rainwater collection systems visible from the principal street frontage, prioritize the use of traditional materials such as metal and wood. If PVC containers or piping are used, paint them to resemble metal.
- 4. GARAGES AND ACCESSORY BUILDINGS
  - a. Attached garages are not compatible with the character of the district and are not permitted.
  - b. Locate new detached garages and accessory buildings at the side or rear of properties.
  - c. Design new garages and accessory buildings to be compatible in scale with and to have an appropriate site relation to the primary building, as well as surrounding buildings.
  - d. When constructing new garages and accessory buildings or repairing existing garages and accessory buildings, use materials and finishes that are compatible with the primary building and the district. This includes garage doors,

## 5. FENCES AND WALLS

- a. Do not construct fences and walls that obscure the front elevation of the primary building. Fences along the principal street frontage shall not exceed four feet in height.
- b. Fence and wall materials, scale, and finish shall be compatible with contributing properties.



This compatible house from 2004 has a garage lacated at the rear of the property.

This incompatible house from 2006 has an attached garage at the front of the house.

## E. New Construction

- 1. ORIENTATION AND SETBACKS
  - a. Position new or moved structures on a lot to maintain the district's historic streetscape pattern.
  - b. Use front and side yard setbacks that equal the prevalent setback of contributing buildings on the same side of the street. When the historic setback pattern is irregular, new construction may use the setbacks of an adjacent contributing property.
- 2. HEIGHT
  - a. Design buildings to respond to the dimensions of the lot.
  - b. Do not exceed the height of the tallest contributing building on a similarly sized lot on the block. If the tallest contributing building is two stories due to a second-story addition, set back the second story on new construction in conformance with the second-story setback requirements for additions to contributing buildings.
- 3. DESIGN AND STYLE
  - a. Design new buildings so that they are compatible with the historic character of the district in terms of form, massing, and proportions; yet also differentiated from contributing buildings.
  - b. Consider the building forms and architectural styles that historically existed within the district as a model for new construction.
  - c. It may be appropriate to incorporate compatible architectural features found in contributing buildings, such as porch columns or transoms. Avoid using historical architectural features that do not appear on contributing buildings.
- 4. EXTERIOR WALLS
  - b. Use exterior wall materials that are compatible with the character of the district in scale, type, size, finish, color, and texture.
  - c. Use exterior materials that correspond with the new building's form and architectural style.
- 5. PORCHES
  - a. Design front porches to reflect the width, height, and depth of porches on similarly scaled contributing buildings.




This new multi-family development is compatible because each unit is a separote building facing the street. The units are compatible in scale ond design.




This multi-family development is not campatible because it is a single large building facing an internal driveway instead of the public street.

- b. Design front porch posts/columns, railings, and detailing to be compatible with contributing buildings.
- c. Do not add false historical architectural elements, such as brackets or gingerbread detailing, to a new porch.
- d. Locate new decks, balconies, and secondary porches at the rear of new residential buildings.
- 6. ROOFS
  - a. Design roofs to be simple in form, reflecting the character of the roofs on contributing buildings. Roof forms should also correspond to the new building's form and architectural style.
  - b. Design roof features and details such as dormers, eave detailing, and bargeboards to correspond with the new building's form and architectural style.
  - c. Use roof materials that reflect the character of the roofs on contributing buildings and also correspond with the new building's form and architectural style.
- 7. WINDOWS AND SCREENS
  - a. Design windows and screens to be compatible with the proportions, configuration, and patterns of windows and doors in contributing buildings.
  - b. Design windows and doors to correspond with the new building's form and architectural style.
  - c. Do not use windows with false muntins attached to or inserted between the glass.
- 8. DOORS
  - a. Locate front doors to face the principal street frontage.
  - b. Match the style, proportions, materials, and finish of the door to the overall style and design of the building.
- 9. CHIMNEYS
  - a. Design chimneys to be compatible with the location and scale of chimneys in contributing buildings, and to correspond with the new building's form and architectural style.



# Property ID 283389 500 E Mary St

# CONTRIBUTING



# Description

Date of	1931	Roof Materials	Composition shingles	Porch Railings	None
Construction	Source: City Directories	Roof Decoration	Clipped Gables, Brackets	Fences	Corrugated metal (around
Stylistic Influences	Colonial Revival	Number of	Exterior: 0, Interior: 0		side and backyard)
Historic Use	Dwelling, single	Chimneys	Extends: 0, intends: 0	Moved	Has Not Moved
Current Use	Dwelling, single	Windows	Wood Double Hung,	Integrity	Side and rear additions.
Stories	1		Decorative Screens, Decorative Shutters		
Plan	Square or rectangular	Door Features	Glazing		
Foundation	Pier-and-Beam, concrete	Porch Type	Partial Width, Independent		
Extenor Materials	Wood	Porch Roof Types.	Gabled		
Roof Type	Side Gable	Porch Supports	Column Full Height		

# Travis Central Appraisal District Data

Map Key # / Property ID	283389
Geo ID	302020420
Subdivision Code	S01528

Subdivision BLUE BONNET HILLS

Legal Acres 0.1507

Main Area SF 1394

# **Historic District Information**

Contributing to Yes Local Historic District

Justification For Contributing Status doesn't detract from historical character  
 Situs
 500 E MARY ST

 Situs Zip
 78704

 Legal Description
 LOT 20 & W 10.7SQ FT TRI OF LOT 19 BLK 9 BLUE BONNET HILLS

 Owner Name
 PARKINSON TONY & MARYANNE

 Addri
 PMB 281
  
 Addr2
 3005 S LAMAR BLVD STE D109

 City
 AUSTIN

 State
 TX

 Zip
 78704

Lip 10104

t Information

Survey Date 1/15/2009

l, hereb		LOT 20 & W 10.7SQ FT TRI OF LOT 19 BLK 9 BLUE BONNET HILLS n for the Mary Street Local Historic District.
	I DO support the application for local his district designation	toric Signature
I DO NOT support the application for loca historic district designation		al Date

# Property ID 283348 501 E Mary St

CONTRIBUTING 00 6 Mary St Lockhair Dr Map data S2014 Goople Description

#### Date of 1931 Roof Type Side Gable, Jerkinhead Porch Roof Types Gabled Construction Source: City Directories Roof Materials Composition shingles Porch Supports Metal Stylistic Influences Craftsman Roof Decoration Exposed Rafter Ends, Porch Railings Metal Historic Use Dwelling, single Brackets Outbuildings 1 Story Detached Current Use Dwelling, single Garage, Garage Wall Material: Wood, Garage Number of Exterior: 0, Interior: 0 Chimneys Stories 1 Roof Type: Gabled Windows Wood Double Hung Plan Square or rectangular Moved Has Not Moved Door Features Glazing Foundation Pier-and-Beam Integrity Possible modern Porch Type Partial Width Exterior Materials Vinyl additions on west side and rear. Siding replaced.

# Travis Central Appraisal District Data

- Map Key # / 283348 Property ID Geo ID 302020301 Subdivision Code S01528
  - Subdivision BLUE BONNET HILLS
  - Legal Acres 0.162 Main Area SF 1142

Contributing to Yes Local Historic District

Justification For Largely Intact Contributing Status

Situs 501 E MARY ST Situs Zip 78704 Legal Description LOT 1 BLK 5 BLUE BONNET HILLS Owner Name WILLIAMS ROBERT T & MARIE

Addr2 501 E MARY ST City AUSTIN State TX

Zip 78704-3142

# **Historic District Information**

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705 Survey Date 1/15/2009

l, the ap	, owner, of <b>LOT 1</b> oplication for the Mary Street Local Historic Distr	BLK 5 BLUE BONNET HILLS hereby state that I have reviewed rict.
	I DO support the application for local historic district designation	Signature
	I DO NOT support the application for local historic district designation	Date

Property ID 283388 502 E Mary St

CONTRIBUTING





Description

Date of		Roof Type	Cross Gable	Porch Roof Types	Gabled
	Source: TCAD	Roof Materials	Composition shingles	Porch Supports	Tapered on Pier, Stucco
Stylistic Influences	Revival - Tudor	Roof Decoration	Exposed Rafter Ends.		Piers
Historic Use	Dwelling, single	Contract and a second second	Brackets	Porch Railings	Metal
Current Use	Dwelling, single		Exterior: 0, Interior: 0	Walls	Height: 2 ft, Stone
Stories	1	Chimneys		Outbuildings	1 Story Detached Garage
Plan	Square or rectangular	Windows	Wood Double Hung, Decorative Screens	o acountarigo	Garage Wall Material: Wood, Garage Roof Material: Composition shingles, Garage Roof Type: Gabled
Foundation	Pier-and-Beam	Door Features	Glazing		
Exterior Materials	Wood	Porch Type	Partial Width, Independent		
				Moved	Has Not Moved
ravis Central A	ppraisal District Data				
Map Key #1	283388	Situs	502 E MARY ST	Addr2	502 E MARY ST
Property ID		Situs Zip	78704	City	AUSTIN
Geo ID	302020419		LOT 19 *LESS W 10.7SQ	State	
Subdivision Code	S01528		FT TRI BLK 9 BLUE BONNET HILLS	0000	
Subdivision	BLUE BONNET HILLS			Zip	78704-3143
		Owner Name	BILODEAU JAMES		
Legal Acres	0.1489				

Main Area SF 1393

# **Historic District Information**

Contributing to Yes Local Historic District


Justification For Intact Contributing Status

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705 Survey Date 1/15/2009

l, state	, owner, of that I have reviewed the application for the Ma	19 *LESS W 10.75SQ FT TRI BLK 9 BLUE BONNET HILLS hereby ary Street Local Historic District.
	I DO support the application for local historic district designation	Signature
	I DO NOT support the application for local historic district designation	Date

Property ID 283349 503 E Mary St

# CONTRIBUTING



Date of	The second	Roof Materials	Metal	Outbuildings	1 Story Detached
Construction	Source: City Directories	Roof Decoration	Brackets		Garage, Garage Wall
Stylistic Influences	Neoclassical	Number of	Exterior: 0, Interior: 0		Material: Wood, Garage Roof Type: Gabled
Historic Use	Dwelling, single	Chimneys		Landscape	3' stone retaining wall.
Current Use	Dwelling, single	Windows	Wood Double Hung,	Features	e erena retantning mant
Stories	1.5		Decorative Screens	Moved	Has Not Moved
Plan	Square or rectangular	Door Features	Glazing	Integrity	Porch railings replaced.
Foundation	Pier-and-Beam	Porch Type	Full Width, Inset		
Exterior Materials	Wood	Porch Supports	Column Full Height		
	Side Gable	Porch Railings	Turned Wood		

# **Travis Central Appraisal District Data**

Map Key #7 283349 Property ID Geo ID 302020302 Subdivision Code S01528 Subdivision BLUE BONNET HILLS

Legal Acres 0.1433 Main Area SF 896

## **Historic District Information**

Contributing to Yes Local Historic District

Justification For Largely Intact Contributing Status Situs 503 E MARY ST Situs Zip 78704 Legal Description LOT 3 BLK 5 BLUE BONNET HILLS Owner Name CALVERT WILLIAM HAMILTON Addr2 503 E MARY ST City AUSTIN State TX Zip 78704-3142

# es

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705 Survey Date 1/15/2009

l, the aj	, owner, of oplication for the Mary Street Local Historic Distr	BLK 5 BLUE BONNET HILLS hereby state that I have reviewed ict.
	I DO support the application for local historic district designation	Signature
	I DO NOT support the application for local historic district designation	Date

Property ID 283387 504 E Mary St

# CONTRIBUTING



Date of		Roof Materials	Composition shingles	Porch Railings	Metal
	Source: TCAD	Roof Decoration	Brackets	Outbuildings	1 Story Detached Garage,
Stylistic Influences	Revival - Tudor	Number of Chimneys	Exterior: 0, Interior: 0		Garage Wall Material: Board & Batten, Garage Roof Material:
Historic Use	Dwelling, single				
Current Use	Dwelling, single	Windows	Wood Double Hung,		Composition shingles,
Stories	1		Decorative Screens		Garage Roof Type: Hipped
Plan	Square or rectangular	Door Features	Glazing, Peephole	Moved	Has Not Moved
Foundation	Pier-and-Beam	Porch Type	Stoop Roof		
Exterior Materials	Wood	Porch Roof Types	Other, Canvas awning over door		
Roof Type	Side Gable	Porch Supports	None		

Travis Central Appraisal District Data

Map Key # / 283387 Property ID Geo ID 302020418 Subdivision Code S01528

Subdivision BLUE BONNET HILLS

Legal Acres 0.1539

Main Area SF 1128

# **Historic District Information**

Contributing to Yes Local Historic District

Justification For Intact Contributing Status

Situs 504 E MARY ST Situs Zip 78704 Legal Description LOT 18 BLK 9 BLUE BONNET HILLS Owner Name TONGATE JOHN T

Addr2 504 E MARY ST City AUSTIN State TX Zip 78704-3143

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705 Survey Date 1/15/2009

l, reviev	wed the application for the Mary Street Local His	<b>8 BLK 9 BLUE BONNET HILLS</b> hereby state that I have storic District.
	I DO support the application for local historic district designation	Signature
	I DO NOT support the application for local historic district designation	Date

# Property ID 283350 505 E Mary St

# CONTRIBUTING Newring And Mary St.F Mary St E Blunn Gree Lockhart n Map data @2014 Gopole

#### Description

Date of	17773	Roof Type	Cross Gable	
Construction	Source: TCAD	Roof Materials	Metal	
Stylistic Influences	Minimal Traditional	Pool Departies	Europed Defer Ends	
Historic Use	Dwelling, single	Root Decolation	Exposed Rafter Ends, Brackets	
Current Use	Dwelling, single	Number of	Exterior: 0, Interior: 0	
Stories	1	Chimneys		
Plan	Square or rectangular	Windows	Wood Double Hung, Decorative Screens	
Foundation	Pier-and-Beam	Porch Type	Partial Width, Inset	
Exterior Materials	Wood	Porch Supports	Square Full Height Wood	

# Porch Railings Metal

Outbuildings 1 Story Detached Garage, Garage Wall Material: Wood, Garage Roof Type: Gabled Moved Has Not Moved Integrity Door replaced.

# **Travis Central Appraisal District Data**

- Map Key #/ 283350 Property ID Geo ID 302020303 Subdivision Code S01528 Subdivision BLUE BONNET HILLS Legal Acres 0.1501
  - Main Area SF 1448

# **Historic District Information**

Contributing to Yes Local Historic District

Justification For Largely Intact Contributing Status

Situs 505 E MARY ST Situs Zip 78704 Legal Description LOT 5 BLK 5 BLUE BONNET HILLS Owner Name BORAH MATTHEW

- Addr2 505 E MARY ST City AUSTIN State TX Zp 78704-3142

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705 Survey Date 1/15/2009

I, the ap	, owner, of5 oplication for the Mary Street Local Historic Dist	BLK 5 BLUE BONNET HILLS hereby state that I have reviewed rict.
	I DO support the application for local historic district designation	Signature
	I DO NOT support the application for local historic district designation Date	

# Property ID 283386 506 E Mary St

# CONTRIBUTING





#### Description

Date of 1931 Construction Source: TCAD Stylistic Influences Craftsman Historic Use Dwelling, single Current Use Dwelling, single Stories 1 Plan Square or rectangular Foundation Pier-and-Beam Exterior Materials Wood Roof Type Front Gable, Jerkinhead

Roof Materials Composition shingles Roof Decoration Exposed Rafter Ends, Brackets Number of Exterior: 0, Interior: 0 Chimneys

Windows Wood Double Hung, Wood Screens Door Features Glazing

Porch Type Partial Width, Independent Porch Roof Types Gabled

Porch Supports Tapered on Pier, Brick Piers

Porch Railings Square Wood

Outbuildings 1 Story Detached Garage, Garage Wall Material: Wood, Garage Roof Material: Composition shingles, Garage Roof Type: Gabled, Large two story building w/wood walls, comp shingles, and clipped gable roof.

Moved Has Not Moved

# Travis Central Appraisal District Data

Map Key #/ 283386 Property ID Geo ID 302020417 Subdivision Code S01528 Subdivision BLUE BONNET HILLS Legal Acres 0.156

Main Area SF 1593

#### **Historic District Information**

Contributing to Yes

Justification For Intact Contributing Status

Situs Zip 78704 Legal Description LOT 17 BLK 9 BLUE BONNET HILLS Owner Name REGIMBEAU PASCAL G & SYBIL R

Situs 506 E MARY ST

Addr2 506 E MARY ST City AUSTIN State TX

Zip 78704-3143

Local Historic District

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705

Survey Date 1/15/2009

l, reviev	, owner, of <b>LOT 1</b> wed the application for the Mary Street Local His	7 BLK 9 BLUE BONNET HILLS hereby state that I have storic District.
	I DO support the application for local historic district designation	Signature
	I DO NOT support the application for local historic district designation	Date



Date of 1931 Construction Source: City Directories Stylistic Influences Craftsman Historic Use Dwelling, single Current Use Dwelling, single Stories 1 Plan Square or rectangular Foundation Pier-and-Beam Exterior Materials Asbestos Roof Type Front Gable

Roof Materials	Metal
Roof Decoration	Exposed Rafter Ends, Brackets
Number of Chimneys	Exterior: 0, Interior: 0
Windows	Wood Double Hung, Wood Screens
Porch Type	Partial Width, Inset
Porch Supports	Square Full Height Wood
Porch Railings	Square Wood
Fences	Stone and iron

Walls Height: 2 ft, Stone

Outbuildings 1 Story Detached Garage, Garage Wall Material: Wood, Garage Roof Type: Gabled Moved Has Not Moved

Integrity Rear historic addition.

Addr2 507 E MARY ST

City AUSTIN

Zip 78704-3142

State TX

# **Travis Central Appraisal District Data**

Map Key #/ 283351 Property ID Geo ID 302020304 Subdivision Code S01528 Subdivision BLUE BONNET HILLS Legal Acres 0.1423 Main Area SF 1000

**Historic District Information** 

Contributing to Yes Local Historic District

Justification For Largely Intact Contributing Status

Situs 507 E MARY ST Situs Zip 78704 Legal Description LOT 7 BLK 5 BLUE BONNET HILLS Owner Name JONES DAVID F & CYNTHIA L WILL

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705

Survey Date 1/15/2009

Addr1 CYNTHIA L WILLIAMS

l,	, owner, of <b>LOT 7</b>	BLK 5 BLUE BONNET HILLS hereby state that I have reviewed
the ap	oplication for the Mary Street Local Historic Distri	ict.
	I DO support the application for local historic district designation	Signature
	I DO NOT support the application for local historic district designation	Date

# Property ID 283385 508 E Mary St

# CONTRIBUTING





#### Description

Date of Construction	1933 Source: City Directories
Stylistic Influences	Revival - Tudor
Historic Use	Dwelling, single
Current Use	Dwelling, single
Stories	1
Plan	Square or rectangular
Foundation	Pier-and-Beam
Exterior Materials	Wood

Roof Type	Side Gable
Roof Materials	Composition shingles
Roof Decoration	Exposed Rafter Ends, Brackets
Number of Chimneys	Exterior: 0, Interior: 0
Windows	Wood Double Hung
Door Features	Glazing, Roman Arch w/peephole
Porch Type	Full Width, Stoop Roof

Situs 508 E MARY ST

Owner Name BARKER NORMAN R JR ETAL

BONNET HILLS

Situs Zip 78704

Legal Description LOT 14 BLK 9 BLUE

Porch Supports	None
Porch Railings	None

Moved Has Not Moved

Addr2 4617 ARAPAHOE TRL

City AUSTIN

Zp 78745-1509

State TX

Integrity Front entrance vestibule resided and possibly enclosed. Front porch enlarged.

# **Travis Central Appraisal District Data**

Map Key #/ 283385 Property ID Geo ID 302020416

Subdivision Code S01528 Subdivision BLUE BONNET HILLS

Legal Acres 0.1642

Main Area SF 1248

# **Historic District Information**

Contributing to Yes Local Historic

District

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705

Other Josh Conrad, Emily Reed Researchers 805 1/2 W. 16th St., Austin, TX 78701

Justification For Moderate Alterations, Contributing Status doesn't detract from historical character

Survey Date 1/15/2009

١, \_, owner, of \_\_\_\_\_\_ LOT 14 BLK 9 BLUE BONNET HILLS hereby state that I have reviewed the application for the Mary Street Local Historic District. I DO support the application for local historic district designation Signature \_ I DO NOT support the application for local historic district designation Date \_\_\_\_

Property ID 283352 509 E Mary St

г



Stylistic Influences	Craftsman		Brackets		
Historic Use	Dwelling, single		Exterior: 1, Interior: 0		3' stone retaining wall at driveway.
Current Use	Dwelling, single	Chimneys		Moved	Has Not Moved
Stones	1	Chimney Materials	Stone	Integrity	Rear addition with stucco
Plan	Square or rectangular	Windows	Wood Double Hung, Decorative Screens		walls and metal roof w/ cupola.
Foundation	Pier-and-Beam	Door Features	Glazing		
Exterior Materials	Wood	Porch Type	Partial Width, Independent		
Roof Type	Hipped with Gable	Porch Roof Types	Gabled		
Fravis Central A	opraisal District Data 283352	Situs	509 E MARY ST	Addr2 1	741 SPYGLASS DR
Property ID		Situs Zo		City A	
Geo ID	302020305		LOT 9 BLK 5 BLUE		
Subdivision Code	S01528	Legar Description	BONNET HILLS	State T.	
Subdivision	BLUE BONNET HILLS	Owner Name	KREPS KAREN R	Zip 7	8746-6888
Legal Acres	0.1479				
Main Area SF	1944				
listoric District	Information				
Contributing to Local Historic District	Yes	Evaluator of	Preservation Central, Terri Myers, 823 Harris Avenue, Austin, TX 78705		Josh Conrad, Emily Reed 805 1/2 W. 16th St., Austin, TX 78701
Contributing Status	Moderate Alterations, doesn't detract from historical character	Survey Date	1/15/2009		

I, reviev	, owner, of wed the application for the Mary Street Local I	T 9 BLK 5 BLUE BONNETT HILLS hereby state that I have Historic District.
	I DO support the application for local histori district designation	ic Signature
	I DO NOT support the application for local historic district designation	Date

# Property ID 283384 510 E Mary St

# NOT CONTRIBUTING



# Description

Date of Construction	1936 Source: TCAD
Stylistic Influences	Revival - Tudor
Historic Use	Dwelling, single
Current Use	Dwelling, single
Stories	2
Moved	Has Not Moved

Integrity Large addition w/deck on front roof plane.

Travis Central A	ppraisal District Data				
Map Key # / Property ID		Situs Situs Zip	510 E MARY ST 78704		510 E MARY ST AUSTIN
Geo ID Subdivision Code	302020415 S01528		LOT 15 BLK 9 BLUE BONNET HILLS	State	
	BLUE BONNET HILLS	Owner Name	LANIER TROY & MIRIAM MURTUZA	Zр	76704-3143
Legal Acres Main Area SF					
Historic District	Information				
Contributing to Local Historic District	No	Evaluator of	Preservation Central, Terri Myers, 823 Harris Avenue, Austin, TX 78705		<ul> <li>Josh Conrad, Emily Reed</li> <li>805 1/2 W. 16th St., Austin, TX 78701</li> </ul>
	Severe alterations or incompatible addition	Survey Date	1/15/2009		
reviewed the ap	plication for the Mary	Street Local Histor	BLK 9 BLUE BONNET HILLS ric District.	_hereby state	that I have
- ibo sup					
district d	lesignation I support the applicati		Signature		

Property ID 283353 511 E Mary St

#### CONTRIBUTING



on east wall. Porch railings replaced. Door replaced.

# **Travis Central Appraisal District Data**

Roof Type Side Gable

Map Key #7 283353 Property ID Geo ID 302020306 Subdivision Code S01528 Subdivision BLUE BONNET HILLS

Exterior Materials Wood

Legal Acres 0.1409

Main Area SF 2276

#### **Historic District Information**

Contributing to Yes Local Historic District

Justification For Moderate Alterations, Contributing Status doesn't detract from historical character Situs Zip 78704 Legal Description LOT 11 BLK 5 BLUE BONNET HILLS Owner Name HUBELE LAUREN & JOACHIM

Situs 511 E MARY ST

Porch Type Partial Width, Stoop Roof

Porch Roof Types Shed

- Addr2 511 E MARY ST City AUSTIN State TX
  - Zp 78704-3142

# antributions to Man

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705 Survey Date 1/15/2009

l, reviev	, owner, of wed the application for the Mary Street Local His	<u>1 BLK 5 BLUE BONNETT HILLS hereby state that I have to be a state that I have have be a state that I have be a state to be a st</u>
	I DO support the application for local historic district designation	Signature
	I DO NOT support the application for local historic district designation	Date

Property ID 283383 512 E Mary St

CONTRIBUTING



# Description

Date of		Roof Type	Hipped with Gable	Porch Railings	Metal
Construction	Source: City Directories	Roof Materials	Composition shingles	Outbuildings	1 Story Detached
Stylistic Influences	Minimal Traditional	Mumber of	Exterior: 0, Interior: 0		Garage, Garage Roof
Historic Use	Dwelling, single	Chimneys			Type: Shed, Carport.
Current Use	Dwelling, single	Windows	Wood Double Hung	Landscape Features	2' concrete retaining wall.
Stones	2	Door Features	Glazing, Roman Arch	Mound	Has Not Moved
Plan	Square or rectangular		w/peephole		
		Porch Type	Partial Width, Inset	Integrity	Large two story addition.
Foundation	Pier-and-Beam				
Exterior Materials	Stucco	Porch Supports	Other, Stucco arch		

# Travis Central Appraisal District Data

Map Key # /	283383	Situs	512 E MARY ST
Property ID		Situs Zip	78704
	302020414	Legal Description	LOT 16 BLK 9 BLUE
Subdivision Code			BONNET HILLS
Subdivision	BLUE BONNET HILLS	Owner Name	OTTO GRETCHEN ALYNNE &
Legal Acres	0.156		
Main Area SF	1928	Addr1	MARK THOMAS SMITH

# **Historic District Information**


Contributing to	Yes
Local Historic	
District	

Justification For Contributing Status doesn't detract from historical character Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705 Survey Date 1/15/2009 Other Josh Conrad, Emily Ree

Addr2 512 E MARY ST City AUSTIN State TX Zip 78704-3143

l, reviev	, owner, of <u>LOT 1(</u> ved the application for the Mary Street Local His	6 BLK 9 BLUE BONNET HILLS hereby state that I have to contract the total to the total tota
	I DO support the application for local historic district designation	Signature
	I DO NOT support the application for local historic district designation	Date

# Property ID 283354



Legal Acres 0.1242 Main Area SF 1147

#### **Historic District Information**

Contributing to Yes Local Historic District

Justification For Moderate Alterations, Contributing Status doesn't detract from historical character

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705

JOSEPH M HEBERT

Survey Date 1/15/2009

l, reviev	, owner, of <u>LOT 1</u> , owner, of <u>LOT 1</u> , ved the application for the Mary Street Local His	<b>.3 BLK 5 BLUE BONNET HILLS</b> hereby state that I have storic District.
	I DO support the application for local historic district designation	Signature
	I DO NOT support the application for local historic district designation	Date

# Property ID 283382 514 E Mary St

CONTRIBUTING



#### Description

Date of Construction	1935 Source: City Directories	Roof Mat
Stylistic Influences	Craftsman	Roof Deco
Historic Use	Dwelling, single	Numi
Current Use	Dwelling, single	Chin
Stories	1	Win
Plan	Square or rectangular	Door Fea
Foundation	Pier-and-Beam	Porch
Exterior Materials	Asbestos	Porch Sup
Roof Type	Front Gable, Jerkinhead	Porch Ra

oof Materials	Metal
of Decoration	Exposed Rafter Ends, Brackets
Number of Chimneys	Exterior: 0, Interior: 0
Windows	Wood Double Hung
oor Features	Glazing
Porch Type	Partial Width, Inset
rch Supports	Tapered on Pier, Brick Piers
orch Railings	Square Wood

Outbuildings	1 Story Detached Garage, Garage Wall Material: Wood, Garage Roof Type: Gabled
	1-4' stone retaining wall on east and west side.
Moved	Has Not Moved
Integrity	Rear addition.

# Travis Central Appraisal District Data

Map Key # /	283382	Situs	514 E MARY ST	Addr2	514 E MARY ST
Property ID		Situs Zip	78704	City	AUSTIN
Geo ID	302020413	Legal Description	LOT 13 BLK 9 BLUE	State	TX
Subdivision Code	S01528		BONNET HILLS		78704-3143
Subdivision	BLUE BONNET HILLS	Owner Name	CURTIS MICHAEL D	др	70704-3143

Legal Acres 0.1673

Main Area SF 1240

# **Historic District Information**

Contributing to Yes Local Historic District

Justification For Largely Intact Contributing Status

Sunceyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705 Survey Date 1/15/2009

l, reviev	, owner, of, wed the application for the Mary Street Local	T 13 BLK 9 BLUE BONNET HILLS hereby state that I have Historic District.
	I DO support the application for local histor district designation	ic Signature
	I DO NOT support the application for local historic district designation	Date

Property ID 283355 515 E Mary St



#### Description

Date of	/1110	Roof Materials	Composition shingles	Porch Railings	None
Stylistic Influences	Source: City Directories Revival - Tudor	Roof Decoration	Exposed Rafter Ends, Brackets	Outbuildings	Modern shed w/gabled roof.
Historic Use	Dwelling, single		Exterior: 0, Interior: 0	Landscape	Modern metal terracing.
Current Use	Dwelling, single	Chimneys		Features	
Stories	1	Windows	Wood Double Hung	Moved	Has Not Moved
Plan	Square or rectangular	Door Features	Glazing		
Foundation	Pier-and-Beam	Porch Type	Stoop Roof		
Exterior Materials	Wood	Porch Roof Types	Gabled, w/brackets		
Roof Type	Side Gable	Porch Supports	None		

# **Travis Central Appraisal District Data**

Map Key #7 Property ID	283355
Geo ID	302020308
Subdivision Code	S01528
Subdivision	BLUE BONNET HILLS
Legal Acres	0.1391

Main Area SF 928

Contributing to Yes Local Historic

Justification For Intact Contributing Status

Situs 515 E MARY ST Situs Zip 78704 Legal Description LOT 15 BLK 5 BLUE BONNET HILLS Owner Name TEXADA EVELYN

Addr2 1402 SANTA ROSA AVE City SANTA BARBARA State CA

Zip 93109-2065

**Historic District Information** 

District

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705

Survey Date 1/15/2009

I, reviev	, owner, of <b>LOT 1</b> wed the application for the Mary Street Local His	<u>5 BLK 5 BLUE BONNET HILLS hereby state that I have</u> storic District.
	I DO support the application for local historic district designation	Signature
	I DO NOT support the application for local historic district designation	Date

# Property ID 283381 516 E Mary St



I DO NOT support the application for local historic district designation

Date



#### Description

Date of		Roof Materials	Composition shingles	Porch Railings
Construction	Source: City Directories	Roof Decoration	Exposed Rafter Ends,	Outbuildings
Stylistic Influences	Craftsman	1100/ 2000/02001	Brackets	Outoundurigs
Historic Use	Dwelling, single		Exterior: 0, Interior: 0	
Current Use	Dwelling, single	Chimneys		
Stones	4	Windows	Wood Double Hung, Wood Screens	Moved
Stones				Integrity
Plan	Square or rectangular	Door Features	Glazing	
Foundation	Pier-and-Beam	Porch Type	Partial Width, Independent	
Exterior Materials	Wood	Porch Roof Types		
Roof Type	Roof Type Hipped	1.1.5		
	, where	Porch Supports	Square Full Height Wood	

#### h Railings Square Wood

1 Story Detached Garage, Garage Wall Material: Wood, Garage Roof Type: Gabled

Moved Has Not Moved

Integrity One story addition.

Addr2 517 E MARY ST

City AUSTIN

Zip 78704-3142

State TX

# Travis Central Appraisal District Data

Map Key # / 283356 Property ID Geo ID 302020309 Subdivision Code S01528 Subdivision BLUE BONNET HILLS

Legal Acres 0.1187 Main Area SF 1316

## **Historic District Information**

Contributing to Yes Local Historic District

Justification For Contributing Status doesn't detract from historical character Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705

Situs 517 E MARY ST

BONNET HILLS

Situs Zip 78704

Legal Description LOT 17 BLK 5 BLUE

Owner Name DOWNER MICHAEL WAYNE

Survey Date 1/15/2009

l, reviev	, owner, ofLOT 1 wed the application for the Mary Street Local Hi	17 BLK 5 BLUE BONNET HILLS hereby state that I have storic District.
	I DO support the application for local historic district designation	Signature
	I DO NOT support the application for local historic district designation	Date

# Property ID 283380 518 E Mary St

# NOT CONTRIBUTING Annie Si E 202 Suns . Mary St E Blunn Creek Greenbelt g Map data @2014 Goode

#### Description

Date of 1994 Construction Source: City Directories R Stylistic Influences Craftsman Historic Use Dwelling, single Current Use Dwelling, single Stories 2 Plan Square or rectangular Foundation Pier-and-Beam E Exterior Materials Wood Roof Type Front Gable

Roof Materials	Metal
Roof Decoration	Exposed Rafter Ends
Number of Chimneys	Exterior: 0, Interior: 0
Windows	Wood Double Hung
Door Features	Glazing
Porch Type	Partial Width, Inset, Enclosed
orch Supports	Square Full Height Wood
Porch Railings	Square Wood

Outbuildings	Large guest house: asbestos siding, comp shingle, hipped roof.
Landscape	Low concrete retaining

Landscape	Low concrete retaining
Features	wall,

Moved Has Not Moved

Integrity Second story added during historic period. Porch enclosed.

#### **Travis Central Appraisal District Data**

Map Key #/ 283380 Property ID Geo ID 302020411 Subdivision Code S01528 Subdivision BLUE BONNET HILLS

Situs 518 E MARY ST Situs Zip 78704 Legal LOT 11 BLK 9 BLUE Description BONNET HILLS

Owner Name LAMBERT ELIZABETH ANN

> Addr1 % PERSONAL ADMINISTRATORS

Addr2 3939 BEE CAVE RD STE C100 City WEST LAKE HILLS

State TX

Zip 78746-6429

Legal Acres 0.1673

Main Area SF 2649

**Historic District Information** 

Contributing to No Local Historic District

Surveyors /	Preservation Central, Terri
Evaluator of	Myers, 823 Harris
Contributing Status	Avenue, Austin, TX 78705

Justification For Severe alterations, porch Contributing Status enclosed

823 Harris e, Austin, TX 78705 Survey Date 1/15/2009

l, reviev	, owner, of <b>LOT</b> ; wed the application for the Mary Street Local Hi	11 BLK 9 BLUE BONNET HILLS hereby state that I have istoric District.
	I DO support the application for local historic district designation	
	I DO NOT support the application for local historic district designation	Date

Property ID 283389 500 E Mary St

#### CONTRIBUTING



# Description

Date of		Roof Materials	Composition shingles	Porch Railings	None
	Source: City Directories	Roof Decoration	Clipped Gables, Brackets	Fences	Corrugated metal (around
Stylistic Influences	Colonial Revival	Number of	Exterior: 0, Interior: 0		side and backyard)
Historic Use	Dwelling, single	Chimneys		Moved	Has Not Moved
Current Use	Dwelling, single	Windows	Wood Double Hung,	Integrity	Side and rear additions.
Stones	1 .		Decorative Screens, Decorative Shutters		
Plan	Square or rectangular	Door Features	Glazing		
Foundation	Pier-and-Beam, concrete	Porch Type	Partial Width, Independent		
Exterior Materials	Wood	Porch Roof Types	Gabled		
Roof Type	Side Gable	Porch Supports	Column Full Height		
Travis Central A	ppraisal District Data				
Map Key # /	283389	Situs	500 E MARY ST	Addr2	3005 S LAMAR BLVD STE
Property ID	Situs Zip	78704		D109	
Geo ID	302020420	Legal Description	LOT 20 & W 10.7SQ FT	City	AUSTIN
Subdivision Code	S01528	anger e en en proc	TRI OF LOT 19 BLK 9	State	тх
Subdivision	BLUE BONNET HILLS		BLUE BONNET HILLS	Zip	78704
		Owner Name	PARKINSON TONY &		

# **Historic District Information**

Main Area SF 1394

Legal Acres 0.1507

Contributing to Yes Local Historic District

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705

MARYANNE

Addr1 PMB 281

Justification For Moderate Alterations, Contributing Status doesn't detract from historical character

Survey Date 1/15/2009


Researchers 805 1/2 W. 16th St., Austin, TX 78701

Other Josh Conrad, Emily Reed

I, ANTHONY BRUCE PARKINSON, OWNER, OF LOT 20 & W 10.75Q FT TRI OF LOT 19 BLK 9 BLUE BONNET HILLS hereby state that I have reviewed the application for the Mary Street Local Historic District. I DO support the application for local historic 10/25/17 V district designation Signature \_ I DO NOT support the application for local Date \_ historic district designation

## Property ID 283388 502 E Mary St

#### CONTRIBUTING



#### Description

Date of		Roof Type	Cross Gable	Parch Roof Types	Gabled
Construction	Source: TCAD	Roof Materials	Composition shingles	Porch Supports	Tapered on Pier, Stucco
Stylistic Influences Revi	Revival - Tudor		on Exposed Rafter Ends,		Piers
Historic Use	Dwelling, single		Brackets	Porch Railings	Metal
Current Use	Dwelling, single		Exterior: 0, Interior: 0	Walls	Height: 2 ft, Stone
Stories	1	Chimneys		Outbuildings	1 Story Detached Garage,
Plan	Square or rectangular	Windows	Wood Double Hung, Decorative Screens		Garage Wall Material: Wood, Garage Roof
Foundation	Pier-and-Beam	Door Features			Material: Composition
Exterior Materials	Wood	Porch Type	Partial Width, Independent		shingles, Garage Roof Type: Gabled
				Moved	Has Not Moved
Map Key #/	ppraisal District Data 283388	Situs	502 E MARY ST	Addr2	502 E MARY ST
Property ID	302020419 Legal Descrip	Situs Zip	78704	City	AUSTIN
		Legal Description	FT TRI BLK 9 BLUE	State	тх
Subdivision Code				Zip	78704-3143
Subdivision	BLUE BONNET HILLS	Owner Name BILODEAU JAMES			
Legal Acres	0.1489	Owner Name	DILODEAU JAMIES		
Main Area SF	1393				
istoric District	1. fr				
	Information				

Local Historic District


Justification For Intact Contributing Status Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705 Survey Date 1/15/2009

Researchers 805 1/2 W. 16th St., Austin, TX 78701

Bi James odray, owner, of LOT 19 \*LESS W 10.75SQ FT TRI BLK 9 BLUE BONNET HILLS hereby 1, state that I have reviewed the application for the Mary Street Local Historic District. I DO support the application for local historic ) alord M ans ( district designation Signature I DO NOT support the application for local 10 Date historic district designation

Property ID 283349

#### CONTRIBUTING



alvert, owner, of LOT 3 BLK 5 BLUE BONNET HILLS hereby state that I have reviewed 1, 4 llia 14.0 the application for the Mary Street Local Historic District. I DO support the application for local historic William Ad. Colve October 13, 2017 X district designation Signature I DO NOT support the application for local Date historic district designation

#### Property ID 283387 504 E Mary St

#### CONTRIBUTING



## Description

 Date of
 1930

 Construction
 Source: TCAD

 Stylistic Influences
 Revival - Tudor

 Historic Use
 Dwelling, single

 Current Use
 Dwelling, single

 Stories
 1

 Plan
 Square or rectangular

 Foundation
 Pier-and-Beam

 Extenor Matenals
 Wood

 Roof Type
 Side Gable

Roof Materials	Composition shingles	
Roof Decoration	Brackets	
Number of Chimneys	Exterior: D, Interior: D	
Windows	Wood Double Hung, Decorative Screens	
Door Features	Glazing, Peephole	
Porch Type	Stoop Roof	
Porch Roof Types	Other, Canvas awning over door	
Porch Supports	None	

Porch Railings Metal

Outbuildings 1 Story Detached Garage, Garage Wall Material: Board & Batten, Garage Roof Material: Composition shingles, Garage Roof Type: Hipped Moved Has Not Moved

Travis Central Appraisal District Data

Map Key # / 283387 Property ID Geo ID 302020418 Subdivision Code S01528 Subdivision BLUE BONNET HILLS

Legal Acres 0.1539

Main Area SF 1128

## **Historic District Information**

Contributing to Yes Local Historic District

Justification For Intact Contributing Status Situs Zp 78704 Legal Description LOT 18 BLK 9 BLUE BONNET HILLS Owner Name TONGATE JOHN T Addr2 504 E MARY ST City AUSTIN State TX Zip 78704-3143

ct Information

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705 Survey Date 1/15/2009

I, <u>JOHNT. TONGME</u> owner, of <u>LOT 18 BLK 9 BLUE BONNET HILLS</u> hereby state that I have reviewed the application for the Mary Street Local Historic District.					
A	I DO support the application for local historic district designation	Signature Spl-Tlongalo			
	I DO NOT support the application for local historic district designation	Date 10/14/2017			

Property ID 283350 505 E Mary St



CONTRIBUTING

Construction	Source: TCAD	Chest Ches	and a state of the second s	1 sector contentinger	
		Roof Materials	Metal	Outbuildings	1 Story Detached
Stylistic Influences	Minimal Traditional	Roof Decoration	Exposed Rafter Ends,		Garage, Garage Wall
Historic Use	Dwelling, single		Brackets		Material: Wood, Garage Roof Type: Gabled
Current Use	Dwelling, single		Exterior: 0, Interior: 0	Moved	Has Not Moved
Stones	Stones 1	Chimneys		Integrity	Door replaced.
Plan	Square or rectangular	Windows	Wood Double Hung, Decorative Screens	nicedurk	boor replaced.
Foundation	Pier-and-Beam	Porch Type	Partial Width, Inset		
Exterior Materials	Wood	Porch Supports	Square Full Height Wood		

Map Key #/	283350	Situs	505 E MARY ST	Addir2	505 E MARY ST
Property ID		Situs Zip	78704	City	AUSTIN
Geo ID	302020303	Legal Description	LOT 5 BLK 5 BLUE	State	TX
Subdivision Code	S01528		BONNET HILLS	Zip	78704-3142
Subdivision	BLUE BONNET HILLS	Owner Name	BORAH MATTHEW	- PP	
Legal Acres	0.1501				
Main Area SF	1448				
istoric District	Information				
Contributing to Local Historic District		Evaluator of	Preservation Central, Terri Myers, 823 Harris Avenue, Austin, TX 78705	Othe Researchers	Josh Conrad, Emily Reed 805 1/2 W. 16th St., Austin, TX 78701
Justification For Contributing Status		Survey Date	1/15/2009		

I, M	HHEW BURAH, owner, of LOT 5 pplication for the Mary Street Local Historic Distri	BLK 5 BLUE BONNET HILLS hereby state that I have reviewed
Ø	I DO support the application for local historic district designation	Signature
	I DO NOT support the application for local historic district designation	Date 10/18/2017

# Property ID 283386 506 E Mary St

#### CONTRIBUTING





Blann Creek Maxidata @2014 Goode



#### Description

Date of	1.4.4.1	Root Matemain	Composition shingles	Forch Ralings	Square Wood
Stylistic information	Source: TCAD Craftsman	Root Decomeda	Exposed Rafter Ends, Brackets	Outbuildings	1 Story Detached Garage, Garage Wall Material:
Historie Une	Dwelling, single	Number of	Exterior: 0, Interior: 0		Wood, Garage Roof Material: Composition
Current Use	Dwelling, single	Clautheys			shingles, Garage Roof
Stores	1	Windows	Wood Double Hung, Wood Screens		Type: Gabled, Large two story building w/wood
Plan	Square or rectangular	Door Features	Glazing		walls, comp shingles, and clipped gable roof.
	Pier-and-Beam	Porch Type	Partial Width, Independent	Movera	Has Not Moved
Extenior Materials		Porch Roof Types	Gabled		
Road Type	Front Gable, Jerkinhead	Porch Supports	Tapered on Pier, Brick Piers		

Siture 506 E MARY ST

Owner Name REGIMBEAU PASCAL G & SYBIL R

BONNET HILLS

Stub Zp 78704

Legal Description LOT 17 BLK 9 BLUE

ŝ

#### Travis Central Appraisal District Data

Map Key #1 283386 Property ID Geo ID 302020417 Subdivision Code S01528 Subdivision BLUE BONNET HILLS Legal Acres 0.156

Main Area SF 1593

# **Historic District Information**

Contributing to Yes Local Historic Distact Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status: Avenue, Austin, TX 78705

Survey Date: 1/15/2009

Addr.<sup>2</sup> 506 E MARY ST City AUSTIN State TX 200 78704-3143

Justi	cist	ion F	Ġr.	Intact
owner,	ind	Stat	ús:	

PA I, <u>a</u> review	CAL REGIMBEAU SUBIL REGIMBEAU you have application for the Mary Street Local Hist	BLK 9 BLUE B oric District.	ONNET HILLS hereby state that I have
$\square$	I DO support the application for local historic district designation	Signature _	5. Pinel
	I DO NOT support the application for local historic district designation	Date	10-15-17-

# Property ID 283351 507 E Mary St

# CONTRIBUTING



# Description

Date of Construction	1931 Source: City Directories
Stylistic Influences	Craftsman
Historic Use	Dwelling, single
Current Use	Dwelling, single
Stories	1
Plan	Square or rectangular
Foundation	Pier-and-Beam
Exterior Materials	Asbestos
Roof Type	Front Gable

Roof Materials	Metal
Roof Decoration	Exposed Rafter Ends, Brackets
Number of Chimneys	Exterior: 0, Interior: 0
Windows	Wood Double Hung, Wood Screens
Porch Type	Partial Width, Inset
Porch Supports	Square Full Height Wood
Porch Railings	Square Wood
Fences	Stone and iron

# Walls Height: 2 ft, Stone

Outbuildings 1 Story Detached Garage, Garage Wall Material: Wood, Garage Roof Type: Gabled Moved Has Not Moved

Integrity Rear historic addition.

Travis Central A	ppraisal District Data				
Map Key # /	283351	Situs	507 E MARY ST	Addr2	507 E MARY ST
Property ID		Situs Zip	78704	City	AUSTIN
Geo ID	302020304	Legal Description	LOT 7 BLK 5 BLUE	State	TX
Subdivision Code	S01528		BONNET HILLS	Zip	78704-3142
Subdivision	BLUE BONNET HILLS	Owner Name	JONES DAVID F & CYNTHIA L WILL	- P	
Legal Acres	0.1423				
Main Area SF	1000	Addri	CYNTHIA L WILLIAMS		
Historic District	Information				
Contributing to Local Historic District		Evaluator of	Preservation Central, Terri Myers, 823 Harris Avenue, Austin, TX 78705	Othe Researcher	
Justification For Contributing Status		Survey Date	1/15/2009		

theat	plication for the Mary Street Local Historic Distr	BLK 5 BLUE BONNET HILLS hereby state that I have reviewed ict.
T	IDO support the application for local historic district designation	Signature
	I DO NOT support the application for local historic district designation	Date 10/14/17

Property ID 283385 508 E Mary St

CONTRIBUTING





#### Description

Date of		Roof Type	Side Gable	Porch Supports	None
Construction	Source: City Directories	Roof Matenals	Composition shingles	Porch Railings	None
Stylistic Influences	Revival - Tudor	Roof Decoration	Exposed Rafter Ends.	Moved	Has Not Moved
Historic Use	Dwelling, single	1001200014001	Brackets		
Current Use	Dwelling, single	Number of	Exterior: 0, Interior: 0	integrity	Front entrance vestibule resided and possibly
Stones	1	Chimneys			enclosed. Front porch
Plan	Square or rectangular	Windows	Wood Double Hung		enlarged.
Foundation	Pier-and-Beam	Door Features	Glazing, Roman Arch w/peephole		
Exterior Materials	Wood	Porch Type	Full Width, Stoop Roof		

#### **Travis Central Appraisal District Data**

Map Key #/ 283385 Property ID Geo ID 302020416

Subdivision Code S01528 Subdivision BLUE BONNET HILLS

Legal Acres 0.1642

Main Area SF 1248

#### **Historic District Information**

Contributing to Yes Local Historic

District

Situs 508 E MARY ST Situs Zip 78704 Legal Description LOT 14 BLK 9 BLUE BONNET HILLS Owner Name BARKER NORMAN R JR ETAL

Addr2 4617 ARAPAHOE TRL City AUSTIN State TX

Zp 78745-1509

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705

Survey Date 1/15/2009

Other Josh Conrad, Emily Reed Researchers 805 1/2 W. 16th St., Austin, TX 78701

Justification For Moderate Alterations, Contributing Status doesn't detract from historical character

I, NORMAN BARICER owner, of LOT 14 BLK 9 BLUE BONNET HILLS hereby state that I have reviewed the application for the Mary Street Local Historic District.

I DO support the application for local historic T district designation

> I DO NOT support the application for local historic district designation

Signature <u>Worman Barhw</u> Date <u>11/3/2017</u>

Property ID 283352 509 E Mary St



Date of	1020	Roof Materials	Composition shingles	Porch Supports	Metal
	Source: City Directories	Roof Decoration	Exposed Rafter Ends,	Porch Railings	Metal
Stylistic Influences	Craftsman		Brackets	Landscape	3' stone retaining wall at
Historic Use	Dwelling, single		Exterior: 1, Interior: 0		driveway.
Current Use	Dwelling, single	Chimneys		Moved	Has Not Moved
Stones	1	Chimney Materials	Stone	Integrity	Rear addition with stucco
Plan	Square or rectangular	Windows	Wood Double Hung, Decorative Screens		walls and metal roof w/ cupola.
Foundation	Pier-and-Beam	Door Features	Glazing		
Exterior Materials	Wood	Porch Type	Partial Width, Independent		
Roof Type	Hipped with Gable	Porch Roof Types	Gabled		
Travis Central A	ppraisal District Data				
Map Key # /	283352	Situs	509 E MARY ST	Addr2	741 SPYGLASS DR
Property ID		Situs Zo	78704	City A	AUSTIN
Geo ID	302020305	Lenal Det motion	LOT 9 BLK 5 BLUE		X
Subdivision Code	S01528	Logar coorription	BONNET HILLS		
Subdivision	BLUE BONNET HILLS	Owner Name	KREPS KAREN R	Др 7	8746-6888

**Historic District Information** 

Legal Acres 0.1479 Main Area SF 1944

Contributing to Yes

Local Historic Distnct

Justification For Moderate Alterations, Contributing Status doesn't detract from historical character

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705

Survey Date 1/15/2009

Other Josh Conrad, Emily Reed Researchers 805 1/2 W. 16th St., Austin, TX 78701

l,	Karen Kreps , owner, of LOT	9 BLK 5 BLUE BONNETT HILLS hereby state that I have
review	ved the application for the Mary Street Local H	istoric District.
ĽX	I DO support the application for local historic district designation	Signature <u>Karen Krepa</u>
	I DO NOT support the application for local historic district designation	DateOct 19, 2017

# Property ID 283353 511 E Mary St

#### CONTRIBUTING



#### Description

Date of Construction	1933 Source: City Directories
Stylistic Influences	Craftsman
Historic Use	Dwelling, single
Current Use	Dwelling, single
Stones	1.5
Plan	Square or rectangular
Foundation	Pier-and-Beam
Exterior Materials	Wood
Roof Type	Side Gable

# Roof Materials Composition shingles Roof Decoration Brackets Number of Exterior: 1, Interior: 0 Chimneys Chimney Materials Wood Windows Wood Double Hung, Decorative Screens Door Features Glazing, Not Original Porch Type Partial Width, Stoop Roof Porch Roof Types Shed

# Porch Supports None Porch Railings Square Wood Number of 1 Dormers Dormer Type Gabled

Moved Has Not Moved

Addr2 511 E MARY ST

Zp 78704-3142

City AUSTIN

State TX

Integrity One story addition on west side. Glass block window on east wall. Porch railings replaced. Door replaced.

# **Travis Central Appraisal District Data**

Map Key # / 283353 Property ID Geo ID 302020306 Subdivision Code S01528

Subdivision BLUE BONNET HILLS

Legal Acres 0.1409

Main Area SF 2276

#### **Historic District Information**

Contributing to Yes Local Historic

District

Justification For Moderate Alterations,

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705

Situs 511 E MARY ST

BONNET HILLS

Situs Zip 78704

Legal Description LOT 11 BLK 5 BLUE

Owner Name HUBELE LAUREN & JOACHIM

> Other Josh Conrad, Emily Reed Researchers 805 1/2 W. 16th St., Austin, TX 78701

Contributing Status doesn't detract from historical character

Survey Date 1/15/2009

OUVEN Hubele, owner, of LOT 11 BLK 5 BLUE BONNETT HILLS hereby state that I have ١, reviewed the application for the Mary Street Local Historic District. I DO support the application for local historic re Aaura Nubeli 12 October 2017 P3 district designation Signature I DO NOT support the application for local Date historic district designation

Property ID 283383 512 E Mary St

CONTRIBUTING



#### Description

Date of		Roof Type	Hipped with Gable	Porch Railings	Metal
Construction	Source: City Directories	Roof Matenals	Composition shingles	Outbuildings	1 Story Detached
	Minimal Traditional Dwelling, single		Exterior: 0, Interior: 0		Garage, Garage Roof Type: Shed, Carport.
	Dwelling, single		Wood Double Hung	Landscape Features	2' concrete retaining wall.
Stories	S	Door Features	Glazing, Roman Arch w/peephole	Moved	Has Not Moved
	Square or rectangular Pier-and-Beam	Porch Type	Partial Width, Inset	Integrity	Large two story addition.
Exterior Materials	2010 C 2020	Porch Supports	Other, Stucco arch		

# Travis Central Appraisal District Data

Map Key #1 283383 Property ID

Geo ID 302020414

Subdivision Code S01528 Subdivision BLUE BONNET HILLS

Legal Acres 0.156

Main Area SF 1928

#### **Historic District Information**

Contributing to Yes Local Historic District

Justification For Moderate Alterations, Contributing Status doesn't detract from historical character Situs 512 E MARY ST Situs Zp 78704 Legal Description LOT 16 BLK 9 BLUE BONNET HILLS Owner Name OTTO GRETCHEN ALYNNE &

Addr1 MARK THOMAS SMITH

Addr2 512 E MARY ST City AUSTIN State TX Zip 78704-3143

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705

Survey Date 1/15/2009

GR 1, JM	ARK SMITH , owner, of LOT 16	BLK 9 BLUE BONNET HILLS hereby state that Phave
review	ved the application for the Mary Street Local History	
$\mathbf{X}$	I DO support the application for local historic district designation	Signature Malfim
	I DO NOT support the application for local historic district designation	Date 10/14/17

Property ID 283355 515 E Mary St

Date of 1933

Stylistic Influences Revival - Tudor

Historic Use Dwelling, single

Construction Source: City Directories



Roof Matenals Composition shingles

Roof Decoration Exposed Rafter Ends,

Brackets

Number of Exterior: D, Interior: D

Porch Railings None

Outbuildings Modern shed w/gabled

Landscape Modern metal terracing.

roof.

Chimneys Features Current Use Dwelling, single Windows Wood Double Hung Moved Has Not Moved Stories 1 Door Features Glazing Plan Square or rectangular Porch Type Stoop Roof Foundation Pier-and-Beam Porch Roof Types Gabled, w/brackets Exterior Materials Wood Porch Supports None Roof Type Side Gable **Travis Central Appraisal District Data** Map Key #/ 283355 Situs 515 E MARY ST Addr2 1402 SANTA ROSA AVE Property ID Situs Zip 78704 City SANTA BARBARA Geo ID 302020308 Legal Description LOT 15 BLK 5 BLUE State CA Subdivision Code S01528 BONNET HILLS Zp 93109-2065 Subdivision BLUE BONNET HILLS Owner Name TEXADA EVELYN Legal Acres 0.1391 Main Area SF 928 **Historic District Information** Contributing to Yes Surveyors / Preservation Central, Terri Other Josh Conrad, Emily Reed Local Historic Evaluator of Myers, 823 Harris Researchers 805 1/2 W. 16th St., Contributing Status Avenue, Austin, TX 78705 District Austin, TX 78701 Justification For Intact Survey Date 1/15/2009 Contributing Status Gowher, of \_LOT 15 BLK 5 BLUE BONNET HILLS hereby state that I have I. reviewed the application for the Mary Street Local Historic District. I DO support the application for local historic M district designation Signature I DO NOT support the application for local Date historic district designation

517 E Mary S	5t				CONTRIBUTING
		1	SCHOOL STREET		
			and the same of		1. 1. 19
Maryste			- TONE -	ALL N	All Star
18				P. A. Carta	10000
				N MAL	Contra la
	Mary St E		/ 1/1/1/	THE REAL PROPERTY	in the
	P Bhan Gree	k	A. States	Non and I a	HARD - AN
	Gieenbe		A State of the second	10 1 2	All of the second
					情報的人間來
1. Delda					
	in or A				
opole i	C Mag			and the state	15 220
		Mao data @2014 Go:	xile		
scription					
Date o	1929	Roof Materials	Composition shingles	Porch Railings	Square Wood
Construction	Source: City Directories		Exposed Rafter Ends,		1 Story Detached
itylistic Influences	Craftsman		Brackets		Garage, Garage Wall Material: Wood, Garage
	Dwelling, single	Number of Chimneys	Exterior: 0, Interior: 0		Roof Type: Gabled
	Dwelling, single		Wood Double Hung, Wood	Moved	Has Not Moved
Stones	Square or rectangular		Screens	Inteduty	One story addition.
	Pier-and-Beam	Door Features			
Exterior Materials			Partial Width, Independent		
Roof Type	Hipped	Parch Roaf Types	Square Full Height Wood		
avis Central A	ppraisal District Data				
Map Key #7	283356	Situs	517 E MARY ST	Addr2 5	17 E MARY ST
Property ID	202020200	Situs Zip	78704	City A	AUSTIN
Subdivision Code	302020309	Legal Description	LOT 17 BLK 5 BLUE	State	TX .
	BLUE BONNET HILLS	Owner Name	BONNET HILLS DOWNER MICHAEL	Zip 7	8704-3142
Legal Acres	0.1187		WAYNE		
Main Area SF					
storic District	information				
Contributing to Local Historic District	Yes	Evaluator of	Preservation Central, Terri Myers, 823 Harris Avenue, Austin, TX 78705		Josh Conrad, Emily Re 805 1/2 W. 16th St., Austin, TX 78701
	Moderate Alterations, doesn't detract from historical character	Survey Date	1/15/2009		

I DO support the application for local historic district designation

D

I DO NOT support the application for local historic district designation

Signature San	nel	& Dow	ner
Date OA	20	2017	

•

Property ID 283386 506 E Mary St

CONTRIBUTING



#### Description

Date	of 1931	Roof Materials	Composition shingles	Porch Railings	Square Wood
	on Source: TCAD		Exposed Rafter Ends,	Outbuildings	1 Story Detached Garage,
Stylistic Influence	es Craftsman		Brackets		Garage Wall Material:
Historic U	se Dwelling, single		Exterior: 0, Interior: 0		Wood, Garage Roof Material: Composition
Current U	se Dwelling, single	Chimneys			shingles, Garage Roof
Stor	es 1	Windows	Wood Double Hung, Wood Screens		Type: Gabled, Large two story building w/wood
P	an Square or rectangular	Door Features	Glazing		walls, comp shingles, and clipped gable roof.
Foundati	on Pier-and-Beam	Porch Type	Partial Width, Independent	Moved	Has Not Moved
Exterior Materi	als Wood	Porch Roof Types	Gabled		
Roof Ty	pe Front Gable, Jerkinhead	Porch Supports	Tapered on Pier, Brick Piers		

#### **Travis Central Appraisal District Data**

283386	Situs	506 E MARY ST
	Situs Zp	78704
302020417	Legal Description	LOT 17 BLK 9 BLUE
S01528		BONNET HILLS
BLUE BONNET HILLS	Owner Name	REGIMBEAU PASCAL G & SYBIL R
0.156		
1593		
	302020417 S01528 BLUE BONNET HILLS 0.156	Situs Zp 302020417 Legal Description S01528 BLUE BONNET HILLS Owner Name 0.156

# **Historic District Information**

Contributing to Yes Local Historic District Justification For Intact

Contributing Status

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705 Survey Date 1/15/2009

Other Josh Conrad, Emily Reed Researchers 805 1/2 W. 16th St., Austin, TX 78701

PASCAL REGIMBEAU I, <u>A SYBIL</u> R, owner, of LOT 17 BLK 9 BLUE BONNET HILLS hereby state that I have reviewed the application for the Mary Street Local Historic District.

I DO support the application for local historic district designation

Signature \_\_\_\_\_\_\_ Date \_\_\_\_\_\_ 10-15-17\_\_\_\_\_

I DO NOT support the application for local historic district designation


Addr2	506 E MARY ST
City	AUSTIN
State	тх
Zip	78704-3143

1
5
IX.

Duplicates

Property ID 283386

# CONTRIBUTING



# Description

Date of 1931 Construction Source: TCAD Stylistic Influences Craftsman Historic Use Dwelling, single Current Use Dwelling, single Stories 1 Ptan Square or rectangular Foundation Pier-and-Beam Exterior Materials Wood Roof Type Front Gable, Jerkinhead  
 Roof Materials
 Composition shingles

 Roof Decoration
 Exposed Rafter Ends, Brackets

 Number of Chimneys
 Exterior: 0, Interior: 0

 Windows
 Wood Double Hung, Wood Screens

 Door Features
 Glazing

 Porch Type
 Partial Width, Independent

 Porch Roof Types
 Gabled

 Porch Supports
 Tapered on Pier, Brick Piers
 Porch Railings Square Wood Outbuildings 1 Story Detached Garage, Garage Wall Material: Wood, Garage Roof Material: Composition shingles, Garage Roof Type: Gabled, Large two story building w/wood walls, comp shingles, and clipped gable roof.

**Travis Central Appraisal District Data** Addr2 506 E MARY ST Situs 506 E MARY ST Map Key #1 283386 City AUSTIN Property ID Situs Zip 78704 Geo ID 302020417 State TX Legal Description LOT 17 BLK 9 BLUE BONNETHILLS Subdivision Code S01528 Zp 78704-3143 Chaner Name REGIMBEAU PASCAL G Subdivision BLUE BONNET HILLS & SYBL R Legal Acres 0.156

Main Area SF 1593

**Historic District Information** 

Contributing to Yes Local Historic District

Justification For Intact Contributing Status

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Hanis Contributing Status Avenue, Austin, TX78705 Survey Date 1/15/2009 Other Josh Conrad, Emily Reed Researchers 805 1/2 W. 16th St., Austin, TX 78701

# PASCAL REGIMBEAU

I, <u>SYBIL</u> R owner, of <u>LOT 17 BLK 9 BLUE BONNET HILLS</u> hereby state that I have reviewed the application for the Mary Street Local Historic District.

5

10.15.17

district designation

Signature 1 DO NOT support the application for local Date historic district designation



Map data @2014 Goode

# Description

Date of	and the second se	Roof Materials	Composition shingles	Porch Railings	Square Wood
Construction	Source: City Directories	Roof Decoration	Exposed Rafter Ends,	Outbuildings	1 Story Detached
Stylistic Influences	Craftsman		Brackets		Garage, Garage Wall
Historic Use	Dwelling, single	Number of	Exterior: 0, Interior: 0		Material: Wood, Garage Roof Type: Gabled
Current Lise	Dwelling, single	Chimneys			
		Windows	Wood Double Hung, Wood	Moved	Has Not Moved
Stones	1		Screens	Integrity	One story addition.
Plan	Square or rectangular	Door Features	Glazing		
Foundation	Pier-and-Beam	Porch Type	Partial Width, Independent		
Extenor Materials	Wood	Porch Roof Types	Gabled		
Roof Type	Hipped	Porch Supports	Square Full Height Wood		

# Travis Central Appraisal District Data

Map Key #/ 283356 Property ID Geo ID 302020309 Subdivision Code S01528 Subdivision BLUE BONNET HILLS

Legal Acres 0.1187 Main Area SF 1316

**Historic District Information** 

Contributing to Yes Local Historic District

Justrication For Moderate Alterations, Contributing Status doesn't detract from historical character

Surveyors / Preservation Central, Terri Evaluator of Myers, 823 Harris Contributing Status Avenue, Austin, TX 78705 Survey Date 1/15/2009

Situs 517 E MARY ST

BONNET HILLS

Situs Zip 78704

Legal Description LOT 17 BLK 5 BLUE

Owner Name DOWNER MICHAEL WAYNE

Other Josh Conrad, Emily Reed Researchers 805 1/2 W. 16th St., Austin, TX 78701

Addr2 517 E MARY ST

City AUSTIN

Zp 78704-3142

State TX

1	ed the application for the Mary Street Local Hist	BLK 5 BLUE BONNET HILLS hereby state that I have oric District.
Ø	I DO support the application for local historic district designation	Signature Jane & Downer
	I DO NOT support the application for local historic district designation	Date 0120,2017

Property ID 283386

# CONTRIBUTING



# Description

Date of 1931 Construction Source: TCAD Stylistic Influences Craftsman Historic Use Dwelling, single Current Use Dwelling, single Stories 1 Plan Square or rectangular Foundation Pier-and-Beam Exterior Materials Wood Roof Type Front Gable, Jerkinhead

**Travis Central Appraisal District Data** 

Roof Materials Composition shingles Roof Decoration Exposed Rafter Ends, Brackets Number of Exterior: 0, Interior: 0 Chimneys Windows Wood Double Hung, Wood Screens Door Features Glazing Porch Type Partial Width, Independent Porch Roof Types Gabled Porch Supports Tapered on Pier, Brick Piers

# Porch Railings Square Wood

Outbuildings 1 Story Detached Garage, Garage Wall Material: Wood, Garage Roof Material: Composition ahingles, Garage Roof Type: Gabled, Large two story building w/wood walls, comp shingles, and clipped gable roof.

Moved Has Not Moved

Add 2 506 E MARY ST Situs 506 F MARY ST Map Key #1 283386 Property ID City AUSTIN Situs Zip 78704 Geo ID 302020417 Legal Description LOT 17 BLK 9 BLUE BONNET HILLS State TX Subdivision Code S01528 Zp 78704-3143 Owner Name REGIMBEAU PASCAL G Subdivision BLUE BONNET HILLS & SYBL R Legal Acres 0.156 Main Area SF 1593 **Historic District Information** Other Josh Conrad, Emily Reed Contributing to Yes Surveyors / Presentation Central, Terri Researchers 805 1/2 W. 16th St., Evaluator of Myena, 823 Hamis Contributing Status Avenue, Austin, TX78705 Local Historic District Austin, TX 78701 Justification For Intact Survey Date 1/15/2009 Contributing Status PASCAL REGIMBEAU , A SYBIL R owner, of LOT 17 BLK 9 BLUE BONNET HILLS hereby state that I have reviewed the application for the Mary Street Local Historic District.

I DO support the application for local historic X Signature \_\_\_\_\_\_ district designation

I DO NOT support the application for local historic district designation

Date 10.15.17

Scanned by CamScanner