





SUBJECT TRACT




PENDING CASE



### **NOTIFICATIONS**

CASE#: C15-2018-0043

LOCATION: 3906 MANCHACA ROAD





This product has been produced by CTM for the sole purpose of geographic reference. No warranty is made by the City of Austin regarding specific accuracy or completeness.



H01/2

### Board of Adjustment General/Parking Variance Application

WARNING: Filing of this appeal stops all affected construction activity.

This application is a fillable PDF that can be completed electronically. To ensure your information is saved, <u>click here to Save</u> the form to your computer, then open your copy and continue.

The Tab key may be used to navigate to each field; Shift + Tab moves to the previous field. The Enter key activates links, emails, and buttons. Use the Up & Down Arrow keys to scroll through drop-down lists and check boxes, and hit Enter to make a selection.

The application must be complete and accurate prior to submittal. *If more space is required, please complete Section 6 as needed.* All information is required (if applicable).

### For Office Use Only

Case #	ROW # _		Tax #		
Section 1: App	olicant Statement	t			
Street Address: 390	3 Manchaca Road				
Subdivision Legal De ABS 676 SUR 19	scription: RIDDLE C H ACR 0.3				
Lot(s):		Bloc	:k(s):		
Outlot:		Divis	sion:		
Zoning District:					
I/We Alicia Browner			on be	ehalf of myself	ourselves as
authorized agent	for RTAB Holdings, LL	_C		;	affirm that on
Month Select	, Day Select	, Year Select	, hereby ap	ply for a hear	ing before the
Board of Adjustme	ent for consideration to	(select approp	riate option bel	ow):	
○ Erect ○ Atta	ach OComplete	Remodel	<ul><li>Maintain</li></ul>	Other:	
Type of Structure	Fabric and steel cant	ilevered awning	to cover parki	na	

Portion of the City of Austin Land Development Code applicant is seeking a variance from:
Steel post supports of the parking awning are within the setback
Section 2: Variance Findings
The Board must determine the existence of, sufficiency of, and weight of evidence supporting the findings described below. Therefore, you must complete each of the applicable Findings Statements as part of your application. Failure to do so may result in your application being rejected as incomplete. Please attach any additional supporting documents.
NOTE: The Board cannot grant a variance that would provide the applicant with a special privilege not enjoyed by others similarly situated or potentially similarly situated.
I contend that my entitlement to the requested variance is based on the following findings:
Reasonable Use The zoning regulations applicable to the property do not allow for a reasonable use because:
Setback is larger than the beginning of the parking area, so awning supports had to be in the setback.
Hardship  a) The hardship for which the variance is requested is unique to the property in that:
A series of small trees at the back of the property provide shade and privacy to us and our neighbors to the back. Copious numbers of birds inhabit the trees for Ligustrum berries; and were damaging the finish on employee's parked cars and bikes. Employees were imposing on neighborhood street parking to avoid the birds. Large pecan root zone to the side of the parking precludes an awning pylon outside the setback.
b) The hardship is not general to the area in which the property is located because:  Most properties do not have parking next to a large number of Ligustrum trees. In fact, though our back yard has this, our front yard does not have this issue.

### **Area Character**

The variance will not alter the character of the area adjacent to the property, will not impair the use of adjacent conforming property, and will not impair the purpose of the regulations of the zoning district in which the property is located because:

	Awning is very attractive; made of green fabric that blends into the trees and provides a low visual impact. Awning allows us to keep the greenery buffer provided by the trees; thus it creates
	orivacy, especially to the neighbor to the back.
Requ	ing (additional criteria for parking variances only) uest for a parking variance requires the Board to make additional findings. The Board may grant riance to a regulation prescribed in the City of Austin Land Development Code Chapter 25-6,
	endix A with respect to the number of off-street parking spaces or loading facilities required if it es findings of fact that the following additional circumstances also apply:
1	Neither present nor anticipated future traffic volumes generated by the use of the site or the uses of sites in the vicinity reasonably require strict or literal interpretation and enforcement of the specific regulation because:
2	. The granting of this variance will not result in the parking or loading of vehicles on public streets in such a manner as to interfere with the free flow of traffic of the streets because:
3	. The granting of this variance will not create a safety hazard or any other condition inconsisten with the objectives of this Ordinance because:
4	. The variance will run with the use or uses to which it pertains and shall not run with the site because:

H01/5


### **Section 3: Applicant Certificate**


I affirm that my statements contained in the con my knowledge and belief.	nplete application are true a	and correct to the best of
Applicant Signature: Alicia Browner	Digitally signed by Alicia Browner DN: cn=Alicia Browner, o, ou, email=abrowner@prefudedynamics.com, c=US	Date: <u>8/14/2018</u>
Applicant Name (typed or printed): Alicia Brown		
Applicant Mailing Address: 3906 Manchaca Rd		**************************************
City: Austin		Zip: 78704
Phone (will be public information): 512-476-510		
Email (optional – will be public information):		
Section 4: Owner Certificate		
I affirm that my statements contained in the commy knowledge and belief.	_	and correct to the best of
Owner Signature: RTAB Holding	p, Inc	Date: 8/14/2018
Owner Name (typed or printed): Alicia Browner		
Owner Mailing Address: 3906 Manchaca Rd		
City: Austin	State: TX	Zip: 78704
Phone (will be public information): 512-476-510	0	
Email (optional – will be public information):		
Section 5: Agent Information		
Agent Name:		
Agent Mailing Address:		
City:		Zip:
Phone (will be public information):		
Section 6: Additional Space (if app	olicable)	
Please use the space below to provide additionate referenced to the proper item, include the Section	al information as needed. T on and Field names as well	(continued on next page).
	The state of the s	- Available - Avai

H01/6

### **Section 3: Applicant Certificate**

I affirm that my statements contained in the complete ap my knowledge and belief.	plication are true	and correct to the best of
Applicant Signature:		Date: <u>8/14/2018</u>
Applicant Name (typed or printed): Alicia Browner and R		
Applicant Mailing Address: 3906 Manchaca Rd		
City: Austin		Zip: 7 <u>8704</u>
Phone (will be public information): 512-476-5100		
Email (optional – will be public information):		
Section 4: Owner Certificate		
I affirm that my statements contained in the complete ap my knowledge and belief.	plication are true	and correct to the best of
Owner Signature:		Date: <u>8/14/2018</u>
Owner Name (typed or printed): Alicia Browner		
Owner Mailing Address: 3906 Manchaca Rd		
City: Austin	State: TX	Zip: 7 <u>8704</u>
Phone (will be public information): 512-476-5100		
Email (optional – will be public information):		
Section 5: Agent Information		
Agent Name:		
Agent Mailing Address:		
City:		Zip:
Phone (will be public information):		
Email (optional – will be public information):		
Section 6: Additional Space (if applicable	e)	
Please use the space below to provide additional informate referenced to the proper item, include the Section and Fi		





### INTRODUCTION

- Owner: Alicia Browner, Ph.D. (RTAB Holdings, LLC)
- Property type: Owner occupied, small business
- Zoned: LO-MU Used as LO ---- 2,300 sf
- Address: 3906 Manchaca Rd., Austin, TX 78704
- Purpose: Seek a variance for a parking lot awning setback

## OUR MISSION STATEMENT

### HO1/10 OUR MIS OUR MIS Mission:

affordable customizable and is efficient, powerful, clinical trial software that animal health with of cures for human and Speed the development

- Locally and privately owned by 30-yr residents of Austin
- In business since 2004.
- 18 Austin employees in high-tech jobs
- center, computers serving FDA clinical trials Bus. Model: "SaaS" software run in a big data
- Not open to the public. No in/out traffic. No shipping. No nights or weekends.

# SOFTWARE TO COLLECT DATA FOR CLINICAL TRIALS







### **Human Studies**


- All Phases of Clinical
- Registries

### **Companion Animal Studies**

- **POC Studies**
- Field Studies
- Registries


### **Production Animal Studies**

- Animal-based
- Pen-based




## PROPERTY HISTORY: GOAL


- pleasing to all and an asset to the neighborhood Create a property that would be aesthetically
- neighborhood nice and protecting neighbors We understand the importance of keeping the
- Richard: served many years on a MUD board
- Alicia: served many years on HOA Board and **Architectural Committee**




## ORIGINAL SITE PLAN

Prior to remodel and rezone








## BEFORE AND AFTER

Property has improved the street, the neighborhood and the city!



H01/19

### LO-MU



Received lots of compliments from neighbors

## TIME LINE FOR 3906 MANCHACA

1948

1985-7

**Building constructed** 

Aug 2012

Upgrade sewer/electric/HVAC

Oct 2012

Remodel #1 - up to code, Cert. of Occupancy

Acquired by RTAB, LLC

May 2013

Re-Zone LO-MU - granted

Nov 2014

Remodel #2 - add 230sf - permit, site plan exemption

Jan 2015

Remodel #3 – add another 230sf – permit, change use

Mar 2017


Awning installed - no permit known to be needed


Mar 2018

Code Violation – leading to BOA hearing – Oct 2018

## HARDSHIP ON THE PROPERTY

- and privacy to us and our neighbors to the back A series of trees at the back of the property provide shade
- parked cars and bikes berries; and were damaging the finish on employee's Copious numbers of birds inhabit the trees for Ligustrum
- Employees were imposing on neighborhood street parking to avoid the birds
- an awning pylon outside the setback Large pecan root zone to the side of the parking precludes





### GOALS

- Position a parking cover to avoid the large pecan root zone; trees) and address parking on property. reduce street impact; minimize its impact (nestled in the
- Choose green fabric that blends into the trees and provides a low visual impact.
- Keep the greenery buffer, providing privacy, especially to the neighbor to the back

mention that we would need a permit. permit or that the supports were subject to a setback. Shade Pro did not We didn't realize an awning was considered a "structure" and required a

# SOLUTION: ADD AN AWNING TUCKED INTO TREES




## FIREPROOF FABRIC

Green

Porous

Low Profile



H01/26 N 28'34'30"E 86. (N 30'00'E 86.0') 86.13 -101 AWNING PL Awning is along this line 18 PECAN ESMT. N 63'23'00'W 162' S 63'32'00"E 164.57\* 175.0') 5.0") Ш EXISTING DECKING PECAN 46.9 LANDING & RAMP EXISTING 1 STORY, BRICK, WOOD CIDERBLOCK BLDG. PECAN op in 11.9 O19" PECAN 25' B.L. EXISTING CONC. DRIVE 1/2" 16" PECAN S 29'57'45'V (S 30'00'W 86.04 85.0') EXISTING CURB CUT EXISTING CUT THM TRIANGLE

## VIOLATION REPORT



P.O. Box 1088, Austin, TX, 78767

DEPARTMENT

AUSTINCODE

NOTICE OF VIOLATION

Case Number: CV-2018-049361

Via Certified Mail # 7014 1820 0000 2198 0072

3906 MANCHACA RD AUSTIN TX 78704 Legally described as ABS 676 SUR 19 RIDDLE C H ACR 0.3200 Locally known as 3906 MANCHACA RD AUSTIN TX 78704 Parcel Number 0404110112 Zoned as LO

RTAB Holdings LLC 3906 Manchaca Road

March 7, 2018

Austin, Texas, 78704

Dear RTAB Holdings LLC:

The City of Austin Gode Department investigated the property described above. Austin City Gode violations were found that require your immediate attention. A description of the violation(s) and compliance timeframe(s) are provided in the attached violation report.

or transfer of this property unless: After receipt of this Notice, and until compliance is attained, the Austin City Code prohibits the sale, lease

- You provide the buyer, lessee, or other transferee a copy of this Notice of Violation; and
- You provide the name and address of the buyer, lessee, or other transferee to the Code Official

Please reference case number CV-2018-048361, Hours of operation are Monday - Friday, 7:30 a.m. -For additional information, I can be reached at (512)974-8115 or David Downing@austintexas.gov

Para obbenet más información, llame al (5/12)874-9315 o enviar un correo electrónico a David Doaming@austintexas-gov. Por favor, consulte caso número CV-2018-049361. El horario de atención est luntes a vientes, 7:30 a.m. - 4:00 p.m.

David Downing, Austin Code Officer City of Austin Code Department

VIOLATION REPORT

Date of Notice:

March 7, 2018

Property Address Case Number: Code Officer: **David Downing** CV-2018-049361

3906 MANCHACA RD AUSTIN TX 78704

Locally known as 3906 MANCHACA RD AUSTIN TX 78704

Zoned as LO

may be taken. Timeframes start from the Date of Notice. violations are not brought into compliance within the timeframes listed in this report The items seed below are violations of the Austin City Code; and require your imms enforcement action diate attention. If the

Violation Type: LAND USE IN KILLING

camoples"

plan from the approved plans for the development of the site Description of Violation: Parking canopies have been installed. These are not shown on the approved site

Date Observed: 03/06/2018

Timeframe to Comply: 30 Day(s)

accessible

and inspection of the parking canopy structures. Recommended Resolution: Submit the necessary appli cation to Device O'S Cost for the approval

ustin City Code Section: Site Plans Required (§25-5-

Description of Violation. The conditions at the site do not match the approved site plan. No accessible

Date Observed: 03/06/2018

space (#6) is labeled and the accessible route has violations.

Timeframe to Comply: 30 Day(s)

apply for a site plan revision to Development Services to approve the conditions as they exist on the site Recommended Resolution: Complete the work at the site to match the approved site plan. Alternatively

Services Department at 512-978-4000. You can also visit attain compliance. For questions concerning land use violations, please contact the Development Notes: Permit violations require the permit(s) to be issued and all required inspections to be completed to

http://www.austintexas.gov/departmen development-services for more information

H01/28 N 28'34'30"E 86. (N 30'00'E 86.0') 86.13 101 CONSIDERED 12.5 18.0 18 PECAN ESMT. N 63'23'00'W 1"164 S 63'32'00'E 164.57° 175.0') PECAN 5.0") W EXISTING DECKING PECAN 46.9 LANDING & RAMP EXISTING 1 STORY, BRICK, WOOD CIDERBLOCK BLDG. PECAN op in 11.9 O19" PECAN 25' B.L. EXISTING CONC. DRIVE 1/2" 16" PECAN S 29'57'45'W 86.04 85.0') 7, 8 1 Ш EXISTING CURB CUT EXISTING CUT THM TRIANGLE

# SOLUTION: SUPPORT OF OUR NEIGHBORS

To City of Austin Officials:

I understand that 3906 Manchaca Rd. is requesting a variance to keep their parking awning at the back of the property, partially in the buffer and configuration. zone. I have no objection to the awning remaining in its current location

My address is 2904 MANICHACA R

To City of Austin Officials:

I understand that 3906 Manchaca Rd. is requesting a variance to keep their parking awning at the back of the property, partially in the buffer and configuration. zone. I have no objection to the awning remaining in its current location

My address is 390 W

To City of Austin Officials:

their parking awning at the back of the property, partially in the buffer zone. I have no objection to the awning remaining in its current location and configuration. l understand that 3906 Manchaca Rd. is requesting a variance to keep

2018 My address is 304 MANNINGA FO

Signed

Signed:

JP SHEPARD

Signed:

Date: 5/22/18

8 Wait

Michael F. LEtte

MIGHEL WHITE - BROKETY OWNER

To City of Austin Officials:

zone. I have no objection to the awning remaining in its current location I understand that 3906 Manchaca Rd. is requesting a variance to keep their parking awning at the back of the property, partially in the buffer and configuration.

My address is Look Porner

Date: MA+ 17- ZN8

OUNTRE A.J. SANDBESON Signed:

My address is 2000

Pather Lane

78704

zone. I have no objection to the awning remaining in its current location their parking awning at the back of the property, partially in the buffer I understand that 3906 Manchaca Rd. is requesting a variance to keep

and configuration.

To City of Austin Officials:

FLORES - A UNIT

Date:

Catherine Sanderson (owner)

## NEIGHBOR SUPPORT

### To City of Austin Officials:

awning at the back of the property, partially in the buffer zone. I have no objection to the awning remaining in its current location and configuration. I understand that 3906 Manchaca Rd. is requesting a variance to keep their parking

- Andrew Sanderson (resident and owner) 2006 Prather Lane (property to the back)
- Catherine Sanderson (resident and owner) 2006 Prather Lane (property to the back)
- Juan Flores (resident) 3904 Manchaca Rd #A (property to the north)
- IJP Shepard (resident) 3904 Manchaca Rd #B (property to the north)
- Michael White (owner) 3904 Manchaca Rd (property to the north)
- Property to the south is a commercial property


## OBTAINED ENGINEERING DRAWINGS

Paid ShadePro \$1077 for engineering drawings

electronic fand transfer from your a bay 5 U.S.C. SSJa(e)(3) as governed to document and return with payment Myle Cocomise ShadePro Represent 13-Aug-18 Date  Rev. 9:10,2015	* Includes Delivery & Installation  Method of Payment  Credit Card Number  Name on Card: XICHARD	ShadePro 1007 rM 306 s 202 New Branchels 1X 78130 830-625-2154 Phone 210-625-2154 Phone 210-625-2154 Phone 210-625-2154 Phone Contact Contact Contact Coty/State/Crp: Phone: E-mail: Coy Size Hgt St
In the second of the second of the second that the second of the second	Number Number	AB Holdings I alchard Tiese & Marchines &
electronic fund transfer from your recount or to proceed the payment as a check transaction. Privacy Act Statement to by 5 U.S.C. SSalei(3) as governed by the rules of the NACHA. If you wish to opt out of check conversion society on this document and return with payment.  Kyle Cocamise  ShadePro Representative  13-Aug-18  Date  ShodePro  Permanent Shade Structures  Date  Permanent Shade Structures	Amount Collected (	Style Netting PIC Color
electronic fund translation or to process the payment at a check translation. Privacy Act Statument engitied by S U.S.C. 9State((3) as governed by the rules of the NACHA. If you wish to ope out of check conversion socily on this document and return with payment.  Kyle Cocomise  ShadePro Representative  13-Aug-18  Date  ShadePro  Permanent ShadePro  Date  Permanent Shade Structures  p 1 of 2	Sub Total Sales Tax Sales Tax Total Amount Due Now Upon Completion S 1,077 09  Security Code	B August 13 August B August B August B August B August II.C RTAB Holdings II.C Richard Token 3906 Manchard Token 3906 Manchard Token 512-478-5100 512-478-5100 512-478-5100 Fig. 428-5301 Tesken Sprendomanica som Unit Price Total 5 985.00



## **INSTALLED AWNING - ENGINEERING**



Project: RTAB Holdings, LLC 3906 Manchaca Rd Austin TX 78704

100% High-density polyethylene woven architectural fabric membrane canopy Commercial 95 by Gale Pacific. Tested to ASTM E-8400 meeting Class A requirements and NFPA 701-99 method 2. Sewn with GoreTenara thread.

All field connections shall be bolted in accordance with ASTM Structural

Mosh per Dotail

Specification for Bolted Connections. No welding shall be done in the field.

seamless, complying with ASTM A-500, Grade B. Columns  $\delta^* \times \delta^* \times 14^*$  Tubing; Beams  $4^* \times \delta^* \times 14^*$  Tubing;

Design Criteria: 2015 International Building Code Roof Live Load Spst Roof Dead Load 1pst

Permanent Shade Structures

ShadePro

snow Load Spsf

All phases of the work shall conform to standard methods of siteal fabrication as and construction as set forth by the 2015 international Building Code and the ASSC Manual of Steel Construction. Concrete / Foundation work shall be in accordance with the ACI 318-14.

All Measurements are Center to Center of Column

Upper Support 2-7/8" Sch 40 Pipe
Column & Besim Flange to Flange Plate Connections 10" x 24" x 1/2" Plate w/
Gussests (6) 34" Bolis, Nuts. Lock Washers & (12) Flat Washers
Columns Embedded 18" x 6" with min. 2500psi Concrete Reinforced with Wire

Wind Velocity Pressure 9psf Seismic Category A Wind Speed 120mph (3 sec. gust) Exposure 8 Occupancy Code II Importance Factor 1.00

15879 IH 35 N Selma TX 78154 Ph 210-651-1041 Fax 210-651-1042

O. Proisie

J. DAVID MACK 46749

ation@ShadePro.com



### FIRE PROOF

"Class A"

TEST REPORT

CLIENT:

Gale Pacific USA, Inc. 285 W. Central Pkwy, Suite 1704 Altamonte Springs, FL 32714

Attn: Susan Yuskaitis

Test Report No: 654:030608 February 22, 2010

SUBJECT: Testing to ASTM E-84

SAMPLE ID:

Sample identified as "Commercial 95" was received from the client on 2/19/10 in good condition. The sample was described by the manufacturer of containing the following

- Sample Description: Commercial 95
  Sample / Style Number: Commercial 95
  Material Content: Knitted HDPE
  Client PO: SY021609

TEST REQUESTED: Perform standard flame spread and smoke density developed classification tests on he sample supplied by the Client in accordance with ASTM Designation E84-09a; "Standard Method of Test for Surface Burning Characteristics of Building Materials". The test procedure is equivalent to UL 723, ANSI/NFPA No. 255, and UBC No. 8-1.

PREPARATION:

The sample material was submitted in one roll and trimmed to fit dimensions of turnel, measuring 21° by 24°. The sample was supported using rods and wire.

TEST DATE:

CLASSIFICATION:

RESULTS:

Results can be found on the following pages and apply only to the sample tested.

The sample received a 'Class A' rating in accordance with the NFPA and IBC classification chart on page two of this report.

SIGNED FOR AND ON BEHALF OF SGS U.S. TESTING COMPANY INC.

Greg Ertel Engineering Technician

Page 1 of 5

J. Brien McDonald Fire Technology Department Manager

This document is stand by the Conney stated to its Clearly Content of Service (private control. Institute on request or accession and the control of the Conney of Service (private control of Service (private Conneyor and Service) and Servic

## WARRANTY, WINDS AND PERMITS

ShadePro 1067 FM 306 #202 New Braunfels TX 78130 830-625-2154 Phone



Warranty

Manufacturer's Warranty.

Powder coating is warranted for one year. against surface rust, however the frame is guaranteed not to fail due to corrosion or rust on the frame, fittings or cable covered for a period of twenty years against failure due to corrosion or faulty workmanship. ShadePro does not warranty warranty will become void if installed on frames other than those manufactured by ShadePro. Steel frames and cables are errors or damage in installation or modification by non ShadePro approved installers and the warranty will become void. The against contact with chemicals, caustic materials, open flames or any other heat source. ShadePro is not responsible for voided. Warranty covers Shade netting failure due to Ultraviolet deterioration, and faulty workmanship for a period of ten Warranty will be validated upon final payment of the invoice. Failure to pay final balance due will result in the warranty being years. Not covered are rips and tears caused by means other than faulty workmanship. Shade netting is not warranted

7. Adverse weather conditions and natural disasters.

warning is issued. The fixed posts will normally withstand hurricane force winds if installed by a ShadePro trained installer. void if a ShadePro product is installed within the boundaries of a flood plane or failure due to saturated terrain or floods. If such as earthquakes, blizzards, shifts of terrain, or tornados in general vicinity. The installation warranty will be considered Shade Structures are warranted not to fail in winds up to 90 miles per hour. The warranty does not cover natural disasters the structure is installed in an area exposed to hurricanes, remove shade netting and roof structure when a hurricane

8. Permits.

Quoted price does not include the cost of permits. It is the customer's responsibility to obtain and pay for all permits Required drawings will be an additional expense

### **OPTIONS**

- Obtain a variance for the awning setback (our preference!)
- property line that the birds occupy Demolish the awning and remove the trees along the

### Thank you for your consideration

From: <u>Heldenfels, Leane</u>
To: <u>Ramirez, Diana</u>

Subject: c15-2018-0043/3906 Manchaca Road amanda, advance packet - put after submittal pics, maps being sent in a

seperate email

Date: Thursday, September 27, 2018 9:50:11 AM

Sent: Monday, September 24, 2018 3:44 PM

To: Heldenfels, Leane

Cc·

Subject: Re: 3906 Manchaca Road Board of Adjustment

Hi Leane,

Facing the property, the southside (left) line is a combination of chain link and wood pickets. That adjacent side is a commercial property.

The chain link on that side is 4ft and extends from the street back for about 1/3 of the line. It is original to the property from the 50's-60's.

Near the where that properties backyard would begin, newer wood fence with vertical pickets continue to the back of their property. Those pickets appear to have been made from trimmed 1x6x6 treated lumber. The net height is 5.5ft and was installed by the property owner next door for their dog training business. Its not our fence. That property owner removed the older chain link, which was falling down in places, to install that wood fence.

The small awning on that side has Class A fire retardant fabric that is several feet above; and not overhanging the wood fence.

### Other fences:

- the westside (back of the property) line is all original legacy chain link. Its 3.5ft. tall, and covered in green plant material, vines etc, naturally screening the backyard of the SF residence behind from view. Its quite opaque.
- the northside (right) line is wood 1x6's, mounted horizontally connecting original posts. Its my repair of old wood pickets that were falling down, and dates to when the property was bought. That property is a Duplex.