# HISTORIC LANDMARK COMMISSION

# PERMITS IN NATIONAL REGISTER HISTORIC DISTRICTS SEPTEMBER 27, 2021 HR-2021-136955

# OLD WEST AUSTIN NATIONAL REGISTER HISTORIC DISTRICT 1908 W. 33rd Street

#### **PROPOSAL**

Demolish a ca. 1949 duplex and garage and replace with new construction.

#### **PROJECT SPECIFICATIONS**

- 1) Demolish existing contributing house.
- 2) Construct new residence. The proposed building is two stories with a covered partial-width porch at the main elevation. It is clad in masonry and horizontal fiber cement siding with a metal roof and compound gabled and shed roofline. Fenestration includes divided multilight windows with varying configurations and fully glazed double entry doors with sidelights. A front-facing two-car garage is included at the easternmost bay of the main façade.

### **ARCHITECTURE**

One-story masonry and board-and-batten duplex with multi-light metal casement windows, a hipped roof, and partial-width covered porches at each entry.

#### RESEARCH

The duplex at 1908 W. 33<sup>rd</sup> Street was built by Billy McElroy in 1949. Early occupants included Eugene and Doris Dickens, co-owners of Dickens Brothers Cleaners; Air Force serviceman Albert Fell and his wife, Phyllis; and University of Texas students and faculty.

#### **DESIGN STANDARDS**

The City of Austin's <u>Historic Design Standards</u> (March 2021) are based on the Secretary of the Interior's Standards for Rehabilitation and are used to evaluate projects in National Register districts. The following standards apply to the proposed project:

#### Residential new construction

#### 1. Location

The proposed new building shares approximately the same location on the lot as the existing building.

#### 2. Orientation

The proposed new building is oriented toward the street.

### 3. Scale, massing, and height and 4. Proportions

Most of the surrounding contributing buildings on the block are one-story Transitional Ranch homes, whose low horizontal forms and modest size are at odds with the proposed building's scale, massing, height, and overall proportions. The proposed new building is strongly vertical, with compound massing and a complex roofline.

#### 5. Design and style

The proposed new building is differentiated from contributing properties by its use of modern cladding materials, modern fenestration patterns and materials, its two-story height, and its gabled standing-seam metal roof. It is somewhat compatible with surrounding buildings.

## 6. Roofs

The proposed building's compound metal roof is not compatible with the surrounding buildings' shingle-clad hipped roofs with deep eaves or simple side-gabled roofs.

# 7. Exterior walls

The proposed building's exterior wall materials are mostly compatible, except for the irregular placement of horizontal fiber-cement siding accents.

#### 8. Windows and doors

Proposed windows are compatible in style and material; however, the vertically oriented windows at main and secondary façades are not compatible with surrounding buildings, whose proportions are largely horizontal. The proposed fully glazed double front door with sidelights is not compatible.

#### 9. Porches

The proposed front porch appears compatible.

#### 10. Chimneys

The proposed chimney is clad in brick and is compatible with the building's modern style.

### 11. Attached garages and carports

The proposed garage faces the street, which is not compatible with contributing properties in the district; however, it is set back from the front wall of the building to lessen visual impact at the streetscape.

### Summary

The project meets some of the applicable standards.

# PROPERTY EVALUATION

The property contributes to the Old West Austin National Register district.

Designation Criteria—Historic Landmark

- 1) The building is more than 50 years old.
- 2) The building appears to retain high integrity.
- 3) Properties must meet two criteria for landmark designation (LDC §25-2-352). Staff has evaluated the property and determined that it does not meet two criteria:
  - a. Architecture. The building displays Transitional Ranch-style influences.
  - b. Historical association. The property does not appear to have significant historical associations.
  - c. Archaeology. The property was not evaluated for its potential to yield significant data concerning the human history or prehistory of the region.
  - d. Community value. The property does not possess a unique location, physical characteristic, or significant feature that contributes to the character, image, or cultural identity of the city, the neighborhood, or a particular demographic group.
  - e. Landscape feature. The property is not a significant natural or designed landscape with artistic, aesthetic, cultural, or historical value to the city.

### STAFF RECOMMENDATION

Release the demolition permit upon completion of a City of Austin Documentation Package. Comment on and release new construction plans.



This product has been produced by CTM for the sole purpose of geographic reference. No warranty is made by the City of Austin regarding specific accuracy or completeness.

Photos





Source: Applicant, 2021

# Occupancy History

City Directory Research, August 2021

A. Russell W. Jordan, renterB. James B. Gebhard, renter 1959

1957 A. No Return B. Benton Johnson, renter Assistant professor at University of Texas

1955 A. R. J. and Cath Bienvenu, renters

B. Robert L. and Ann S. Wood Jr., renters Student

1952 A. Albert W. and Phyllis Fell, renters USAF

B. Eugene F. and Doris B. Dickens, renters Dickens Bros Cleaners

1949 Address not listed

Biographical Information



CIGARS AND CONGRATULATIONS — Lieutenant Stanley J. Noble, left, of 1908 West 33rd Street, accepts a cigar from newly-promoted Captain Guy E. Huddleston of 1621 West 14th Street. Huddleston, a World War II veteran who has been a member of the 90th Intantry Division, Army Reserve, for the past three years, recently received his promotion to captain. Passing out cigars at promotion time is a custom of considerably long standing in the military.

# Austin Man Drowns In Travis

Eugene Frank Dickens, 47, of 3215 Funsion, drowned Monday about 10 p.m. while fishing on Lake Travis. Justice of the Peace Buck Smith ruled the death accidental.

Dickens' body was found Tuesday by divers. He was owner of Dickens Cleaners. Funeral is pending at Weed-Corley Funeral Home.

Survivors include his widow, Mrs. Doris Dickens of Austin: two sons, John Ross Dickens of Georgia and Mike Eugene Josephine Newburn of Dallas; Houston: a grandson.

### EUGENE FRANK DICKENS


Eugene Frank "Hootie" Dickens, 47, 3215 Funston, died suddenly Monday on Lake Travis. He was owner and operator of Dickens Cleaners, 2918 Guadalupe, for 20 years

Survivors are his wife, Mrs. Doris Dickens, Austin; two sons, John Ross Dickens, Air Force in Georgia; Mike Eugene Dickens, Austin; grandson, John Eugene Dickens Jr., Georgia; one sister Mrs. Josephine Newburn, Dallas; two brothers, Lewis "Babe" Dickens, Austin; Sam B. Dickens Jr., Houston; great-aunts, Mrs. Marguerite Kyser and Mrs. Mamie Hewitt, both of Austin.

Funeral services will be held Dickens of Austin; a sister, Mrs. at 2 p.m. Thursday at Weed-Corley Funeral Home. Pastor two brothers, Lewis Dickens of Merle G. Franke will officiate Austin and Sam Dickens Jr. of and burial will be in Austin Memorial Park.

The Austin Statesman (1921-1973); May 15, 1968

Permits



Water Service Permit, 1950

Billy McElroy

1908-A&B West 33rd St.

208

6

1

Brykerwoods "G"

Frame duplex and garage.

42661 12-6-49

\$8500.00

Owner