

Water Treatment Plant 4

Environmental Board
February 4, 2015
Robyn Smith – Public Works Dept.





Project Status

- Substantial Completion –December 11, 2014
- Currently finalizing equipment tests
- Site Finishes ongoing
 - Final Stabilization
 - Convert ponds to bio-filtration
 - Permanent fencing and gates
- > Punch lists ongoing





Commissioning and Start-Up

Water Quality Requirements for Storm Water Pond Discharge

Characteristic	Requirements	Units
рН	6.5 – 8.5	
Total Chlorine	<0.01	mg/L
Total Dissolved Solids	≤400	mg/L

Commissioning and Start-Up



Water Management

- Daily communication between Contractor and COA EV Manager
- Lake water utilized for various tests Raw water pumps
- Disinfection water treated, tested and logged prior to release
- Re-use of testing & disinfection water where feasible
- Regular communication and coordination with downstream neighbors



Final Stabilization

- ➤ Treatment Plant and Raw Water Pump Station
 - Native grasses
 - Native plants
 - Trees Escarpment plateau seed stock
- Four Points and Spicewood shaft sites
 - Native grasses
- ➤ Jollyville Reservoir shaft site
 - Bermuda grass (existing vegetation)

Spicewood Shaft Site







City of Austin, TX Water Treatment Plant #4

Image #150117 6112 Date 01.17.15



Questions?

info@wtpfour.com

http://austingo.austintexas.gov/department/water



