

## Tree Work- May 2015

<u>Problem</u>	<u>Species</u>	<u>dbh</u>	<u># of trees</u>	<u>Brush</u>	
				<u>Only</u>	<u>Date</u>
Private hanging limb	american elm	8"	1		5/1/2015
ROW limb down	cedar elm	10"	1		5/1/2015
Private hanging limb	cedar elm	22"	1		5/1/2015
ROW tree limb	live oak	24"	1		5/4/2015
ROW view obstruct.	crape myrtle	12"	1		5/4/2015
ROW view obstruct.	rose bushes	5"	2		5/4/2015
ROW repair cut			1		5/4/2015
sign obstruction	cedar elm	8"	4		5/4/2015
ROW split limb	chinaberry	15"	1		5/4/2015
ROW split limb	live oak	18"	1		5/5/2015
ROW repair cut	hackberry	20"	1		5/5/2015
ROW hanging limb	american elm	25"	1		5/5/2015
ROW limb obstruct.	red bud	8"	1		5/5/2015
ROW limb obsrtuct.	red tips	15"	1		5/5/2015
private limb down	arizona ash	28"	1		5/5/2015
ROW limb obstruct.	crape myrtle	12"	2		5/5/2015
ROW limb obstruct.	crape myrtle	8"	1		5/5/2015
ROW limb obstruct.	american elm	15"	1		5/5/2015
ROW limb obstruct.	live oak	16"	1		5/5/2015
ROW tree removal	osage oarange	5"	1		5/5/2015
ROW repair cut	pecan	30"	1		5/5/2015
ROW hanging limb	cedar elm	20"	1		5/5/2015
ROW tree down	hackberry	24"	1		5/6/2015
Private tree down	cedar elm	22"	1		5/6/2015
ROW limb down	monterey oak	8"	1		5/6/2015
Private tree down	arizona ash	26"	1		5/6/2015
Private split limb	arizona ash	22"	1		5/6/2015
ROW tree down	bradford pear	15"	1		5/6/2015
ROW limb down	hackberry	26"	1		5/6/2015
sign obstruction	red oak	12"	1		5/6/2015
Private hanging limb	arizona ash	10"	1		5/6/2015
ROW low limbs	live oak	20"	2		5/6/2015
ROW dead tree	post oak	18"	1		5/7/2015
Private split limb	arizona ash	24"	1		5/7/2015
ROW sidewalk obstr.	mesquite	16"	1		5/7/2015
Private hanging limb	hackberry	20"	1		5/7/2015
ROW dead tree	live oak	16"	1		5/7/2015
traffic signal obstruct	pecan	26"	1		5/7/2015
ROW low limbs	red oak	30"	1		5/8/2015
ROW low limbs	pecan	30"	1		5/8/2015
ROW low limbs	red oak	12"	17		5/8/2015
ROW low limbs	live oak	16"	1		5/8/2015

sign obstruction	red oak	12"	1		5/8/2015
brush pick-up				50' X 5'	5/11/2015
ROW limb down	american elm	15"	1		5/11/2015
limb blocking trl.	hackberry	14"	1		5/11/2015
Private split limb	arizona ash	22"	1		5/11/2015
ROW sidewalk obstr.	crape myrtle	12"	1		5/11/2015
ROW limb down	hackberry	12"	1		5/11/2015
tree down in ROW	ailianthus	16"	1		5/11/2015
brush pick-up				20' X 5'	5/11/2015
ROW tree limb	arizona ash	22"	1		5/11/2015
ROW tree down	hackberry	18"	1		5/11/2015
ROW view obstruct.	arizona ash	5"	1		5/12/2015
ROW view obstruct.	agave plant	10"	1		5/12/2015
ROW tree removal	juniper	16"	1		5/12/2015
ROW hanging limb	live oak	32"	1		5/12/2015
ROW repair cut	pecan	28"	1		5/12/2015
ROW low limbs	hackberry	12"	2		5/12/2015
ROW low limbs	american elm	8"	1		5/12/2015
ROW low limbs	pecan	10"	1		5/12/2015
ROW tree down	huisache	8"	1		5/12/2015
ROW limb down	cedar elm	21"	1		5/13/2015
ROW tree removal	chinaberry	15"	1		5/13/2015
ROW low limbs	hackberry	15"	4		5/13/2015
ROW low limbs	ligustrum	12"	1		5/13/2015
ROW tree removal	mexican plum	5"	1		5/13/2015
private limb down	arizona ash	20"	1		5/13/2015
brush pick-up				15' X 5'	5/13/2015
brush pick-up				15' X 5'	5/13/2015
private limb down	arizona ash		1		5/13/2015
brush pick-up				20' X 6'	5/13/2015
sidewalk obstruction	jasmine			20' X 5'	5/14/2015
sidewalk obstruction	pecan	12"	1		5/14/2015
sidewalk obstruction	pecan	10"	1		5/14/2014
ROW low limbs	live oak	14"	1		5/14/2015
ROW low limbs	red tips	12"	6		5/14/2015
sidewalk obstruction	live oak	12"	1		5/14/2015
sidewalk obstruction	cedar elm	10"	1		5/14/2015
brush pick-up				15' X 10	5/14/2015
ROW hanging limb	live oak	20"	1		5/14/2015
ROW low limbs	hackberry	15"	1		5/14/2015
ROW low limbs	cherry loral	8"	1		5/14/2015
ROW low limbs	arizona ash	5"	1		5/14/2015
ROW split limb	live oak	12"	1		5/15/2015
ROW hanging limb	pecan	26"	1		5/15/2015
Private tree down	cedar elm	22"	1		5/17/2015
private limb down	pecan	26"	1		5/17/2015
ROW tree down	cottonwood	15"	1		5/17/2015

[illegible]

[illegible]

Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/25/2015
Emergency Call			1	5/26/2015
Emergency Call			1	5/26/2015
Emergency Call	american elm		1	5/26/2015
Emergency Call	cedar elm		1	5/26/2015
Emergency Call	american elm		1	5/26/2015
brush pick-up			1	5/26/2015
Emergency Call			1	5/26/2015
Emergency Call			1	5/26/2015
Emergency Call			1	5/26/2015
Emergency Call			1	5/26/2015
Emergency Call			1	5/26/2015
Emergency Call			1	5/26/2015
Emergency Call			1	5/26/2015
Emergency Call			1	5/27/2015
sidewalk obstruction	live oak	10"	3	5/27/2015
sidewalk obstruction	pecan	15"	2	5/27/2015
sidewalk obstruction	Mt.Laurel	10"	1	5/27/2015
sidewalk obstruction	red bud	8"	1	5/27/2015
sidewalk obstruction	red tips	12"	10	5/27/2015
Emergency Call	cedar elm	16"	1	5/27/2015
Emergency Call	american elm	26"	1	5/27/2015
Emergency Call	american elm	24"	1	5/27/2015
repair cut			1	5/27/2015
Emergency Call	arizona ash	28"	1	5/27/2015

Emergency Call	arizona ash	30"	1	5/27/2015
Emergency Call	cedar elm	24"	1	5/27/2015
repair cut	live oak	30"	1	5/27/2015
repair cut	live oak	24"	1	5/27/2015
repair cut	live oak	28"	1	5/27/2015
ROW removal	hackberry	15"	1	5/28/2015
cracked ROW tree	chinese pistache	15"	1	5/28/2015
ROW broken hanger	live oak	22"	1	5/28/2015
ROW tree removal	cedar elm	16"	1	5/28/2015
Private split tree	chinese pistache	15"	1	5/29/2015
private limb down	cedar elm	22"	1	5/29/2015
brush removal	vitex		15' X 5'	5/29/2015