

3602 Grant Street
ca. 1957



OCCUPANCY HISTORY 3602 Grant Street

City Directory Research, Austin History Center
By City Historic Preservation Office
January, 2017

1992

1985-86 Merrick D. and Lola Jiles, renters
Retired

1981 Vacant

1977

1973 Lillie Haynes, renter
Maid

1968	Lillie E. Haynes, renter Maid
1965	Leslie and Lillie E. Moore, owners Construction worker
1963	Leslie and Lillie E. Moore, owners Construction worker
1962	Leslie and Lillie E. Moore, owners Construction worker
1961	The street is not listed in the directory.

Clarence Flourney

3602 Grant St.

337 16

Ebony Acres

Frame Res with no C. P. or Garage

66327

4/16/57

3000.00

owner

5

Water Tap #13262

Sept^{ic} Approved by Health Dept by phone

WATER SERVICE PERMIT

Austin, Texas

E No 13262 337

INDEXED

Received of CLORENCE FLOURNOY Date 7-15-57
 Address 3602 GRANT ST
 Amount JOHNSTON
 Plumber L.H. MEISKE Size of Tap 3/4"

Date of Connection 7-5-57
 Size of Tap Made 3/4"
 Size Service Made 3/4"
 Size Main Tapped 6" C.I.
 From Front Prop. Line to Curb Cock 7'5"
 From E. Prop. Line to Curb Cock 16'
 Location of Meter FRONT
 Type of Box Round
 Depth of Main in St. 1'
 Depth of Service Line 1'
 From Curb Cock to Tap on Main 1'
 Approved by Engr. Dept. 8-13-57 em

No. Fittings	Size
1 Corp. Cock	3/4"
1 Elbow	3/4"
1 St. Elbow	3/4"
1 Bushing	3/4"
1 Reducer	3/4" to 1/2"
1 Pipe	3/4" C.I.
1 Lead Comp.	3/4"
2 Nipples	3/4"
1 Union	3/4"
1 Plug	3/4"
1 Tee	3/4"
1 Stop	3/4"
1 Box	Round
1 Lid	3/4"
Valves	
Job No.	W 323-200-502
Req. No.	

INDEXED

A. Powell

SANITARY SEWER SERVICE PERMIT

Austin, Texas

No 40105 ✓

Received of L. E. Moore Date 6-6-63
 Address 3602 GRANT ST.
 Amount 10/100
 Builder or Owner James E. Moore Plumber McGill
 Lot 16 Block - Subdivision Elmwood Plat No. 337

Date of Connection 6-7-63
 By City 1' W. of ELL
 By Plumber Swisher
 Checked By Swisher
 Size Main 8" Depth 5'
 Main Assign. 20.53 1/2 R
 Stub Depth 3' Prop. Line 3'
 Stub Location ELL
 Book No. A 5413
 Paving Cut 10 X 2 No. 6-7-63 Anderson

No. Fittings	Size	Price
2 1" Pipe	6'	5.25
1 Pipe		
1 Wye		
1 Bend		
1 Reducer		
1 Plug		
1 Sand		
1 Gravel		
1 Remix		
1 Stopper		
1 Castings		
1 Other		
1 Band		
Labor		
Total		22.34

The windows were replaced in 2015.

A two-story accessory structure with a workshop was approved in 2016.