HISTORIC LANDMARK COMMISSION NOVEMBER 27, 2017 DEMOLITION AND RELOCATION PERMITS HDP-2017-0513 919 VALDEZ STREET

PROPOSAL

Demolish a church building moved onto the property in 1957.

ARCHITECTURE

One-story, rectangular-plan, front-gabled wood-frame building constructed in a vernacular style with a shed-roofed addition. The building is clad in shiplap wood siding and features 8-light wood-sash windows and a partially enclosed entry porch. A small gable-roofed bell tower sits atop the ridge line.

RESEARCH

919 Valdez Street was moved onto the property in 1957 for use as a church. The building's original location, construction date, and use are not known. It does not appear that it was used previously as a church, as the building permit for the relocation notes work to include "repair and convert for church." Beginning in 1959, the building was occupied by the Gethsemane Assembly of God, later called Templo Getsemani de las Asambleos de Dios.

In 1961, a one-story frame addition was constructed on the north side of the building to house a kitchen and dining room. A one-story masonry addition at the northeast corner was proposed in 1977-78. However, it is not clear if it was constructed, as the entire building appears to be of wood-frame construction.

The Gethsemane Assembly of God was chartered in 1957 and first located at 807 Montopolis Drive. Records from the General Council of the Assemblies of God show that the church was chartered as Gethsemane de las Asambleas de Dios, though Austin city directories list the name in English. The church changed its name twice: in 1971 to Gethsemani de las Asambleas de Dios and in 2006 to Gethsemani Assembly of God.

STAFF COMMENTS

The house is beyond the bounds of any City survey. It is not designated at the state or national levels.

919 Valdez Street does not appear to meet the criteria for designation as a historic landmark.

Designation Criteria—Historic Landmark

- 1) The building is more than 50 years old, having been constructed prior to 1957.
- 2) The building retains a low degree of integrity. Though the building's materials appear to be original, it sustained a large side addition and was moved from its original location.
- 3) Properties must meet two historic designation criteria for landmark designation (City of Austin Land Development Code (Section 25-2-352). The property does not appear to demonstrate significance according to any of the criteria.
 - a. **Architecture.** The building is built in a vernacular style. It does not appear to be architecturally significant.

- b. **Historical association**. The building was associated with an Assembly of God congregation from 1959 until 2016. However, there do not appear to be significant historical associations based on archival research and community inquiries.
- c. **Archaeology**. The property was not evaluated for its potential to yield significant data concerning the human history or prehistory of the region.
- d. **Community value**. The property does not possess a unique location, physical characteristic, or significant feature that contributes to the character, image, or cultural identity of the city, the Montopolis neighborhood, or a particular group.
- e. Landscape feature. The property is not a significant natural or designed landscape with artistic, aesthetic, cultural, or historical value to the city.

STAFF RECOMMENDATION

Encourage rehabilitation and adaptive re-use. If rehabilitation and adaptive re-use are not feasible, then encourage relocation over demolition and release the permit upon completion of a City of Austin Documentation Package consisting of photographs of all elevations, a dimensioned sketch plan, and a narrative history, for archiving at the Austin History Center.

LOCATION MAP



PROPERTY INFORMATION

Photos



Primary (west) façade of 919 Valdez Street



Detail of north elevation

D.3 - 5



Building, n.d. (Source: Austin's Montopolis Neighborhood, by Fred L. McGhee, p. 88)

Occupancy History

City directory research, Austin History Center By Historic Preservation Office staff October 2017

- 1955 Address not listed
- 1959 Address not listed
- 1962-73 Gethsemane Assembly of God Rev. Mary Powers is listed from ca. 1968 to ca. 1973.
- 1977-86 Templo Getsemani de las Asambleos [sic] de Dios

Occupant Notes

No information was found on Gethsemane Assembly of God or Templo Getsemani in newspaper archives, with the exception of a few funeral notices.

Staff initiated research on Rev. Mary Powers but was not able to distinguish between many individuals with that name in historical records.

Building Permits

· · · <u>.</u> ·	م میں کے		the the section of	
Assembly	of God Churc	ch	919 Valdez St.	
680	10		8	
Ch	ernosky #16			
	Building	onto lot _ :	repair& convert fo	r
	68118	12/20/57	church. 600.00	
OWD	e r		4	
	13581		28335	

OFF STREET PARKING AS PER ORDINANCE CHURCH

Permit to relocate, repair, and convert a building into a church, 12/20/1957.

	SEWER SERVICE PERMIT Austin, Texas Nº 28335 Å
Address 919 110	Gid Haire H Date 13. 30. 5 Place Charles Charles Plumber Princes (Subdivision cully) Plat No. 580
Date of Connection $3 - 27 - 58$ By City $3^{\circ} - 59$ NLL By Plumber	Price 3.75 3.75 30.00 1.50 1.98
Ghecked By $\begin{array}{c} \begin{array}{c} \begin{array}{c} \begin{array}{c} \begin{array}{c} \begin{array}{c} \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \end{array} \\ \begin{array}{c} \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \end{array} \\ \end{array} \\ \begin{array}{c} \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \end{array} \\ \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \end{array} \\ \end{array} \\ \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \end{array} \\ \end{array} $	s Size 6. 6. 6. 6. 1 6. 6. 6. 6. 6. 1 6. 6. 6. 6. 6. 6. 1 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
Stub Location to be $C NLL$ Book No. $A-4080$ Paving Cut No. $CH = 3 - 21 - 57$ $SF = -21 - 57$	No. Fittings No. Fittings // Pipe / Bends / Bends / Bends / Sand Gravel Remix Stoppers Stoppers Labor: / bends / Inter. h


Sewer permit, 12/20/1959.

Assembley of God Church 919 Valdez St. 680 10 8 Chernosky #16 Frame addition to church bldg. 79443 4-12-51 700.00 owners 1 sink

KITCHEN & DINING ROOM

Building permit for wood-frame addition, 4/12/1961.

	· _ ·							
ADDRESS: 91	PYALDE:	2 St.	LOT.	10	BLK, 🖌 SU	B. CL	lins	ky #16
PLAT: 680	FIRE ZONE	J USE D	IST. A	н	A DIST.	000	UPANCY	KITIG. DIN. RM.
4-24 61 LAYOUT 5-18-64 FRAMING 5-18-6 FINAL 7 944 3								
FLOWIN ACC PRINC ACC PRINC ACC. PRINC ACC SPECIAL NOTES								
BLD G FOUNDATION	CON BIKS	FLOOR-JOIST SIZE & O.C.	- 76		NECESSARY BLDG. CONN.			30×12+10×12
FR: SETBACK	30	CEILING-JOIST SIZE & O. C.	249		ROOM VENTILATION			church.
AGGREGATE & MIN. SIDE YD.	30	STUD SIZE & O. C.	2 X 4 16		WATER & SEWER RELEASE			W.D. SIDING.
SIDE STREET YARD		MASONRY WALL			PLMB. DEPT. RELEASE			
		STAIRS REQ. AND NO.			HEATING & A/C RELEASE			
		ATTIC FIRE STOPS REQ.			ELECTRIC DEPT. RELEASE			
<u></u>		FIRE WALLS REQ. & NO.			ENG. DEPT. RELEASE			
		ROOF OVERHANG	1		FIRE MARSHAL RELEASE			
					ROOF OVERHANG	F.C.	Pawe	12.61 26. D Church.
					PAVED PARK REQ. & NO.	ane	mbly	\$ 6. D Church.
		5-0	× //	9.20	ð			
								,
		<u>`</u> ['			{			



Inspection form for wood-frame addition, 5/18/1961.

D.3 - 8

OWNER Assembley Of God Chapperess	<u>919 Valdez St.</u>
PLAT 680 LOT 10	
SUBDIVISION Chernosky #16	.
OCCUPANCYChurch Classrm	
BLD PERMIT #161603 DATE 1-14-77	OWNERS ESTIMATE 2,500.00
CONTRACTOR Same	NO. OF FIXTURES BONG
WATER TAP REC # SEWER T	AP_REC #

<u>l stry mas addn to existing church</u> Building permit for masonry addition, 3/7/1978. It is not clear if the addition was constructed.

D.3 - 9

,							D.3 - 9
_Address: 919	UALI	DEZ ST		Permit:		03 P1	at: 680
Lot:		+ 	Block g	Subdivi	soon:		
/0	· ·		Outlot	CherNa	osky	# 16	
Fire Zone: 3	Use l	Dist. $A \notin I^{\mathcal{F}}$	Occupancy 0 <i>NE</i> STo		ADON 1	DEXISTING C	hurch
1-19-77	Layout		Framing	3-2-28	Fina <u>l</u>	·	Commercial
Foundation		Floor joist	$\sqrt{1}$	Bldg. Conn.		Parking	
Front setback		size & o.c.		Room Vent.		Exits	
Total & Min.		ceiling jois		Stairs	1	Exit lights	
side yard		size & o.c.	r A	Rails		Fences	
Side St. Yard		stud size		Attic Vent.		Corriders	
				Insulation	+		
Type Const.		W.Insulation		Hood Vent.			
Spec.Permit #		Sheetrock	54	Glass	· · · · · · · · · · ·		
BOA		Commercial \$	beetrock	Deadbolts Fireplaces	<u>∤</u>		
DON		Occup.Sep.		FITEPIACES	<u> </u>		
	•	Thru out	1			· · · · · · · · · · · · · · · · · · ·	
		<u></u>		<u> </u>	<u> </u>		
Owner: Assemb	Ly oF	Gos Chur	ch	Contractor:	OWNE	n	
	10	T. S V Existing xo T ? V			Clerk	Fi /w Dat	e /- /4_ 77
L	VAS	quez					
				Ins	spector:	alt.K	

Inspection form for masonry addition, 3/7/1978. It is not clear if the addition was constructed.