# HISTORIC LANDMARK COMMISSION JANUARY 29, 2018 DEMOLITION AND RELOCATION PERMITS HDP-2017-0762 801 W. LIVE OAK STREET

### **PROPOSAL**

Demolish a ca. 1936 house.

#### ARCHITECTURE

One-story, rectangular-plan, front-gabled wood-frame house with Craftsman influences. The house is clad in wood lap siding and features a paneled, partially-glazed door and double-hung wood-sash windows. Ornamentation includes exposed rafter tails, bargeboards at the gable ends, and iron columns supporting a large entry hood.

### RESEARCH

801 W. Live Oak Street was built in 1936 by James J. Farrell, an electrical contractor, and his wife Bertie. The Farrells moved out around 1944, when a succession of occupants began. In 1957, Abundio and Felicita Ruiz moved into the house, where they remained until at least 1992. Abundio worked variously as a cotton picker and construction worker before working as a truck driver at Capitol Aggagito from ca. 1965 until he retired ca. 1992.

## STAFF COMMENTS


801 W. Live Oak Street does not appear in any City survey. The house does not meet the criteria for designation as a historic landmark.


Designation Criteria—Historic Landmark

- 1) The house is more than 50 years old, having been constructed ca. 1936.
- 2) The house retains a high degree of integrity.
- 3) Properties must meet two historic designation criteria for landmark designation. The property does not appear to demonstrate significance according to any of the criteria (City of Austin Land Development Code, Section 25-2-352).
  - a. **Architecture.** The house does not appear to possess architectural distinction.
  - b. **Historical association**. The building was occupied for at least 35 years by Abundio and Felicita Ruiz. There do not appear to be historically significant associations.
  - c. **Archaeology**. The property was not evaluated for its potential to yield significant data concerning the human history or prehistory of the region.
  - d. **Community value**. The property does not appear to possess a unique location, physical characteristic, or significant feature that contributes to the character, image, or cultural identity of the community, Austin, or Texas.
  - e. **Landscape feature**. The property is not a significant natural or designed landscape with artistic, aesthetic, cultural, or historical value to the city.

#### STAFF RECOMMENDATION

Encourage rehabilitation and adaptive re-use of the existing building. If the Commission votes to release the permit, then staff recommends relocation over demolition, and completion of a City of Austin Documentation Package, consisting of photographs of all elevations, a dimensioned sketch plan, and a narrative history, for archiving at the Austin History Center.





# **NOTIFICATIONS**

CASE#: HDP-2017-0762 LOCATION: 801 W Live Oak Street

This product is for informational purposes and may not have been prepared for or be suitable for legal, engineering, or surveying purposes. It does not represent an on-the-ground survey and represents only the approximate relative location of property boundaries.

1"=139'

This product has been produced by CTM for the sole purpose of geographic reference. No warranty is made by the City of Austin regarding specific accuracy or completeness.



# PROPERTY INFORMATION

# Photos



Primary (north) façade of 801 W. Live Oak Street.



West elevation and primary façade.

# Occupancy History

City directory research, Austin History Center By Historic Preservation Office staff January 2018

1939-42	James J. and Bertie Farrell, owners Electrical contractor
1944-45	A. H. Laws, owner Civil engineer
1947	Charles E. Banks, owner Southern Pacific Lines brakeman
1949	Vacant
1952-53	John L. and Janie Guerrero, owners

1955 Manuel and Dorcas Salas, renters

Pipe fitter, City Water Department

Baker, Austin Baking

1957-92 Abundio and Felicita Ruiz, owners Employment included cotton picker (1957-58), construction worker at McKown & Son (1959-1961), driver at Capitol Aggagito (1965-1990), and retired (1992).

# Biographical Notes

Abundio Ruiz was born in 1915 in Caldwell County, Texas. He worked as a cotton picker, construction worker, and truck driver. He died in 1996 in Austin.

Felicita Navarro Ruiz was born in 1920, likely in Texas. She married Abundio Ruiz in 1937 in Travis County and they had 14 children. Felicita died in Austin in 2007.

Unless the Plumbing is done in strict accordance with City Ordi	7	1				
PERMIT FOR WATER SERV	VICE AUSTIN	, TEXAS .	Nº 44	18/192		
M. J. J. Fairell	Address 80	1 ZU	Live	and g		
	ize of Tap		Date 8-	27-36		
		·				
Foreman Foreman	s Report	· <b>&gt;</b> 				
Date of Connection.	18€		<i>j</i>	6		
Size of Tap Made	199	3	3"	1.		
Size Main Tapped	18	2	1/1/1			
From Front Prop. Line to Curb Cock.	10 1 3 1			,		
From E. Prop. Line to Curb Cock 2/1	10 1 2	Ó	1,11			
Location of Meter	11/1/1/3	•				
A Company of the Comp	3 6 1	$U_{i,j}$	12 1	.0.		
Depth of Main in St.	Lilbow St. Elbow Bushing. Reducer Pipe	Nipples Union Plua	, de	Valves Req. No		
Depth of Main in St. 2.	St. St. Prit	Nipp Unio	Teé Sto Box Lid	Re		
From Curb Cock to Tap on Main 126"	1111					
Checked by Engr Debt 19-2-36	nan's Signature	124	CNC CIA	/		
INDEXED	•	00	11700			
Vater tap permit issued to J. J. Farrell, 8/25/1936	3.					
e e e e e e e e e e e e e e e e e e e				•		
		•	•			
J. L. Guerrero 801 West Live Oak						
115B** 9.**** .****	·	8	•	-		
Davis & Dawson						
Repairs to f	ront porch	•				
45811 8-3-50		;	\$150.00			

Building permit issued to J. L. Guerrero for front porch repairs, 8/3/1950.

Owner