



East elevation at front of house, view from street level on Baylor Street (camera facing northeast)





East elevation at front of house facing Baylor Street (camera facing north)

610 Baylor Street

Application for Certificate of Appropriateness





East elevation, front of house, view of basement entrance and south side of entry stairs (camera facing northeast)





Northeast corner of house at main entry, view from property line along W. 7<sup>th</sup> Street (camera facing west)





North elevation, view from street level on W. 7t Street (camera facing south)





West elevation, rear of property with view from parking area (camera facing southwest)





Northwest corner of house at screened in porch off Kitchen (camera facing south)





South elevation of house showing non-historic exterior stairs (camera facing northeast)





South elevation of house showing non-historic stairs and porch (camera facing northeast)





South elevation showing enclosed front porch, and basement (camera facing northeast)





South elevation of first floor and basement (camera facing northwest)





Southeast corner of house: Existing condition LEFT, undated historic photo, RIGHT





Front of House (East Elevation) undated Historic photo taken from street level on Baylor Street