

Duckworth Residence

2414 Harris Blvd.  
Austin, TX 78703



DATE	ISSUED FOR
12.03.18	INTERIORS REVIEW
01.08.19	INTERIORS REVIEW
01.18.19	OWNER REVIEW
01.21.19	OWNER REVIEW
02.11.19	FOR FRAMING
02.20.19	OWNER REVIEW
04.23.19	OWNER REVIEW
05.06.19	MASONRY SCOPE

COPYRIGHT © 2019  
Norma Yancey, AIA  
PROJECT 0000

EXTERIOR ELEVATIONS

A2.0

HALF-SIZE SET




EXTERIOR ELEVATION NOTES:

- EXISTING BRICK TO REMAIN; REPAIR/REPOINT AS NEEDED PRIOR TO REPAINT.
- EXISTING TILE ROOF TO REMAIN AS NOTED ON THE ROOF PLAN. CONTRACTOR TO TAKE NECESSARY PRECAUTIONS TO PROTECT EXISTING TILE DURING CONSTRUCTION. CONTRACTOR TO REPAIR/REMEDiate EXISTING ROOF TILE TO REMAIN AS NEEDED.


MASONRY NOTES:



- HATCH DENOTES AREA OF HISTORI MASONRY TO BE REMOVED AND RE-INSTALLED
- 5/8" AVG. MORTAR JOINTS
- BRICK COURSING COUNTS CONTINUE AROUND ALL FACADES



2 NORTH ELEVATION  
1/4" = 1'-0"



1 WEST ELEVATION  
1/4" = 1'-0"

MASONRY NOTES:



1. HATCH DENOTES AREA OF HISTORI MASONRY TO BE REMOVED AND RE-INSTALLED
2. 5/8" AVG. MORTAR JOINTS
3. BRICK COURSING COUNTS CONTINUE AROUND ALL FACADES

Sidetracked Studio

1605 E. 7th St. Unit B  
Austin, Texas  
512 774 4261

PRELIMINARY  
NOT FOR CONSTRUCTION

This drawing was prepared  
under the supervision of Norma  
Yancey. It is not to be used for  
regulatory approval, permitting,  
or construction purposes.

FIELD INSPECTION REQUIRED

Prior to performing any bidding,  
new construction, and/or  
repairs, general contractor shall  
visit the site, inspect all existing  
conditions, and report any  
discrepancies to the architect.

Duckworth Residence

2414 Harris Blvd.  
Austin, TX 78703

DATE	ISSUED FOR
12.03.18	INTERIORS REVIEW
01.08.19	INTERIORS REVIEW
01.18.19	OWNER REVIEW
01.21.19	OWNER REVIEW
02.11.19	FOR FRAMING
02.20.19	OWNER REVIEW
04.23.19	OWNER REVIEW
05.06.19	MASONRY SCOPE

COPYRIGHT © 2019  
Norma Yancey, AIA  
PROJECT 0000

EXTERIOR ELEVATIONS

A2.1


HALF-SIZE SET

PRELIMINARY  
NOT FOR CONSTRUCTION

This drawing was prepared under the supervision of Norma Yancey. It is not to be used for regulatory approval, permitting, or construction purposes.

FIELD INSPECTION REQUIRED

Prior to performing any bidding, new construction, and/or repairs, general contractor shall visit the site, inspect all existing conditions, and report any discreoancies to the architect.



1 MASONRY VENEER WALL DETAIL  
3" = 1'-0"

Duckworth Residence

2414 Harris Blvd.  
Austin, TX 78703

DATE	ISSUED FOR
12.03.18	INTERIORS REVIEW
01.08.19	INTERIORS REVIEW
01.18.19	OWNER REVIEW
01.21.19	OWNER REVIEW
02.11.19	FOR FRAMING
02.20.19	OWNER REVIEW
04.23.19	OWNER REVIEW
05.06.19	MASONRY SCOPE

COPYRIGHT © 2019  
Norma Yancey, AIA  
PROJECT 0000

DETAILS


A5.1

HALF-SIZE SET





PREVIOUS OWNERS INFILLED  
SIDE PORCH TO CREATE NEW  
ENTRY; REMOVED AND STORED  
MANSBENDEL FRONT DOOR IN  
THE GARAGE.



PHOTOGRAPH OF RESIDENCE WHEN CURRENT HOMEOWNERS  
PURCHASED THE HISTORIC HOME AND CHOSE TO PURSUE HISTORIC  
LANDMARK STATUS. THE SIDE PORCH WAS RETURNED TO ITS  
ORIGINAL CONDITION AS AN OPEN AIR PORCH. THE MANSBENDEL  
FRONT DOOR WAS REMOVED FROM STORAGE, RESTORED, AND  
RE-INSTALLED IN ITS ORIGINAL LOCATION.



**PROJECT**  
2414 Harris Blvd.  
Historic Knippa-Huffman House

**DATE**  
May 6th, 2019





DOCUMENTATION OF EXISTING CONDITION OF ORIGINAL BUILDING FELT WITHIN WALL CAVITY.



IMAGES OF AUSTIN COMMON MASONRY LEFT EXPOSED AT INTERIOR OF GARAGE AS WELL AS IMAGES OF PAINTED AUSTON COMMON MASONRY AT EXTERIOR OF RESIDENCE.



**PROJECT**  
2414 Harris Blvd.  
Historic Knippa-Huffman House

**DATE**  
May 6th, 2019







IMAGES OF COMPLETED WORK BY MASON, MICHAEL WILLIAMS. MR. WILLIAMS HAS WORKED ON SEVERAL HISTORIC, THE CONTRACTOR HAS RETAINED MR. WILLIAMS SERVICES BASED ON HIS SPECIFIC SKILL SET WORKING WITH HISTORIC MASONRY.



**PROJECT**  
2414 Harris Blvd.  
Historic Knippa-Huffman House

**DATE**  
May 6th, 2019

