

1805 E. 3<sup>rd</sup> Street - Condition Photos  
Taken by City staff 6/6/2019



*North elevation*





*Detail of west wall*



*Detail of west wall*



*Foundation*






*Foundation*



*Foundation*



*Interior*



*Interior*






*Interior*



*Interior detail*




*Interior*



*Interior of rear addition*





*Rear addition*



*Rear addition*